

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9920U**AAD1908-127***Not Notified*
11 Sep @ 1850h

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

20 AUG 2019

SHD 9920U

VF1ABL15AUC277504

RENAULT

LATITUDE

18.8.19

AIG

5/6/2014

		PART	LIST	
1	1	BUMPER COVER REAR	\$ Bu 1,108.46	—
2	1	BUMPER LOWER REAR	\$ Ad/ly 768.84	—
3	1	BUMPER BRACKET CTR REAR	\$ Sn 113.47	}
4	1	BUMPER BRACKET SIDE RH REAR	\$ Sn 135.97	
5	1	BUMPER RETAINER RH REAR	\$ Sn 44.99	
6	1	BUMPER REFLECTOR RH	\$ Sn 43.61	
7	1	BUMPER BRACKET SIDE LH REAR	\$ Sn 135.97	
8	1	BUMPER RETAINER LH REAR	\$ Sn 44.99	
9	1	BUMPER REFLECTOR LH	\$ Sn 43.61	
10	1	BUMPER BEAM REAR	\$ R 777.52	
11	1	BUMPER BEAM BRACKET LH REAR	\$ R 225.95	
12	1	BUMPER BEAM BRACKET RH REAR	\$ R 225.95	
13	1	OUTER PANEL REAR (End Panel)	\$ R 1,471.77	} X
14	1	OUTER PANEL REAR (End Panel)TRIM	\$ Sn 404.56	
15	1	TAILLAMP RH	\$ Sn 552.55	
16	1	TAILLAMP PANEL RH	\$ R 986.70	
17	1	TAILLAMP LH	\$ n-c (CRM) 552.55	
18	1	TAILLAMP PANEL LH	\$ R 986.70	
19	1	BOOT REAR	\$ R 2,872.68	
20	1	BOOT FINISHER	\$ Sn 470.06	
21	1	BOOT WHEATERSTRIP	\$ Sn 323.05	
22	1	BOOT REFLECTOR LAMP LH	\$ Sn 493.35	
23	1	BOOT REFLECTOR LAMP RH	\$ Sn 493.35	
24	1	BOOT BADGE 'RENAULT'	\$ R 225.36	
25	1	BOOT BADGE	\$ R 225.36	
26	1	BOOT STRUT LH	\$ Sn 276.08	
27	1	BOOT STRUT RH	\$ Sn 276.08	
28	1	BOOT HINGE LH	\$ R 367.84	
29	1	BOOT HINGE RH	\$ R 367.84	

Trans-cab Auto Services Pte Ltd**AAD1908-127**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9920U

30	1	BOOT INNER TRIM	\$	Sh	586.45	}	X
31	1	BOOT SWITCH	\$	Sh	168.13		
32	1	BOOT LOCK	\$	n	202.67		
33	1	BOOT LOCK CATCH	\$	n	74.40		
34	1	FENDER PANEL INNER TRIM REAR LH	\$	Sh	671.45		
35	1	FENDER PANEL REAR LH	\$	n	3,299.13		
36	1	WHEELARCH REAR LH	\$	n	543.47		
TOTAL			\$		20,560.93		
10%			\$		2,056.09		
			\$		18,504.84		

Special Nett

Special Nett					
1	1SET	PARKING AID	\$	Sh	700.00 X
2	1SET	REAR BUMPER CLIP	\$	na	66.00 —
3	1SET	BUMPER BRACKET CTR CLIP	\$	na	33.00 —
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00 X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	na	20.00 X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00 X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	na	20.00 X
8	1SET	BUMPER LOWER REAR RIVET	\$	na	22.00 X
9	1SET	BUMPER LOWER REAR CLIP	\$	na	66.00 —
10	1	BOOT STICKER "Trans-cab"	\$	na	30.00
11	1	BOOT STICKER "6555-3333"	\$	na	30.00
12	1	EXHAUST MOUNTING REAR	\$	Sh	17.82
13	2	REAR WINDSCREEN SEALANT	\$	na	80.00
14	1	WINDSCREEN MOULDING	\$	na	100.00
15	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00
16	1	BOOT INNER TRIM CLIP	\$	na	45.00
17	1SET	BOOT FINISHER CLIP	\$	na	24.20
18	1	TAILLAMP CLIP LH	\$	na	5.00
19	1	TAILLAMP CLIP RH	\$	na	5.00
20	1	Rear Bumper Protector	\$	na	100.00
21	1SET	FENDER WHEELARCH REAR LH CLIP	\$	na	35.00
22	1	FENDER INNER TRIM CLIP LH	\$	na	28.00
23	1	REAR LEFT TYRE	\$	Sh	300.00
24	1	REAR LEFT TYRE RIM	\$	Sh	380.00
TOTAL			\$		2,227.02

Trans-cab Auto Services Pte Ltd**AAD1908-127**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9920U**TOTAL PARTS \$ 20,731.86****LABOUR**

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i> 170.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	<i>nn</i> 170.00	<i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	<i>X</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>601</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,500.00	<i>2001</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	<i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>4</i> 170.00	<i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>4</i> 170.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>L</i> 220.00	<i>X</i>
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>4</i> 380.00	<i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>4</i> 380.00	<i>X</i>

Trans-cab Auto Services Pte Ltd**AAD1908-127**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9920U

Putty And Spray Painting Of The Affected Portion.	\$	4,500.00	220/
TOTAL	\$	11,930.00	
Over All Total	\$	32,661.86	

LUMP SUM (REPAIR DAY)~~15 DAYS~~

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: