



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

QBE INSURANCE (SINGAPORE) PTE LTD

INV No. AC2102956

1 RAFFLES QUAY #29-10 SOUTH TOWER
SINGAPORE 048583

INV Date 28/04/2021
Reference CC3/QBE19014786/K1ea3q

Code QBE

PROFESSIONAL SERVICE FEE

Vehicle No. SHA 7272K

Insured Veh. SGD 2008L

Claim No. VC013589

Policy No.

Accident Date 20/08/2019

Inspection Date 21/08/2019

Description	Total
Survey Inspection	300.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	300.00
GST (7%)	21.00
Grand Total	321.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
QBE INSURANCE (SINGAPORE) PTE LTD 1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583			Ref: CC3/QBE19014786/K1ea3q2	
			Date: 28/04/2021	
			Code: QBE	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGD 2008L	Veh. Inspected	SHA 7272K	
Policy No.		Coverage (\$)	0.00	
Claim No.	VC013589	Excess (\$)	0.00	
Assign From		Assign Date	21/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI IONIQ	c.c	1580	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	KMHC851CVKU165233	Colour	BLUE	
Odometer	5738 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	MICHELIN	9 mm	
L/H Front Tyre	195/65 R15	MICHELIN	9 mm	
R/H Rear Tyre	195/65 R15	MICHELIN	9 mm	
L/H Rear Tyre	195/65 R15	MICHELIN	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/08/2019	Inspection Date	21/08/2019	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 7272K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER COVER	TO REPAIR SEE LABOUR	418.30	-
1	FRONT BUMPER BRACKET TOP (RH)	SERVICEABLE	35.00	-
1	FRONT BUMPER BRACKET (RH)	SERVICEABLE	28.00	-
10	FRONT BUMPER CLIPS	NECESSARY	22.00	22.00
1	HEADLAMP (RH)	SERVICEABLE	1,198.80	-
1	FRONT FENDER (RH)	BUCKLED	490.70	490.70
1	FRONT FENDER SHIELD (RH)	SERVICEABLE	114.70	-
1	FRONT FENDER RETAINER	SERVICEABLE	41.40	-
1	EMBLEM -BLUE DRIVE (RH)	NECESSARY	26.60	26.60
	LESS 20% DISCOUNT		-475.10	-
	LESS 25% DISCOUNT		-	-134.82
			1,900.40	404.48
	<u>LABOUR</u>			
	PANEL BEATING .INCLUSIVE OF THE REPAIR OF FRONT BUMPER COVER .		400.00	200.00
	SPRAY PAINTING CHARGE.		600.00	400.00
	WIRING CHARGE.	NOT NECESSARY	50.00	-
	TUFF KOTE.		50.00	20.00
			1,100.00	620.00
GRAND TOTAL			3,000.40	1,024.48
RECOMMENDED COST OF REPAIRS				1,024.48

Report Ref No. CC3/QBE19014786/K1ea3q2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 7272K

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 7272K

RE-INSPECTION

