

REPAIR ESTIMATE*


VEHICLE NO : SHA 7272K

DATE 20/8/2019 17:09

MAKE :

MODEL : HYUNDAI IONIQ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>x repair</i>			\$ 418.30
	Front Bumper Bracket Top (RH) <i>x su</i>			\$ 35.00
	Front Bumper Bracket (RH) <i>x su</i>			\$ 28.00
	Front Bumper Clips 10 pcs <i>- su</i>			\$ 22.00
	Headlamp (RH) <i>x su</i>			\$ 1,198.80
	Front Fender (RH) <i>- R/LK</i>			\$ 490.70
	Front Fender Shield (RH) <i>x su</i>			\$ 114.70
	Front Fender Retainer <i>x su</i>			\$ 41.40
	Emblem-Blue Drive (RH) <i>- su</i>			\$ 26.60
	SUB TOTAL			\$ 2,375.50
	LESS 20% <i>250/0</i>			\$ 475.10
	DISCOUNTED TOTAL			\$ 1,900.40
	Labour Charge			200
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 600.00 <i>400</i>
	Wiring Charge			\$ 50.00 <i>x 2</i>
	Tuff Kote			\$ 50.00 <i>20</i>
	TOTAL LABOUR			\$ 1,100.00
	ESTIMATE TOTAL			\$ 3,000.40
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				



Ka/ini (LKK)
21/8/19 1110 hrs.
2 Days
P/P
Before Paint p/hts