

ASS. REF. BY:

REF: CS/CT119014788/R2w30

Special Instructions:

SUNVA/OT Rosul

ASSIGNMENT (Office)

From (Person):

Tan Kah Leong

of

CT1

Date/Time:

22.8.19 15.29p.m

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLT 8909D

Insured:

GBJ 6377Y

at Workshop m/s:

Performan

Tel:

6390174

of 303 Alexandra Road

Policy No:

DMCVSY50489119000

Claim No:

SNM/9D203882102

Sum Insured:

Excess:

Make of Veh:

D.O.A.

18.8.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

my

Date/Time:

22.8.19 4.17p.m

Person Contacted:

Caroline

H.O.D. Endorsement

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	GBJ 6377Y - CS/CT119014788/R2w30 D.O.A. 18/8/2019
	SLT 8909D - X
6/11/19	Recd email from Sharon vehicle did not carry out repair job at PML
7/11/19	Submit preli report - vehicle not send in for repair

Rare

REF: CRI

227C

ASSIGNMENT

Front

Date

2/10/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLT 8909D

at Workshop n/s

Performance Motor

of

303 Alexandra Road

Insured:

Policy No

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

10 am (waiting)

Intervin

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLT 8909D

Yt Regn:

2017 / NOV

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

B.M.W 520I LED NAV

C.C.

1998

Colour:

GREY

A/C:

Insured / Std / NI / NA

Sp. Reading

55967

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WBAJA12040BE45101

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/45R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A:

18/08/19

D.O.L:

01/10/19

Survey held at

PERFORMANCE

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 07 NOV 2019

Date/Time, File Path to?



Prel. Report

1)



Final Report

Date/Time, File Path to?

2/11 - typist

Report Format:

Memorandum

Long Sum / UIC:

Days Of Repair:

11

Resurvey No. of Trip:

Art Fee:



Site Insp (5)



Interview (5)



Tech. Insp (5)



Visual Insp (5)

Survey Fee:

220

Transportation:

3 x 100 = 300

Phone

1000

1000

1000

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Aug 2019		22 Aug 2019 15:29 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	KM KINLEY MARKETING PTE LTD, Co. Reg. No.: 20041227C		
Vehicle Reg. No.:	SLT8909D	Date of Loss:	18/08/2019 12:00 - :59
Claim Type:	TP / SNM19D203883C02	Policy/Cover Note No.:	DMCVSN30489119000
Vehicle Reg. No. (Insured):	G8J6377Y	Policy No. (Claimant):	VA1/GA295316
		Excess:	S\$350.00
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 02/09/2019]		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Wednesday, 25 September 2019 3:37 PM
To: assignments
Cc: Inthiran Thurasamy
Subject: SURVEY APPOINTMENT - SNM19D203883-GBJ6377Y-TKL - FW: REQUEST FOR DIRECT SETTLEMENT - SLT8909D & GBJ6377Y ON 18/08/2019

Dear Sirs

Please arrange a survey on 2 Oct 2019 at 10am.

***Owner waiting.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

Veron Chen (LKKAUTO)

From: Sharon Heng L K <sharon.heng.leekun@simedarby.com.sg>
Sent: Wednesday, 6 November 2019 5:38 PM
To: Veron Chen (LKKAUTO); Cresendo Llorca Lagman
Cc: Keith Leo Chi Yung; Teng Wai Khan; Toh Jing Xuan; mohd.sanif@simedarby.com
Subject: RE: PENDING FINALISE (4 VEHICLES)

Dear Veron

Check our system, SBV2228h & SLT8909D did not carry out repair job at PML

Best Regards

Sharon Heng
Performance Motors Ltd
Body & Paint
DID : 63190123
Fax : 64743229



"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Wednesday, 6 November, 2019 5:06 PM
To: Sharon Heng L K; Cresendo Llorca Lagman
Cc: Keith Leo Chi Yung; Teng Wai Khan; Toh Jing Xuan; mohd.sanif@simedarby.com
Subject: RE: PENDING FINALISE (4 VEHICLES)

Dear Sharon,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

VEHICLE DOA

- 1) SDQ 3128J 16/10/2019
- 2) SBV 2228H 13/8/2019
- 3) SLT 8909D 18/8/2019
- 4) SLP 9069S 15/10/2019

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sharon Heng L K <sharon.heng.leekun@sime-darby.com.sg>

Sent: Tuesday, 22 October 2019 4:26 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Cresendo Lurca Lagman <cresendo.lagman@sime-darby.com.sg>

Cc: Keith Leo Chi Yung <keith.leo.chiyung@sime-darby.com.sg>; Teng Wai Khan <teng.wai.khan@sime-darby.com.sg>; Toh Jing Xuan <toh.jing.xuan@sime-darby.com.sg>; mohd.sanif@sime-darby.com

Subject: RE: PENDING FINALISE (2 VEHICLES)

Dear Cre

Both are Gary's, SLL6119Y, job card issue on 30.9.2019, please help to hand over job folder to me.
SBV2228H, no job card, but estimate # is 52308

Best Regards

Sharon Heng
Performance Motors Ltd
Body & Paint
DID : 63190123
Fax : 64743229



"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Tuesday, 22 October, 2019 4:16 PM
To: Sharon Heng L K
Cc: Keith Leo Chi Yung; Teng Wai Khan; Toh Jing Xuan; mohd.sanif@simedarby.com
Subject: RE: PENDING FINALISE (2 VEHICLES)

Dear Sharon,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

VEHICLE DOA

- 1) SBV 2228H 13/8/2019
- 2) SLL 6119Y 19/8/2019

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Friday, 4 October 2019 3:19 PM
To: Sharon Heng L K <sharon.heng.leekun@simedarby.com.sg>
Cc: Keith Leo Chi Yung <keith.leo.chiyung@simedarby.com.sg>; Teng Wai Khan <teng.wai.khan@simedarby.com.sg>; Toh Jing Xuan <toh.jing.xuan@simedarby.com.sg>; mohd.sanif@simedarby.com
Subject: RE: PENDING FINALISE (2 VEHICLES)

Dear Sharon,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

VEHICLE DOA

- 1) SBV 2228H 13/8/2019
- 2) SLH 9709X 6/8/2019

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Monday, 23 September 2019 10:38 AM
To: Sharon Heng L K <sharon.heng.leekun@simedarby.com.sg>
Cc: Keith Leo Chi Yung <keith.leo.chiyung@simedarby.com.sg>; Teng Wai Khan <teng.wai.khan@simedarby.com.sg>; Toh Jing Xuan <toh.jing.xuan@simedarby.com.sg>; mohd.sanif@simedarby.com
Subject: PENDING FINALISE (3 VEHICLES)

Dear Sharon,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

VEHICLE DOA

- 1) SLA 2729X 12/8/2019
- 2) SBV 2228H 13/8/2019
- 3) SLH 9709X 6/8/2019

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/08/2019 15:18
Date Of Accident	18/08/2019 12:35
Exact Location Of Accident	BLK 125A CARPARK OPEN
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT8909D
Insured/Policyholder	
Name Of Registered Owner	KM KINLEY MARKETING PTE LTD
Co Reg No	20041227C
Email Address	SAMUEL@KINLEY.COM.SG
Mobile Phone No	(LOCAL) +65-96551425
Alternative Phone No	OFFICE-96551425

Vehicle Particulars

Manufacturer	BMW
Model	520
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VA1/GA295316
Cover Note Number	

Driver

Name of Driver	HAN SWEE HIN
NRIC No	S7016389F
Date Of Birth	14/05/1970
Occupation	INDOOR
Date Of Driving Pass	12/12/1996
Driving Experience	22 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96551425
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	28 BUKIT BATOK EAST AVENUE 2 #15-18
Postcode	659921
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : POON SWEE PENG GENDER: : FEMALE
Passenger 2	NAME: : HAN ROY HEE GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBJ6377Y
Vehicle Make/Model/Colour	FIAT BLACK
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	LIM WENG KAI
NRIC/Passport Number	S9182000E
Contact Number	
Address	BLK 146 LORONG 2 TOA PAYOH #30-316
Postcode	310146

Insurance Company Name

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Nature Of Damage

REAR

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Person's Signature
Name: Insurance AC Pursuant
NRIC/FIN No: Performance Motors Ltd
202 Alexandra Road
Sime Early Performance Centre
Singapore 119941

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- Waiting @ the junction & waiting for the vehicle to clear.
- Suddenly the vehicle (GBJ 6377Y) had reversed and knocked into my car @ rear left portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

John Long
Policyholder's Signature

Date & Time: 19/8/17



[Signature]
Driver's Signature
(If driver is not the policyholder)

Date & Time:

[Signature]
Reporting Centre Personnel's Signature
Name: Performance Unit Limited
NRIC/FIN No.: 803478000000
(Singapore Police Department)
Singapore 110047

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747775

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64756501 (AfterSales)
64756524 (Motorrad)



Survey LKK
2/10/19 at
10am

GST REG. NO : M2 - 0020081 - X

Kah Leong
22 AUG 2019

ESTIMATE

Estimate No. : b1 52424
Date Estimated : 22/08/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
KM Kinley Marketing Pte Ltd
17 Tech Park Crescent

Singapore 638115

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLT8909D	BE45107	22/11/2017	520iA	0

DESCRIPTION

To replace rear right fender ,rear bumper and attachments=.

VALUE
5100 6,800.00

Painting rear bumper, rear right fender, roof frame and trunk floor.

2749 3,085.00

To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs.

742 878.00

To supply and install rear windscreen solar film.

? 531.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

To remove and install fuse box at the rear section to facilitate repairs.

451 531.00

To remove and install fuel tank to facilitate repairs including extract fuel and conduct leak tests.

451 531.00

To carry out body cavity preservation.
(For cut panel).

451 531.00

Sundries.

150.00

Total Labour 1: 13,179.00

DESCRIPTION

PLASTIC NUT FOR COARSE THREADED PIN ?

QTY	PRIC	VALUE
8	0.80	6.40

REAR RH SIDE PANEL b1

1	1,984.25	1,984.25
---	----------	----------

Reinforcemen ?

1	52.40	52.40
---	-------	-------

Reinforcemen ?

1	52.40	52.40
---	-------	-------

T WELD BOLT L=5.4MM ?

12	0.85	10.20
----	------	-------

REAR BUMPER RH SIDE GUIDE ?

1	67.45	67.45
---	-------	-------

REAR BUMPER PANEL PRIMED (PDC/PMA) repair

1	1,619.15	1,619.15
---	----------	----------

SET MOUNTING PMA SENSOR ?

1	69.00	69.00
---	-------	-------

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

103, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

118, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 52424
Date Estimated : 22/08/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLT8909D	BE45107	22/11/2017	520iA	0

DESCRIPTION	QTY	PRIC	VALUE
PLASTIC NUT <i>see</i>	5	0.85	4.25
BUMP STOP <i>see</i>	10	3.50	35.00
REAR WINDOW GREEN (ESG) ? <i>photo?</i>	1	962.25	962.25
REAR RH LIGHT IN THE SIDE PANEL <i>see</i>	1	622.10	622.10
SET ADHESIVE PADS FOR ACE 2.0 <i>see</i>	1	41.15	41.15
CAVITY PROTECTION WAX REMOVER 500ML <i>see</i>	1	18.45	18.45
BLIND RIVET AVIBVLB <i>see</i>	18	0.55	9.90
SCREW (SF PLUS M5X15) <i>see</i>	5	0.55	2.75
(DG/SL) BODY ADHESIVE K5B (195ML) <i>see</i>	1	326.80	326.80
(DG) BODYWORK ADHESIVE K5A (50ML) <i>see</i>	1	112.70	112.70
(DG) CLEANER R1 (100ML) <i>see</i>	1	26.15	26.15
(DG) CLEANER R1 (100ML) <i>see</i>	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) <i>see</i>	1	131.55	131.55
PUNCH RIVET N4 <i>see</i>	42	0.55	23.10
(DG/SL) GLASS PRIMER 30ML (VP206) <i>see</i>	1	27.85	27.85
(S/L) SEAM SEAL 300ML <i>see</i>	1	33.80	33.80

Total Parts : 6,265.20

Claim's CD / End Party / Uninsured losses / Direct Settlement

Reg No. _____ Claim No. _____

Date/Time 01/10/19 @ 0950 Excess \$ _____

Surveyor's Name P. Ravi Sign _____

Surveyor's Tel. 900 60668 Authorised Yes / No _____

Author's Name _____ Time _____

REPAIR PARTS PHOTO B EMPLOYER Yes / No _____ P.M. Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommended 11 days

LRS Auto Consultants hence notify the Repairer of the following:

- To recovery before/after survey parking
- To display damaged part(s) during recovery
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insuring Company

Acknowledged by Repairer

Signature: _____

Date: _____

11/10/20

Labour 1	:	13,179.00
Parts	:	6,265.20
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,361.09
Grand Total	:	20,805.29

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Aug 2019		22 Aug 2019 15:29 Edit Adj Rpt	S\$13,669.95 Edit Estimates	S\$13,669.95 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	Co. Reg. No.: -		
Main Claimant:	KM KINLEY MARKETING PTE LTD, Co. Reg. No.: 20041227C		
Vehicle Reg. No.:	SLT8909D	Date of Loss:	18/08/2019 12:00 - :59 [20 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D203883C02	Policy/Cover Note No.:	DMCVSN30489119000
Vehicle Reg. No. (Insured):	GBJ6377Y	Policy No. (Claimant):	VA1/GA295316
		Excess:	S\$350.00
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 02/09/2019]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLT8909D (SNM19D203883C02)
[GBJ6377Y]
TP
KM KINLEY MARKETING PTE LTD
Aug 18 2019 12:00PM
[-]
Performance Motors Limited


Upload Documents Upload Photos Compose New Letter

View View in Browser

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/11/19 09:08	General View	 Load PDF	

Linked Accident Report Documents

View View in Browser

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	19/08/19 17:31	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	19/08/19 17:28	Accident Photo	 Load JPG <input checked="" type="checkbox"/>	
2	19/08/19 17:28	Accident Photo	 Load JPG <input checked="" type="checkbox"/>	
3	19/08/19 17:28	Accident Photo	 Load JPG <input checked="" type="checkbox"/>	
4	19/08/19 17:28	Accident Photo	 Load JPG <input checked="" type="checkbox"/>	
5	19/08/19 17:28	Accident Photo	 Load JPG <input checked="" type="checkbox"/>	
6	19/08/19 17:28	Accident Photo	 Load JPG <input checked="" type="checkbox"/>	
7	19/08/19 17:28	Accident Photo	 Load JPG <input checked="" type="checkbox"/>	
8	19/08/19 17:28	Accident Photo	 Load JPG <input checked="" type="checkbox"/>	
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	19/08/19 15:23	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119014788/R1VF3E2

Date: 21/11/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN30489119000
 Claimant Vehicle No: SLT8909D Insured Vehicle No: GBJ6377Y
 Date of Loss: 18/08/2019 Nature of Claim: TP Claim No: SNM19D203883C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLT8909D**
 Make & Model: BMW 520i, 2.0 (A) Engine No: 23965043B48B20A
 Reg. Date: 22/11/2017 (Man. Year: 2017) Chassis No: WBAJA12040BE45107
 Colour: Grey Odometer: 55967 km
 Engine Capacity: 1998 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 245/45 R18 Rear Tyre Size: 245/45 R18
 Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
 Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,415.20	3,575.95	2,839.25	44.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,029.00	10,094.00	2,935.00	22.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,444.20	13,669.95	5,774.25	29.70
+ GST 7.00/7.00% (S\$)	1,361.09	956.90	404.19	29.70
Nett Amount (S\$)	20,805.29	14,626.85	6,178.44	29.70

INSPECTION

Date of Assignment: 22/08/2019
 Date Inspected: 01/10/2019 Inspected At: Performance Motors Limited (Alexandra)
 303 Alexandra Road, Sime Darby Performance Centre
 Singapore 159941
 Estimated Period of Repair: 11.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$1,751.10 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Nov 2019)
Parts:	143	BMW 520i 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT8909D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	8		*PLASTIC NUT FOR COARSE THREADED PIN	* Check	6.40 FS	*- FS
3	1		*REAR RH SIDE PANEL	Bent	1,984.25 FS	*1,984.25 FS
4	1		*REINFORCEMENT	* Check	52.40 FS	*- FS
5	1		*REINFORCEMENT	* Check	52.40 FS	*- FS
6	12		*T WELD BOLT L=5.4MM	* Check	10.20 FS	*- FS
7	1		*REAR BUMPER RH SIDE GUIDE	* Check	67.45 FS	*- FS
8	1		*REAR BUMPER PANEL PRIMED (PDC / PMA)	Repair	1,619.15 FS	*- FS
9	1		*SET MOUNTING PMA SENSOR	* Check	69.00 FS	*- FS
10	5		*PLASTIC NUT	Necessary	4.25 FS	*4.25 FS
11	10		*BUMP STOP	Necessary	35.00 FS	*35.00 FS
12	1		*REAR WINDOW GREEN (ESG)	* Check	962.25 FS	*- FS
13	1		*REAR RH LIGHT IN THE SIDE PANEL	Cracked	622.10 FS	*622.10 FS
14	1		*SET ADHESIVE PADS FOR ACE 2.0	Necessary	41.15 FS	*41.15 FS
15	1		*CAVITY PROTECTION WAX REMOVER 500ML	Necessary	18.45 FS	*18.45 FS
16	18		*BLIND RIVET AVIBVLB	Necessary	9.90 FS	*9.90 FS
17	5		*SCREW (SF PLUS M5X15)	Necessary	2.75 FS	*2.75 FS
18	1		*(DG/SL) BODY ADHESIVE K5B (195ML)	Necessary	326.80 FS	*326.80 FS
19	1		*(DG) BODYWORK ADHESIVE K5A (50ML)	Necessary	112.70 FS	*112.70 FS
20	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26.15 FS
21	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26.15 FS
22	1		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	131.55 FS	*131.55 FS
23	1		*PUNCH RIVET N4 (42PCS)	Necessary	23.10 FS	*23.10 FS
24	1		*(DG/SL) GLASS PRIMER 30ML (VP206)	Necessary	27.85 FS	*27.85 FS
25	1		*(S/L) SEAM SEAL 300ML	Necessary	33.80 FS	*33.80 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	6,415.20	3,575.95
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR RIGHT FENDER, REAR BUMPER AND ATTACHMENTS	New	6,800.00	5,100.00
2	PAINTING REAR BUMPER, REAR RIGHT FENDER, ROOF FRAME AND TRUNK FLOOR	New	3,055.00	2,749.00
3	TO REMOVE AND INSTALL REAR HAT-TRAY, REAR SEAT, CARPET AND ROOF TOP LINING TO FACILITATE REPAIRS	New	873.00	742.00
4	TO SUPPLY AND INSTALL REAR WINDSCREEN SOLAR FILM (* Check)	New	531.00	0.00
5	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
6	TO REMOVE AND INSTALL FUSE BOX AT THE REAR SECTION TO FACILITATE REPAIRS	New	531.00	451.00
7	TO REMOVE AND INSTALL FUEL TANK TO FACILITATE REPAIRS INCLUDING EXTRACT FUEL AND CONDUCT LEAK TESTS	New	531.00	451.00
8	TO CARRY OUT BODY CAVITY PRESERVATION. (FOR CUT PANEL)	New	531.00	451.00
Gross Labour Cost (S\$)			13,029.00	10,094.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >