

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AXA INSURANCE (S) PTE LTD
 8 SHENTON WAY
 #27-02 AXA TOWER
 SINGAPORE 068811

TEL: 63387288 FAX: 68804739
 ATTN: Motor Claim Department

WS Ref: TP/AXA/AMK
 Claim Type: Third Party
 Accident Date: 21/08/2019
 TP Veh Reg No: SLD851Y

FAX: 68804739

Estimate No: ES1991910/AMK

Date: 22 Aug 2019

Policy No: 5086625028-02 DC

Veh Reg No: SJR5258C

Make/Model: TOYOTA COROLLA
 ALTIS 1.6 AUTO

Chassis No: MR053ZEE106147765

Engine No: 3ZZ4902492

Reg. Date: 26/06/2009

Estimate Repair Cost to Vehicle No :SJR5258C

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
List Price				
1 REAR BUMPER	534.60	1 PC	B ₁ 534.60	✓
2 REAR BUMPER RH SIDE RETAINER	58.60	1 PC	CM 58.60	✓
3 REAR BUMPER RH CORNAL RETAINER	37.80	1 PC	CM 37.80	✓
4 REAR BUMPER SPONGE	155.70	1 PC	CM 155.70	?
5 REAR BUMPER RH REFLECTOR	42.70	1 PC	CM 42.70	✓
6 REAR BUMPER CLIP	3.89	5 PC	M 19.45	✓
7 REAR BOOT	911.60	1 PC	B ₁ 911.60	✓
8 REAR BOOT INNER LOCK	126.80	1 PC		?
9 REAR BOOT INNER RUBBER	194.70	1 PC	dis/b ₁ 194.70	502m
10 REAR BOOT LOGO	55.80	1 PC	M 55.80	✓
11 REAR BOOT EMBLEM '1.6'	32.13	1 PC	M 32.13	✓
12 REAR BOOT EMBLEM 'COROLLA'	51.17	1 PC	M 51.17	✓
13 REAR BOOT EMBLEM 'ALTIS'	50.22	1 PC	M 50.22	✓
14 REAR BOOT RH REFLECTOR	195.70	1 PC	CM 195.70	✓
15 RH TAILLAMP	424.10	1 PC	B ₁ 424.10	✓
16 RH TAILLAMP PANEL	103.40	1 PC	B ₁ 103.40	✓
17 RH TAILLAMP CLIP	3.89	1 PC	MC 3.89	✓
18 REAR RH FENDER	927.45	1 PC	B ₁ 927.45	✓
19 REAR RH FENDER INNER TRIM	388.90	1 PC	Reform 388.90	✓
20 REAR RH FENDER AIR GRILLE	155.40	1 PC	D ₁ 155.40	✓
21 REAR END PANEL	580.60	1 PC	B ₁ 580.60	✓
22 REAR END PANEL INNER TOP GARNISH	227.20	1 PC	mg d ₁ 227.20	✓
23 REAR END PANEL INNER TOP GARNISH CLIP	3.21	2 PC	M 6.42	✓
24 REAR SPARE TYRE PANEL INNER TOP BOARD	369.20	1 PC	CM 369.20	✓
25 REAR WINDSCREEN GLASS MOULDING	109.78	1 PC	M 109.78	✓
26 REAR MUFFLER	791.71	1 PC	B ₁ 791.71	✓
27 REAR MUFFLER RUBBER MOUNTING	47.80	1 PC	T ₁ 47.80	✓
			6,602.82	
Less 25%			1,650.71	4,952.12
Special Net				
28 REVERSE SENSOR	200	1 SET	Short 200.00	✓
29 REAR WINDSCREEN GLASS SEALANT	40	1 PC	M 40.00	✓
30 REAR END PANEL SEALANT	40	1 PC	M 40.00	✓
			280.00	280.00
Labour				

Not authorized

1/1 Day @ ?

Running After Repair

10 days

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AXA INSURANCE (S) PTE LTD
8 SHENTON WAY
#27-02 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

WS Ref: TP/AXA/AMK

Claim Type: Third Party

Accident Date: 21/08/2019

TP Veh Reg No: SLD851Y

Estimate No: ES1991910/AMK

Date: 22 Aug 2019

Policy No: 5086625028-02 DC

Veh Reg No: SJR5258C

Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO

Chassis No: MR053ZEE106147765

Engine No: 3ZZ4902492

Reg. Date: 26/06/2009

Estimate Repair Cost to Vehicle No :SJR5258C

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
31 TOWING	50	1 LA	50.00	✓
32 REMOVE AND REFIX REAR WINDSCREEN GLASS	120	1 LA	120.00	✓
33 REMOVE & REFIX REAR BUMPER,REAR BOOTLID & ATTACHMENTS,TAILLAMPS;TO CUT,WELD & RENEW REAR END PANEL,REAR RH FENDER;KNOCKING & REPAIR REAR RH DOOR,REAR CHASSIS FRAME,REAR SPARE TYRE PANEL & REALIGN THE SAME	1,400	1 LA	1,400.00	1200 ✓
34 PUTTY & RESPRAY REAR BUMPER,REAR BOOT,REAR FENDERS,REAR END PANEL,REAR SPARE TYRE PANEL,CHASSIS FRAME,REAR RH DOOR & ALL AFFECTED AREAS	1,300	1 LA	1,300.00	1200 ✓
35 REMOVE & REFIX REAR EXHAUST MUFFLER & REALIGN THE SAME	60	1 LA	60.00	✓
36 REMOVE & REFIX REAR SEAT,CARPET TO FACILITATE REPAIR	100	1 LA	100.00	✓
37 RUSTPROOFING	120	1 LA	120.00	90 ✓
38 TO MOUNT ON CAR-O-LINER,JACK & STRAIGHTEN CHASSIS	250.00	1 LA	250.00	✓
			3,400.00	3,400.00
			Total	S\$ 8,632.12
			Add GST @ 7%	604.25
			Total Amount Payable	S\$ 9,236.37

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance company

Acknowledged by Repairer:
Signature:
Date:



24 Hours Towing Services

Efficient Towing Services

403 Sin Ming Avenue #13-307, Sin Ming Garden, Singapore 570403

Ah Di Mobile: 8588 8877

Email : efficienttowing.sg@gmail.com

Business Reg. No.: 53349344K

CASH SALE / JOB ORDER

NO. 36858

Date : 21/8/19

Messrs: CHENG HOE
 车牌 SJR5258C 车型 TOYOTA ALTIS
 Vehicle No. SJR5258C Model No: TOYOTA ALTIS
 时间 (日/夜) 2005 联络号码 81836020
 Time (day/night): 2005 Contact No: 81836020
 由 541 HOUGANG AVE 8
 Location: 541 HOUGANG AVE 8
 到 AUTO POINT #01-04
 To: AUTO POINT #01-04
 银额 50/ 其他
 Cash \$ 50/ Others:
 经手人 DENISE Tow Truck 720
 Authorised By: DENISE Driver Name: 720

- ☐ Jump Start/Changing of battery
- ☐ Tyre Replacement
- ☐ Accident/Breakdown
- ☐ Multi/Basement
- ☐ With Load/Cargo Box
- ☐ King Dolly
- ☐ Transport Charge
- ☐ Low Body Kit
- ☐ Door Opening Service
- ☐ Crane Up/Winch Out
- ☐ Collect Doc/Key
- ☐ Repo
- ☐ Woodlands and Tuas Checkpoint

注意: 本公司对所拖之车辆, 在进行中如有任何损失或破坏, 一概由车主自行负责。

Note: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

E. & O. E.