

15/02/2019

INS. CASE OWNER:

SALIHA

CC4/AIG19014796/Uea3

LKK:

IDAC:

Surveyor:

MARCUS

DOI: 22/08/2019

Date / Time: 22/08/2019

Registered in Merimen: 22/08/2019

Pre-assign / CCU / FTE



Insured Vehicle No. : SMN 1194P

Name of Insured : CHIAM CHYE MENG

Insured Tel No. : HP: _____

Excess Sec II : S\$ _____ D.O.A 21/08/2019 08:30

Is driver the owner? (YES / NO) Nature of Accident : _____

If NO, Driver Name / Age : CHIAM CHOON KAI DARRYL

Driver Tel No. : +65-90909093 (V/L: YES / NO)

Claim No. : 1530218236SG

Policy No. : 1900140943

Make / Model : BMW 540I-3.0 SR LED NAV

Place of Accident : SACARA ROAD

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

SMA 9074T

INSRS:
WSP: ASIA MOTORSPORTS
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time		STAGE	DATE / PIC
	SMA 9074T	Non-Reporting ltr (1st):	
	SMN 1194P - NA/INC19014728/z4; DOA:21/8/19	Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
05/09/19 #10-30	CAUSED AND REPORTED ACCIDENT. DID OVERSOME TP. TP MAKE A RUSH TURN. INSURED TP CLAIM. DID MENTION THAT HIS CASE WAS PASS TO HIS OWN LAWYER TO HANDLE.	Notification ltr (if non-pickup):	
		Call OI: 2PM 05/09/19	
		After call ltr to OI:	
		Documentation Check List: Handler	Typist
		Notification ltr (if non-pickup)	☐
		After call ltr to OI:	☒
		Authorisation To Act:	☒
		Release Voucher:	☒
		Final Repair Bill:	☒
		Car Rental Invoice:	☐
		Towing Invoice:	☐
		LTA / GIA :	☒
		Medical Bill:	☐
		PIR:	☐
		Mandate/Reject Instruction:	☒
		LOD	☒
		Payment Breakdown Form:	☐
		Post-Repair Photos:	☐
		Others:	☐

PRELIMINARY ADVICE	Date/Time:	Sent By:	Confirm by: CLK
FINALIZATION	Date/Time:	Confirm with:	Confirm by: CLK
Repair Cost: \$5,400.00	(4 days) Reduction: 54 %	Email ☒ Call ☐	
FINAL SETTLEMENT	Date/Time: 12/11/19	Confirm with:	Email ☒ Call ☐
Final Liability: 100% \$50,000.00	(Agreed / Assessed) BOLA S/N No. : 3A (1/21)	If NO or B 28, Ass. Lia :	
Repair Cost: \$5,400.00	\$50,000.00	TP OVERSOME, A RUSH TURN.	
Loss of Rental (LOR): \$500.00	(5 days)		
Loss of Use (LOU): \$500.00	(\$60 x 5 days)		
Loss of Income (LOI): \$500.00	(\$ x days)		
LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LOI ☐	[Tick only one]		
GIA/LTA Search \$145	\$500.00		
Medical: \$500.00			
Disbursement: \$500.00	(e.g. Tow/ Independent)		
Legal Cost: \$500.00			
Total: \$5,101.45	\$52,851.45	Global Sum \$5:	
FINAL PAYMENT	Date/Time: 12/11/19	Confirm with:	Email ☒ Call ☐
Payee 1: \$52,851.45	Name 1: ASIA MOTORSPORTS SOLUTION PTE LTD		
Payee 2: (Strike if N.A.) \$5	Name 2:		
Payee 3: (Strike if N.A.) \$5	Name 3:		

COPY SENT

- 1) Claim status: Normal/Reject/Private Settle
- 2) Report Format: TP
- 3) Survey fee: \$320

VEHICLE NO SMA 9074T HONDA VEZEL

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	RHS Front Fender 580	Body	980.00	✓
1	RHS Front Fender wheel arch garnish	Dis	283.00	✓
1	RHS Front Fender Inner splash Shield	To	267.00	✓
1	Bonnet	REPAIR	0.00	X
1	Radiator grille	11	382.00	X
1	Front Bumper 801.70	DI	1428.00	✓
1	Front Bumper fog lamp cover RHS	11	244.00	✓
1	Front Bumper fog lamp RHS 327.70	one	428.00	✓
1	Front Bumper lower skirt (spoiler) 420	DI	780.00	✓
2	Front Bumper side retainers RHS & LHS 45.00	O/scre	142.00	IPC
1	RHS Front door	REPAIR	0.00	X
1	RHS Lower sill (rocker panel)	cut/torn	652.00	✓
1	RHS Headlamp	scr	1280.00	✓
1	RHS Headlamp lower bracket	11	248.00	X
1	RHS Front Shock Absorber	scr	592.00	X
1	RHS Front Shock Absorber Coil Spring	11	209.00	X
1	RHS Front Lower Arm	scr	488.00	✓
1	RHS Front lower link	11	278.00	X
1	RHS Front Knuckle Arm	scr	498.00	✓
1	RHS Front Wheel Bearing	scr	279.00	✓
			9458.00	
less 20%			1891.60	20%
			7566.40	
SPECIAL NETT ITEMS				
1SET	RHS Front fender inner shield clips	11	50.00	X
1SET	Front bumper clips	scr	60.00	50
1set	Front fender wheel arch RH clips	11	60.00	X
1	RHS Front sports rim	cut/scr	980.00	480
TOTAL PARTS			8716.40	

6165.40
20%
94932.32
530.00
1300.00
6762.32
20
8409

Not Authorised
Hk
4/5 5400
Hk
To be phd after rep-

VEHICLE NO SMA 9074T HONDA VEZEL

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	1200.00 —	450
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired (RHS front door and bonnet)	1000.00 —	600
3	To check wiring and focus headlamp beam	150.00 —	20
4	To remove and replace RHS front undercarriage parts (suspension system)	300.00 —	120
5	To carry out anti rust treatment on affected areas	150.00 —	30
6	To conduct full computerised wheel alignment test	120.00 —	80
	Labour Total :	2920.00	
	TOTAL (PARTS & LABOUR):	11636.40	1300

NOTE: The parts listed in this preliminary estimate will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts

LKK Auto Consultants hence notify the Repairer of the following:

- To remove vehicle from spray painting
- To deliver damaged parts during resurvey
- Parts may be subjected to confirmation
- Estimate supplied is on a "Without Prejudice" basis
- No other modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Customer: SMA9074T
 Company:
 License NO:
 Odometer:

Date: 22-Aug-19 3:30 PM - 22-Aug-19 3:32
 VIN
 Technician:
 Order NO:

VEHICLE ALIGNMENT REPORT

HONDA, CR-Z, 11-11 (Customized)

Primary Angles

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	—	2.3°	4.3°	—
		Right	—	2.3°	4.3°	—
	Camber	Left	0.7°	-1.0°	1.0°	0.7°
		Right	-0.8°	-1.0°	1.0°	-0.8°
	Toe	Left	-0.35°	-0.15°	0.15°	-0.35°
		Right	0.40°	-0.15°	0.15°	0.40°
Total		0.05°	-0.30°	0.30°	0.05°	
Rear	Camber	Left	-1.7°	-2.5°	-0.5°	-1.7°
		Right	-1.6°	-2.5°	-0.5°	-1.6°
	Toe	Left	0.20°	0.00°	0.30°	0.20°
		Right	0.10°	0.00°	0.30°	0.10°
		Total	0.30°	0.00°	0.55°	0.30°
	Max Thrust Angle		-0.1°	—		-0.1°

Secondary Angles

Secondary Angles		Initial	Specifications		Final
			Min.	Max.	
SAI	Left	----	12.3°	12.3°	----
	Right	----	12.3°	12.3°	----
Included Angle	Left	----	----	----	----
	Right	----	----	----	----
Toe Out On Turns	Left	----	----	----	----
	Right	----	----	----	----
Max Turn Inside	Left	----	----	----	----
	Right	----	----	----	----
Toe Curve Change	Left	----	----	----	----
	Right	----	----	----	----
Setback	Front	-6mm	----	----	-6mm
	Rear	-3mm	----	----	-3mm
Track Width Diff.		16mm			16mm
Wheel Base Diff.		-3mm			-3mm
Front Ride Height	Left	----	----	----	----
	Right	----	----	----	----
Rear Ride Height	Left	----	----	----	----
	Right	----	----	----	----
Frame Angle					----

Phone Number:

Fax Number:

Customer: SMA9074T

Company:

License NO:

Odometer:

Date: 27-Aug-19 4:37 PM - 27-Aug-19 4:49

VIN

Technician:

Order NO:

VEHICLE ALIGNMENT REPORT

HONDA CR-Z, 11-11 (Customized)

Primary Angles

Primary Angles			Initial	Specifications		Final
				Min	Max	
Front	Caster	Left	—	2.3°	4.3°	—
		Right	—	2.3°	4.3°	—
	Camber	Left	0.7°	-1.0°	1.0°	0.7°
		Right	-0.8°	-1.0°	1.0°	-0.8°
	Toe	Left	-0.35°	-0.15°	0.15°	0.05°
		Right	0.40°	-0.15°	0.15°	0.05°
Total		0.05°	-0.30°	0.30°	0.10°	
Rear	Camber	Left	-1.7°	-2.5°	-0.5°	-1.7°
		Right	-1.6°	-2.5°	-0.5°	-1.6°
	Toe	Left	0.20°	0.00°	0.30°	0.20°
		Right	0.10°	0.00°	0.30°	0.10°
		Total	0.30°	0.00°	0.55°	0.30°
	Max Thrust Angle		-0.1°	—		-0.1°

Secondary Angles

Secondary Angles		Initial	Specifications		Final
			Min.	Max.	
SAI	Left	----	12.3°	12.3°	----
	Right	----	12.3°	12.3°	----
Included Angle	Left	----	----	----	----
	Right	----	----	----	----
Toe Out On Turns	Left	----	----	----	----
	Right	----	----	----	----
Max Turn Inside	Left	----	----	----	----
	Right	----	----	----	----
Toe Curve Change	Left	----	----	----	----
	Right	----	----	----	----
Setback	Front	-6mm	----	----	-6mm
	Rear	-3mm	----	----	-3mm
Track Width Diff.		15mm			15mm
Wheel Base Diff.		-3mm			-3mm
Front Ride Height	Left	----	----	----	----
	Right	----	----	----	----
Rear Ride Height	Left	----	----	----	----
	Right	----	----	----	----
Frame Angle					----

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 982D

Vehicle Details

Vehicle No.: SMA9074T
Vehicle to be Exported: No
Intended Deregistration Date: 23 Aug 2019
Vehicle Make: HONDA
Vehicle Model:* VEZEL 1.5X CVT
Primary Colour: White
Manufacturing Year: 2017
Engine No.: L15B4432905
Chassis No.: RU11232901
Maximum Power Output: 96.0 kW (128 bhp)
Open Market Value: \$22,085.00
Original Registration Date: 22 Jun 2018
First Registration Date: 22 Jun 2018
Transfer Count: 0
Actual ARF Paid: \$12,919.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 21 Jun 2028
PARF Rebate Amount: \$9,689.00

Intended COE Rebate Details

COE Expiry Date: 21 Jun 2028
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$36,426.00
COE Rebate Amount: \$32,163.00
Total Rebate Amount: \$41,852.00

The information contained herein is correct as at 23 Aug 2019

OK

14796

PRE-REPAIR INSPECTION REQUEST – SMA9074T vs SMN1194P (OI) on D.O.A.: 21/08/2019

From: Hor, Yinnul
 To: assignments@lkkauto.com, Admin A (admin-a@lkkauto.com)
 Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Marissa; Azlan, Syazairina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divy
 Sent: Thursday, 22 August 2019 10:40:57 AM

Hi,

Please refer to the enclosed request from Asia Motorsports Solution Pte Ltd.

Claim no : 1530218236SG003
 Case Owner : Wan Nur Saliha Binte Syed Yusoff

If you have any queries/concerns, please let us know.
 Kindly assist to assign **Marcus Chua** as Single Joint Expert as requested.

Thanks & Regards,

Hor Yin Rul (Viviane)
 AIG
 FNOL Adjuster I
 Singapore FNOL | Claims Operations - Auto

Yinnul.Hor@aig.com | www.aig.sg

P. Loo
 T: 11-00 6-00
 V. 17
 E: ✓

From: Asia Motorsports Solution Pte Ltd [mailto:asiamotorsports@hotmail.com]

Sent: Thursday, August 22, 2019 10:29 AM

To: Hor, Yinnul

Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Marissa; Azlan, Syazairina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashni; Tong, Wahxin

Subject: [EXTERNAL] ACCIDENT INVOLVING SMA 9074 T & SMN 1194 P ON 21 AUGUST 2019 - APPOINTMENT OF LKK AUTO CONSULTANTS PTE LTD (MARCUS CHUA) AS SINGLE JOINT EXPERT

This message is from an external sender; be cautious with links and attachments.

Your Ref:

Our Ref: SMA 9074 T

22 Aug 2019

AIG Asia Pacific Insurance Pte. Ltd.
 AIG Building
 78 Shenton Way
 #07-16
 Singapore 079120

PROPERTY CLAIM
 (WITHOUT PREJUDICE
 TO: Any Personal Injury
 Claims)

Attn: Claims Department

Via Email

Dear Sir/Mdm,

ACCIDENT INVOLVING SMA 9074 T & SMN 1194 P ON 21 AUGUST 2019 - APPOINTMENT OF LKK AUTO CONSULTANTS PTE LTD (MARCUS CHUA) AS SINGLE JOINT EXPERT

Thank you so much for your reply dated 22 August 2019. We are pleased to inform you that we are agreeable to your selection of **LKK Auto Consultants Pte Ltd (Marcus Chua)** as the Single Joint Expert.

In compliance with the New State Courts Practice Directions, we shall await your kind office to instruct **LKK Auto Consultants Pte Ltd (Marcus Chua)** (as the Single Joint Expert) to attend to the pre-repair survey of our client's damaged vehicle at our premise at 15 Kaki Bukit Road 4 #01-05/53 Bartley Biz Centre Singapore 417808.

We seek your assistance in arranging for the pre-repair survey by **26 August 2019 (Monday), 1100H** so that we can commence repair on our client's damaged vehicle as soon as possible and expedite the return of the vehicle to our client.

Thank you and we hope to hear from you soonest.

Regards,
 Asia Motorsports Solution Pte Ltd
 6745 3811
 6746 5110 (fax)
asiamotorsports@hotmail.com

*Please note that with effect from 1st June 2019, we have shifted to and are now operating from the following address:
 37A Everitt Road

Singapore 428586

Kindly update your records accordingly and send all future correspondence to the new address above please.

From: Hor, Yinnul <Yinnul.Hor@aig.com>
 Sent: Thursday, August 22, 2019 10:05 AM

To: asiamotorsports@hotmail.com <asiamotorsports@hotmail.com>

Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>; Parthiban, Theerthan <Theerthan.Parthiban@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>; Tong, Wahain <Wahain.Tong@aig.com>

Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMN1194P AND SMA9074T ON 21/08/2019



Disclaimer: This email and its content are confidential and intended solely for the use of the individual named. If you have received this email in error or simply doubt it

Sourced by Fourpoint Insurance, Copyright © 2019-2017 Fourpoint, Inc. All rights reserved.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Yinnul Hor<Yinnul.Hor@aig.com>

To: asiamotorsports@hotmail.com

Cc: Andy-SY.Fong<Andy-SY.Fong@aig.com>; Lee-

Ying.Chin<Ying.Chin@aig.com>; NoorMariesa.AbuKassim<NoorMariesa.AbuKassim@aig.com>; Syazairdina.Azlan<Syazairdina.Azlan@aig.com>; yokeshi.chan<yokeshi.chan@aig.com>; ShengYang.Lim<ShengYang.Lim@aig.com>; Aashweenjeetkaur.Mithoosingh<Aashweenjeetkaur.Mithoosingh@aig.com>; Theerthan.Parthiban

Subject: agency PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMN1194P AND SMA9074T ON 21/08/2019

Date: Thu, 22 Aug 2019 02:05:11 +0000

Without Prejudice

Your Reference : SMA9074T
Our Reference : SMN1194P

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pung Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiang	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufik	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Muhammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rui (Viviane)

AIG

PNOL Adjuster I

Singapore FNOI | Claims Operations – Auto

Yong.Hui@sig.com / www.aig.sg

From: Asia Motorsports Solution Pte Ltd (<mailto:asiamotorsports@hotmail.com>)

Sent: Wednesday, August 21, 2019 5:53 PM

To: Hor, Yinnul

Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Manesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur

Subject: [EXTERNAL] NOTICE OF ACCIDENT: ACCIDENT INVOLVING SMA 9074 T & SMN 1194 P ON 21 AUGUST 2019

This message is from an external sender; be cautious with links and attachments.

Your Ref:

Our Ref: SMA 9074 T

21 Aug 2019

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way
#07-16
Singapore 079120

**PROPERTY CLAIM
(WITHOUT PREJUDICE
TO: Any Personal Injury
Claims)**

Attn: Claims Department

Via Email

Dear Sir/Mdm,

NOTICE OF ACCIDENT: ACCIDENT INVOLVING SMA 9074 T & SMN 1194 P ON 21 AUGUST 2019

We are instructed to notify you of a road traffic accident on **21 August 2019** at about **0830H** at **Saraca Road Towards Sunflower IKID Childcare** involving our client's vehicle registration number **SMA 9074 T** and vehicle registration number **SMN 1194 P** driven by your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client/we proceed to repair the damaged vehicle, please let us know within **2 working days** of your receipt of this notice and your proposed list of 10 recommended motor surveyors for our appointment.
Kindly note that if we do not hear from you by **23 August 2019 (Friday), 1800H**, we will be forwarding our proposed list of 10 motor surveyors for your appointment, in accordance to the new regulations.

Thank you and we hope to hear from you soonest.

Regards,
Asia Motorsports Solution Pte Ltd
37A Everitt Road
Singapore 428586
6745 3811
6746 5110 (fax)
asiamotorsports@hotmail.com

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To : AIG Asia Pacific Insurance Pte. Ltd.
Attn : Syed-Yusoff, Saliha

Your Ref : 1530218236SG
Our Ref : CC4/AIG19014796/UEA3
Date : 02 Oct 2019

"WITHOUT PREJUDICE"**ACCIDENT INVOLVING SMN1194P & SMA9074T ON 21/08/2019**

Refer to the above accident.

The accident occurred when insured overtake third party vehicle while third party making a right turn on a two way carriage. We have clarified with the OI on the nature of the accident and he/she is aware that his/her NCD would be affected.

On behalf of AIG Asia Pacific Insurance Pte. Ltd., we have **successfully / not successfully** carried out **TP Express Settlement** between your insured (vehicle no. SMN1194P) and third party claimant (vehicle no. SMA9074T).

Summary of offer made to workshop Asia Motorsports Solution Pte Ltd is as follows :

	Claimed	Revised
Cost of Repairs	\$ 11,636.40	\$ 5,400.00
Loss of Use (5days x \$140)	\$ 700.00	\$ 300.00 (5days x \$60)
LTA Search Fee	\$ 7.45	\$ 7.45

Amount of claim at **Liability 100%** \$ 5,707.45

Enclose herewith the relevant supporting documents for your perusal.

For your approval please.

Regards,
Asher Sng Rong Yi
LKK Auto Consultants Pte Ltd

10/22/2019

Merimen e-Claims

Print Received Message

This mail is associated with :

***SMA9074T (1530218236SG)**
[SMN1194P]

TP

MARK LIM JIT SING (LIN RIXIN)

Aug 21 2019 12:00AM

[CHIAM CHYE MENG]

Asia Motorsports Solution Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 21/10/2019 11:23 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$2857.45) - SMA9074T - Claim Handler: Syed-Yusoff, Saliha

Approved:2857.45:pls offer at 50% liability as TP driver stopped her vehicle momentarily before making a right turn and did not signal her intention.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Aug 2019 Edit Reg		22 Aug 2019 00:00 Edit Adj Rpt	\$55,400.00 Edit Estimates	\$55,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	CHIAM CHYE MENG, ID: S7101295F								
Main Claimant:	MARK LIM JIT SING (LIN RIXIN), ID: S7308982D								
Vehicle Reg. No.:	SMA9074T	Date of Loss:	21/08/2019 00:00 - :59 [13 Months and 30 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1530218236SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SMN1194P	Policy No. (Claimant):	5101358226-01						
		Excess:							
Repairer:	Asia Motorsports Solution Pte Ltd (HQ) 37A Everitt, 428586 Joo Chiat - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 02/09/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (24/10/2019): Alert - Adj Mandate Maintained - SMA9074T - Claim Handler: Syed-Yusoff, Saliha - AIG_SG_EXPRESS (21/10/2019): Alert - Adj Mandate Approved (\$2857.45) - SMA9074T - Claim Handler: Syed-Yusoff... - AIG_SG (23/08/2019): TP GIA REPORT									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMA9074T (1530218236SG)
[SMN1194P]
TP
MARK LIM JIT SING (LIN RIXIN)
Aug 21 2019 12:00AM
[CHIAM CHYE MENG]
Asia Motorsports Solution Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Video

1 per page

No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	28/08/19 15:28	Video - Accident From: SC - Reg. No: SMN1194P, Claimant: CHIAM CHYE MENG		Load AVI	

Letters/Correspondences

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit	

Assessment Reports

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	02/10/19 10:40	Adjuster Immediate Advice		Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	22/08/19 17:57	Odometer Reading		Load JPG	
2	22/08/19 17:57	Chassis Number		Load JPG	
3	22/08/19 17:57	General View		Load JPG	
4	22/08/19 17:57	General View		Load JPG	
5	22/08/19 17:57	General View		Load JPG	
6	22/08/19 17:57	General View		Load JPG	
7	22/08/19 17:57	General View		Load JPG	
8	22/08/19 17:57	General View		Load JPG	
9	22/08/19 17:57	General View		Load JPG	
10	22/08/19 17:57	General View		Load JPG	
11	22/08/19 17:57	General View		Load JPG	
12	22/08/19 17:57	General View		Load JPG	
13	22/08/19 17:57	General View		Load JPG	
14	22/08/19 17:57	General View		Load JPG	
15	22/08/19 17:57	General View		Load JPG	
16	22/08/19 17:57	General View		Load JPG	
17	22/08/19 17:57	General View		Load JPG	
18	22/08/19 17:57	General View		Load JPG	
19	22/08/19 17:57	General View		Load JPG	
20	22/08/19 17:57	General View		Load JPG	
21	22/08/19 17:57	General View		Load JPG	
22	22/08/19 17:57	General View		Load JPG	
23	22/08/19 17:57	General View		Load JPG	
24	22/08/19 17:57	General View		Load JPG	
25	22/08/19 17:57	General View		Load JPG	
26	22/08/19 17:57	General View		Load JPG	
27	22/08/19 17:57	General View		Load JPG	
28	22/08/19 17:57	General View		Load JPG	
29	22/08/19 17:57	General View		Load JPG	
30	22/08/19 17:57	General View		Load JPG	
31	22/08/19 17:57	General View		Load JPG	
32	22/08/19 17:57	General View		Load JPG	

Video			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
33	22/08/19 17:57	General View	 Load JPG	☒
34	22/08/19 17:57	General View	 Load JPG	☒
35	22/08/19 17:57	General View	 Load JPG	☒
36	22/08/19 17:57	General View	 Load JPG	☒
37	22/08/19 17:57	General View	 Load JPG	☒
38	22/08/19 17:57	General View	 Load JPG	☒
39	22/08/19 17:57	General View	 Load JPG	☒
40	22/08/19 17:57	General View	 Load JPG	☒
41	22/08/19 17:57	General View	 Load JPG	☒
42	22/08/19 17:57	General View	 Load JPG	☒
43	22/08/19 17:57	General View	 Load JPG	☒
44	22/08/19 17:57	General View	 Load JPG	☒
45	22/08/19 17:57	General View	 Load JPG	☒
46	22/08/19 17:57	General View	 Load JPG	☒
47	22/08/19 17:57	General View	 Load JPG	☒
48	23/08/19 15:13	Reinspection Photo	 Load JPG	☒
49	23/08/19 15:13	Reinspection Photo	 Load JPG	☒
50	23/08/19 15:13	Reinspection Photo	 Load JPG	☒
51	23/08/19 15:13	Reinspection Photo	 Load JPG	☒
52	23/08/19 15:13	Reinspection Photo	 Load JPG	☒
53	23/08/19 15:13	Reinspection Photo	 Load JPG	☒
54	23/08/19 15:13	Reinspection Photo	 Load JPG	☒
55	23/08/19 15:13	Reinspection Photo	 Load JPG	☒
56	23/08/19 15:13	Reinspection Photo	 Load JPG	☒
57	23/08/19 15:13	Reinspection Photo	 Load JPG	☒
58	23/08/19 15:13	Reinspection Photo	 Load JPG	☒
59	23/08/19 15:13	Reinspection Photo	 Load JPG	☒
60	23/08/19 15:13	Reinspection Photo	 Load JPG	☒
61	23/08/19 15:13	Reinspection Photo	 Load JPG	☒
62	23/08/19 15:13	Reinspection Photo	 Load JPG	☒
63	23/08/19 15:13	Reinspection Photo	 Load JPG	☒
64	23/08/19 15:13	Reinspection Photo	 Load JPG	☒
65	23/08/19 15:13	Reinspection Photo	 Load JPG	☒
66	23/08/19 15:13	Reinspection Photo	 Load JPG	☒
67	23/08/19 15:13	Reinspection Photo	 Load JPG	☒
68	23/08/19 15:13	Reinspection Photo	 Load JPG	☒
69	23/08/19 15:13	Reinspection Photo	 Load JPG	☒
70	23/08/19 15:13	Reinspection Photo	 Load JPG	☒
71	23/08/19 15:13	Reinspection Photo	 Load JPG	☒
72	23/08/19 15:13	Reinspection Photo	 Load JPG	☒
73	23/08/19 15:13	Reinspection Photo	 Load JPG	☒
74	23/08/19 15:13	Reinspection Photo	 Load JPG	☒
75	23/08/19 15:13	Reinspection Photo	 Load JPG	☒
76	23/08/19 15:13	Reinspection Photo	 Load JPG	☒
77	23/08/19 15:13	Reinspection Photo	 Load JPG	☒
78	23/08/19 15:13	Reinspection Photo	 Load JPG	☒
79	23/08/19 15:13	Reinspection Photo	Load JPG	☒
80	23/08/19 15:13	Reinspection Photo	Load JPG	☒
81	28/08/19 09:02	After Repair Photo	Load JPG	☒
82	28/08/19 09:02	After Repair Photo	Load JPG	☒
83	28/08/19 09:02	After Repair Photo	Load JPG	☒
84	28/08/19 09:02	After Repair Photo	Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/08/19 17:56	ACKNOWLEDGEMENT EMAIL TO AIG DD 22.08.2019	 Load PDF	
2	22/08/19 17:56	EMAIL FROM AIG DD 22.08.2019	 Load PDF	

Video			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
3	02/10/19 10:36	TP ESTMATE - MARKED		Load PDF
4	02/10/19 10:36	TP LOD		Load PDF
5	23/10/19 13:48	EMAIL FROM WSP DD 231019		Load PDF
6	02/12/19 08:50	WORKSHOP INVOICE		Load PDF
7	02/12/19 08:50	AUTHORISATION TO ACT FORM		Load PDF
8	02/12/19 08:50	Release Voucher		Load PDF
9	02/12/19 08:50	LTA SEARCH		Load PDF
10	02/12/19 08:50	LOD		Load PDF
11	02/12/19 08:50	LETTER TO OI		Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	23/08/19 15:13	OI GIA REPORT		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) ^ v			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SMN1194P (Insd veh)	Model:	HONDA VEZEL 1.5 X CVT
	SMA9074T (TP veh)		(A)
Date of Accident:	21/08/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	11,636.40
Final Repair Cost	:	\$	2,700.00
Loss of Use	:	\$	150.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	7.45
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	2,857.45

5.00 days at \$60.00 per day
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability 50 (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Asia Motorsports Solution Pte Ltd	:	\$ 2,857.45
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

02 Dec
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19014796/UEA3Q2

Date: 02/12/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant

Vehicle No : SMA9074T

Insured Vehicle No : SMN1194P

Date of Loss: 21/08/2019

Nature of Claim: TP

Claim No: 1530218236SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMA9074T

Make & Model: HONDA VEZEL, 1.5 X CVT (A)

Engine No: L15B4432905

Reg. Date: 22/06/2018 (Man. Year: 2017)

Chassis No: RU11232901

Colour: White

Odometer: 19718 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side: Dunlop 7 mm

Rear Left Side:

Dunlop 7 mm

Front Right Side: Dunlop 7 mm

Rear Right Side:

Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,716.40	5,462.32	3,254.08	37.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,920.00	1,300.00	1,620.00	55.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,636.40	6,762.32	4,874.08	41.89
Approved Total (Overridden) (S\$)		5,400.00		
Nett Amount (S\$)	11,636.40	5,400.00	6,236.40	53.59
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
(S\$)		5,700.00		
Liab Amount (50.00%) (S\$)		2,850.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,857.45		

INSPECTION

Date of Assignment: 22/08/2019

Date Inspected: 22/08/2019 Inspected At:

Asia Motorsports Solution Pte Ltd
(HQ)
37A Everitt
Singapore 428586

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RHS FRONT FENDER	Badly Dented	980.00 FL	*580.00 FL
2	1		*RHS FRONT FENDER WHEEL ARCH GARNISH	Distorted	283.00 FL	*283.00 FL
3	1		*RHS FRONT FENDER INNER SPLASH SHIELD	Torn	267.00 FL	*267.00 FL
4	1		*BONNET (NPA)	Not Necessary	0.00 FL	*- FL
5	1		*RADIATOR GRILLE	Not Necessary	382.00 FL	*- FL
6	1		*FRONT BUMPER	Distorted	1,428.00 FL	*801.70 FL
7	1		*FRONT BUMPER FOG LAMP COVER RHS	Twisted	244.00 FL	*244.00 FL
8	1		*FRONT BUMPER FOG LAMP RHS	Cracked	428.00 FL	*327.70 FL
9	1		*FRONT BUMPER LOWER SKIRT (SPOILER)	Distorted	780.00 FL	*420.00 FL
10	1		*FRONT BUMPER SIDE RETAINER RHS & LHS	O/S Cracked	142.00 FL	*45.00 FL
11	1		*RHS FRONT DOOR (NPA)	Repair	0.00 FL	*- FL
12	1		*RHS LOWER SILL (ROCKER PANEL)	Cut / Torn	652.00 FL	*652.00 FL
13	1		*RHS HEADLAMP	Scratched	1,280.00 FL	*1,280.00 FL
14	1		*RHS HEADLAMP LOWER BRACKET	Not Necessary	248.00 FL	*- FL
15	1		*RHS FRONT SHOCK ABSORBER	Serviceable	592.00 FL	*- FL
16	1		*RHS FRONT SHOCK ABSORBER COIL SPRING	Not Necessary	209.00 FL	*- FL
17	1		*RHS FRONT LOWER ARM	Bent	488.00 FL	*488.00 FL
18	1		*RHS FRONT LOWER LINK	Not Necessary	278.00 FL	*- FL
19	1		*RHS FRONT KNUCKLE ARM	Bent	498.00 FL	*498.00 FL
20	1		*RHS FRONT WHEEL BEARING	Necessary	279.00 FL	*279.00 FL
21	1		*SET RHS FRONT FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
22	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 FS	*50.00 FS
23	1		*SET FRONT FENDER WHEEL ARCH RH CLIPS	Not Necessary	60.00 FS	*- FS
24	1		*RHS FRONT SPORTS RIM	Cut / Bent	980.00 FS	*480.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,608.00	6,695.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,891.60	1,233.08
Total Parts (\$\$)	8,716.40	5,462.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,REPLACE DAMAGED PARTS AND COMPONENTS	New	1,200.00	450.00
2	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED & REPAIRED (RHS FRONT DOOR AND BONNET)	New	1,000.00	600.00
3	TO CHECK WIRING AND FOCUS HEADLAMP BEAM	New	150.00	20.00
4	TO REMOVE AND REPLACE RHS FRONT UNDERCARRIAGE PARTS (SUSPENSION SYSTEM)	New	300.00	120.00
5	TO CARRY OUT ANTI RUST TREATMENT ON AFFECTED AREAS	New	150.00	30.00
6	TO CONDUCT FULL COMPUTERISED WHEEL ALIGNMENT TEST	New	120.00	80.00
Gross Labour Cost (S\$)			2,920.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >