

ASS. REC. BY:

REF

es/FCI/9014809/T1 v d3

n2

Special Instruction:

Assigner: Taufik

ASSIGNMENT (Office)

WS

From (Person):

Henny kao

of

FCI

Date/Time:

2.41pm @ 22/8/2019

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FS3989G

Insured:

SHB2199S

at Workshop m/s

Karz Work

Tel:

68445938

of

53 ubi Ave 1 # 02-24

Policy No:

Claim No:

D19005402MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

17/8/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

5.07pm @ 22/8/19

Person Contacted:

shu shen

Vehicle IN / OUT

Date/Time

Action/Instruction

Estimated (✓)

28/8/19

Email preli revised to FCI

31/9/19

LS \$1000 confirmed by email (Red 7648, 889)
MV: \$1500 (EST) LTA: \$131 MV: \$1369

Signature

Tanph.

REF:

FCI

ASSIGNMENT

60E 2020 May
2000, July

From: _____ Date: _____
Estimated Cost: _____
OD (TP) WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$1500.
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT
Damen

Veh No: FS3989G Yr Regn: 2000, July
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Yamaha RXT C.C. 133
Colour: Black A/C: Insured / Std / NI / NA
Sp. Reading: 51097 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: ZMC 253721
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 80/10 R18
R: 4. -
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or IRC
Front _____ Rear _____
R/Bal. 5 mm R/Bal. 5 mm
L/Bal. mm L/Bal. mm
D.O.A. _____ D.O.I. 22/8/19
Survey held at Teamwork.
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
13/9	Inform Damen Repair limit \$1000. 45 \$1000, 4 days

RECEIVED 23 SEP 2019

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) 23/9 - typist

Report Format: CWS

Lump Sum / I.B.I: (\$ 1000) =

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Survey Fee:

Transportation:

) \$ + RS, \$

) Photos

) Others

TOTAL:

160
50
50
85
345



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19005402MFSH

Our ref: CS/FCI19014809/T1vd3

Date: 28/8/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. FS 3989G


We thank you for your instruction on 22/8/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on
27/8/2019 at the premises of M/s KARZ WORKS PTE LTD
and have the following to report:-

Workshop Estimate Amount	: S\$8,648.00
Revised Estimate Amount	: S\$4,344.00
"Check" Items Amount	: S\$750.00
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the
front portion and o/s body



Comments/Present Status:

Damages Consistent

Yours faithfully,

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automobile Assessor

MOTOR SURVEY ASSIGNMENT

Date	20-08-2019	Our Ref No. D19005402MFSH
Accident Date	17-08-2019	Claim Type. Third Party
Insured Vehicle	SHB2199S	Third Party Vehicle. FS3989G
Survey Location	53 UBI AVENUE 1 #02-24 PAYA UBI INDUSTRIAL PARK	
Contact Person.	SHU SHAN	
Contact No.	68445938/ 0	Fax No. 68442474
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	KARZ WORK SOLUTIONS	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 28 August 2019 2:30 PM
To: 'CWS Motor Claims'
Cc: 'Henry Kao'; SUR
Subject: RE: SURVEY ASSESSMENT - D19005402MFSH/1-FS 3989G
Attachments: FS 3989G PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle FS 3989G
Date of survey: 27/8/2019
Number of days (estimated) : 4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Thursday, 22 August 2019 5:09 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry Kao' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19005402MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 22 August 2019 2:41 PM
To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao <HenryKao@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19005402MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Veron Chen (LKKAUTO)

From: Darren <karzworks.sg@gmail.com>
Sent: Saturday, 21 September 2019 11:35 AM
To: Veron Chen (LKKAUTO); KARZWORKSSG@GMAIL.COM; SUR
Subject: RE: FS 3989G-DOA: 17/8/2019

Hi Veron,

We confirmed COR @ \$1000

Darren
Karz Works Pte Ltd
53 Ubi Avenue 1
#01-23 Paya Ubi Industrial Park
Singapore 408934
Tel: 68442475
Fax: 68442474

From: Veron Chen (LKKAUTO)
Sent: Thursday, 19 September 2019 12:33 PM
To: KARZWORKSSG@GMAIL.COM; SUR
Subject: FS 3989G-DOA: 17/8/2019

Dear Darren,

WITHOUT PREJUDICE

Offer Lump Sum repair limit \$1000/- @ 4 working days.

PARTS-\$1940 (less 10%)=\$1746
SN-\$120
LABOUR-\$750
TOTAL-\$ 2616 (less 20%)=2092.80

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAUTO)

From: karzworks.sg@gmail.com
Sent: Saturday, 21 September 2019 11:40 AM
To: Taufikh (LKKAUTO)
Cc: karzworks.sg@gmail.com
Subject: finalised FS3989G

Importance: High

Hi Taufikh ,

We confirm COR @ \$1000 and DOR @ 4 DAYS

Thank you and have a nice day! ☺

Letitia

KARZ WORKS PTE LTD
53 Ubi Avenue 1
#01-23 Paya Ubi Industrial Park
Singapore 408934
Tel: 6844 5938
Fax: 6844 2474

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Foreign Identification Number
Owner ID:	446U

Vehicle Details

Vehicle No.:	FS3989G
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Aug 2019
Vehicle Make:	YAMAHA
Vehicle Model:	RXZ
Primary Colour:	Purple
Manufacturing Year:	2000
Engine No.:	3BS253721
Chassis No.:	ZMC253721
Maximum Power Output:	-
Open Market Value:	\$3,613.00
Original Registration Date:	20 Jul 2000
First Registration Date:	20 Jul 2000
Transfer Count:	9
Actual ARF Paid:	\$542.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	31 May 2020
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$1,115.00
COE Rebate Amount:	\$131.00
Total Rebate Amount:	\$131.00

Message

Please note that the National Environment Agency (NEA) is offering an incentive for the owner of this motorcycle to deregister the motorcycle on or before 5 April 2023.

This motorcycle is currently eligible for an incentive of \$3,500 from NEA. If the COE is renewed from now till its deregistration on or before 5 April 2023, the incentive will be reduced to \$2,000. The last registered owner of this motorcycle will receive the incentive from NEA.

This motorcycle will no longer be allowed for use on Singapore's roads after 30 June 2028.

For more information, please visit <http://www.nea.gov.sg/mtcincentive> or contact NEA at 1800-2255-632.

The information contained herein is correct as at 27 Aug 2019

OK

KARZ WORKS PTE LTD
53 UBI AVENUE 1 #01-23, PAYA UBI INDUSTRIAL PARK
SINGAPORE 408934
(TEL) 6 8 4 4 5 9 3 4 (FAX) 6 8 4 4 2 4 7 4 (E-MAIL) KARZWORKSSG@GMAIL.COM

AIG Singapore
78 Shenton Way
Singapore 079120

REPAIR PERFORMANCE INVOICE

Vehicle number	FS3989G
Make / Model	YAMAHA RXZ
Chassis number	ZMC253721
Accident date	17.08.19
Reference	KK1908-43

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
	FRONT FAIRING	180 350.00 cut
1	FRONT HEADLAMP	420.00 X nn
1	FRONT RH SIGNAL LIGHT	60 180.00 cut
1	FRONT FENDER	150 350.00 cut
1	BRAKE LEVER	60 210.00 cut
1 SET	BALANCER	50 250.00 cut
1 SET	WING MIRROR	100 300.00 cut
1	BELLY PANEL	300 650.00 cut
1	FOOTREST	180.00 cut
1	FOOTSTAND	150.00 X nn
1	FOOTSTAND BRACKET	90.00 X nn
1	REAR EXHAUST	450 900.00 dd
1	FRONT WINDSHIELD	150.00 cut
1	FOOT BRAKE	210.00 bt
1	PILLION FOOT REST	130.00 cut
1	REAR FAIRING	410.00 X nn
1 SET	HANDLE BAR	350.00 X nn
1 SET	HANDLE GRIP	230.00 X nn
1	FRONT LH FORK	bt Rx 550.00 } SN 120
1	FRONT RH FORK	bt Rx 550.00 }
		6610.00
	Less 10%	661.00
	Subtotal	5949.00
	Balance C/F	5949.00
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
	Balance B/F	5949.00
1	REAR BOX	300.00 X
1	GEAR SHIT SHAFT OIL SEAL	12.00 X
1	FORK OIL SEAL	45.00 X
1	FORK OIL	12.00 X
1	REAR CARPLATE	50.00 X
1	RIM	500.00 X
	Subtotal	919.00
	Balance C/F	
S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
	Balance B/F	6868.00
1	REPLACE, REALIGN AND ADJUST ABOVE DAMAGE PARTS AND CHECK WIRING AND LIGHTING SYSTEM	600.00 300
2	TO REMOVE/REFIT, REPLACE FRONT FORK	380.00 100
3	SPRAY PAINTING	400.00 200
4	REMOVE AND RESTICK STICKER	400.00 150
	Subtotal	1780.00
	Grand total	8648.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:


28/8/19

Tay Guan 27/8/19
"wp"
27/8/19 E Spm

Lumpsum
Resurvey at the repair
4 days

sure lkk auto cover
check repair limit

4/5/1000, 4 days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19014809/T1vd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 26-09-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 2199S	Veh. Inspected	FS 3989G	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19005402MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	22/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA RXZ	c.c	133	
Engine No.	HIDDEN	Year of Reg.	2000	
Chassis No.	ZMC253721	Colour	BLACK	
Odometer	51097	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	80/90 R18	IRC	5 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	80/90 R18	IRC	5 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/08/2019	Inspection Date	27/08/2019	
Survey held at	KARZ WORK SOLUTIONS 53 UBI AVE 1 #02-24 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FS 3989G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT FAIRING	CRACKED	350.00	100.00
1	FRONT HEADLAMP	NOT NECESSARY	420.00	-
1	FRONT RH SIGNAL LIGHT	CUT	180.00	60.00
1	FRONT FENDER	CUT	350.00	150.00
1	BRAKE LEVER	BROKEN	210.00	60.00
1	SET BALANCER	CUT	250.00	50.00
1	SET WING MIRROR	CUT	300.00	100.00
1	BELLY PANEL	CRACKED	650.00	300.00
1	FOOTREST	CUT	180.00	180.00
1	FOOTSTAND	NOT NECESSARY	150.00	-
1	FOOTSTAND BRACKET	NOT NECESSARY	90.00	-
1	REAR EXHAUST	DENTED	900.00	450.00
1	FRONT WINDSHIELD	CUT	150.00	150.00
1	FOOT BRAKE	BENT	210.00	210.00
1	PILLION FOOT REST	CUT	130.00	130.00
1	REAR FAIRING	NOT NECESSARY	410.00	-
1	SET HANDLE BAR	NOT NECESSARY	350.00	-
1	SET HANDLE GRIP	NOT NECESSARY	230.00	-
	LESS 10% DISCOUNT		-551.00	-194.00
			4,959.00	1,746.00
1	FRONT LH FORK (LOCAL REPAIR)(SN) }	BENT	550.00	120.00
1	FRONT RH FORK (LOCAL REPAIR)(SN) }	BENT	550.00	-
	LESS 10% DISCOUNT		-110.00	-
			990.00	120.00
SPECIAL NETT ITEMS				
1	REAR BOX (SN)	NOT NECESSARY	300.00	-
1	GEAR SHIT SHAFT OIL SEAL (SN)	NOT NECESSARY	12.00	-
1	FORK OIL SEAL (SN)	NOT NECESSARY	45.00	-
1	FORK OIL (SN)	NOT NECESSARY	12.00	-

Report Ref No. CS/FCI19014809/T1vd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR CARPLATE (SN)	NOT NECESSARY	50.00	-
1	RIM (SN)	NOT NECESSARY	500.00	-
			919.00	-
	LABOUR			
	REPLACE,REALIGN AND ADJUST ABOVE DAMAGE PARTS AND CHECK WIRING AND LIGHTING SYSTEM.		600.00	300.00
	TO REMOVE/REFIT,REPLACE FRONT FORK.		380.00	100.00
	SPRAY PAINTING.		400.00	200.00
	REMOVE AND RESTICK STICKER.		400.00	150.00
			1,780.00	750.00
GRAND TOTAL			8,648.00	2,616.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,000.00

Report Ref No. CS/FCI19014809/T1vd3n2

MARKET VALUE: \$1,500.00 (EST)-LTA REIMBURSEMENT VALUE: \$131.00=NETT VALUE: \$1,369.00

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.