



SMA8993Y [SDJ81R] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



4/35: Inspection Photo



5/35: Inspection Photo



6/35: Inspection Photo


SMA8993Y [SDJ81R] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



7/35: Inspection Photo



8/35: Inspection Photo



9/35: Inspection Photo


SMA8993Y [SDJ81R] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



10/35: Inspection Photo




11/35: Inspection Photo



12/35: Inspection Photo

SMA8993Y [SDJ81R] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



13/35: Inspection Photo




14/35: Inspection Photo




15/35: Inspection Photo

SMA8993Y [SDJ81R] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



16/35: Inspection Photo



17/35: Inspection Photo



18/35: Inspection Photo

SMA8993Y [SDJ81R] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



19/35: Inspection Photo



20/35: Inspection Photo



21/35: Inspection Photo

SMA8993Y [SDJ81R] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



22/35: Inspection Photo



23/35: Inspection Photo



24/35: Inspection Photo


SMA8993Y [SDJ81R] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



25/35: Repairer's Photo




26/35: Repairer's Photo



27/35: Repairer's Photo

SMA8993Y [SDJ81R] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



28/35: Repairer's Photo



29/35: Repairer's Photo



30/35: Repairer's Photo


SMA8993Y [SDJ81R] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



31/35: Repairer's Photo



32/35: Repairer's Photo



33/35: Repairer's Photo

SMA8993Y [SDJ81R] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



34/35: Repairer's Photo



35/35: Repairer's Photo