



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info	
Tan Morgan 9 Sengkang Square #13-14 Singapore 545075 Contact No Mobile: 94528888	Cust No/Name	/Tan Morgan
	Reg No/Reg Date	SJG7888D / 12/02/201
	Date In/Mileage	/ 0
	Chassis No	MMBSTA13AJH000934
	Engine No	3A92UGP1003
	Make/Model	MIT/18MY ATTRAGE 1.2 CVT
	Colour/Trim	T06 MED BLUE MICA / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	17/08/2019/ 14:17	QUE	261 / Edwin Caina	43894			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1650 3850.00
RENEW RR BUMPER , RR BUMPER BODY KIT , RR END PNL & BOOTLID								
REPAIR LHR FENDER , RHR FENDER & RR FLR PNL								1890 2940.00
E PNT98000								
RESPRAY RR BUMPER , RR BUMPER BODY KIT , BOOTLID , RR FLR PNL ,								
RR END PNL , LHR FENDER & RHR FENDER								✓ 275.00
E PNT88000								
REMOVE & REFIT BOOTLID COMPONENT								✓ 275.00
E PNT88000								
REMOVE & REFIT RR FLR BOARD, TRIM & CARPET TO FACILITATE REPAIR								30 50.00
A 54900099								
CHECK WIRING ELECTRICAL SYSTEM								✓ 200.00
A 10028901								
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
M SUNDRY								80 120.00
APPLY ANTI CORROSION ON AFFECTED AREAS								80 180.00
M SUNDRY								
SUPPLY BODY SEALANT								X 80.00
M SUNDRY								
SUPPLY RR NUMBER PLATE WITH CASING								60 100.00
E PNT88000								
REMOVE & REFIT REVERSE SENSOR								120 220.00
M SUNDRY								
SUPPLY REVERSE SENSOR								40 40.00
M SUNDRY								
SUPPLY C&C BADGE								20 50.00
M SUNDRY								
Sundries								740 740.00
M FACE, RR BUMPER					1.00	740.00	00.00	740.00
M BRACKET, RR BUMPER, LH					1.00	27.00	00.00	27.00
M BRACKET, RR BUMPER, RH					1.00	27.00	00.00	27.00
M CLIP, RR BUMPER					4.00	3.00	00.00	12.00

Estimate

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info	
Tan Morgan 9 Sengkang Square #13-14 Singapore 545075 Contact No Mobile: 94528888	Cust No/Name	/Tan Morgan
	Reg No/Reg Date	SJG7888D / 12/02/201
	Date In/Mileage	/ 0
	Chassis No	MMBSTA13AJH000934
	Engine No	3A92UGP1003
	Make/Model	MIT/18MY ATTRAGE 1.2 CVT
	Colour/Trim	T06 MED BLUE MICA / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	17/08/2019/ 14:17	QUE	261 / Edwin Caina	43894			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	PANEL,RR END				1.00	421.00	00.00	bt 421.00
M	TRIM,RR END				1.00	65.00	00.00	de 65.00
M	BOARD,TRUNK ROOM FLOOR				1.00	193.00	00.00	an 193.00
M	DUCT,RR VENTILATOR				1.00	30.00	00.00	7 30.00
M	COVER,RR VENTILATOR				1.00	40.00	00.00	7 40.00
M	CLIP,GEARSHIFT CONTROL LIN				3.00	3.00	00.00	7 9.00
M	BUZZER,KEYLESS OPERATIO,RR				1.00	90.00	00.00	7 90.00
M	ANT,KEYLESS OPERATION,RR				1.00	95.00	00.00	7 95.00
M	MUD GUARD,RR LH				1.00	40.00	00.00	x 40.00
M	MUD GUARD,RR RH				1.00	40.00	00.00	x 40.00
M	PANEL,TRUNK LID				1.00	688.00	00.00	bt 688.00
M	WEATHERSTRIP,TRUNK LID				1.00	155.00	00.00	tw 155.00
M	HINGE,TRUNK LID,LH				1.00	201.00	00.00	Rp 201.00
M	HINGE,TRUNK LID,RH				1.00	201.00	00.00	Rp 201.00
M	STRIKER,TRUNK LID LATCH				1.00	20.00	00.00	1 20.00
M	LATCH,TRUNK LID				1.00	216.00	00.00	7 216.00
M	MARK,ATTRAGE				1.00	21.00	00.00	new 21.00
M	MARK,THREE-DIA				1.00	45.00	00.00	new 45.00
M	LAMP ASSY,COMB,RR LH				1.00	332.00	00.00	7 332.00
M	LAMP ASSY,COMB,RR RH				1.00	332.00	00.00	7 332.00
M	DECAL,MIVEC				1.00	36.00	00.00	new 36.00
M	BODY KIT, ATTRAGE, T69				1.00	1643.00	00.00	de 1643.00

SURVEYOR NAME: Tanpin 9749577
 SURVEYOR SIGNATURE: [Signature]
 DATE: 26/8/19 @ 330 pm
 REMARKS: * Repairing before paint
shoe [Signature]
7 days.

Confirm & accepted by

Net 14,099.00
 7% GST on 14099.00 986.93
Total Payable 15,085.93

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.