

(08/11/13)

Surveyor: Kelvin

REF: CC3/TM1/904816/15 F302

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspected Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHD 4835R Yr Regn: 6 Mar 2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Z40 c.c. 1685

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 504968 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KMHLB414ME404842X

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inoper / Jammed / Leaked / Burnt or

Brake: Inoper / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD Rim or

Tyre Size: F: 205/60R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front Rear

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 2/8/19 D.O.I. 22/8/19

Survey held at C/DHE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear / 16Rer

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SHD 4835R - 4A / AIG 4835R - 4A
	STW 30244 - X
2/9/19	Calculated L/S \$ 7550 / 7 Dgs. ( \$ 5,099.78 Red - 40% )

RECEIVED 02 SEP 2019

Date/Time, File Pass to?

02/09/19

☐ : Preli. Report☒ : Final Report

1) Type

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 7

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : \_\_\_\_\_ (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

S + RS SI

Photos

Other

Report Format

45 \$ 7,530/-

TOTAL


261

Team: ARC Repair TP(CLS0)1	JOB CARD	Sales Order:	JC NO.: 305326661
STOMER	REGN NO.: SHD4835R	MILEAGE	
COMFORT TRANSPORTATION PTE LTD	MAKE : HYUNDAI	FUEL	
7010045	MODEL I-40	E.....1/2.....F	
STOMER NO. 383 SIN MING DRIVE	YR OF MANU 06.03.2014	DATE/TIME IN 21.08.2019 13:00	
DRESS Singapore SINGAPORE 575717	CHASSIS CODE KMHLB41UMEU048434	TARGET DATE	
65508755		COMPLETION DATE/TIME:	
(R)			
(P)			
COUNT CARD NO.			

Accident Date: 21.08.2019  
NATURE: 3P 21.08.2019

JOB DESCRIPTION

S/NO LABOR CODE DESCRIPTION



CKED & PASSED OUT BY:			
SERVICE ADVISOR		CUSTOMER'S SIGNATURE	
Acknowledgement Slip		Exit Pass	
No.: SHD4835R	CHIANG	Vehicle No.: SHD4835R	
Signature/Date	Name of Service Advisor	Date	
Returned to Service Reception upon collection		To be kept by Security Guard	

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	22/08/2019 08:51
Date Of Accident	21/08/2019 11:30
Exact Location Of Accident	CTE(SLE) NEAR SELETAR WEST LINK EXIT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD4835R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

### Driver

Name of Driver	TEO CHER TECK
NRIC No	S1205148D
Date Of Birth	12/11/1955
Occupation	OUTDOOR
Date Of Driving Pass	24/05/1977
Driving Experience	42 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90991215
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 548 BEDOK NORTH AVENUE 1 #10-408
Postcode	460548
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLS REFER TO ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJW3024Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	TOKIO MARINE INSURANCE SINGAPORE LTD
Nature Of Damage	FRONT, LF DOOR

No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

GBB7476E

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

RIGHT FRT

No. Of Passenger (Including Driver)

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:


Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

GIARMC Sketch Plan Form\_V3



# Sketch Plan Pg. 2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 21/8/19 at about 1130hrs while I was travelling in lane 2, Veh B collided onto the rear of my vehicle. When I came out of my vehicle to check, Veh B + Veh C was stopped on the road shoulder when I verify the collision with both Veh B + Veh C, it was realized the Veh B tried to filter to lane 3 and collided with Veh C and the impact caused Veh B to sway to the lane 2 again and collide onto the rear of my vehicle. The impact caused my vehicle to spin 360° and halted on Lane 1 facing the opposite side of traffic flow.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 189303821R


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:   
NRIC/FIN No.: 21/8/19

GIAR/MC SketchPlanForm\_V3





Our Job Ref No : 305326661

Date : 30/08/19

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

Vehicle Reg No. : SHD4835R

21/08/2019

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

Z The repair job shall bill to: TOKIO SJW3024Y

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

**Total for Part-By-Part Repair Cost**

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

**Final Lumpsum Repair cost**

\$7,550.00

3. Estimated normal period for repairs: 7 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : CHIANG

Tel : 62148314

Fax : 65468156

Signature : 

Name : KALVIN

Date : 2/9/19

## For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

**ComfortDelGro Engineering Pte Ltd** (Co.Reg.No:199506048W)  
 59 Loyang Drive  
 Singapore 508969  
 Tel: 6214 8300

**TP INSURER:** Tokio Marine Insurance Singapore Ltd (HQ)  
**CTPL**

Singapore

**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:	MK000519	Date of Loss:	21/08/2019
Vehicle Reg. No.:	SHD4835R	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Vehicle Reg. Date:	06/03/2014
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	D4FDFU504515	Chassis No:	KMHLB41UMEU048434
Odometer:	504968 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair	8		
(day)			
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

<b>COST OF CLAIMS</b>	<b>Amount</b>
Parts	9,692.74
Miscellaneous Items	11.00
Labour	2,570.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>12,273.74</b>
<b>+ GST 7.00% (S\$)</b>	<b>859.16</b>
<b>Nett Amount (S\$)</b>	<b>13,132.90</b>

**This claim is handled by: JUMANI BIN MASUDIN**

*Generated using Merimen e-Claims Internet Estimation & Adjusting System*

**REPAIR DETAILS****Reference**

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 22 Aug 2019)
<b>Parts:</b>	143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	ComfortDelGro Engineering Pte Ltd/SHD4835R/23/08/2019 11:02	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*BOOT LID	20.00	0.00	*2,174.90 FL	BUL
2	1		*BOOT LID LOCK UPPER	20.00	0.00	*102.60 FL	JAM
3	1		*BOOT LID LOCK LOWER	20.00	0.00	*31.70 FL	BT
4	1		*BOOT LID H EMBLEM	20.00	0.00	*28.70 FL	NEL
5	1		*BOOT LID CRDI PLATE	20.00	0.00	*27.90 FL	NEL
6	1		*BOOT LID MOULDING	20.00	0.00	*85.00 FL	CRA
7	1		*BOOT LID I40 EMBLEM	20.00	0.00	*27.90 FL	NE L
8	1		*BOOT LID LOWER GRANISH	20.00	0.00	*227.90 FL	CRA
9	1		*REAR BUMPER	20.00	0.00	*553.00 FL	DE
10	1		*REAR BUMPER REINFORCEMENT	20.00	0.00	*428.40 FL	CRA
11	2		*REAR BUMPER REINFORCEMENT BRACKET LH/RH	20.00	0.00	*160.60 FL	BT
12	10		*REAR BUMPER CLIP	20.00	0.00	22 *22.40 FL	NEL
13	2		*REAR BUMPER BRACKET	20.00	0.00	*71.20 FL	SVC
14	1		*REAR BUMPER SPONGE	20.00	0.00	*103.50 FL	TN
15	1		*REAR BUMPER UNDER COVER	20.00	0.00	*228.00 FL	CRA
16	2		*REAR BUMPER REFLECTOR LH RH	20.00	0.00	*61.20 FL	CRA
17	2		*TAIL LAMP LH RH	20.00	0.00	*1,395.60 FL	CRA
18	1		*REAR PANEL	20.00	0.00	*526.70 FL	BUL
19	1		*REAR PANEL GARNISH	20.00	0.00	*57.70 FL	CRA
20	1		*REAR PANEL LOWER PANEL	20.00	0.00	*89.40 FL	BUL
21	1		*REAR FENDER LH	20.00	0.00	*2,171.40 FL	R
22	1		*REAR FENDER INNER LINING LH	20.00	0.00	*169.30 FL	SVC
23	1		*REAR WINDSCREEN MOULDING	20.00	0.00	*28.30 FL	NN
24	2		*EXHAUST SILENCER	20.00	0.00	*1,935.40 FL	BT
25	1		*EXHAUST PIPE CENTER	20.00	0.00	*730.10 FL	BT
26	2		*BOOT LID COMFORTCENTERSTICKER	0	0.00	30 *60.00 FS	NEL
27	1		*REAR BUMPER REVERSE SENSOR	0	0.00	*135.70 FS	SHO
28	1		*REAR BUMPER RUBBER MAT	0	0.00	*50.00 FS	NEL
29	1		*REAR BUMPER ADVERTISEMENT LOGO	0	0.00	*50.00 FS	NEL
30	2		*REAR FENDER ADVERTISEMENT LOGO LH/RH	0	0.00	*200.00 FS	NEL
31	2		*REAR WIND SEALANT	0	0.00	*46.00 FS	NN

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>11,980.50</b>
<b>- List Item Discount on L Items (S\$)</b>	<b>2,287.76</b>
<b>Total Parts (S\$)</b>	<b>9,692.74</b>

ComfortDelGro Engineering Pte Ltd/SHD4835R/23/08/2019 11:02. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	PANEL BEATING	New	<del>800.00</del> 600
2	SPRAY PAINTING	New	<del>1,200.00</del> 1000
3	WIRING	New	<del>50.00</del> 20
4	TUFF KOTE	New	<del>50.00</del> 30
5	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	<del>150.00</del> 50
6	REMOVE/REFIX WINDSCREEN	New	<del>120.00</del> n/a
7	REMOVE/REFIX REVERSE SENSOR	New	<del>80.00</del> 30
8	REMOVE/REFIX EXHAUST PIPE	New	<del>120.00</del> 40
Gross Labour Cost (S\$)			2,570.00

ComfortDelGro Engineering Pte Ltd/SHD4835R/23/08/2019 11:02. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

## REPAIR ESTIMATE\*

DATE 22/8/2019 9:43

DATE 22/8/2019 9:43 \* Tokia  
Cheng

**MODEL : HYUNDAI i40**

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid — Rubber			\$ 2,174.90
	Boot Lid Lock Upper — Small			\$ 102.60
	Boot Lid Lock Lower — Boot			\$ 31.70
	Boot Lid 'H' Emblem — nee			\$ 28.70
	Boot Lid CRDI Plate — nee			\$ 27.90
	Bootlid Moulding — crn			\$ 85.00
	Bootlid i40 Emblem — nee			\$ 27.90
	Bootlid Lower Garnish — crn			\$ 227.90
	Rear Bumper — Refurb			\$ 553.00
	Rear Bumper Reinforcement — crn			\$ 428.40
	Rear Bumper Reinforcement Bracket (LH/RH) — Bent	\$	80.30	\$ 160.60
	Rear Bumper Clip 10 pcs — nee			\$ 22.00
	Rear Bumper Bracket X su	\$	35.60	\$ 71.20
	Rear Bumper Sponge — tin			\$ 103.50
	Rear Bumper Under Cover — crn			\$ 228.00
	Rear Bumper Reflector Lamp (LH/RH) — crn	\$	30.60	\$ 61.20
	Tail Lamp (LH/RH) — crn	\$	697.80	\$ 1,395.60
	Rear Panel — Rubbed			\$ 526.70
	Rear Panel Garnish — crn			\$ 57.70
	Rear Panel Lower Panel — Rubbed			\$ 89.40
	Rear Fender (LH) X repair			\$ 2,171.40
	Rear Fender Inner Lining (LH) X suit			\$ 169.30
	Rear Windscreen Moulding X "			\$ 28.30
	Exhaust Pipe Insulator X su	\$	58.55	\$ 117.10
	Exhaust Silencer — Bent	\$	967.70	\$ 1,935.40
	Exhaust Pipe Hanger X su	\$	58.55	\$ 117.10
	Exhaust Pipe Centre — Bent			\$ 730.10
<b>SUB TOTAL</b>				<b>\$ 11,672.60</b>
<b>LESS 20%</b>				<b>\$ 2,334.52</b>
<b>DISCOUNTED TOTAL</b>				<b>\$ 9,338.08</b>
	Boot Lid Comfort Logo & Tel No. Sticker — nee			\$ 30.00
	Rear Bumper Reverse Sensor — Shuts			\$ 135.70
	Rear Bumper Rubber Mat — nee			\$ 50.00
	Rear Bumper Advertisement Logo — nee			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH) — nee	\$	100.00	\$ 200.00
	Rear Windscreen Sealant X "			\$ 46.00
				<b>\$ 511.70</b>

SHD 4835R

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	<b>Labour Charge</b>			<b>600</b>
	Panel Beating			\$ <del>850.00</del>
	Spray Painting Charge			\$ <del>1,200.00</del> 1000
	Wiring Charge			\$ <del>50.00</del> 20
	Tuff Kote			\$ <del>50.00</del> 30
	Remove/Refix Cushion & Upholstery Rear			\$ <del>150.00</del> 50
	Remove/Refix Rear Windscreen Glass			\$ <del>120.00</del> 50
	Remove/Refix Reverse Sensor			\$ <del>80.00</del> 30
	Remove/Refix Exhaust Pipe			\$ <del>300.00</del> 40
	<i>Meriken fee</i>			\$ 11 -
	<b>TOTAL LABOUR</b>			<b>\$ 2,800.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 12,649.78</b>
<p><i>Kg for 16(1/2)</i></p> <p><i>1050km 24/8/19</i></p> <p><i>7 Py,</i></p> <p><i>4/5</i></p> <p><i>After Repair ph</i></p>				
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Aug 2019 17:35 <a href="#">Sendback Est</a>	23 Aug 2019 11:02 <b>S\$12,273.74</b>	23 Aug 2019 11:03 <a href="#">Edit Adj Rpt</a>	<b>S\$7,550.00</b> <a href="#">Edit Estimates</a>	<b>S\$7,550.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured:	CTPL, Co. Reg. No.: 199303821R								
Main Claimant:	CTPL								
Vehicle Reg. No.:	SHD4835R	Date of Loss:	21/08/2019 12:00 - :59 [65 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / M1906440	Policy/Cover Note No.:	MK000519 (Third Party Only) Coverage: 07/06/2019 - 06/06/2020						
Vehicle Reg. No. (Insured):	SJW3024Y	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Ng Kwai Kay Francis]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN ] ... [Final Rpt due 03/09/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

SHD4835R (M1906440)

[SJW3024Y]

TP

CTPL

Aug 21 2019 12:00PM

[CTPL]

ComfortDelGro Engineering Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
**View**
[View in Browser](#)

### Assessment Reports

1 per page



























No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	23/08/19 11:02	Repairer Estimates	Load HTM	
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)	Thumbnail	Print
1	23/08/19 11:07	Accident Statement From:TP - Reg. No: SHD4835R, Claimant: CTPL	Load HTM	

### Photos/Images

3 per page



No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/08/19 07:51	General View	Load JPG	<input checked="" type="checkbox"/>
2	26/08/19 07:51	General View	Load JPG	<input checked="" type="checkbox"/>
3	26/08/19 07:51	General View	Load JPG	<input checked="" type="checkbox"/>
4	26/08/19 07:51	General View	Load JPG	<input checked="" type="checkbox"/>
5	26/08/19 07:51	General View	Load JPG	<input checked="" type="checkbox"/>
6	26/08/19 07:51	General View	Load JPG	<input checked="" type="checkbox"/>
7	26/08/19 07:51	General View	Load JPG	<input checked="" type="checkbox"/>
8	26/08/19 07:51	General View	Load JPG	<input checked="" type="checkbox"/>
9	26/08/19 07:51	General View	Load JPG	<input checked="" type="checkbox"/>
10	26/08/19 07:51	General View	Load JPG	<input checked="" type="checkbox"/>
11	26/08/19 07:51	General View	Load JPG	<input checked="" type="checkbox"/>
12	26/08/19 07:51	General View	Load JPG	<input checked="" type="checkbox"/>
13	26/08/19 07:51	General View	Load JPG	<input checked="" type="checkbox"/>
14	26/08/19 07:51	General View	Load JPG	<input checked="" type="checkbox"/>
15	26/08/19 07:51	General View	Load JPG	<input checked="" type="checkbox"/>
16	26/08/19 07:51	General View	Load JPG	<input checked="" type="checkbox"/>
17	26/08/19 07:51	General View	Load JPG	<input checked="" type="checkbox"/>
18	26/08/19 07:51	General View	Load JPG	<input checked="" type="checkbox"/>
19	26/08/19 07:51	General View	Load JPG	<input checked="" type="checkbox"/>
20	26/08/19 07:51	General View	Load JPG	<input checked="" type="checkbox"/>
21	26/08/19 07:51	General View	Load JPG	<input checked="" type="checkbox"/>
22	26/08/19 07:51	General View	Load JPG	<input checked="" type="checkbox"/>
23	26/08/19 07:51	General View	Load JPG	<input checked="" type="checkbox"/>
24	26/08/19 07:51	General View	Load JPG	<input checked="" type="checkbox"/>
25	26/08/19 07:51	General View	Load JPG	<input checked="" type="checkbox"/>
26	26/08/19 07:51	General View	Load JPG	<input checked="" type="checkbox"/>
27	26/08/19 07:51	General View	Load JPG	<input checked="" type="checkbox"/>
28	26/08/19 07:51	General View	Load JPG	<input checked="" type="checkbox"/>
29	26/08/19 07:51	General View	Load JPG	<input checked="" type="checkbox"/>
30	26/08/19 07:51	General View	Load JPG	<input checked="" type="checkbox"/>
31	26/08/19 07:51	General View	Load JPG	<input checked="" type="checkbox"/>
32	26/08/19 07:51	General View	Load JPG	<input checked="" type="checkbox"/>
33	26/08/19 07:51	General View	Load JPG	<input checked="" type="checkbox"/>
34	26/08/19 07:51	General View	Load JPG	<input checked="" type="checkbox"/>
35	26/08/19 07:51	General View	Load JPG	<input checked="" type="checkbox"/>
36	26/08/19 07:51	General View	Load JPG	<input checked="" type="checkbox"/>
37	26/08/19 07:51	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
38	26/08/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
39	26/08/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
40	26/08/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
41	26/08/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
42	26/08/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
43	26/08/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
44	26/08/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
45	26/08/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
46	26/08/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
47	26/08/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
48	26/08/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
49	26/08/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
50	26/08/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
51	26/08/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
52	26/08/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
53	26/08/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
54	26/08/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
55	26/08/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
56	26/08/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
57	02/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	02/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	02/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	03/09/19 16:24	LOD, Invoice, LOR, Mileage Record, LA, LTA Search Fee	 Load PDF	
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	22/08/19 18:02	E-filed GIA report	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19014816/K1SF3E2

Date: 16/09/2019

## REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MK000519

Claimant Vehicle No : SHD4835R

Insured Vehicle No : SJW3024Y

Date of Loss: 21/08/2019

Nature of Claim: TP

Claim No: M1906440

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SHD4835R

Make &amp; Model: HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)

Engine No: D4DFDU504515

Reg. Date: 06/03/2014 (Man. Year: 2014)

Chassis No: KMHLB41UMEU048434

Colour: Blue

Odometer: 504968 km

Engine Capacity: 1685 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Average

## CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Hankook 7 mm

Rear Left Side: Hankook 7 mm

Front Right Side: Hankook 7 mm

Rear Right Side: Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,692.74	7,664.26	2,028.48	20.93
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,570.00	1,770.00	800.00	31.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,273.74</b>	<b>9,445.26</b>	<b>2,828.48</b>	<b>23.04</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>7,550.00</b>		
<b>(S\$)</b>	12,273.74	7,550.00	4,723.74	38.49
<b>+ GST 7.00/7.00% (S\$)</b>	859.16	528.50	330.66	38.49
<b>Nett Amount (S\$)</b>	<b>13,132.90</b>	<b>8,078.50</b>	<b>5,054.40</b>	<b>38.49</b>

## INSPECTION

Date of Assignment: 23/08/2019 Present Location:

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 22/08/2019 Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)  
59 Loyang Drive  
Singapore 508969

Estimated Period of Repair: 7.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 16 Sep 2019)
<b>Parts:</b>	143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHD4835R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Buckled	2,174.90 FL	*2,174.90 FL
2	1		*BOOT LID LOCK UPPER	Jammed	102.60 FL	*102.60 FL
3	1		*BOOT LID LOCK LOWER	Bent	31.70 FL	*31.70 FL
4	1		*BOOT LID H EMBLEM	Necessary	28.70 FL	*28.70 FL
5	1		*BOOT LID CRDI PLATE	Necessary	27.90 FL	*27.90 FL
6	1		*BOOT LID MOULDING	Cracked	85.00 FL	*85.00 FL
7	1		*BOOT LID I40 EMBLEM	Necessary	27.90 FL	*27.90 FL
8	1		*BOOT LID LOWER GRANISH	Cracked	227.90 FL	*227.90 FL
9	1		*REAR BUMPER	Deformed	553.00 FL	*553.00 FL
10	1		*REAR BUMPER REINFORCEMENT	Cracked	428.40 FL	*428.40 FL
11	2		*REAR BUMPER REINFORCEMENT BRACKET LH/RH	Bent	160.60 FL	*160.60 FL
12	10		*REAR BUMPER CLIP	Necessary	22.40 FL	*22.00 FL
13	2		*REAR BUMPER BRACKET	Serviceable	71.20 FL	*- FL
14	1		*REAR BUMPER SPONGE	Torn	103.50 FL	*103.50 FL
15	1		*REAR BUMPER UNDER COVER	Cracked	228.00 FL	*228.00 FL
16	2		*REAR BUMPER REFLECTOR LH RH	Cracked	61.20 FL	*61.20 FL
17	2		*TAIL LAMP LH RH	Cracked	1,395.60 FL	*1,395.60 FL
18	1		*REAR PANEL	Buckled	526.70 FL	*526.70 FL
19	1		*REAR PANEL GARNISH	Cracked	57.70 FL	*57.70 FL
20	1		*REAR PANEL LOWER PANEL	Buckled	89.40 FL	*89.40 FL
21	1		*REAR FENDER LH	Repair	2,171.40 FL	*- FL
22	1		*REAR FENDER INNER LINING LH	Serviceable	169.30 FL	*- FL
23	1		*REAR WINDSCREEN MOULDING	Not Necessary	28.30 FL	*- FL
24	2		*EXHAUST SILENCER	Bent	1,935.40 FL	*1,935.40 FL
25	1		*EXHAUST PIPE CENTER	Bent	730.10 FL	*730.10 FL
26	2		*BOOT LID COMFORTCENTERSTICKER	Necessary	60.00 FS	*30.00 FS
27	1		*REAR BUMPER REVERSE SENSOR	Shorted	135.70 FS	*135.70 FS
28	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS
29	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 FS	*50.00 FS
30	2		*REAR FENDER ADVERTISEMENT LOGO LH/RH	Necessary	200.00 FS	*200.00 FS
31	2		*REAR WIND SEALANT	Not Necessary	46.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>11,980.50</b>	<b>9,463.90</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>2,287.76</b>	<b>1,799.64</b>
<b>Total Parts (\$\$)</b>	<b>9,692.74</b>	<b>7,664.26</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	OD/TP Case (Insurer)	11.00	11.00
<b>Sub Total (\$\$)</b>			<b>11.00</b>	<b>11.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	800.00	600.00
2	SPRAY PAINTING	New	1,200.00	1,000.00
3	WIRING	New	50.00	20.00
4	TUFF KOTE	New	50.00	30.00
5	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	50.00
6	REMOVE/REFIX WINDSCREEN	New	120.00	0.00
7	REMOVE/REFIX REVERSE SENSOR	New	80.00	30.00
8	REMOVE/REFIX EXHAUST PIPE	New	120.00	40.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,570.00</b>	<b>1,770.00</b>

Report was unsubmitted during this print-out.
---

&lt; END OF ESTIMATES &gt;