

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0996/2019/NS
Date : 21-Aug-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : MR TEOW KHEK SOO
Address : 760 JURONG WEST ST 74
#12-02
Singapore 248732
Telephone : HP +65 97376819
Type of Claim : Own Damage Claims
Policy No. : 1800137600
Vehicle No : **SGN 8618 J**
Model Code : Audi Q5 SPORT 2.0 TFSI qu
Model / Year : 27/11/2018
Engine No : DAX 046070
Chassis No : WAUZZZF5J2239125
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 17-Aug-19
Place of Accident : ALONG PIE TOWARDS TUAS

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SGN 8618]

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	✓
2	To remove and transfer aircond condenser, charged air cooler, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry put vacuum and regas.	S/N \$ 1,400.00 ✓	✓
3	To dismantle both front door panel trims. To remove and reinstall both wing mirror assys.	S/N \$ 600.00 ✓	✓
4	To dismantle and renew front bumper, both front fenders, bonnet and both headlights. To repair both front doors. Renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$ 8,000.00 4000 ✓	✓
5	To respray front bumper, front bumper lower spoiler, both front fenders, bonnet hinges, both front wheel arch trims and both front doors.	\$ 7,800.00 3850 4250 ✓	✓
6	To renew both rims and carry out wheel alignment.	S/N \$ 320.00 ✓	✓
7	To carry out diagnostic checks.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: <u>\$ 18,792.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGN 8618]

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER - LH / RH <i>tan /</i>	2 \$	2,180.00 1891.20
2	FRONT BUMPER CONNECTING PIECE - CENTRE <i>can X suc</i>	\$	184.00 X
3	FRONT BUMPER FIXING PARTS <i>new X na</i>	\$	244.00 X
4	FRONT BUMPER SECURING STRIP - LH / RH <i>cut /</i>	2 \$	68.00 52.96
5	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>de /</i>	2 \$	202.00 161.60
6	FRONT BUMPER GRILLE - CENTRE <i>can /</i>	\$	129.00 102.80
7	FRONT BUMPER SPOILER <i>can /</i>	\$	685.00 548
8	FRONT BUMPER GUARD <i>at /</i>	\$	431.00 344.80
9	FRONT BUMPER CLOSING ELEMENT <i>de /</i>	\$	156.00 124.40
10	RADIATOR GRILLE <i>can /</i>	\$	3,258.00 2606.40
11	QUATTRO INSCRIPTION <i>na /</i>	\$	87.00 69.28
12	RADIATOR GRILLE STRIKER PLATE <i>at /</i>	\$	222.00 177.20
13	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>Mis /</i>	2 \$	1,038.00 829.60
14	FRONT BUMPER END CAP - LH / RH <i>Mis /</i>	2 \$	166.00 131.68
15	FRONT BUMPER LOCKING CLIP <i>na /</i>	4 \$	15.00 11.52
16	FRONT BUMPER CARRIER <i>st /</i>	\$	831.00 664.40
17	FOAM FILLER PIECE <i>Mis /</i>	\$	260.00 207.20
18	FRONT LOWER SIGHT SHIELD <i>2 cut /</i>	\$	116.00 92.40
19	FRONT BUMPER BRACKET - LH / RH <i>st /</i>	2 \$	462.00 368.80
20	FRONT BUMPER GUIDE SECTION - LH / RH <i>2 can /</i>	2 \$	68.00 54.24
SUB TOTAL SPARE PARTS			\$ 10,802.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGN 8618]

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/Nett		
21	CAUTION SIGN <i>nee</i> /	NEC \$	13.00	9.76
22	AIRCON STICKER <i>nee</i> /	NEC \$	18.00	14
23	HORN - LH LOW TONE <i>9. cm</i> /	\$	178.00	142.40
24	HORN - RH - HIGH TONE <i>7. cm</i> /	\$	178.00	142.40
25	FENDER - LH / RH <i>bt</i> /	2 \$	2,602.00	2081.60
26	FENDER ATTACHMENT PARTS - FRONT <i>? X sue</i>	2 \$	119.00	X
27	FENDER BRACE - LH / RH <i>9. bt</i> /	2 \$	412.00	328.80
28	FENDER BRACKET - LH / RH <i>nee</i> /	2 \$	32.00	24.64
29	CLOSURE PANEL - LH / RH OUTER <i>nee</i> /	2 \$	56.00	44.48
30	CLOSURE PANEL - LH / RH INNER <i>nee</i> /	2 \$	72.00	56.80
31	INNER SHIELD - LH / RH OUTER <i>nee X sue</i>	2 \$	142.00	X
32	WHEEL HOUSING LINER - LH / RH <i>X sue</i>	2 \$	492.00	X
33	WHEEL HOUSING LINER ATTACHMENT PARTS FRONT <i>X sue</i>	2 \$	69.00	X
34	WHEEL HOUSING LINER - LH / RH <i>sue</i> /	2 \$	285.00	227.60
35	BONNET <i>bt</i> /	\$	3,707.00	2965.60
36	BONNET LID HINGE - LH / RH <i>X sue</i>	2 \$	292.00	X
37	BONNET ATTACHMENT PARTS <i>X sue</i>	2 \$	127.00	X
38	GAS FILLED STRUT <i>X sue</i>	2 \$	217.00	X
39	BONNET STRIKER - LH / RH <i>? X sue</i>	2 \$	218.00	X
40	ENGINE BONNET SOUND ABSORBER <i>X sue</i>	\$	289.00	X
SUB TOTAL SPARE PARTS		\$	9,518.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGN 8618 J

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/Nett		
41	IMPACT PROTECTION - LH / RH / CENTRTE <i>neu ✓</i>	3	\$ 75.00	59.44
42	PLENUM CHAMBER COVER <i>X svc</i>		\$ 131.00	X
43	WATER BOX SEAL <i>X svc</i>		\$ 185.00	X
44	FRONT BUMPER SEAL STRIP - LH / RH <i>? X svc</i>	2	\$ 30.00	X
45	FRONT BUMPER CUSHION - LH / RH <i>? X svc</i>	2	\$ 30.00	X
46	BONNET LID LOCK - FRONT <i>? X svc</i>	2	\$ 391.00	X
47	MICRO SWITCH <i>? X svc</i>	2	\$ 24.00	X
48	CONNECTOR HOUSIN BRACKET <i>? X svc</i>	2	\$ 18.00	X
49	BONNET BOWDEN CABLE - CENTRE <i>? X svc</i>		\$ 53.00	X
50	BONNET RELEASE ELEMENT <i>X can ✓</i>		\$ 53.00	44.68
51	BONNET RELEASE LEVER <i>X svc</i>		\$ 13.00	X
52	BONNET LID LOCK CABLE <i>X svc</i>		\$ 67.00	X
53	FRONT PARKING AID SENSOR - INNER / OUTER <i>MS ✓</i>	2	\$ 924.00	739.00
54	PARKING AID SEAL RING <i>neu ✓</i>	4	\$ 12.00	8.96
55	BUMPER WIRING SET <i>? cut ✓</i>		\$ 378.00	302
56	MAIN BEAM HEADLIGHT MOUNTING - LH / RH <i>neu ✓</i>	2	\$ 214.00	171.00
57	LED HEADLIGHT - LH / RH <i>bro ✓</i>	2	\$ 14,454.00	11,563.00
58	LIGHT CONTROL SYSTEM CONTROL UNIT <i>? X svc</i>	2	\$ 1,383.00	X
59	MAIN LIGHT ELECTRONICS POWER MODULE <i>? X svc</i>	2	\$ 1,385.00	X
60	LED WITH HEAT SINK - LH / RH <i>? X svc</i>	2	\$ 1,980.00	X
SUB TOTAL SPARE PARTS			\$ 21,800.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGN 86181

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/Nett		
61	HEADLIGHT HOSE - LH / RH ? <i>you</i>	2	\$ 70.00	X
62	HEADLIGHT WASHER LIFT CYLINDER - LH / RH ? <i>can</i>	2	\$ 256.00	204
63	LIFT CYLINDER HOSE ? <i>can</i>		\$ 113.00	90
64	HEADLIGHT WASHER PUMP ?		\$ 147.00	X
65	PUMP INSULATOR ?		\$ 19.00	X
66	WASH WATER RESERVOIR HOSE ?		\$ 61.00	X
67	WASH WATER RESERVOIR ?		\$ 200.00	X
68	WINDSCREEN WASHER SYSTEM PUMP ?		\$ 118.00	X
69	RESERVOIR CAP X		\$ 24.00	X
70	WATER RESERVOIR END CAP X		\$ 59.00	X
71	COOLANT RADIATOR LOCK CARRIER <i>can</i>		\$ 1,169.00	935.00
72	RADIATOR SUPPORT - LH / RH ? <i>can</i>	2	\$ 96.00	76.64
73	RADIATOR BRACE - LH / RH LOWER ? <i>can</i>	2	\$ 104.00	81.76
74	EXTERNAL TEMPERATURE SENSOR ? <i>you</i>		\$ 54.00	X
75	TEMPERATURE SENSOR BRACKET <i>can</i>		\$ 14.00	11.00
76	A/C CONDENSER ? <i>bt</i>		\$ 547.00	437.60
77	REFRIGERANT LINE ?		\$ 263.00	X
78	REFRIGERANT LINE ? <i>you</i>		\$ 273.00	X
79	A/C ADAPTER CABLE ?		\$ 27.00	X
80	RADIATOR ? <i>bt</i>		\$ 820.00	655.60
SUB TOTAL SPARE PARTS			\$ 4,434.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGN 86181

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/Nett		
81	READY MIX COOLANT <i>neu ✓</i>	4	\$ 84.00	67.20
82	CHARGE AIR COOLER <i>bt ✓</i>		\$ 724.00	578.80
83	CHARGE AIR COOLER SEAL RING <i>neu ✓</i>	2	\$ 82.00	64.96
84	CHARGE AIR COOLER PRESSURE HOSE <i>? xsc ✓</i>		\$ 283.00	X
85	CHARGE AIR COOLER PRESSURE PIPE <i>? xsc ✓</i>		\$ 477.00	X
86	FAN RING <i>? ca ✓</i>		\$ 373.00	298.40
87	RADIATOR FAN WITH CONTROL UNIT <i>? neu ✓</i>		\$ 2,159.00	1727.20
88	RADIATOR AIR GUIDE - UPPER / LOWER <i>? ca ✓</i>	2	\$ 86.00	67.68
89	RADIATOR AIR GUIDE - CENTRE <i>? ca ✓</i>		\$ 37.00	29.52
90	RADIATOR AIR GUIDE - LH / RH <i>cut ✓</i>	2	\$ 100.00	79.36
91	RADIATOR LOUVRE <i>? ca ✓</i>		\$ 483.00	386
92	ADJUST MOTOR <i>?</i>		\$ 166.00	X
93	AIR INTAKE DUCT AIR GUIDE <i>? } xsc ✓</i>		\$ 79.00	X
94	AIR INTAKE HOSE <i>? }</i>		\$ 85.00	X
95	AIR INTAKE AIR FILTER <i>? }</i>		\$ 368.00	X
96	WHEEL COVER - LH / RH FRONT <i>scr ✓</i>	2	\$ 1,154.00	922.40
SUB TOTAL SPARE PARTS			\$ 6,740.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGN 8618 J

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/Nett		
97	S-LINE INSCRIPTION <i>new /</i>	2	\$ 225.00	180
98	NOISE INSULATION <i>? new /</i>		\$ 743.00	594.40
99	WINDOW SLOT SEAL - LH / RH FRONT <i>cut / (2/2/2/2)</i>	2	\$ 1,074.00	859.00
100	WINDOW GUIDE TRIM STRIP <i>X sur</i>	2	\$ 622.00	X
101	ALUMINIUM RIM - LH <i>(LH & RH) cut /</i>	2	\$ 1,846.00	1476.80
102	ALUMINIUM RIM RUBBER VALVE <i>new / X sur</i>	<i>2/2/2/2</i>	\$ 13.00	X
103	ACCELERATOR PEDAL <i>cut /</i>		\$ 216.00	170.80
104	ACCELERATOR PEDAL CAP <i>X sur</i>		\$ 64.00	X
105	ACCELERATOR PEDAL CBRACKET <i>? X sur</i>		\$ 712.00	X
106	BRAKE PEDAL <i>X sur</i>		\$ 338.00	X
107	FRONT NO. PLATE <i>bt /</i>	S/N	\$ 40.00	40
108	SUNDRIES <i>? new /</i>		\$ 700.00	133.52
TOTAL SPARE PARTS			\$ 59,887.00	
TOTAL LABOUR CHARGES			\$ 18,792.00	
GRAND TOTAL			\$ 78,679.00	

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved
 Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks


29/8/19
: RASUL - Hp 90010068
: 22/08/19 @ 1500
: 12 days
: EXCESS: TBA
: REVERT

Resurvey before paint

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant