

# Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

## Supplementary Estimate 1

GST Reg No. 19-9902271-W

**AIG Asia Pacific Insurance Pte Ltd**  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
Attn: Mr. Adrian Ling - Motor Claims Dept  
Tel: 6841 0055 - Fax: 6256 4315

Estimate No. PA/OD/0996/2019/N5  
Date 3-Sep-19  
Service Advisor Glory Tan  
Pages 1 of 1  
Regn No SGN 8618 J  
Model No Audi Q5 SPORT 2.0 TFSI qu

Quantity	Description	Unit Price	Amount
<b>Parts</b>			
1	Air cond compressor <i>? see -</i>	\$ 1,769.00	1445.00
2	Poly V-Belt <i>? X see</i>	\$ 47.00	
3	Vibration damper <i>see -</i>	\$ 396.00	316.80
4	Wiring set for starter and alternator <i>at -</i> with earth lead	\$ 772.00	617.20
5	Butt connector, watertight GG11-F-2 <i>ca -</i>	\$ 48.00	38.40
6	Butt connector, watertight GG11-F-1 <i>ca -</i>	\$ 48.00	38.40
		<b>\$ 3,080.00</b>	

### LABORS

1	To renew air cond compressor, poly v-belt S/N and other engine components.	\$ 480.00
---	---	-----------

Labour total	\$ 480.00
Part total	\$ 3,080.00
<b>GRAND TOTAL</b>	<b>\$ 3,560.00</b>

For Premium Automobiles Pte Ltd

Authorised Signature

# Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

## Supplementary Estimate 1

GST Reg No. 19-9902271-W

<b>AIG Asia Pacific Insurance Pte Ltd</b> 78 Shenton Way #07-16 AIG Building Singapore 079120 <b>Attn: Mr. Adrian Ling - Motor Claims Dept</b> <b>Tel: 6841 0055 - Fax: 6256 4315</b>		<b>Estimate No.</b> PA/OD/0996/2019/NS <b>Date</b> 17-Sep-19 <b>Service Advisor</b> Glory Tan <b>Pages</b> 1 of 1 <b>Regn No</b> SGN 8618 J <b>Model No</b> Audi Q5 SPORT 2.0 TFSI qu	
Quantity	Description	Unit Price	Amount
<b>Parts</b>			
1	Rear bumper wheel arch cover LHS	\$ 487.00	389.60
2	Rear bumper wheel arch cover RHS	\$ 487.00	389.60
		<b>\$ 974.00</b>	
<b>LABORS</b>			
1	To remove and reinstall rear parking aid and rear lid kick sensor assy.	S/N \$ 360.00	✓
2	To dismantle rear bumper. Repair rhs rear door. Reinstall all parts removed.	\$ <del>1,600.00</del> 750	✓
3	To respray rhs A-pillar, rhs rear door, rear bumper, lower spoiler and both wheel arch trims.	\$ <del>3,800.00</del> 2050	
Labour total		<b>\$ 5,760.00</b>	
Part total		<b>\$ 974.00</b>	
<b>GRAND TOTAL</b>		<b>\$ 6,734.00</b>	

For Premium Automobiles Pte Ltd

\_\_\_\_\_  
 Authorised Signature