SS. REC. BY:	HOCK Ann ASSIGNMEN	<u>r</u> (Office)	
yom (Person): Estimated Cost:	Chong Boon Sen of CTI	Date/Time: 21 /08/2019	
OD/TP/WS	TP RES / OD RES / EVA / INV / MV / CS	Insured: PC 2/843	
at Workshop m	icle No: SLG 34423 Neo Automotive Pte Ltd	Tel: 6385 5262	
of 25 06 Policy No: D	MBISN30386519000	Claim No: SNM 19 D203820 CO)	
Sum Insured: Make of Veh: (Client's Record)	D.O.A. 15[08]2019	
	REP. / REV 24 HRS	MIS MLO Vehicle IN OUT	
Date/Time	Action/Instruction (X) Estimate		
	PC 21843 : NA/INC 19014293/24 SLG 34423 : NA/INC 19014293/24	D. 0. A. 15 0.8 20 P	
	Diemantle: 26/8/2019.		

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adt Assigned	Adj Rpt	Adj Subi	mitted	Ins Auth'ed	Status	
Main	15 Aug 2019		28 Aug 2019 09:05 Edit Adj Rpt					Pending for S Report Cancel Case	iurvey
	Main	Re	ference		Claim Details		Document	s	Show All
CLAIM SU	IBFOLDER DE	TAILS		- Savet		[Created	d by insurer]		
Insured:									
Main Claimant:	NEO AUT	D LEASING PTE	LTD, Co. Reg.	No.: 201814	915N				
Vehicle Re	SLG344	SLG3442J				15/08/20	19 18:00 - :59		
Claim Type	: TP / SN	TP / SNM19D203820C02			Policy/Cover Note No.:	DMB1SN30386519000			
Vehicle Re No. (Insured):	PC2184J				Policy No. (Claimant):				
(Insurce).		Excess: S\$0.00							
Repairer:	Neo Auto	motive (HQ) 53	UBI AVE 1 #05-4	44 PAYA UBI	INDUSTRIAL PAR	RK SINGAP	ORE, 408934 Ubi	- Tel:	
Handling Insurer:	China Tai	ping Insurance	(Singapore) Pt	e. Ltd. (HQ) - Tel: 6389 611	1 [Hand	lled by Chong Bo	on Sen]	
Claimant's Insurer:	NTUC Inc	ome Insurance							. (2040)
Adjuster:	LKK Auto	Consultants Pto	Ltd (HQ) - Tel:	6256-3561	[Handled by I	LEE HOCK	ANN] [Final	Rpt due 06/0	9/2019]
ASSOCIA	TED MAIL RE	CEIVED						View All Comp	ose Case Mail
There are	no mail for this	case.							
ALL ASS	OCIATED TAS	sks⊟				View All	Search Tasks	Create New Tas	k Complete
Due Da	te Priority	Type Task	Group Sub	ject Har	ndler Assign	ned By	Completed On	Created (On Done

Nivitha (LKK Auto)

From:

Chong Boon Sen

boonsen.chong@sg.cntaiping.com>

Sent:

Wednesday, 21 August 2019 9:17 AM

To:

ling@centrollc.com.sg

Cc:

assignments

Subject:

our ref: snm19d203820 / pri : your ref: cllc.pd.128.2019

WITHOUT PREJUDICE

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle. Please merimen as usual.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 6389617 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please

Centro-Legal Law orporation ADVOCATES AND SOLICITORS

151 Chin Swee Road #02-21 Manhattan House Singapore 169876

Tel: 6235 0633 Fax: 6235 6939

Your ref

To be advised (PC2184J)

Our ref

CLLC.PD.128.2019

20.08.2019

CHINA TAIPING INSURANCE (S'PORE) PTE LTD

#16-00 Springleaf Tower Singapore 079909

Attn: Officer-In-Charge

Dear Sirs,

NOTICE TO INSURANCE TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION

We act for NEO AUTO LEASING PTE LTD, the owner of motor vehicle SLG3442J, who has appointed us to act on his behalf to claim against your insured's vehicle no PC2184J in regards to the road traffic accident on 15.08.2019.

Please be informed that the said motor vehicle can be inspected at:-

NEO AUTOMOTIVE PTE LTD 53 UBI AVE 1, #05-44 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934

Tel: 6385 5262 Fax: 6385 8262

Kindly contact: Mrs Neo Tel: 9091 4853

Please note that if you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully, RPOR4702

CENTRO-LEGAL LAW CORPORATION Cc Mrs Nepth

6385 8262

MNA119107441 / National Assessment Centre Services - Ubi ENTRY DATE & TIME: 16/08/2019 14:37 SUBMITTED BY: Jackson Ho Zhao Tian

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

100

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

	ACCIDENT STATEMENT	
Date Of Report	16/08/2019 14:37	
Date Of Accident	15/08/2019 18:00	
Exact Location Of Accident	HOUGANG ST 93	
Country/State of Loss	SINGAPORE	
	DETAILS OF OWN VEHICLE	

DE MILO O.	
F	

SLG3442J Vehicle Registration Number

Insured/Policyholder

NEO AUTO LEASING PTE LTD Name Of Registered Owner

201814915N Co Reg No

NOEMAIL Email Address

(LOCAL) +65-91449265 Mobile Phone No OFFICE-91449265 Alternative Phone No.

Vehicle Particulars

TOYOTA Manufacturer

COROLLA AXIO 1.5X A Model

Exact Purpose for which vehicle was being used at COMMERCIAL USE

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No. Please state action to be taken

THIRD PARTY PRIVATE HIRE

Vehicle Category

Insurance Company

NTUC INCOME INSURANCE CO-OPERATIVE LTD Name of Insurance Company

THIRD PARTY FIRE AND/OR THEFT Type Of Coverage

YES Fleet Policy

5103424803 Policy Number

Cover Note Number

Driver

SHAIFUL ANUAR BIN MOHAMAD SEDIK Name of Driver

S9225341D NRIC No 22/07/1992 Date Of Birth OUTDOOR Occupation 08/07/2011 Date Of Driving Pass

8 YEARS AND 1 MONTH Driving Experience

MALE Gender

(LOCAL) +65-98296083 Mobile Number

Fax Number

OFFICE-98296083 Contact Number

NOEMAIL EMail Address

Address

BLK 204A COMPASSVALE DRIVE

#04-441

Postcode

541204

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - CHANGE/CROSS LANE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved in the accident

2

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

SENGKANG NEIGHBOURHOOD POLICE CENTRE

ROAD: 2 SENGKANG SQUARE #01-02 SINGAPORE, POSTCODE:

Police Station Address

545025, COUNTRY: SINGAPORE

Police Station Contact

TEL NO: 1800 - 3438999 - FAX NO:

Was notice of intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT - T/20190816/2008.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

VIDEO FOOTAGE WITH DRIVER

Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

PC2184J

Vehicle Make/Model/Colour

Details Of Properties

BUS

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

V. Or Passenger (moduling 5.1.5.)					
DETAILS OF INJURED PERSON 1					
SHAIFUL ANUAR BIN MOHAMAD SEDIK					
BODY					
SLG3442J					
YES					
NO					
	BODY SLG3442J YES				

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1 Please report correctly the details of the accident to speed up the claims process.
- 2 This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful</u> and <u>accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4 The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8 Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents@including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time: Driver's Signature (If driver is not the policyholder) Date & Time: Reporting Centre Personner's Sign Name: NRIC/FIN No.

Accident Sketch Plan



Telde to policit report of policit report

DECLARATION OF THE PROPERTY OF

400

particulars are true in every respect.

Policyholder's Signature Date & Time: Oriver's Signature (If driver is not the policyholder) Date & Time: Reporting Centre Personales Signature Name: NRIC/FIN No.:

Police Report





1 of 4

Report No. T/20190816/2008



Police Station Of Origin: Sengkang N P C 2 Sengkang Square #01-02 SINGAPORE 545025

Tel No. 1800-343 8999

REPORT	OF A	TRAFFIC	ACCIDENT
--------	------	---------	----------

Date/Time Report Made: 16/08/2019 02:17			Vide Report No.: F/20190815/0145	Station Diary No 19	
Informa	nt's Partic	ulars			
	Informant: L ANUAR E	BIN MOHAMAD	Address: APT BLK 204A COMP 541204	PASSVALE DRIVE #04-441 SINGAPORE	
ID Type / ID No.: NRIC NO / S9225341D			Contact No.: Home/Office: Mobile: 98296083		
Nationality: SINGAPORE CITIZEN		Email:			
Sex: Age: Date of Birth: Male 27 22/07/1992			Type of Informant: Driver		
Race Malay		Language: Institution / School Na			
Occupation: SELF-EMPLOYED (GRAB DRIVER)			Driving Licence Information: Class: 3 Date of Expiry:		

Type of Accident:	Injury Attended by Police					
Location: Along Road 1 HOUGANG S Along Houga Weather: Clear		gang Street 91 Road Surface:		Road Speed Limit:		
				Traffic Volume:		
Traffic Flow:						

Details of Vehicle Involved						
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenge
PC2184J	Bus/Coach/Mi nibus	-				0
SLG3442J	Car					0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Police Report





Police Station Of Origin: Sengkang N.P.C 2 Sengkang Square #01-02 SINGAPORE 545025

2 of 4 Report No. T/20190816/2008

Tel No: 1800-343 8999

CONTINUATION OF REPORT

Driver	Control of the Contro		SEARCH STATE	Design	12390	
Name	SHAIFUL ANUAR BIN MOHAMAD SEDIK			ID No		S9225341D
Related Vehicle	SLG3442J (Car)				ct No.	98296083
Hospital/Clinic	SENGKANG GENERAL HOSPITAL PLTD.			Class Drivin Licent Expiry	g ce &	Class: 3 Date of Expiry: NIL
Date Treatment	15/08/2019	15/08/2019 Date D			NIL	
No. of Days granted Medical Leave 05			Degree of	Injury	NIL	
Driver				1000	1000	Harry State of the Control of the Co
Name	DHALIWAL TALWINDER SINGH			ID No		G2528329K
Related Vehicle	NIL			Conta	ct No.	NIL
Hospital/Clinic	NIL			Class Drivin Licent Expiry	g ce &	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	70.00	Date Disch	narge	NIL	
No. of Days gran	ted Medical Leave	NIL	Degree of			

Brief Details.

On 15/08/2019 at about 1800hrs, I was driving my vehicle registration plate number SLG3442J along Hougang Street 93 towards Hougang Street 91. I was filtering out from single lane road into a two lane road. I was travelling along the left of two lanes road. I observed that one white school bus registration plate number PC2184J whom was in front of my vehicle went to the right lane and was signaling left. As I was travelling straight, I assume that the bus PC2184J left signal was for his initial filtering lane. I then just continue to drive straight. The bus PC2184J then suddenly made a left turn into Hougang Secondary School. The said road is a school zone road.

The bus PC2184J then collided onto my vehicle right rear. Due to the impact, I was unable to control my vehicle. I then drove forward and collided onto the railing along the road side. The bus PC2184J then continued and drove into the school. The driver of PC2184J then parked his vehicle in the school and came to me. I then called for police assistance.

My in-built CCTV media card was handover to the traffic police. I am not sure the number of passengers in the bus.

During the accident, no one required at medical attention. After the incident, I then went to Sengkang General Hospital for medical check and was given 5 days' medical leave.

Police Report



....



Police Station Of Origin: Sengkang N.P.C 2 Sengkang Square #01-02 SINGAPORE 545025 Tel No: 1800-343 8999 3 of 4 Report No. T/20190816/2008

CONTINUATION OF REPORT

Schedule of Surveyor's Attendance for Conducting PRI

This document indicates that the 3rd party surveyor has inspected the vehicle as follows: : Neo Automotive Pte Ltd Workshop : 54, 8910 8 SLG 3442J Vehicle No. Date of Accident Name of TP Insurer Co. : Surveyor's Firm & Name : Hock Am Contact No. 1st PRI Conducted. Date & Time of Inspection : 2.15pm / 23/8/19 Require of Resurvey Hidden/Check Items : YES / NO Signature / Name 2nd PRI Conducted Hidden/Check Damages Items. Date & Time Informed Surveyor : _____ (By Repaire) Date & Time of Inspection : 26/8/11, 2045p Require of Resurvey After Repair: YES / NO Remarks : Signature / Name 3rd PRI Conducted After Repairs. Date & Time Informed Surveyor : ______(By Repaire) Date & Time of Inspection Signature / Name

> Back to OneMotoring

Enquire Transfer Fee

- dance manager Lee	
Vehicle Details	
Vehicle No. :	SLG3442J
Vehicle Type :	
Vehicle Attachment 1:	Z10 - Private Hire (Chauffeur) Motor Car No Attachment
Vehicle Scheme:	Normal
Vehicle Make :	TOYOTA
Vehicle Model:	COROLLA AXIO 1.5X A
Chassis No.:	NRE1610019371
Propellant:	Petrol
Engine No.:	2NR8642825
Engine Capacity:	
Maximum Power Output :	1496 cc
Maximum Laden Weight:	80.0 kW (107 bhp)
Unladen Weight:	1365 kg
Year Of Manufacture :	1090 kg
Original Registration Date :	2016
Lifespan Expiry Date:	28 Sep 2016
COE Category :	A C-
Quota Premium :	A - Car up to 1600cc & 97kW (130bhp)
COE Expiry Date:	\$53,334,00
Road Tax Expiry Date :	27 Sep 2026
PARF Eligibility Expiry Date :	27 Sep 2019
Inspection Due Date:	27 Sep 2026
Intended Transfer Date :	27 Sep 2019
CO2 Emission	27 Aug 2019
CEV/VES Rebate Utilised	114.00 (g/km)
Amount:	\$10,000.00
CO Emission:	
HC Emission :	
NOx Emission :	
PM Emission :	
	Sep 2019. You may renew the road tax from 28 Jun 2019 with all are required to the second
renowed ett - 275	rep 2019. You may renew the road tax from 28 Jun 2019 with all

The current road tax expiry is 27 Sep 2019. You may renew the road tax from 28 Jun 2019 with all pre-requisite(s) fulfilled. If the road tax is renewed after 27 Sep 2019, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable. Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred. Amount Payable (From 28 Sep 2019 to 27 Mar 2020)

20 Sep 20	19 to 27 Mar 2020)	o o mier mier its owi	nership is being transferred.
Transfer Fee : Sub Total :	Amount Before GST (S\$) 25.00	GST Amount (S\$)	Amount After GST (S\$) 25.00
Nett Road Tax Amount (After Offsetting Over Payment) : Total Amount Payable :	341.00	3	25.00 341.00
Amount Payable (From 28 Sep 201	9 to 27 Sep 2020) Amount Before GST	GST Amount	366.00
Transfer Fee : Sub Total :	(\$\$) 25.00	(5\$)	Amount After GST (S\$) 25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	682.00	*	25.00 682.00
Total Amount Payable: You may print this page for refe	erence.		707.00

OK Print

Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars Owner ID Type:		
Owner ID:	Company	
Vehicle Details	915N	
Vehicle No.:	DAGO SOCIONADO	
Vehicle to be Exported:	SLG3442J	
Intended Deregistration Date:	Yes	
Vehicle Make:	27 Aug 2019	
Vehicle Model:	TOYOTA	
Primary Colour:	COROLLA AXIO 1.5X A	
Manufacturing Year:	Black	
Engine No.:	2016	
Chassis No.:	2NR8642825	
Maximum Power Output:	NRE1610019371	
Open Market Value:	80.0 kW (107 bhp)	
Original Registration Date:	\$16,324,00	
First Registration Date:	28 Sep 2016	
ransfer Count:	28 Sep 2016	
Actual ARF Paid:	2	
ntended PARF Rebate Details	\$6,324.00	
ARF Eligibility:	> 3/62	
ARF Eligibility Expiry Date:	Yes	
ARF Rebate Amount:	27 Sep 2026	
ntended COE Rebate Details	\$4,743.00	
OE Expiry Date:		
OE Category:	27 Sep 2026	
OE Period(Years):	A - Car up to 1600cc & 97kW (130bhp)	
P Paid:	10	
OE Rebate Amount:	\$53,334.00	
etal Rebate Amount:	\$37,778.00	
nformation contained herein is correct as at 27 Aug 2019	\$42,521.00	

OK

mv - 52700

NV - 12+79

mv -51-52

Bolance: 7 ym /mmth Deeplum: 7000 ym 7000 1 12 = 583 month

SGCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

UPLOAD A PHOTO of your beloved car to Facebook & tag @mobillubes #askforMobil

Price Range

OR

▼ Depreciation ▼ 2016

FOLLOW US on Lazada Flash it at our booth to redeem a token to play F1 Red Bull Simulator!

Map

Vehicle Type



Home » Used Cars » Motor-East Pte Ltd » Toyota Corolia Axio 1.5A X

Toyota Corolla Axio 1.5A X

toyota axio

Overview	Financial	Insurance	Accessories	Similar	Research	Photos
Price	\$57,800	rii.				
Depreciation ()	\$7,870 /y View mod	r dels with similar d	Reg Date		23-Aug-2016 (6yrs 11mths 26day	s COE left)
Mileage	70,799 kr	n (23.5k /yr)	Manufact	ured 🕥 📑	2016	
Road Tax 🕜	\$682 /yr		Transmiss	sion ,	Auto	
Dereg Value ①	\$41,224 a	s of today (chang	e) OMV 🗇		\$15,557	
COE	\$53,000		ARF	\$	5,557	
Engine Cap	1,496 cc		Power	8	0.0 kW (107 bhp)	
Curb Weight 🕜	1,090 kg		No. of Ow	ners 🗀 2		
Type of Vehicle	Mid-Sized	Sedan				

Features

1.5L Reliable And Efficient 16 Valves 4 Cylinders VVT-i DOHC Engine, Low Fuel Consumption At 17.2Km/L, ABS, Dual SRS Airbags, Remote Alarm Control. View specs of the Toyota Corolla Axio (2015-2019)

Accessories

Pioneer Touch Screen DVD/Bluetooth/Audio Sound System, Leather Seats, Retractable Side Mirrors, Halogen Headlights.

Description

Special Offer Till 31 August Only. Come With 2 Years Third Party Warranty, Easy And Flexible In House Loan And Balloon Scheme Available, No Gimmicks! Low Fuel Consumption, Reverse Camera, Leather Seats, White In Colour, Maintained And Serviced Regularly.

Category

PARE Car

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free

Find out the market value of your existing car for free, Get started

Posted on: 22-Aug-2019 | Last Updated on: 26-Aug-2019

Upfront Payment

Transfer Fee \$25

\$17,340 (change)

Maximum 70% Loan

1s Company

Down

\$588

Based on 2.98% interest rate


















Shortlist Compare Add note Report Error More Actions

Seller Information

Company	Motor-East Pte	Ltd
	» dealer's pricelist	
	* 29 vehs sold 55	vehs available
Address	31 West Coast High	way #01-23
	Search cars nearby	
Location	West Coast Car Mart	
Office No	67772200	
Contact Person(s)	Bernard Teng	96818152

SGCARMART.COM

Login Sign up

New Cars

Sell My Car

Directory

Products

Insurance

Articles

Мар

Forum

Resources



Home » Used Cars » Prime Car Traders Pte Ltd » Toyota Corolle Axio 1.5A X

Toyota Corolla Axio 1.5A X

Overview	Financial	Insurance	Accessories	Similar	Research	Photos
Price	\$60,800					
Depreciation ()	\$7,740 /yr View mode	ls with similar de	Reg Date		06-Mar-2017 (7yrs 6mths 6days 0	COE left)
Mileage	23,300 km	(9.4k /yr)	Manufacture	ed	2016	
Road Tax	\$682 /yr		Transmission	n	Auto	
Dereg Value	\$39,979 as	of today (change) OMV (5)		\$15,139	
COE	\$48,000		ARF (9)		\$5,139	
Engine Cap	1,496 cc		Power		80.0 kW (107 bhp)	
Curb Weight	1,090 kg		No. of Owner	s 🕚	1	
Type of Vehicle	Mid-Sized Se	dan				



Reliable And Efficient 16 Valves 4 Cylinders WT-i DOHC Engine, Low Fuel Consumption At 16Km/L, ABS, Dual SRS Airbags, Retractable Side Mirrors. View specs of the Toyota Corolla Axio (2015-2019)

Accessories

Leather Seats, Pioneer DVD Audio System With Bluetooth, Solar Films, Reverse Sensors, Reverse Camera, In Car

Description

Excellent Condition, Very Well Maintained By Previous Owner, View To Believe, Bank Loan/Loan/In House Loan Available! Trade In Most Welcome! Call/SMS/WhatsApp Our Friendly Sales Reps Today To Arrange For Viewing

Category

PARF Car, Low Mileage Car

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free

Find out the market value of your existing car for free. Get started

Posted on: 02-Jul-2019 | Last Updated on: 23-Aug-2019

Upfront Payment

Transfer Fee

1s Compare

\$25 \$18,240 (change)

Maximum 70% Loan

\$612 Based on 2.98% interest rate https://www.sgcarmart.com/used_cars/info.php?ID=814046&DL=3518
















22.17.1 7.7		8 mace
Click on the point to view	the	vehicle

Shortlist

Compare

Add note

Summary

Report Error

More Actions

Seller Information

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Votified	Est Submitted	Adj Assigned	Adj Rpt	Adj Su	bmitted	Ins Auth'ed	Status	
Main	15 Aug 2019		28 Aug 2019 09:05 Edit Adj Rpt	S\$0.00 Edit Estimate	S\$0.0	0		Pending for Report Cancel Case	Survey
P	lain	Re	ference	C	laim Details		Documer	nts	Show All
CLAIM SUE	FOLDER DE	TAILS				[Creat	ed by insurer]		CONTRACTOR OF STREET
Insured:	-, Co. Reg	g. No.: -					-		
Main Claimant:	NEO AUTO	LEASING PTE L	.TD, Co. Reg. f	No.: 2018149	15N				
Vehicle Reg. No.:	SLG344	23			Date of Loss		2019 18:00 - :59 onths and 18 Days I	From LTA Reg Da	te (Man Yr)]
Claim Type:	2-11-16-11-1								
Vehicle Reg. No. (Insured):	PC2184J Policy No. (Chimnet) 5103424803								
					Excess:	S\$0.00			
Repairer:	Neo Autor	motive (HQ) 53 l	JBI AVE 1 #05-4	4 PAYA UBI IN	NDUSTRIAL PA	ARK SINGA	PORE, 408934 Ubi	- Tel:	
Handling Insurer:	China Tai	ping Insurance (Singapore) Pte	e. Ltd. (HQ) -	Tel: 6389 61	11 [Har	ndled by Chong Bo	oon Sen]	
Claimant's Insurer:	NTUC Inc	ome Insurance (Co-operative Lt	d (HQ) - Tel:					
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-3561	. [Handled by	LEE HOC	K ANN] [Final	Rpt due 06/0	9/2019]
ASSOCIAT	ED MAIL RE	CEIVED						View All Com	pose Case Mai
There are no	mail for this	case.							
ALL ASSO	CIATED TAS	KS⊟				View /	All Search Tasks	Create New Tas	sk Complet
Due Date	Priority	Type Task	Group Subj	ect Handl	ler Assic	ned By	Completed O	-	
				200 6 1 1 1 1 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2					

Claim Documents

*SLG3442J (SNM19D203820C02)
[PC2184J]
TP
NEO AUTO LEASING PTE LTD
Aug 15 2019 6:00PM [-] **Neo Automotive**

Acc	essment Reports		1 per	page v	•
Vo.	Finalized On	National Assessment Centre Services (Ubi)	1 per	Thumbnail	
1	16/08/19 14:46	Accident Statement	0	Load HTM	Print
Pho	tos/Images		3 per	page ▼	€
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	16/08/19 14:43	Accident Photo [Linked Accident Report Documents]	0	Load JPG	✓
2	16/08/19 14:43	Accident Photo [Linked Accident Report Documents]	0	Load JPG	Y
3	16/08/19 14:43	Accident Photo [Linked Accident Report Documents]	0	Load JPG	•
4	16/08/19 14:43	Accident Photo [Linked Accident Report Documents]	0	Load JPG	•
5	16/08/19 14:43	Accident Photo [Linked Accident Report Documents]	0	Load JPG	•
6	16/08/19 14:43	Accident Photo [Linked Accident Report Documents]	0	Load JPG	•
7	16/08/19 14:43	Accident Photo [Linked Accident Report Documents]	0	Load JPG	•
8	16/08/19 14:43	Accident Photo [Linked Accident Report Documents]	0	Load JPG	•
9	16/08/19 14:43	Accident Photo [Linked Accident Report Documents]	0	Load JPG	•
10	16/08/19 14:43	Accident Photo [Linked Accident Report Documents]	0	Load JPG	•
11	16/08/19 14:43	Accident Photo [Linked Accident Report Documents]	0	Load JPG	•
12	16/08/19 14:43	Accident Photo [Linked Accident Report Documents]	0	Load JPG	•
13	16/08/19 14:43	Accident Photo [Linked Accident Report Documents]	0	Load JPG	•
14	16/08/19 14:43	Accident Photo [Linked Accident Report Documents]	0	Load JPG	•
15	16/08/19 14:43	Accident Photo [Linked Accident Report Documents]	0	Load JPG	•
16	16/08/19 14:43	Accident Photo [Linked Accident Report Documents]	0	Load JPG	•
17	16/08/19 14:43	Accident Photo [Linked Accident Report Documents]	0	Load JPG	✓
18	16/08/19 14:43	Accident Photo [Linked Accident Report Documents]	0	Load JPG	•
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	30/08/19 09:56	Odometer Reading	0	Load JPG	•
2	30/08/19 09:56	Chassis Number	0	Load JPG	•
3	30/08/19 09:56	General View	0	Load JPG	•
4	30/08/19 09:56	General View	0	Load JPG	•
5	30/08/19 09:56	General View	0	Load JPG	•
6	30/08/19 09:56	General View	0	Load JPG	•
7	30/08/19 09:56	General View	0	Load JPG	•
8	30/08/19 09:56	General View	0	Load JPG	•
9	30/08/19 09:56	General View	0	Load JPG	•
10	30/08/19 09:56	General View	0	Load JPG	•
11	30/08/19 09:56	General View	0	Load JPG	•
12	30/08/19 09:56	General View	0	Load JPG	•

Blo.	Finalized On	Notice of Assessment Control of the	1 per		•
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	1
13	30/08/19 09:56	General View	0	Load JPG	V
14	30/08/19 09:56	General View	0	Load JPG	•
15	30/08/19 09:56	General View	0	Load JPG	~
16	30/08/19 09:56	General View	0	Load JPG	•
17	30/08/19 09:56	General View	0	Load JPG	•
18	30/08/19 09:56	General View	0	Load JPG	•
19	30/08/19 09:56	General View	0	Load JPG	•
20	30/08/19 09:56	General View	0	Load JPG	•
21	30/08/19 09:56	General View	0	Load JPG	•
22	30/08/19 09:56	General View	0	Load JPG	•
23	30/08/19 09:56	General View	0	Load JPG	•
24	30/08/19 09:56	General View	0	Load JPG	•
25	30/08/19 09:56	General View	0	Load JPG	•
26	30/08/19 09:56	General View	0	Load JPG	•
27	30/08/19 09:56	General View	0	Load JPG	•
28	30/08/19 09:56	General View	0	Load JPG	•
29	30/08/19 09:56	General View	0	Load JPG	•
30	30/08/19 09:56	General View	0		
31	30/08/19 09:56	General View	0	Load JPG	•
32	2000-00-00-00-00-00-00-00-00-00-00-00-00			Load JPG	-
D. Sec.	30/08/19 09:56	General View	0	Load JPG	€
33	30/08/19 09:56	General View	0	Load JPG	•
34	30/08/19 09:56	General View	0	Load JPG	•
35	30/08/19 09:56	General View	0	Load JPG	•
36	30/08/19 09:56	General View	0	Load JPG	•
37	30/08/19 09:56	General View	0	Load JPG	•
38	30/08/19 09:56	General View	0	Load JPG	•
39	30/08/19 09:56	General View	0	Load JPG	8
40	30/08/19 09:56	General View	0	Load JPG	€
41	30/08/19 09:56	General View	0	Load JPG	•
42	30/08/19 09:56	General View	0	Load JPG	•
43	30/08/19 09:56	General View	0	Load JPG	•
44	30/08/19 09:56	General View	0	Load JPG	•
45	30/08/19 09:56	General View	0	Load JPG	•
46	30/08/19 09:56	General View	0	Load JPG	•
47	30/08/19 09:56	General View	0	Load JPG	2
48	30/08/19 09:56	General View	0	Load JPG	•
49	30/08/19 09:56	General View	0	Load JPG	•
50	30/08/19 09:56	General View	0	Load JPG	4
51	30/08/19 09:56	General View	0	Load JPG	•
52	30/08/19 09:56	General View	0	Load JPG	•
53	30/08/19 09:56	General View	0	Load JPG	•
54	30/08/19 09:56	General View	0	Load JPG	•
55	30/08/19 09:56	General View	0	Load JPG	•
56	30/08/19 09:56	General View	0	Load JPG	•
57	30/08/19 09:56	General View	0	Load JPG	•
58	30/08/19 09:56	General View	0	Load JPG	2
59	30/08/19 09:56	General View	0	200000000000000000000000000000000000000	2
200		General View		Load JPG	-
60	30/08/19 09:56	250/ACCUSENTIONEN/II	0	Load JPG	2
61	30/08/19 09:56	General View General View	0	Load JPG	•
			0	Load JPG	-
63	30/08/19 09:56	General View	0	Load JPG	2
64	30/08/19 09:56	General View	0	Load JPG	•

A551	essment Reports		1 per		2
No	Finalized On	National Assessment Centre Services (Ubi)	-	Thumbnail	-
56	30/08/19 09:56	General View	0	Load JPG	~
57	30/08/19 09:56	General View	0	Load JPG	2
8	30/08/19 09:56	General View	0	Load JPG	
9	30/08/19 09:56	General View	0	Load JPG	
70	30/08/19 09:56	General View	0	Load JPG	
1	30/08/19 09:56	General View	0	Load JPG	1
72	30/08/19 09:56	General View	0	Load JPG	9
'3	30/08/19 09:56	General View	0	Load JPG	8
4	30/08/19 09:56	General View	0	Load JPG	8
5	30/08/19 09:56	General View	0	Load JPG	8
6	30/08/19 09:56	General View	0	Load JPG	8
7	30/08/19 09:56	General View	0	Load JPG	6
78	30/08/19 09:56	General View	0	Load JPG	8
9	30/08/19 09:56	General View	0	Load JPG	8
30	30/08/19 09:56	General View	0	Load JPG	8
31	30/08/19 09:56	General View	0	Load JPG	6
2	30/08/19 09:56	General View	0	Load JPG	8
		General View	0		1 6
33	30/08/19 09:56	General View	0	Load JPG	8
400	30/08/19 09:56	MANUAL CONTROL OF THE PARTY OF		Load JPG	+
35	30/08/19 09:56	General View	0	Load JPG	1 6
36 37	30/08/19 09:56	General View General View	0	Load JPG	6
200	30/08/19 09:56		1100	Load JPG	1
38	30/08/19 09:56	General View	0	Load JPG	- 6
39	30/08/19 09:56	General View	0	Load JPG	1
90	30/08/19 09:56	General View	0	Load JPG	1
91	30/08/19 09:56	General View	0	Load JPG	1
92	30/08/19 09:56	General View	0	Load JPG	1
93	30/08/19 09:56	General View	0	Load JPG	1
94	30/08/19 09:56	General View	0	Load JPG	1
95	30/08/19 09:56	General View	0	Load JPG	1
96	30/08/19 09:56	General View	0	Load JPG	1
97	30/08/19 09:56	General View	0	Load JPG	1
98	30/08/19 09:56	General View	0	Load JPG	1
99	30/08/19 09:56	General View	0	Load JPG	1
100	30/08/19 09:56	General View	0	Load JPG	
101	30/08/19 09:56	General View	0	Load JPG	
102	30/08/19 09:56	General View	0	Load JPG	1
103	30/08/19 09:56	General View	0	Load JPG	
104	30/08/19 09:56	General View	0	Load JPG	
105	30/08/19 09:56	General View	0	Load JPG	
106	30/08/19 09:56	General View	0	Load JPG	1
107	30/08/19 09:56	General View	0	Load JPG	1
108	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	
109	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	
110	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	1
111	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	1
112	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	
113		Photographs of Damaged Parts	0	Load JPG	
114		Photographs of Damaged Parts	0	Load JPG	t
115		Photographs of Damaged Parts Photographs of Damaged Parts	0	Load JPG	1 3
. 6		Photographs of Damaged Parts	0		
116			0	Load JPG	1
117	30/08/19 09:58	Photographs of Damaged Parts	- 0	Load JPG	1

	essment Reports		1 per		•
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	-
119	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	₹
120	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	2
121	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	•
122	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	•
123	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	•
124	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	•
125	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	•
126	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	1
127	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	•
128	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	•
129	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	•
20000	Enghanden angerenger		0	CONTRACTOR OF C	•
130	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	-
131	30/08/19 09:58	Photographs of Damaged Parts		Load JPG	8
132	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	2
133	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	•
134	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	2
135	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	•
136	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	•
137	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	•
138	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	•
139	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	•
140	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	•
141	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	•
142	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	2
143	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	•
144	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	•
145	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	•
146	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	•
147	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	•
148	The section of the se	Photographs of Damaged Parts	0	Load JPG	•
149		Photographs of Damaged Parts	0	Load JPG	2
			0		+
150		Photographs of Damaged Parts		Load JPG	2
151	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	2
152		Photographs of Damaged Parts	0	Load JPG	(4)
153		Photographs of Damaged Parts	0	Load JPG	Ø
154	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	€
155		Photographs of Damaged Parts	0	Load JPG	2
156	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	8
157	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	•
158	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	•
159	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	•
160	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	•
161	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	•
162	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	•
163	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	•
164	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	•
165	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	•
166	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	•
167	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	•
168		Photographs of Damaged Parts	0	Load JPG	•
169		Photographs of Damaged Parts	0	Load JPG	•
170		Photographs of Damaged Parts	0	Load JPG	2
-,0	30,00,13 03.30	, notagraphs or buildaged raits	9	LUGU JPG	1

	ssment Reports		1 per		•
No	Finalized On	National Assessment Centre Services (Ubi)	-	Thumbnail	+
172	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	•
173	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	9
174	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	•
175	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	•
176	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	•
177	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	•
178	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	•
179	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	•
180	30/08/19 09:58	Photographs of Damaged Parts	0	Load JPG	•
Contract of	0.5100 0.0100 0.0100 0.000		0	Load JPG	•
181	30/08/19 09:59	Photographs of Damaged Parts	0		•
182	30/08/19 09:59	Photographs of Damaged Parts		Load JPG	•
183	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	-
184	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	•
185	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	•
186	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	•
187	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	•
188	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	•
189	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	•
190	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	9
191	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	•
192	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	•
193	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	•
194	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	~
195	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	•
196	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	
197	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	•
	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	2
198			0	Load JPG	•
199	30/08/19 09:59	Photographs of Damaged Parts	0	10.000000000000000000000000000000000000	€
200	30/08/19 09:59	Photographs of Damaged Parts		Load JPG	2
201	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	-
202	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	•
203	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	2
204	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	•
205	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	•
206	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	~
207	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	•
208	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	4
209	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	•
210	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	•
211	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	•
212	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	~
213	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	•
214	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	•
215	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	•
216	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	•
217	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	•
218	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	2
219	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	•
		Photographs of Damaged Parts Photographs of Damaged Parts	0	Load JPG	•
220	30/08/19 09:59	2 Control of the Cont	0	Load JPG	2
221	30/08/19 09:59	Photographs of Damaged Parts			-
222	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	•
223	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	•

sse	ssment Reports		1 per page	•	2
o	Finalized On	National Assessment Centre Services (Ubi)	Thumb		_
25	30/08/19 09:59	Photographs of Damaged Parts	① Load :	PG	•
26	30/08/19 09:59	Photographs of Damaged Parts	① Load:	PG	•
27	30/08/19 09:59	Photographs of Damaged Parts	1 Load	PG	•
28	30/08/19 09:59	Photographs of Damaged Parts	1 Load	PG	
29	30/08/19 09:59	Photographs of Damaged Parts	① Load:	PG	•
30	30/08/19 09:59	Photographs of Damaged Parts	1 Load :	PG	
31	30/08/19 09:59	Photographs of Damaged Parts	₫ Load	PG	
32	30/08/19 09:59	Photographs of Damaged Parts	1 Load	IPG	
33	30/08/19 09:59	Photographs of Damaged Parts	① Load	IPG	8
34	30/08/19 09:59	Photographs of Damaged Parts	€ Load	JPG	
35	30/08/19 09:59	Photographs of Damaged Parts	① Load	JPG	6
36	30/08/19 09:59	Photographs of Damaged Parts	● Load	IPG	6
37	30/08/19 09:59	Photographs of Damaged Parts	₫ Load	JPG	8
38	30/08/19 09:59	Photographs of Damaged Parts	① Load	JPG	6
39	30/08/19 09:59	Photographs of Damaged Parts	① Load	JPG	8
40	30/08/19 09:59	Photographs of Damaged Parts	1 Load	JPG	6
41	30/08/19 09:59	Photographs of Damaged Parts	① Load	JPG	6
42	30/08/19 09:59	Photographs of Damaged Parts	1 Load	JPG	8
43	30/08/19 09:59	Photographs of Damaged Parts	1 Load	JPG	6
44	30/08/19 09:59	Photographs of Damaged Parts	1 Load	JPG	8
45	30/08/19 09:59	Photographs of Damaged Parts	① Load	JPG	6
46	30/08/19 09:59	Photographs of Damaged Parts	① Load	JPG	8
47	30/08/19 09:59	Photographs of Damaged Parts	① Load	JPG	
48	30/08/19 09:59	Photographs of Damaged Parts	① Load	JPG	-
49	30/08/19 09:59	Photographs of Damaged Parts	① Load	JPG	
50	30/08/19 09:59	Photographs of Damaged Parts	① Load	JPG	1
51	30/08/19 09:59	Photographs of Damaged Parts	① Load	JPG	1
52	30/08/19 09:59	Photographs of Damaged Parts	① Load	JPG	1
53	30/08/19 09:59	Photographs of Damaged Parts	① Load	JPG	1 8
54	30/08/19 09:59	Photographs of Damaged Parts	① Load	JPG	1
55	30/08/19 09:59	Photographs of Damaged Parts	1 Load	JPG	
56	30/08/19 09:59	Photographs of Damaged Parts	① Load	JPG	1
57	30/08/19 09:59	Photographs of Damaged Parts	① Load	JPG	T
58	30/08/19 09:59	Photographs of Damaged Parts	① Load	JPG	1
59	30/08/19 09:59	Photographs of Damaged Parts	① Load	JPG	T
60	30/08/19 09:59	Photographs of Damaged Parts	① Load	JPG	
61	30/08/19 09:59	Photographs of Damaged Parts	① Load	JPG	
62	30/08/19 09:59	Photographs of Damaged Parts	① Load	JPG	
63	30/08/19 09:59	Photographs of Damaged Parts	① Load	JPG	
64	30/08/19 09:59	Photographs of Damaged Parts	① Load	2000	T
65	30/08/19 09:59	Photographs of Damaged Parts	● Load		1
66	30/08/19 09:59	Photographs of Damaged Parts	6 Load		ti
67	30/08/19 09:59	Photographs of Damaged Parts	1 Load		
68	30/08/19 09:59	Photographs of Damaged Parts	1 Load	130130	
69	30/08/19 09:59	Photographs of Damaged Parts	₫ Load		
70	30/08/19 09:59	Photographs of Damaged Parts	1 Load		
71	30/08/19 09:59	Photographs of Damaged Parts	6 Load	0.00000	T
72	30/08/19 09:59	Photographs of Damaged Parts	O Load	A SCHOOL	+
73		Photographs of Damaged Parts	O Load		+
74	30/08/19 09:59	Photographs of Damaged Parts Photographs of Damaged Parts	O Load		+
75	30/08/19 09:59	Photographs of Damaged Parts	O Load		
76	30/08/19 09:59	Photographs of Damaged Parts Photographs of Damaged Parts	O Load		-
,,0	30/08/19 09:59	Photographs of Damaged Parts Photographs of Damaged Parts	O Load	10000	H

Asse	ssment Reports		1 per		2
Vo	Finalized On	National Assessment Centre Services (Ubi)	Α.	Thumbnail	_
78	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	•
79	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	
80	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	4
81	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	
82	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	
83	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	
84	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	6
85	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	6
86	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	8
87	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	6
-	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	6
88			0	Load JPG	8
89	30/08/19 09:59	Photographs of Damaged Parts	0		6
90	30/08/19 09:59	Photographs of Damaged Parts	S - S	Load JPG	8
91	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	-
92	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	1
93	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	1
94	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	1
95	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	1
96	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	
97	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	
98	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	
99	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	
00	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	
01	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	T
11.0	To action with the second	Photographs of Damaged Parts	0	Load JPG	t
02	30/08/19 09:59		0	Load JPG	t
303	30/08/19 09:59	Photographs of Damaged Parts	0	75-10-10-50-50-5	H
04	30/08/19 09:59	Photographs of Damaged Parts		Load JPG	-
805	30/08/19 09:59	Photographs of Damaged Parts	0	Load JPG	
306	11/09/19 17:06	After Repair Photo	0	Load JPG	
307	11/09/19 17:06	After Repair Photo	0	Load JPG	L
808	11/09/19 17:06	After Repair Photo	0	Load JPG	
309	11/09/19 17:06	After Repair Photo	0	Load JPG	
310	11/09/19 17:06	After Repair Photo	0	Load JPG	
311	11/09/19 17:06	After Repair Photo	0	Load JPG	
312	11/09/19 17:06	After Repair Photo	0	Load JPG	
313	11/09/19 17:06	After Repair Photo	0	Load JPG	
14	11/09/19 17:07	After Repair Photo	0	Load JPG	П
315	11/09/19 17:07	After Repair Photo	0	Load JPG	Е
316	11/09/19 17:07	After Repair Photo	0	Load JPG	
17	11/09/19 17:07	After Repair Photo	0	Load JPG	
318		After Repair Photo	0	Load JPG	T
319		After Repair Photo	0	Load JPG	T
2015	1000 0000000000000000000000000000000000	A TURNS SERVICE CONTRACTOR WITHOUT	0	Load JPG	
320		After Repair Photo	0	1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	+
321		After Repair Photo	0	Load JPG	-
22		After Repair Photo		Load JPG	+
23		After Repair Photo	0	Load JPG	+
324	11/09/19 17:07	After Repair Photo	0	Load JPG	+
325	11/09/19 17:07	After Repair Photo	0	Load JPG	1
326	11/09/19 17:07	After Repair Photo	0	Load JPG	1
327	11/09/19 17:07	After Repair Photo	0	Load JPG	
328	11/09/19 17:07	After Repair Photo	0	Load JPG	
329	11/09/19 17:07	After Repair Photo	0	Load JPG	
330	11/09/19 17:07	After Repair Photo	0	Load JPG	

Assessment Reports		1 per	1 per page ▼		
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
331	11/09/19 17:07	After Repair Photo	0	Load JPG	•
332	11/09/19 17:07	After Repair Photo	0	Load JPG	•
333	11/09/19 17:07	After Repair Photo	0	Load JPG	•
334	11/09/19 17:07	After Repair Photo	0	Load JPG	
335	11/09/19 17:07	After Repair Photo	0	Load JPG	•
336	11/09/19 17:07	After Repair Photo	0	Load JPG	•
337	11/09/19 17:07	After Repair Photo	0	Load JPG	•
338	11/09/19 17:07	After Repair Photo	0	Load JPG	•
339	11/09/19 17:07	After Repair Photo	0	Load JPG	•
340	11/09/19 17:07	After Repair Photo	0	Load JPG	•
341	11/09/19 17:07	After Repair Photo	0	Load JPG	•
342	11/09/19 17:07	After Repair Photo	0	Load JPG	•
343	11/09/19 17:07	After Repair Photo	0	Load JPG	•
344	11/09/19 17:07	After Repair Photo	0	Load JPG	•
345	11/09/19 17:07	After Repair Photo	0	Load JPG	•
Doc	umentation		1 per	page ▼	•
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	16/08/19 14:44	Accident Sketch Plan [Linked Accident Report Documents]	0	Load JPG	•
2	16/08/19 14:44	Accident Sketch Plan [Linked Accident Report Documents]	0	Load JPG	•
3	16/08/19 14:44	Police Report [Linked Accident Report Documents]	0	Load JPG	•
4	16/08/19 14:44	Police Report [Unked Accident Report Documents]	0	Load JPG	•
5	16/08/19 14:44	Police Report [Unked Accident Report Documents]	0	Load JPG	•
6	16/08/19 14:44	Police Report [Linked Accident Report Documents]	0	Load JPG	•

Linked Accident Report Documents

			View	View in Brow	vser ▼
Ass	Assessment Reports		1 per	page 🔻	•
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	16/08/19 14:46	Accident Statement	0	Load HTM	
Pho	tos/Images		3 per	page ▼	•
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	16/08/19 14:43	Accident Photo	0	Load JPG	•
2	16/08/19 14:43	Accident Photo	0	Load JPG	•
3	16/08/19 14:43	Accident Photo	0	Load JPG	•
4	16/08/19 14:43	Accident Photo	0	Load JPG	•
5	16/08/19 14:43	Accident Photo	0	Load JPG	•
6	16/08/19 14:43	Accident Photo	0	Load JPG	•
7	16/08/19 14:43	Accident Photo	0	Load JPG	•
8	16/08/19 14:43	Accident Photo	0	Load JPG	•
9	16/08/19 14:43	Accident Photo	0	Load JPG	•
10	16/08/19 14:43	Accident Photo	0	Load JPG	•
11	16/08/19 14:43	Accident Photo	0	Load JPG	•
12	16/08/19 14:43	Accident Photo	0	Load JPG	•
13	16/08/19 14:43	Accident Photo	0	Load JPG	•
14	16/08/19 14:43	Accident Photo	0	Load JPG	✓
15	16/08/19 14:43	Accident Photo	0	Load JPG	•
16	16/08/19 14:43	Accident Photo	0	Load JPG	•
17	16/08/19 14:43	Accident Photo	0	Load JPG	•
18	16/08/19 14:43	Accident Photo	0	Load JPG	•

Assessment Reports		1 per	page 🔻		
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
Documentation		1 per	1 per page ▼		
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	16/08/19 14:44	Accident Sketch Plan	0	Load JPG	•
2	16/08/19 14:44	Accident Sketch Plan	0	Load JPG	V
3	16/08/19 14:44	Police Report	0	Load JPG	•
4	16/08/19 14:44	Police Report	0	Load JPG	•
5	16/08/19 14:44	Police Report	0	Load JPG	•
6	16/08/19 14:44	Police Report	0	Load JPG	•

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured,	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/CTI19014828/HCF3S2

Date:

12/09/2019

REFERENCE

Handling Insurer:

China Taiping Insurance (Singapore) Pte. Ltd.

Policy No:

DMB1SN30386519000

Claimant Vehicle

Insured Vehicle

No:

SLG3442J

No:

PC2184J

TP

Date of Loss:

15/08/2019

Nature of Claim:

Claim

No:

SNM19D203820C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SLG3442J

Make & Model:

TOYOTA COROLLA, 1.5 AXIO (A) 28/09/2016 (Man. Year: 2016)

Engine No: Chassis No: 2NR8642825 NRE1610019371

Reg. Date: Colour:

Black

Odometer:

215718 km

Engine Capacity:

1496 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Fair

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Engine Modification: Yes

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

185/60 R15

Rear Tyre Size:

185/60 R15

Front Left Side:

Firenza 5 mm

Rear Left Side:

Firenza 5 mm

Front Right Side:

Firenza 5 mm

Rear Right Side:

Firenza 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0,00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:

28/08/2019

Neo Automotive (HQ)

Date Inspected:

23/08/2019 Inspected At:

53 UBI AVE 1 #05-44 PAYA UBI INDUSTRIAL

PARK SINGAPORE

Singapore 408934

Estimated Period of Repair:

9.0 days

LEE HOCK ANN Adjuster:

Manager:

CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$9,000.00 - \$10,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Sep 2019)

Parts: 143 TOYOTA COROLLA 1.5 AXIO (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLG3442J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >