



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

Alh d Jick

Not Authorized

28 August 2019

ACCIDENT DATE : 21 Aug 2019
OWNER : YONG WEN GIN LEONARD
REG NO. : SLX 4580 Y
MAKE/MODEL : KIA CERATO

2/s \$7000/ body.

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEMS</u>	
1	Rear windscreen moulding	\$ 111 98.60 X
1	Rear boot lid	\$ 7793.80
2	Rear boot lock sensor	\$ 250.00
2	Rear boot lamps	\$ 373.00
1	Rear boot inner lock	\$ 126.50
1	Rear boot rubber	\$ 128.60
1	Rear boot "KIA" emblem	\$ 52.50
1	Rear boot "CERATO" emblem	\$ 42.50
1	Rear boot "K3" emblem	\$ 45.00
1	Rear boot "C&C" emblem	\$ 45.60
2	Rear taillamps	\$ 975.20
1	Rear end panel	\$ 598.50
1	Rear end panel inner garnish	\$ 152.50
1	Rear bumper	\$ 658.00
1	Rear bumper lower garnish	\$ 145.50
2	Rear bumper reflectors	\$ 136.00
1	Rear bumper reinforcement	\$ 356.00
2	Rear bumper reinforcement stays	\$ 305.00 X
3	Rear bumper reinforcement brackets	\$ 68.70
2	Rear bumper side retainers	\$ 77.00 X
4	Rear bumper PDC sensors	\$ 746.00 2pcs
1	Rear bumper lower tray garnish	\$ 198.50
2	Rear fenders	\$ 1,779.20 X
1	Rear fender inner trim	\$ 117.20
1	Rear floor board	\$ 280.50 X
1	Rear floor panel	\$ 885.00 X
1	Rear exhaust silencer	\$ 726.50
2	Rear exhaust mountings	\$ 87.00 X
1	Rear exhaust chrome tail pipe	\$ 115.00
		\$ 10,363.40
	Less 10%	\$ 1,036.34
		\$ 9,327.06

6475.1

<u>SPECIAL NETT ITEMS</u>	
1	Rear windscreen sealant
1	Rear bumper clip (1 set)
1	Rear bumper lower spoiler
1	Rear number plate with holder

\$	11	80.00	X
\$	11	50.00	40
\$	11	750.00	600
\$	11	50.00	X
\$		930.00	

<u>S/N</u>	<u>LABOUR CHARGES</u>
1	To remove, replaced damaged lamps and check up rear wiring.
2	To remove and refit inner garnishes.
3	To remove and refit rear reverse sensor.
4	To transfer boot lid mechanism and wiring assembly.
5	To remove and refit rear windscreen glass.
6	To remove, refit and replace exhaust silencer and mountings.
7	To apply undercoating.
8	Panel beating.
9	To re-spray painting on the affected areas.

\$	80.00	30
\$	150.00	80
\$	150.00	50
\$	120.00	60
\$	11	180.00
\$	150.00	60
\$	200.00	60
\$	1,800.00	800
\$	1,800.00	200
\$	4,630.00	

GRAND TOTAL :

\$ 14,887.06

880 7.59

Exhibit to Consultants hence notify the Repairer of the following:

- To resurvey before re-spray painting
- To resurvey damaged part(s) during resurvey
- All items are subject to confirmation
- The resurvey is on a "Without Prejudice" basis
- No modification(s) is allowed
- Supplementary item(s) must be resurveyed and
- is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: