

ASS. REC. BY:

REF: CS/SMD 19014839/krf322

Special Instruction:

SURVIVOR

Kenneth

ASSIGNMENT (Office)

From (Person):

Ng Chun How

of

SMD

Date/Time:

23.8.19 10.10 a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKT 9339D

Insured:

at Workshop m/s

Lai Huat

Tel:

64538110

of 160 Sin Ming Drive #4-01

Policy No:

D18 MTPV 01015284

Claim No:

CMTD1903932

Sum Insured:

Excess:

0

Make of Veh:

(Client's Record)

D.O.A.

18.8.2019

CA / REV

REP. / REV 24 HRS

mv: \$90K

H.O.D. Endorsement:

Date/Time:

23.8.19 11.13 a.m

Person Contacted:

Jenny

Vehicle:

IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKT 9339D - CS/SMD 19014839/ RKF322 RCL 19/08/2019
23/8/19	Revert via merimen
26/8/19	Recd approved \$5355.35 from Agnes by merimen
26/8/19	Informed Jenny c/A Ex 0 by email
31/8/19	@403pm Jenny will email us finalise

ASS. REC. BY:

REF:

S/MO/CS/SMO/90/4834/Kv43

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 File pass to

30/9 85191-35 Custom (Red 504, 91%)

RECEIVED 1 OCT 2019

Date/Time, File Pass to?

☐

: Prel. Report

11

☐

: Final Report

Date/Time, File Return to?

21

1/10 - typst

Report Format:

Lump Sum / I.B.I. (\$) 519635

menmen

519635

Days Of Repair:

5

Resurvey No. of Trlp:

2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Fees

Others

TOTAL

280
11
261

Veh No:

SKT9339D

Yr Regn:

10, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Toy Home

c.c

1986

Colour:

M.P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

133164

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

ESU60

0050845

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235/55R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

18/8/19

D.O.I.

23/8/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Aug 2019 Sendback Est	23 Aug 2019 10:34 \$45,505.35	23 Aug 2019 10:41 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	TAN WOON SZU, ID: S1624025G								
Vehicle Reg. No.:	SKT9339D	Date of Loss:	18/08/2019 15:00 - :59 [46 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / CMTD1903932	Policy/Cover Note No.:	D18MTPV01015284 (Comprehensive)						
	Excess:								
Repairer:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/09/2019]								
Driver/Custodian:	ANG WOON CHOO (S1 / Female), NRIC: S1796044Z, Tel: +6586138249 Email: eveangwc@yahoo.com								
Adj Asp. Remarks:	Nivitha, pls assist to arr suv today (asap)								
ASSOCIATED MAIL RECEIVED									
View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 26 August 2019 12:27 PM
To: Jenny Lim ; SUR
Subject: SKT 9339D-DOA: 18/8/2019 (SOMPO OD)

Dear Jenny,

As instructed by our client , please proceed to repair the **insured vehicle SKT 9339D (Excess \$0-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

SKT9339D (CMTD1903932)

OD

Aug 18 2019 3:00PM

[TAN WOON SZU]

Lai Huat (Meng Kee) Motor Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From Sompo Insurance Singapore Pte. Ltd. (SOMPO_SG), sent on 26/08/2019 12:15 PM,

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$5355.35) - SKT9339D - Claim Handler: CHAN SHU HUI AGNES

Approved:5355.35.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: CHAN SHU HUI AGNES

Date: 23 Aug 2019

Preliminary Advice

Vehicle No	: SKT9339D	Accident Date	: 18/08/2019
Make	: TOYOTA HARRIER	Policy No.	: D18MTPV01015284
Assignment Date	: 23/08/2019	Excess	: S\$0.00
Date of Inspection	: 23/08/2019	Est. Duration of Repair	: 5.00
Inspection At	: LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING) 160 SIN MING DRIVE #04-01, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,505.35
Revised Amount	:S\$	4,816.55
Check Items (Estimated)	:S\$	538.80
Total	:S\$	5,355.35

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	90,000.00
COE / PARF Rebate	:S\$	56,009.00
Salvage Value	:S\$	
Margin for Repair	:S\$	33,991.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments : KINDLY ADVISED POLICY EXCESS

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	025G
Vehicle Details	
Vehicle No.:	SKT9339D
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Aug 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER 2.0 PREMIUM
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	3ZRB600196
Chassis No.:	ZSU600050845
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$28,613.00
Original Registration Date:	14 Oct 2015
First Registration Date:	14 Oct 2015
Transfer Count:	0
Actual ARF Paid:	\$27,059.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Oct 2025
PARF Rebate Amount:	\$20,294.00
Intended COE Rebate Details	
COE Expiry Date:	13 Oct 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$58,190.00
COE Rebate Amount:	\$35,715.00
Total Rebate Amount:	\$56,009.00

The information contained herein is correct as at 23 Aug 2019

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 025G

Vehicle Details

Vehicle No.: SKT9339D
Vehicle to be Exported: Yes
Intended Deregistration Date: 21 Aug 2019
Vehicle Make: TOYOTA
Vehicle Model: HARRIER 2.0 PREMIUM
Primary Colour: White
Manufacturing Year: 2015
Engine No.: 3ZRB600196
Chassis No.: ZSU600050845
Maximum Power Output: 111.0 kW (148 bhp)
Open Market Value: \$28,613.00
Original Registration Date: 14 Oct 2015
First Registration Date: 14 Oct 2015
Transfer Count: 0
Actual ARF Paid: \$27,059.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 13 Oct 2025
PARF Rebate Amount: \$20,294.00

Intended COE Rebate Details

COE Expiry Date: 13 Oct 2025
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$58,190.00
COE Rebate Amount: \$35,747.00
Total Rebate Amount: \$56,041.00

The information contained herein is correct as at 21 Aug 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/08/2019 18:17
Date Of Accident	18/08/2019 15:10
Exact Location Of Accident	PIE TOWARDS CHANGI BEFORE EXIT 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKT9339D
Insured/Policyholder	
Name Of Registered Owner	TAN WOON SZU
NRIC No	S1624025G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98532811
Alternative Phone No	OFFICE-98532811

Vehicle Particulars

Manufacturer	TOYOTA
Model	HARRIER 2.0 PREMIUM
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES

If No, Please state action to be taken.

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPV01015284
Cover Note Number	

Driver

Name of Driver	ANG WOON CHOO
NRIC No	S1796044Z
Date Of Birth	14/10/1967
Occupation	INDOOR
Date Of Driving Pass	02/07/1992
Driving Experience	27 YEARS AND 1 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-86138249
Fax Number	
Contact Number	
Email Address	EVEANGWC@YAHOO.COM

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS DRIVING ALONG PIE TOWARDS CHANGI . VEHICLE B WAS DRIVING AT MY LEFT LANE . SUDDENLY VEHICLE B CUT INTO MY LANE WITHOUT SIGNAL . I CAN'T STOP IN TIME AND COLLIDED ONTO REAR OF VEHICLE B . NO INJURIES INVOLVED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGJ8021B
Vehicle Make/Model/Colour	TOYOTA / COROLLA ALTIS 1.6 AUTO
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TEO
NRIC/Passport Number	
Contact Number	90220544
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Sketch Plan

TENTH

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Consent under the Personal Data Protection Act (PDPA)

- I understand, acknowledge, agree and consent that:
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


VERIFIED BY AJAX MARS
REPORTING OFFICER
JUN KEAT

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

I WAS DRIVING ALONG PIE TOWARDS CHANGI . VEHICLE B WAS DRIVING AT MY LEFT LANE . SUDDENLY VEHICLE B CUT INTO MY LANE WITHOUT SIGNAL . I CAN'T STOP IN TIME AND COLLIDED ONTO REAR OF VEHICLE B . NO INJURIES INVOLVED.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
WONG JUN KEAT

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

18 August 2019 at 5:58 PM

Date/Time:

18 August 2019 at 5:58 PM



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
 6 Raffles Quay #18-00 Singapore 048580
 Tel (65) 6224 0030 Fax (65) 6224 0030
 Operating Hours : Monday to Friday, 09:00 – 17:00
 UEN: S6550020G / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MBHH19108023-01 Vehicle Registration No: SKT9339D
 Name (as shown in NRIC) : ANG WOON CHOO NRIC/FIN/Passport No : S1796044Z
 (*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
 Address : _____ Singapore()
 Contact (Tel) : _____ Mobile No. : 86138249
 Email Address : EVEANGWC@YAHOO.COM
 Date of Accident : 18/08/2019 Time of Accident : 15:10
 Place of Accident : PIE TOWARDS CHANGI BEFORE EXIT 1
 Insurance Company: SOMPO INSURANCE SINGAPORE PTE. LTD.

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

AMEND TO OWN DAMAGE CLAIM

 Policyholder / Driver's Signature
 Date:

Shirley Loo
 Reporting Centre Personnel's Signature
 Name: Shirley Loo
 NRIC/FIN No.: _____
 Date: 23 AUGUST 2019

Certificate of Insurance**MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)**

Cert No./Policy No. : D18MTPV01015284
Insured : TAN WOON SZU
Motor Car (Registration No.) : SKT9339D
Cover : Comprehensive - ExcelDrive GOLD
Policy Commencement Date : 14 OCTOBER 2018 00:00
Policy Expiry Date : 13 OCTOBER 2019 23:59
Maximum Liability (Section I) : Market value at time of loss
Excess* : \$600 - Section I
(Waived up to \$51,000 if accident repair is done at ExcelDrive Workshops for the first claim per policy year)
Voluntary Excess* : N.A.
Windscreen Excess* : \$5100.00 - Waived if Repair at ExcelDrive Workshop
Loss of Use : Per Policy Schedule

* Subject to GST wherever applicable

Persons or Classes of Persons entitled to drive*

1. The Insured.
2. Any other person who is driving on the Insured's order or with his permission.
3. In the event of the death of the insured:
 - a. any member of the insured's family, or a paid driver who has been driving the Motor Car during the life of the insured and permission to drive had not been withdrawn prior to the death of the insured; and
 - b. any other person who has been given permission to drive the Motor Car prior to the death and such permission had not been withdrawn by the Insured.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Car or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Car. And provided further that the Motor Car is registered under the Road Traffic Act (Chapter 276) and its registration under the Road Traffic Act (Chapter 276) has not been cancelled at the time of the accident, loss or damage.

Limitations As To Use

Use only for social, domestic and pleasure purpose and for the Insured's business. The Policy does not cover use for hire or reward, racing, pace-making, speed testing, reliability trial, the carriage of goods other than samples in connection with any trade or business or use for any purposes in connection with the Motor Trade.


ExcelDrive Workshops and Accident Reporting

It is a condition precedent to liability that the Insured shall call at the Company's Accident Reporting Center with the Motor Car within 24 hours of the accident or by the next working day thereof.

All accident repairs to the Motor Car must be carried out at ExcelDrive Workshops, otherwise the claim is not payable under the Policy. For ExcelDrive-Prestige Plan, accident repairs to the Motor Car can be carried out at any workshop other than ExcelDrive Workshops.

For the list of Accident Reporting Centres and ExcelDrive Workshops, please visit our website at www.sompo.com.sg or call our Emergency Hotline: (65) 6226 3323.

I/We HEREBY CERTIFY that the policy in which this Certificate relates is issued in accordance with (1) the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia); and (2) the Policy terms, conditions and exceptions of the Private Car Policy ref MTP 27.

Sompo Insurance Singapore Pte. Ltd.**Authorised Signatory****Date/Time of Issue** : 04 SEPTEMBER 2018 17:47**IMPORTANT NOTICE**

- o Keep the Certificate in your Motor Car.
- o Under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189), it shall be unlawful for any person to use or cause to permit any other person to use a motor vehicle without a valid policy of insurance under the Act.
- o On the sale of the Motor Car or if for any reason the insurance is terminated during its currency, the Insured must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a statutory declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).
- o This Policy will cease to be valid once the Motor Car has been sold to another person. The Policy is not transferable to the new owner of the Motor Car.

來發(明記)摩多有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sin Ming Autocity
160 Sin Ming Drive #04-01/#04-02/#07-03 Singapore 575722
Tel: 64538110 Fax: 64596267 Email: info@laihuat.com.sg
UEN: 199407592C

INSURER: Sompoo Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	70794
Policy No:	D18MTPV01015284	Date of Loss:	18/08/2019
Vehicle Reg. No.:	SKT9339D	Driveable?	
Driver Age/Info:	51 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TAN WOON SZU		
Driver:	ANG WOON CHOO		

Make/Model:	TOYOTA HARRIER, 2.0 Premium (A)	Vehicle Reg. Date:	14/10/2015
Vehicle Colour:	White		
Engine No:	3ZRB600196	Chassis No:	ZSU600050845
Odometer:	133164 KM		

Paint Type: *Not Autherized*
 Total Loss? *NO*
 Est. Duration of Repair (day) *8 5 days* *Repair B4 paint*
Excess? *fax: 62564315*

Description of Accident/Loss: I WAS DRIVING ALONG PIE TOWARDS CHANGI. VEHICLE B WAS DRIVING AT MY LEFT LANE. SUDDENLY VEHICLE B CUT INTO MY LANE WITHOUT SIGNAL. I CAN'T STOP IN TIME AND COLLIDED ONTO REAR OF VEHICLE B. NO INJURIES INVOLVED.

Present Location: LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING)

COST OF CLAIMS		Amount
Parts		3,870.35
Miscellaneous Items		235.00
Labour		550.00
Paintwork Labour		850.00
Towing		0.00
	Gross Total (S\$)	5,505.35
	+ GST 7.00% (S\$)	385.37
	Nett Amount (S\$)	5,890.72

This claim is handled by: JENNY LIM LAI FOONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Aug 2019)
Parts: M1-SUV TOYOTA HARRIER 2.0 Premium (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Lai Huat (Meng Kee) Motor Pte Ltd/SKT9339D/23/08/2019 10:34
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*Front radiator top cover	0.00	0.00	*120.00 F	✓
2	6		*Front radiator top cover clips	0.00	0.00	*6.00 F	✓
3	1		*Front bumper	0.00	0.00	*450.00 F	✓
4	1		*Front bumper lower centre grille	0.00	0.00	*90.00 F	✓
5	1		*Front bumper lower grille	0.00	0.00	*110.00 F	✓
6	1		*Radiator grille	0.00	0.00	*195.00 F	✓
7	6		*Radiator grille clips	0.00	0.00	*9.00 F	✓
8	1		*Front headlamp LH	0.00	0.00	*950.00 F	✓
9	1		*Front headlamp RH	0.00	0.00	*950.00 F	✓
10	1		*Front bumper centre beam	0.00	0.00	*90.00 F	✓
11	1		*Front bumper beam LH	0.00	0.00	*50.00 F	✓
12	1		*Front bumper beam RH	0.00	0.00	*50.00 F	✓
13	1		*Front bumper inner retainer LH	0.00	0.00	*25.00 F	✓
14	1		*Front bumper inner retainer RH	0.00	0.00	*25.00 F	✓
15	1		*Front bumper outer retainer RH	0.00	0.00	*38.00 F	✓
16	1		*Front fender RH	0.00	0.00	*270.00 F	✓
17	6		*Front fender inner shield clips RH - 1	0.00	0.00	*6.00 F	✓
18	3		*Front fender inner shield clips RH - 2	0.00	0.00	*4.50 F	✓
19	1		*Front bumper sponge LH	0.00	0.00	*20.00 F	✓
20	1		*Front bumper sponge RH	0.00	0.00	*20.00 F	✓
21	1		*Front bumper centre sponge	0.00	0.00	*40.00 F	✓

F=Franchise part.

Sub Total (S\$) 3,518.50
 + Margin on L,N Items 10.00% (S\$) 351.85
Total Parts (S\$) 3,870.35

Lai Huat (Meng Kee) Motor Pte Ltd/SKT9339D/23/08/2019 10:34. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	Front number plate	mil 35.00 ✓
2	1	Front parking sensor with installation	200.00 ?X
Sub Total (S\$)			235.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	To spray paint (blending front door RH)	New	850.00 750
<u>Labour Items</u>			
2	To straighten front body, to knock dents on front support panel and renew of parts	New	550.00 500
Gross Labour Cost (S\$)			1,400.00

Lai Huat (Meng Kee) Motor Pte Ltd/SKT9339D/23/08/2019 10:34. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

來發(明記)摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sin Ming Autocity
160 Sin Ming Drive #04-01/#04-02/#07-03 Singapore 575722
Tel: 64538110 Fax: 64596267 Email: info@laihuat.com.sg
UEN: 199407592C

(SUPPLEMENTARY)

INSURER: Sampo Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	70794
Policy No:	D18MTPV01015284	Date of Loss:	18/08/2019
Vehicle Reg. No.:	SKT9339D	Driveable?	
Driver Age/Info:	51 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TAN WOON SZU		
Driver:	ANG WOON CHOO		

Make/Model:	TOYOTA HARRIER, 2.0 PREMIUM (A)	Vehicle Reg. Date:	14/10/2015
Vehicle Colour:	WHITE	Chassis No:	ZSU600050845
Engine No:	3ZRB600196		
Odometer:	133164 KM		

Paint Type:
Total Loss? **NO**
Est. Duration of Repair (day) 8

Description of Accident/Loss: I WAS DRIVING ALONG PIE TOWARDS CHANGI . VEHICLE B WAS DRIVING AT MY LEFT LANE . SUDDENLY VEHICLE B CUT INTO MY LANE WITHOUT SIGNAL . I CAN'T STOP IN TIME AND COLLIDED ONTO REAR OF VEHICLE B . NO INJURIES INVOLVED.

Present Location: LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING)

COST OF CLAIMS		Amount
Parts		110.00
Miscellaneous Items		0.00
Labour		80.00
Paintwork Labour		0.00
Towing		0.00
Gross Total (S\$)		190.00
+ GST 7.00% (S\$)		13.30
Nett Amount (S\$)		203.30
+ Previous Estimates (S\$)		5,890.72
Claim Total (S\$)		6,094.02

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 06 Sep 2019)**Parts:** M1-SUV TOYOTA HARRIER 2.0 Premium (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Lai Huat (Meng Kee) Motor Pte Ltd/SKT9339D/06/09/2019 10:56**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Bonnet chrome moulding	0.00	0.00	<i>mgm</i> *100.00 F. ?
						Sub Total (S\$) 100.00
						+ Margin on L,N Items 10.00% (S\$) 10.00
						Total Parts (S\$) 110.00

F=Franchise part.

Lai Huat (Meng Kee) Motor Pte Ltd/SKT9339D/06/09/2019 10:56. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	To remove + refix front parking camera and parking sensors	New	80.00
Gross Labour Cost (S\$)			80.00

Lai Huat (Meng Kee) Motor Pte Ltd/SKT9339D/06/09/2019 10:56. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Veron Chen (LKKAUTO)

From: Jenny Lim <jenny.lim@laihuat.com.sg>
Sent: Friday, 27 September 2019 3:25 PM
To: SUR
Subject: FW: Finalisation - SKT 9339D / Toyota Harrier
Attachments: 06092019114617.pdf; 06092019114623.pdf

Follow Up Flag: Follow up
Flag Status: Flagged

Dear Veron

FYI

Thank you.

Kind regards.

Jenny Lim
for LAI HUAT (MENG KEE) MOTOR PTE LTD
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722
Tel: 64538110
Fax: 64596267

From: Jenny Lim [mailto:jenny.lim@laihuat.com.sg]
Sent: Friday, 6 September, 2019 11:47 AM
To: Kenneth Kong
Subject: Finalisation - SKT 9339D / Toyota Harrier

Dear Sir

For your confirmation, please:

- Parts: 3478.50 (include supplementary)
- 10%: 347.85
- SN: 35.00
- L&M: 1330.00
- Sub-total: 5191.35
- Less XC: waived
- Total: \$5191.35

Supporting documents are enclosed and uploaded into Merimen for your reference. Photographs will send to you in separate email.

We look forward to hearing from you soon.

Thank you.

Kind regards
Jenny Lim
Lai Huat (Meng Kee) Motor Pte Ltd
Sin Ming Autocity
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Singapore 575722

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Aug 2019)
 Parts: M1-SUV TOYOTA HARRIER 2.0 Premium (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Lai Huat (Meng Kee) Motor Pte Ltd/SKT9339D/23/08/2019 10:34
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*Front radiator top cover	0.00	0.00	*120.00 F	
2	6		*Front radiator top cover clips	0.00	0.00	*6.00 F	
3	1		*Front bumper	0.00	0.00	*450.00 F	
4	1		*Front bumper lower centre grille	0.00	0.00	*90.00 F	
5	1		*Front bumper lower grille	0.00	0.00	*110.00 F	
6	1		*Radiator grille	0.00	0.00	*195.00 F	
7	6		*Radiator grille clips	0.00	0.00	*9.00 F	
8	1		*Front headlamp LH	0.00	0.00	*950.00 F	C
9	1		*Front headlamp RH	0.00	0.00	*950.00 F	C
10	1		*Front bumper centre beam	0.00	0.00	*90.00 F	✓
11	1		*Front bumper beam LH	0.00	0.00	*50.00 F	✓
12	1		*Front bumper beam RH	0.00	0.00	*50.00 F	✓
13	1		*Front bumper inner retainer LH	0.00	0.00	*25.00 F	
14	1		*Front bumper inner retainer RH	0.00	0.00	*25.00 F	
15	1		*Front bumper outer retainer RH	0.00	0.00	*38.00 F	
16	1		*Front fender RH	0.00	0.00	*270.00 F	
17	6		*Front fender inner shield clips RH - 1	0.00	0.00	*6.00 F	
18	3		*Front fender inner shield clips RH - 2	0.00	0.00	*4.50 F	
19	1		*Front bumper sponge LH	0.00	0.00	*20.00 F	
20	1		*Front bumper sponge RH	0.00	0.00	*20.00 F	
21	1		*Front bumper centre sponge	0.00	0.00	*40.00 F	

F=Franchise part.

Sub Total (S\$) 3,518.50
 + Margin on L,N Items 10.00% (S\$) 351.85
 Total Parts (S\$) 3,870.35

Lai Huat (Meng Kee) Motor Pte Ltd/SKT9339D/23/08/2019 10:34. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	Front number plate	35.00 ✓
2	1	Front parking sensor with installation	200.00 ✗
Sub Total (S\$)			235.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	To spray paint (blending front door RH)	New	850.00 750
<u>Labour Items</u>			
2	To straighten front body, to knock dents on front support panel and renew of parts	New	550.00 500
Gross Labour Cost (S\$)			1,400.00

Lai Huat (Meng Kee) Motor Pte Ltd/SKT9339D/23/08/2019 10:34. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

SUPPLEMENTARY

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Sep 2019)
Parts: M1-SUV TOYOTA HARRIER 2.0 Premium (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Lai Huat (Meng Kee) Motor Pte Ltd/SKT9339D/06/09/2019 10:56
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Bonnet chrome moulding	0.00	0.00	*100.00 F
Sub Total (\$\$)						100.00
+ Margin on L,N Items 10.00% (\$\$)						10.00
Total Parts (\$\$)						110.00

F=Franchise part.

Lai Huat (Meng Kee) Motor Pte Ltd/SKT9339D/06/09/2019 10:56. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

SUPPLEMENTARY

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	To remove + refix front parking camera and parking sensors	New	80.00
Gross Labour Cost (S\$)			80.00

Lai Huat (Meng Kee) Motor Pte Ltd/SKT9339D/06/09/2019 10:56. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

豐達汽車私人有限公司

FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
 Tel: 67494988, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
 Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949832
 Tel: 62992158, 62942354, 62935021
 Mail: ftrpnet@mbx3.singnet.com.sg
 CB Reg No.: 198301435R

LAI HUAT (MENG KEE) MOTOR PTE LTD
 SIN MING DRIVE
 -01/#04-02 SIN MING AUTO CITY
 SINGAPORE 575722

GST Reg. No.: M2-0059747-8

NISSAN TOYOTA OPEL OEM PARTS
 TEL: 67426888 62949832 67479292
 67426878 62985333 67455824

MAZDA/FORD DIV
 TEL: 62935722
 67420368

HYUNDAI/HYUNDAI DIV
 TEL: 62970688 64542288
 67493588

MAZDA/FORD DIV
 TEL: 62935722
 67420368

AIRCON/W/S GLASS
 TEL: 62952336
 67498997

NISSAN **TOYOTA** **OPEL**
 Genuine Parts GENUINE PARTS GENUINE PARTS

MAZDA **FORD** **HYUNDAI**
 Genuine Parts GENUINE PARTS GENUINE PARTS

TOKICO **ACE** **ACE** **ACE** **ACE** **ACE** **ACE** **ACE** **ACE** **ACE**

TAX INVOICE

TAX INVOICE NO.: CL403153

INVOICE DATE : 24/08/2019

CREDIT TERMS : 30 DAYS

SALES ORDER NO.:

SALESMAN : YKN

PAGE(S) : 1

DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	(SIN)	(SIN)
289-48020 RADIATOR COVER		1	120.000	✓120.00	✓
467-07211 CLIP		6	1.000	✓6.00	✓
119-48C70-A0 F/BUMPER		1	450.000	✓450.00	✓
112-48150 F/B CENTER GRILLE		1	90.000	✓90.00	✓
411-48020 F/BUMPER SPOILER		1	110.000	✓110.00	✓
101-48913 GRILLE		1	195.000	✓195.00	✓
161-16010 BUMPER CLIP		6	1.500	✓9.00	✓
370-48890 HEADLAMP UNIT		1 PCS	950.000	✓950.00	✓
140-48440 HEADLAMP UNIT		✓	950.000	✓950.00	✓
329-48010 F/BUMPER REINFORCEMENT		1	90.000	✓90.00	✓
523-48020 F/BUMPER RETAINER		1	50.000	✓50.00	✓

FONG TAT MOTOR CO. PTE. LTD. GOODS SOLD ARE NOT RETURNABLE FOR CASH GOODS RECEIVED TOTAL

SIGNATURE 1/10 SIGNATURE

豐達汽車私人有限公司

FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
 Tel: 67494988, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
 Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949832
 Tel: 62992158, 62942354, 62935021
 Mail: ftrpnet@mbx3.singnet.com.sg
 CB Reg No.: 198301435R

LAI HUAT (MENG KEE) MOTOR PTE LTD
 SIN MING DRIVE
 -01/#04-02 SIN MING AUTO CITY
 SINGAPORE 575722

GST Reg. No.: M2-0059747-8

NISSAN TOYOTA OPEL OEM PARTS
 TEL: 67426888 62949832 67479292
 67426878 62985333 67455824

MAZDA/FORD DIV
 TEL: 62935722
 67420368

HYUNDAI/HYUNDAI DIV
 TEL: 62970688 64542288
 67493588

MAZDA/FORD DIV
 TEL: 62935722
 67420368

AIRCON/W/S GLASS
 TEL: 62952336
 67498997

NISSAN **TOYOTA** **OPEL**
 Genuine Parts GENUINE PARTS GENUINE PARTS

MAZDA **FORD** **HYUNDAI**
 Genuine Parts GENUINE PARTS GENUINE PARTS

TOKICO **ACE** **ACE** **ACE** **ACE** **ACE** **ACE** **ACE** **ACE** **ACE**

TAX INVOICE

TAX INVOICE NO.: CL403153

INVOICE DATE : 24/08/2019

CREDIT TERMS : 30 DAYS

SALES ORDER NO.:

SALESMAN : YKN

PAGE(S) : 2

DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	(SIN)	(SIN)
538-48020 F/BUMPER RETAINER		1	50.000	✓50.00	✓
133-48050 HEADLAMP BRACKET		1	25.000	✓25.00	✓
134-48050 HEADLAMP BRACKET		1	25.000	✓25.00	✓
535-48040 F/BUMPER RETAINER		1 PCS	38.000	✓38.00	✓
311-48210 F/FENDER		1	270.000	✓270.00	✓
167-10183 COWLING CLIP		6	1.000	✓6.00	✓
189-06013 COWLING CLIP(6)		3	1.500	✓4.50	✓
512-48030 F/BUMPER SPONGE		1	20.000	✓20.00	✓
511-48170 F/BUMPER SPONGE		1	20.000	✓20.00	✓
514-48040 F/BUMPER SPONGE		1	40.000	✓40.00	✓
516-48020 F/BUMPER RETAINER		1 PCS	100.000	✓100.00	✓

FONG TAT MOTOR CO. PTE. LTD. GOODS SOLD ARE NOT RETURNABLE FOR CASH GOODS RECEIVED TOTAL

SIGNATURE SIGNATURE

達汽車私人有限公司 ONG TAT MOTOR CO. PTE. LTD.

d Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347483
67494988, 67479202 Fax: 67490980, 67477481 Website: www.fongtat.com
n Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949832
62992156, 62942354, 62935021
it: fongtat@mbos3.singnet.com.sg
3 Reg No.: 198301435R

LAI HUAT (MENG KEE) MOTOR PTE LTD
SIN MING DRIVE
01/#04-02 SIN MING AUTO CITY
APORE 575722

GST Reg. No.: M2-0059747-8

NISSAN TOYOTA OPEL OEM PARTS
TEL: 67426889 62949832 67479202
67426878 62985333 67455824
MITSUBISHI/PROTON
TEL: 62954551
67490954

LH Honda/HYUNDAI DIV

TEL: 62970688 64542288
67493588

MAZDA/FORD DIV

TEL: 62935722
67420368

AIRCON/W/S GLASS

TEL: 62962336
67496997

NISSAN TOYOTA OPEL
Genuine Parts GENUINE PARTS GENUINE PARTS

MAZDA TOYOTA OPEL
Genuine Parts GENUINE PARTS GENUINE PARTS

NISSAN TOYOTA OPEL
Genuine Parts GENUINE PARTS GENUINE PARTS

TAX INVOICE

TAX INVOICE NO.: CL403153
INVOICE DATE : 24/08/2019
CREDIT TERMS : 30 DAYS
SALES ORDER NO.:
SALESMAN : YKN
PAGE(S) : 3

DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	(SIN)	(SIN)
3390 (ZSU60) JASON					
GST Excl Amount :					3618.50
Special Discount :					
GST @ 7 % :					253.30

OTOR CO. PTE. LTD.

GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL

3871.80

PRINT BY :

YKN 24/08/2019 09:46:57

INATURE

SIGNATURE

達汽車私人有限公司 ONG TAT MOTOR CO. PTE. LTD.

d Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347483
67494988, 67479202 Fax: 67490980, 67477481 Website: www.fongtat.com
n Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949832
62992156, 62942354, 62935021
it: fongtat@mbos3.singnet.com.sg
3 Reg No.: 198301435R

LAI HUAT (MENG KEE) MOTOR PTE LTD
SIN MING DRIVE
01/#04-02 SIN MING AUTO CITY
APORE 575722

GST Reg. No.: M2-0059747-8

NISSAN TOYOTA OPEL OEM PARTS
TEL: 67426889 62949832 67479202
67426878 62985333 67455824
MITSUBISHI/PROTON
TEL: 62954551
67490954

LH Honda/HYUNDAI DIV

TEL: 62970688 64542288
67493588

MAZDA/FORD DIV

TEL: 62935722
67420368

AIRCON/W/S GLASS

TEL: 62962336
67496997

AUTHORISED STOCKISTS:
NISSAN TOYOTA OPEL
Genuine Parts GENUINE PARTS GENUINE PARTS

MAZDA TOYOTA OPEL
Genuine Parts GENUINE PARTS GENUINE PARTS

NISSAN TOYOTA OPEL
Genuine Parts GENUINE PARTS GENUINE PARTS

TAX INVOICE

TAX INVOICE NO.: CL403352
INVOICE DATE : 28/08/2019
CREDIT TERMS : 30 DAYS
SALES ORDER NO.:
SALESMAN : YKN
PAGE(S) : 1

DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	(SIN)	(SIN)
25-33090-CO		1		20.00	20.00
4520 (ZSU60) JASON					
GST Excl Amount :					20.00
Special Discount :					
GST @ 7 % :					1.40

OTOR CO. PTE. LTD.

GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL

21.40

PRINT BY :

YKN 28/08/2019 17:06:33

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Aug 2019 Sendback Est	23 Aug 2019 10:34 S\$5,505.35	23 Aug 2019 10:41 Edit Adj Rpt	S\$5,191.35 Edit Estimates	S\$5,191.35 View Rpt		Pending for Survey Report Cancel Case
Supp #1	06 Sep 2019 10:55	06 Sep 2019 10:56 S\$190.00	06 Sep 2019 10:56			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: TAN WOON SZU , ID: S1624025G									
Vehicle Reg. No.: SKT9339D		Date of Loss: 18/08/2019 15:00 - :59 [46 Months and 4 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / CMTD1903932		Policy/Cover Note No.: D18MTPV01015284 (Comprehensive)							
		Excess: S\$0.00							
Repairer: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110									
Handling Insurer: Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 03/09/2019]									
Driver/Custodian: ANG WOON CHOO (51 / Female) , NRIC: S1796044Z, Tel: +6586138249 Email: eveangwc@yahoo.com									
Adj Asg. Remarks: Nivitha, pls assist to arr suv today (asap)									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• SOMPO_SG (26/08/2019): Alert - Adj Mandate Approved (S\$5355.35) - SKT9339D - Claim Handler: CHAN SHU HU...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SKT9339D (CMTD1903932)
 OD
 Aug 18 2019 3:00PM
 [TAN WOON SZU]
 Lai Huat (Meng Kee) Motor Pte Ltd

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View [View in Browser](#)

Assessment Reports					
			1 per page	☒	
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	23/08/19 10:34	Repairer Estimates		Load HTM	
2	06/09/19 10:56	Repairer Estimates Suppl. #1		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	23/08/19 14:36	Adjuster Immediate Advice		Load HTM	
Photos/Images					
			3 per page	☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	26/08/19 10:10	General View		Load JPG	☒
2	26/08/19 10:10	General View		Load JPG	☒
3	26/08/19 10:10	General View		Load JPG	☒
4	26/08/19 10:10	General View		Load JPG	☒
5	26/08/19 10:10	General View		Load JPG	☒
6	26/08/19 10:10	General View		Load JPG	☒
7	26/08/19 10:10	General View		Load JPG	☒
8	26/08/19 10:10	General View		Load JPG	☒
9	26/08/19 10:10	General View		Load JPG	☒
10	26/08/19 10:10	General View		Load JPG	☒
11	26/08/19 10:10	General View		Load JPG	☒
12	26/08/19 10:10	General View		Load JPG	☒
13	26/08/19 10:10	General View		Load JPG	☒
14	26/08/19 10:10	General View		Load JPG	☒
15	26/08/19 10:10	General View		Load JPG	☒
16	26/08/19 10:10	General View		Load JPG	☒
17	26/08/19 10:10	General View		Load JPG	☒
18	26/08/19 10:10	General View		Load JPG	☒
19	26/08/19 10:10	General View		Load JPG	☒
20	26/08/19 10:10	General View		Load JPG	☒
21	26/08/19 10:10	General View		Load JPG	☒
22	26/08/19 10:10	General View		Load JPG	☒
23	01/10/19 10:02	Reinspection Photo		Load JPG	☒
24	01/10/19 10:02	Reinspection Photo		Load JPG	☒
25	01/10/19 10:02	Reinspection Photo		Load JPG	☒
26	01/10/19 10:02	Reinspection Photo		Load JPG	☒
27	01/10/19 10:02	Reinspection Photo		Load JPG	☒
28	01/10/19 10:02	Reinspection Photo		Load JPG	☒
29	01/10/19 10:02	Reinspection Photo		Load JPG	☒
30	01/10/19 10:02	Reinspection Photo		Load JPG	☒
31	01/10/19 10:02	Reinspection Photo		Load JPG	☒
32	01/10/19 10:02	Reinspection Photo		Load JPG	☒
33	01/10/19 10:02	Reinspection Photo		Load JPG	☒
34	01/10/19 10:02	Reinspection Photo		Load JPG	☒
35	01/10/19 10:02	Reinspection Photo		Load JPG	☒
36	01/10/19 10:02	Reinspection Photo		Load JPG	☒
37	01/10/19 10:02	Reinspection Photo		Load JPG	☒
38	01/10/19 10:02	Reinspection Photo		Load JPG	☒

Assessment Reports				1 per page	☒
No	Finalized On			Thumbnail	Print
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)			
Documentation				1 per page	☒
No	Finalized On			Thumbnail	Print
1	05/09/19 18:21	CLAIM FORM DT 30.08.19 FR INSURED - SKT9339D			Load PDF
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)			
1	23/08/19 10:33	E-filed GIA report			Load PDF
2	06/09/19 11:49	Supplier Bill			Load PDF
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			
1	10/09/19 09:49	SUPPLEMENTARY			Load PDF
2	14/10/19 11:14	Parts Invoice			Load PDF

Linked Accident Report Documents

				View	View in Browser
Video				1 per page	☒
No	Finalized On			Thumbnail	Print
1	18/08/19 18:23	Video - Accident			Load MP4
2	18/08/19 18:23	Video - Accident			Load MP4
3	18/08/19 18:24	Video - Accident			Load MP4
Assessment Reports				1 per page	☒
No	Finalized On			Thumbnail	Print
1	18/08/19 18:25	Accident Statement			Load HTM
2	22/08/19 22:49	Accident Statement Addm. #1			Load HTM
3	23/08/19 10:54	Addendum Sheet			Load TIFF
4	23/08/19 10:56	Accident Statement Addm. #2			Load HTM
Photos/Images				3 per page	☒
No	Finalized On			Thumbnail	Print
1	18/08/19 18:21	Accident Photo			Load JPG
2	18/08/19 18:21	Accident Photo			Load JPG
3	18/08/19 18:21	Accident Photo			Load JPG
4	18/08/19 18:21	Accident Photo			Load JPG
5	18/08/19 18:21	Accident Photo			Load JPG
6	18/08/19 18:21	Accident Photo			Load JPG
7	18/08/19 18:21	Accident Photo			Load JPG
8	18/08/19 18:21	Accident Photo			Load JPG
9	18/08/19 18:21	Accident Photo			Load JPG
10	18/08/19 18:21	Accident Photo			Load JPG
11	18/08/19 18:21	Accident Photo			Load JPG
12	18/08/19 18:21	Accident Photo			Load JPG
13	18/08/19 18:21	Accident Photo			Load JPG
14	18/08/19 18:21	Driving License			Load JPG
15	18/08/19 18:21	Driving License			Load JPG
Documentation				1 per page	☒
No	Finalized On			Thumbnail	Print
1	18/08/19 18:21	Sketch Plan			Load JPG
2	18/08/19 18:21	Common Statement			Load TIFF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place, #05-01/06, Singapore Land Tower
Singapore 048623

Our File No: CS/SMO19014839/KVF3E2

Date: 14/10/2019

REFERENCE

Insured/Claimant: TAN WOON SZU Policy No: D18MTPV01015284
Date of Loss: 18/08/2019 Nature of Claim: OD Claim No: CMTD1903932

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKT9339D**
Make & Model: TOYOTA HARRIER, 2.0 Premium (A) Engine No: 3ZRB600196
Reg. Date: 14/10/2015 (Man. Year: 2015) Chassis No: ZSU600050845
Colour: Metallic Pearl White Odometer: 133164 km
Engine Capacity: 1986 cc
Market Value/New Car Price: S\$90,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R18 Rear Tyre Size: 235/55 R18
Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm
Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,980.35	3,826.35	154.00	3.87
Miscellaneous Items	235.00	35.00	200.00	85.11
Labour	630.00	580.00	50.00	7.94
Paintwork Labour	850.00	750.00	100.00	11.76
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,695.35	5,191.35	504.00	8.85
+ GST 7.00/7.00% (S\$)	398.67	363.39	35.28	8.85
Nett Amount (S\$)	6,094.02	5,554.74	539.28	8.85

INSPECTION

Date of Assignment: 23/08/2019 Present Location: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
Date Inspected: 23/08/2019 Inspected At: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
160 Sin Ming Drive #04-01, Sin Ming AutoCity
Singapore 575722
Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Oct 2019)
Parts:	M1-SUV	TOYOTA HARRIER 2.0 Premium (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKT9339D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front radiator top cover (WCP)	Dented	120.00 F	*120.00 F
2	6		*Front radiator top cover clips (WCP)	Necessary	6.00 F	*6.00 F
3	1		*Front bumper (WCP)	Cracked	450.00 F	*450.00 F
4	1		*Front bumper lower centre grille (WCP)	Distorted	90.00 F	*90.00 F
5	1		*Front bumper lower grille (WCP)	Dented / Distorted	110.00 F	*110.00 F
6	1		*Radiator grille (WCP)	Cracked	195.00 F	*195.00 F
7	6		*Radiator grille clips (WCP)	Necessary	9.00 F	*9.00 F
8	1		*Front headlamp LH (WCP)	Cracked	950.00 F	*950.00 F
9	1		*Front headlamp RH (WCP)	Mtg Cracked	950.00 F	*950.00 F
10	1		*Front bumper centre beam (WCP)	Repair	90.00 F	*- F
11	1		*Front bumper beam LH (WCP)	Distorted	50.00 F	*50.00 F
12	1		*Front bumper beam RH (WCP)	Repair	50.00 F	*- F
13	1		*Front bumper inner retainer LH (WCP)	Distorted	25.00 F	*25.00 F
14	1		*Front bumper inner retainer RH (WCP)	Distorted	25.00 F	*25.00 F
15	1		*Front bumper outer retainer RH (WCP)	Distorted	38.00 F	*38.00 F
16	1		*Front fender RH (WCP)	Buckled	270.00 F	*270.00 F
17	6		*Front fender inner shield clips RH - 1 (WCP)	Necessary	6.00 F	*6.00 F
18	3		*Front fender inner shield clips RH - 2 (WCP)	Necessary	4.50 F	*4.50 F
19	1		*Front bumper sponge LH (WCP)	Cracked	20.00 F	*20.00 F
20	1		*Front bumper sponge RH (WCP)	Cracked	20.00 F	*20.00 F
21	1		*Front bumper centre sponge (WCP)	Cracked	40.00 F	*40.00 F
Supplementary #1						
22	1		*Bonnet chrome moulding (WCP)	Mtg Cracked	100.00 F	*100.00 F

F=Franchise part.

Sub Total (S\$)	3,618.50	3,478.50
+ Margin on L,N Items 10.00/10.00% (S\$)	361.85	347.85
Total Parts (S\$)	3,980.35	3,826.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	Front number plate (MISSING)	35.00	35.00
2	1	Front parking sensor with installation (NOT NECESSARY)	200.00	0.00
Sub Total (\$\$)			235.00	35.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	To spray paint (blending front door RH)	New	850.00	750.00
<u>Labour Items</u>				
2	To straighten front body, to knock dents on front support panel and renew of parts	New	550.00	500.00
<u>Supplementary #1</u>				
<u>Labour Items</u>				
3	To remove + refix front parking camera and parking sensors	New	80.00	80.00
Gross Labour Cost (\$\$)			1,480.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >