

Personal

ASS. REC. BY:

REF:

CS/A1G19014849/Kqd3er

Original Instructions:

Assignee:

Kenneth

ASSIGNMENT (Office)

From (Person):

Chin lee Ying

of

A1G

Date/Time:

23/8/19 @ 11:18am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLA 8246H

Insured:

at Workshop in/

Tong Luck

Tel:

6250 0088

at

160 Sing Ming Drive # 07-01

Policy No:

0919914159

Claim No:

934628974059

Sum Insured:

Excess:

\$18A 1500

Make of Veh:

(Client's Record)

D.O.A

13/08/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:26pm @ 23/8/19

Person Contacted:

Candy

Vehicle

IN/OUT

Date/Time	Action/Instruction
	SLA 8246H - X
23/8/19 @ 2:24pm	revert to lee ying via Meianan.
23/8/19 @ 5:20pm	Victor informed c/a via Meianan.
23/8/19 @ 5:34pm	Informed Tong Luck c/a & ex: \$1500 by email.
	Kenneth confirmed final fig \$7394.60.
	(led to 3270.40, 30%)

ASS. REC. BY:

REF:

116/CS/AG/1904849/kqd3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

8104k

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5-6 days

Res.: Yes or No

Lum Sum:

1.81 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLA 824614

Yr Regn:

03, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Esting Acrag

Colour:

M. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

50048

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

ACR50 - 0194737

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

Dun 225/50R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

21/9/19 @ 11.4pm 2nd visit to Victor van mannen. (supplementary)

Part by part \$7394.60 (Cled: 3220.40 : 30%)

RECEIVED 30 SEP 2019

Date/Time, File Pass to?

12/10 Typist

Date/Time, File Return to?

21



: Prell. Report



: Final Report

Days Of Repair:

5

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

\$ - RS - SI

: Fuel

: Others

TOTAL

Report Format :

OD

Lump Sum / I.B. : (\$

7394.60

200

11

211

Estimated cost for repairing of vehicle no.: SLA8246H -- OD Claim

From: Chin, Lee-Ying
To: assignments, Admin A
Cc: Fong, Andy-SY
Sent: 8/23/2019 11:18:52 AM
Attachments:  SLA8246H - Estimate.pdf

Hi LKK.

Kindly appoint Xing Guo Qiang to conduct survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

From: Operation / Yu Ching [mailto:operation@tlauto.com.sg]
Sent: Friday, August 23, 2019 11:05 AM
To: Chin, Lee-Ying
Subject: [EXTERNAL] Estimated cost for repairing of vehicle no.: SLA8246H -- OD Claim

This message is from an external sender; be cautious with links and attachments.

Dear Lee Ying,

Please find attached documents for your attention and necessary action.

The vehicle is now garage at our workshop

Kindly arrange your surveyor to inspect the vehicle at an earlier date

Thanks & regards,
Yu Ching



Tong Luck Auto Pte Ltd

160 Sin Ming Drive
#07-01/06 Sin Ming Autocity
Singapore 575722
Tel: 6250 0088 Fax: 6250 5545
Email: operation@tlauto.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and

permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Yap, Weijoe

Date: 25 Sep 2019

Preliminary Advice

Vehicle No	: SLA8246H	Accident Date	: 13/08/2019
Make	: TOYOTA ESTIMA	Policy No.	: 0999994159
Assignment Date	: 23/08/2019	Excess	: S\$1,500.00
Date of Inspection	: 23/08/2019	Est. Duration of Repair	: 5.00
Inspection At	: TONG LUCK AUTO PTE LTD (HQ) 160 SIN MING DRIVE, #07-01 SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,615.00	(ESTIMATE \$9,794.40 + SUPPLEMENTARY \$820.60)
Revised Amount	:S\$	7,394.60	(INCLUSIVE OF SUPPLEMENTARY & CHECK ITEMS)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	7,394.60	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	104,000.00
COE / PARF Rebate	:S\$	58,478.00
Salvage Value	:S\$	
Margin for Repair	:S\$	45,522.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY & CHECK ITEMS.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 27 August 2019 5:34 PM
To: tlauto@singnet.com.sg
Subject: OD VEHICLE SLA 8246H (DOA: 13/08/2019)

Dear Sir/Madam,

As instructed by our client, please proceed to repair the insured vehicle **SLA 8246H Excess \$1,500/-**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	13 Aug 2019 13:37	Cim Veh Model Changed		[I] Merimen Administrator
2	13 Aug 2019 13:37	Cim Created	Reg No: SLA8246H, Policy No: 999995580, Acct Date: 2019/08/13, Claim Type: S C. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG), Ins.Status => Notification, Created from SAS:MBHH19105180	[I] Merimen Administrator
3	14 Aug 2019 17:00	Cim Registration Modified	Acct Time:08:50:00->09:00:00, Pol No:999995580->0999994159.	[I] AIG OneClaim Integration User
4	23 Aug 2019 14:07	Cim Registration Modified	Setl.Type:3->0, Claim Type:SC->OD.	[I] Nivitha Govindasamy
5	23 Aug 2019 14:07	Adj Cim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[I] Nivitha Govindasamy
6	23 Aug 2019 14:07	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Nivitha Govindasamy
7	23 Aug 2019 14:07	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/09/03	[A] Nivitha Govindasamy
8	23 Aug 2019 14:07	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] Nivitha Govindasamy
9	23 Aug 2019 14:07	Cim Registration Modified	Rep:1137->200237.	[A] Nivitha Govindasamy
10	23 Aug 2019 14:07	Cim Veh Model Changed	(202385) TOYOTA ESTIMA 2.4 (A).	[A] Nivitha Govindasamy
11	23 Aug 2019 14:07	Adj Adjuster Assigned	[None] -> KENNETH KONG	[A] Nivitha Govindasamy
12	23 Aug 2019 14:19	Adj Rpt Initiated		[A] SHIAU CHAN
13	23 Aug 2019 14:19	Cim Dtl Modified	JPJ Reg. Date: -> 2016/03/18.	[A] SHIAU CHAN
14	23 Aug 2019 14:19	Cim Details Notified		[A] SHIAU CHAN
15	23 Aug 2019 14:21	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/09/03	[A] SHIAU CHAN
16	23 Aug 2019 14:24	Adj Mandate Request	Cur.Reg:8658.90:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE N OT AUTHORISE REPAIR.	[A] SHIAU CHAN
17	26 Aug 2019 15:23	Cim Registration Modified	Init,Est.->5,000 - 6,000, Excess: -> 1500.00, 2F Remarks: -> Not Applicable, GST: -> 7.00.	[I] Yap, Weijoe
18	26 Aug 2019 16:24	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
19	27 Aug 2019 17:20	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/09/03. Mandate Remarks: Labour to adjust to 1.5 days \$300.00 or justify why 3 days labour given, Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK
20	27 Aug 2019 17:20	Adj Mandate Set	Approved:3617.70:Labour to adjust to 1.5 days \$300.00 or justify why 3 days labour given, Re-inspection to be done for damage check and supplementary items / labour, Reinsp:Yes.	[I] Koh, Victor-CK

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2255630	23/08/2019 14:19	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLA8246H		11.77

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 23 Aug 2019

Preliminary Advice

Vehicle No	: SLA8246H	Accident Date	: 13/08/2019
Make	: TOYOTA ESTIMA	Policy No.	: 0999994159
Assignment Date	: 23/08/2019	Excess	: S\$0.00
Date of Inspection	: 23/08/2019	Est. Duration of Repair	: 6.00
Inspection At	: TONG LUCK AUTO PTE LTD (HQ) 160 SIN MING DRIVE, #07-01 SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,794.40
Revised Amount	:S\$	3,617.70
Check Items (Estimated)	:S\$	5,041.20
Total	:S\$	8,658.90

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	104,000.00
COE / PARF Rebate	:S\$	58,478.00
Salvage Value	:S\$	
Margin for Repair	:S\$	45,522.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	778Z
Vehicle Details	
Vehicle No.:	SLA8246H
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Aug 2019
Vehicle Make:	TOYOTA
Vehicle Model:	ESTIMA AERAS PREMIUM 2.4 CVT
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	2AZ4A19289
Chassis No.:	ACR500194737
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$31,665.00
Original Registration Date:	18 Mar 2016
First Registration Date:	18 Mar 2016
Transfer Count:	0
Actual ARF Paid:	\$36,331.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Mar 2026
PARF Rebate Amount:	\$27,248.00
Intended COE Rebate Details	
COE Expiry Date:	17 Mar 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,604.00
COE Rebate Amount:	\$31,230.00
Total Rebate Amount:	\$58,478.00

The information contained herein is correct as at 23 Aug 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/08/2019 13:12
Date Of Accident	13/08/2019 08:50
Exact Location Of Accident	ALONG MOULMEIN ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLA8246H
Insured/Policyholder	
Name Of Registered Owner	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.
Co Reg No	199803778Z
Email Address	NORAZMAN.ABDUL_AZIZ@DAIMLER.COM
Mobile Phone No	
Alternative Phone No	OFFICE-88762075

Vehicle Particulars

Manufacturer	TOYOTA
Model	ESTIMA AERAS PREMIUM 2.4 CVT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken.	

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995580
Cover Note Number	

Driver

Name of Driver	SAMSURI BIN SUMADI
NRIC No	S1349587D
Date Of Birth	06/10/1959
Occupation	INDOOR
Date Of Driving Pass	14/09/1981
Driving Experience	37 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90540260
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was driving on the slowest lane and wanted to change lane to the 3rd lane. I check my blind spot and made a safe lane changing. As I was about to complete my lane changing I didn't realise that the vehicle on that lane had stop due to a red light ahead. I accidentally bump onto the rear of the front vehicle. We exchange particulars. No injury involved.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJH6936A
Vehicle Make/Model/Colour	SUZUKI / SX4 1.6HB AT / WHITE
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KONG SWEE SIEW
NRIC/Passport Number	S7300254J
Contact Number	81267609
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Sketch Plan

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Reports Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers", the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/postal packages; and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

VERIFIED BY AJAX MARS
REPORTING OFFICER
Mohammad Azaly Bin Abdullah
Witnessed by Reporting Centre
Personnel

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

I was driving on the slowest lane and wanted to change lane to the 3rd lane. I check my blind spot and made a safe lane changing. As I as about to complete my lane changing I didn't realise that the vehicle on that lane had stop due to a red light ahead.

I accidentally bump onto the rear of the front vehicle.

We exchange particulars.

No injury involved.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect.

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHAMMAD AZALY BIN ABDULLAH

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

13 August 2019 at 10:48 AM

Date/Time:

13 August 2019 at 10:48 AM



HOTLINE TEL: (65) 6419-3000

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1967
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1969 (MALAYSIA)

M 2 400

COMPREHENSIVE COMMERCIAL MOTOR	OWN DAMAGE EXCESS	S\$1,500.00 (1)
CERTIFICATE NO. 999994159/100782366-00000	WINDSCREEN EXCESS	S\$100.00
	(for policies with effect from 1st November 2022)	
	SUM INSURED	S\$1.00
	INSURING WITH COE/PARF	YES
1) VEHICLE REGISTRATION NO.	SLA8246H	
2) NAME OF INSURED	Dairlier Fleet Management Singapore Pte Ltd	
3) EFFECTIVE DATE OF THE COMMENCEMENT OF INSURANCE FOR THE PURPOSES OF THE ACT	1 Jan 2019	
4) DATE OF EXPIRY OF INSURANCE	31 Dec 2019	
5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE *		
1) Any drivers who is driving on the Insured's order or with their permission. 2) Excess \$2,500 applies to drivers age 21 to 26 years old unless otherwise specified 3) Additional Excess \$3,500 applies to drivers age below 21 or above 55 years old and or less than years driving experience unless otherwise specified		
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.		
6) LIMITATION AS TO USE *		
1) Use for social, domestic, pleasure purposes and business purposes of the Insured and or hirer whom the vehicle is hired to. The Policy does not cover: 1) Use for the carriage of passengers for hire or reward 2) Use for driving tuition, driving test, racing, pace-making, reliability trial or speed-testing. 3) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle 4) Use for any purpose in connection with the Motor Trade. In the event of accident claim, the repairs to the Vehicle must be carried out by either one of our AIG Authorized Repairers or a particular Repairer approved by AIG LOSS OF USE NOT INCLUDED * NAMED DRIVER N/A HIRE PURCHASE COMPANY N/A * Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.		

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore 11 Apr 2019

AIG ASIA PACIFIC INSURANCE PTE. LTD.

030035-000
JARDINE LLOYD THOMPSON PTE LTD
138 MARKET STREET
#07-01 CAPITA GREEN
SINGAPORE 048946



Authorised Representative

ORIGINAL

SSCOSK



Identification Card



REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence No: **S1349587D**

(NOM)

SAMSURI BIN SUMADI

Birth Date: **06 Oct 1959**

Issue Date: **06 May 2003**



000456337J


YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of
which unladen does not exceed 2500 kilograms

14 Sep 1981

NP 428A



Licence No: S1349587D



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

Not Notified

Runny Bpaim

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 13/08/2019

5-6 days



ESTIMATE

NO : QUOT201908-000056(00)

DATE : 22/08/2019

POLICY NO : 999995580

VEH REG NO : SLA8246H

MAKE/MODEL : TOYOTA ESTIMA AERAS
PREMIUM 2.4 CVT

CHASSIS NO : ACR500194737

ENGINE NO : 2AZ4A19289

REG. DATE : 2015

Estimate Repair Cost to Vehicle No : SLA8246H

18x 62564315

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Bonnet	1	380.00 <i>B</i>	380.00 ✓
2 Bonnet lock	1	68.00 <i>SAC</i>	68.00 7x
3 Bonnet insulator clips	10	5.00 <i>me</i>	50.00 ✓
4 Support panel	1	580.00 <i>R</i>	580.00 7x
5 Support panel top garnish	1	160.00 <i>Sn</i>	160.00 x
6 Brace panel	1	85.00 <i>B</i>	85.00 —
7 Front bumper	1	480.00 <i>Bu</i>	480.00 ✓
8 Front bumper reinforcement	1	280.00 <i>W</i>	280.00 7x
9 Front bumper sponge	1	68.00 <i>CRG</i>	68.00 7x
10 Front bumper bracket - LH/RH	2	58.00 <i>R</i>	116.00 7x
11 Front bumper side retainer - LH/RH	2	45.00 <i>ALD</i>	90.00 4x
12 Front bumper towing cover	1	32.00 <i>DJ</i>	32.00 ✓
13 Front bumper lower grille	1	295.00 <i>D.I</i>	295.00 —
14 Front bumper lower grille chrome	1	190.00 <i>CM</i>	190.00 —
15 Front bumper clips	15	5.00 <i>SD</i>	75.00 —
16 Front grille assy	1	320.00 <i>CM</i>	320.00 —
17 Front grille emblem	1	55.00 <i>me</i>	55.00 —
18 Headlamp assy - LH/RH	2	950.00 <i>ALD</i>	1,900.00 ?
19 Radiator Assy	1	800.00 <i>me</i>	800.00 7x
20 Air-con condenser	1	580.00 <i>me/me</i>	580.00 7x
			6,604.00
		Add 10%	660.40
			7,264.40
SPECIAL NET			
21 Radiator coolant (tin)	2	30.00 <i>me</i>	60.00 7x
22 Front number plate	1	40.00 <i>B</i>	40.00 ✓
			100.00
LABOUR			
23 To remove and refit air-con condenser, pipes, radiator assy, inter-cooler assy and refill air-con gas	1	150.00 <i>150</i>	150.00 ?
24 To check and rectify wiring system	1	80.00	80.00 200
25 To panel beat and straighten front chassis frame including replacement of parts and align where necessary, to refit and adjust the same	1	1,200.00 <i>500</i>	1,200.00 600
26 To putty and spray paint on affected areas	1	1,000.00	1,000.00 750



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000 FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 13/08/2019

ESTIMATE

NO : QUOT201908-000056(00)

DATE : 22/08/2019

POLICY NO : 999995580

VEH REG NO : SLA8246H

MAKE/MODEL : TOYOTA ESTIMA AERAS
PREMIUM 2.4 CVT

CHASSIS NO : ACR500194737

ENGINE NO : 2AZ4A19289

REG. DATE : 2015

Estimate Repair Cost to Vehicle No : SLA8246H

Description	Quantity	Unit Price	Amount
		S\$	S\$
			2,430.00
		TOTAL	S\$ 9,794.40
		ADD GST @ 7%	685.61
		GRAND TOTAL	S\$ 10,480.01

SINGAPORE DOLLAR TEN THOUSAND FOUR HUNDRED EIGHTY AND CENTS ONE ONLY

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FOR TONG LUCK AUTO PTE LTD

10615

AUTHORISED SIGNATURE



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 13/08/2019

Not Notified
Runny Bepain



5-6 days

ESTIMATE

NO : QUOT201908-000056(00)

DATE : 22/08/2019

POLICY NO : 999995580

VEH REG NO : SLA8246H

MAKE/MODEL : TOYOTA ESTIMA AERAS
PREMIUM 2.4 CVT

CHASSIS NO : ACR500194737

ENGINE NO : 2AZ4A19289

REG. DATE : 2015

Estimate Repair Cost to Vehicle No : SLA8246H

15x 62564315

Description	Quantity	Unit Price	Amount
		SG	SG
PARTS			
1 Bonnet	1	380.00	380.00 ✓
2 Bonnet lock	1	68.00	68.00 ✓
3 Bonnet insulator clips	10 6	5.00	50.00 ✓
4 Support panel	1	580.00	580.00 ✓
5 Support panel top garnish	1	180.00	180.00 ✓
6 Brace panel	1	85.00	85.00 ✓
7 Front bumper	1	480.00	480.00 ✓
8 Front bumper reinforcement	1	280.00	280.00 ✓
9 Front bumper sponge	1	68.00	68.00 ✓
10 Front bumper bracket - LH/RH	2	58.00	116.00 ✓
11 Front bumper side retainer (LH/RH)	1-2 110.00	45.00	90.00 ✓
12 Front bumper towing cover	1	32.00	32.00 ✓
13 Front bumper lower grille	1	295.00	295.00 ✓
14 Front bumper lower grille chrome	1	190.00	190.00 ✓
15 Front bumper clips	10 10	5.00	50.00 ✓
16 Front grille assy	1	320.00	320.00 ✓
17 Front grille emblem	1	55.00	55.00 ✓
18 Headlamp assy (LH/RH)	2 1	950.00	1,900.00 ✓
19 Radiator Assy	1	800.00	800.00 ✓
20 Air-con condenser	1	580.00	580.00 ✓
			6,604.00
			Add 10%
			660.40
			7,264.40
SPECIAL NET			
21 Radiator coolant (tin)	2	30.00	60.00 ✓
22 Front number plate	1	40.00	40.00 ✓
			100.00
LABOUR			
23 To remove and refit air-con condenser, pipes, radiator assy, inter-cooler assy and refill air-con gas	1	150.00	150.00 ✓
24 To check and rectify wiring system	1	80.00	80.00 ✓
25 To panel beat and straighten front chassis frame including replacement of parts and align where necessary, to refit and adjust the same	1	1,200.00	1,200.00 ✓
26 To putty and spray paint on affected areas	1	1,000.00	1,000.00 ✓

4,640.00

10%

464.00

5,104.00

100%

20%

60%

750%



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16

AIG BUILDING

SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 13/08/2019

ESTIMATE

NO : QUOT201908-000056(00)

DATE : 22/08/2019

POLICY NO : 999995580

VEH REG NO : SLA8246H

MAKE/MODEL : TOYOTA ESTIMA AERAS
PREMIUM 2.4 CVT

CHASSIS NO : ACR500194737

ENGINE NO : 2AZ4A19289

REG. DATE : 2015

Estimate Repair Cost to Vehicle No : SLA8246H

Description	Quantity	Unit Price	Amount
		S\$	S\$
SUPPLEMENTARY PARTS			
1 Front bumper lower bar	1	520.00	520.00
2 Horn - RH / LH	2	85.00	170.00
3 Radiator guide - RH / LH	2	28.00	56.00
			746.00
		Add 10%	74.60
			820.60
		TOTAL	S\$ 820.60
		ADD GST @ 7%	57.44
		GRAND TOTAL	S\$ 878.04

SINGAPORE DOLLAR EIGHT HUNDRED SEVENTY-EIGHT AND CENTS FOUR ONLY

$$\begin{array}{r}
 \$ 7,814.60 \\
 \times \$ 1,500.00 \\
 \hline
 \$ 6,014.60 \\
 7\% \quad 421.02 \\
 \hline
 \$ 6,435.62
 \end{array}$$

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16

AIG BUILDING

SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 13/08/2019

ESTIMATE

NO : QUOT201908-000056(00)

DATE : 22/08/2019

POLICY NO : 999995580

VEH REG NO : SLA8246H

MAKE/MODEL : TOYOTA ESTIMA AERAS
PREMIUM 2.4 CVT

CHASSIS NO : ACR500194737

ENGINE NO : 2AZ4A19289

REG. DATE : 2015

Estimate Repair Cost to Vehicle No : SLA8246H

Description	Quantity	Unit Price	Amount
		S\$	S\$
			2,430.00
		TOTAL	S\$ 9,794.40
		ADD GST @ 7%	685.61
		GRAND TOTAL	S\$ 10,480.01

SINGAPORE DOLLAR TEN THOUSAND FOUR HUNDRED EIGHTY AND CENTS ONE ONLY

Kenneth Kong take photos ? items
on 28/8/2019 @ 1100 hrs

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Aug 2019		23 Aug 2019 14:07 Edit Adj Rpt	\$7,394.60 Edit Estimates	\$7,394.60 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD., Co. Reg. No.: 199803778Z								
Vehicle Reg. No.:	SLA8246H	Date of Loss:	13/08/2019 09:00 - :59 [40 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 9346289740SG	Policy/Cover Note No.:	0999994159 (Comprehensive) Coverage: 01/01/2019 - 31/12/2019						
		Excess:	S\$1,500.00						
Repairer:	Tong Luck Auto Pte Ltd (HQ) 160 Sin Ming Drive, #07-01 Sin Ming AutoCity, 575722 Sin Ming - Tel: 6250 0088								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Yap, Weijoe] Weijoe.Yap@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 03/09/2019]								
Driver/Customer:	SAMSURI BIN SUMADI (59 / Male) , NRIC: S1349587D, Tel: +6590540260 Email: NOEMAIL								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (02/10/2019): Alert - Adj Mandate Approved (\$7394.60) - SLA8246H - Claim Handler: Yap, Weijoe - AIG_SG (27/08/2019): Alert - Adj Mandate Approved (\$3617.70) - SLA8246H - Claim Handler: Yap, Weijoe - AIG_SG (26/08/2019): SLA8246H / OD / 13/08/2019 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLA8246H (9346289740SG)

OD

Aug 13 2019 9:00AM

[DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.]

Tong Luck Auto Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/08/19 14:21	Adjuster Immediate Advice	 Load HTM	☐
2	25/09/19 11:45	Adjuster Immediate Advice	 Load HTM	☐
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/08/19 15:44	General View	 Load JPG	☒
2	26/08/19 15:44	General View	 Load JPG	☒
3	26/08/19 15:44	General View	 Load JPG	☒
4	26/08/19 15:44	General View	 Load JPG	☒
5	26/08/19 15:44	General View	 Load JPG	☒
6	26/08/19 15:44	General View	 Load JPG	☒
7	26/08/19 15:44	General View	 Load JPG	☒
8	26/08/19 15:44	General View	 Load JPG	☒
9	26/08/19 15:44	General View	 Load JPG	☒
10	26/08/19 15:44	General View	 Load JPG	☒
11	26/08/19 15:44	General View	 Load JPG	☒
12	26/08/19 15:44	General View	 Load JPG	☒
13	26/08/19 15:44	General View	 Load JPG	☒
14	26/08/19 15:44	General View	 Load JPG	☒
15	26/08/19 15:44	General View	 Load JPG	☒
16	26/08/19 15:44	General View	 Load JPG	☒
17	26/08/19 15:44	General View	 Load JPG	☒
18	26/08/19 15:44	General View	 Load JPG	☒
19	26/08/19 15:44	General View	 Load JPG	☒
20	26/08/19 15:44	Odometer Reading	 Load JPG	☒
21	26/08/19 15:44	Chassis Number	 Load JPG	☒
22	26/08/19 15:44	General View	 Load JPG	☒
23	25/09/19 11:32	Reinspection Photo	 Load JPG	☒
24	25/09/19 11:32	Reinspection Photo	 Load JPG	☒
25	25/09/19 11:32	Reinspection Photo	 Load JPG	☒
26	25/09/19 11:32	Reinspection Photo	 Load JPG	☒
27	25/09/19 11:32	Reinspection Photo	 Load JPG	☒
28	25/09/19 11:32	Reinspection Photo	 Load JPG	☒
29	25/09/19 11:32	Reinspection Photo	 Load JPG	☒
30	25/09/19 11:32	Reinspection Photo	 Load JPG	☒
31	25/09/19 11:32	Reinspection Photo	 Load JPG	☒
32	25/09/19 11:32	Reinspection Photo	 Load JPG	☒
33	25/09/19 11:32	Reinspection Photo	 Load JPG	☒
34	25/09/19 11:32	Reinspection Photo	 Load JPG	☒
35	25/09/19 11:32	Reinspection Photo	 Load JPG	☒
36	25/09/19 11:32	Reinspection Photo	 Load JPG	☒
37	25/09/19 11:32	Reinspection Photo	 Load JPG	☒
38	25/09/19 11:32	Reinspection Photo	 Load JPG	☒
39	25/09/19 11:32	Reinspection Photo	 Load JPG	☒
40	25/09/19 11:32	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
41	25/09/19 11:32	Reinspection Photo	 Load JPG	☒
42	25/09/19 11:32	Reinspection Photo	 Load JPG	☒
43	25/09/19 11:32	Reinspection Photo	 Load JPG	☒
44	25/09/19 11:32	Reinspection Photo	 Load JPG	☒
45	25/09/19 11:32	Reinspection Photo	 Load JPG	☒
46	25/09/19 11:32	Reinspection Photo	 Load JPG	☒
47	25/09/19 11:32	Reinspection Photo	 Load JPG	☒
48	25/09/19 11:32	Reinspection Photo	 Load JPG	☒
49	25/09/19 11:32	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/08/19 14:16	ESTIMATE	 Load PDF	
2	26/08/19 15:43	Driver's Driving License	 Load PDF	
3	25/09/19 11:30	SUPPLEMENTARY LIST	 Load PDF	
4	30/09/19 14:44	ESTIMATE	 Load PDF	
5	01/10/19 15:03	supplier's Invoice	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	13/08/19 13:37	Accident Statement	 Load HTM	
2	22/08/19 15:03	Addendum Sheet	 Load TIF	
3	22/08/19 15:10	Accident Statement Addm. #1	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	13/08/19 13:35	Accident Photo	 Load JPG	☒
2	13/08/19 13:35	Accident Photo	 Load JPG	☒
3	13/08/19 13:35	Accident Photo	 Load JPG	☒
4	13/08/19 13:35	Accident Photo	 Load JPG	☒
5	13/08/19 13:35	Accident Photo	 Load JPG	☒
6	13/08/19 13:35	Accident Photo	 Load JPG	☒
7	13/08/19 13:35	Accident Photo	 Load JPG	☒
8	13/08/19 13:35	Accident Photo	 Load JPG	☒
9	13/08/19 13:35	Accident Photo	 Load JPG	☒
10	13/08/19 13:35	Accident Photo	 Load JPG	☒
11	13/08/19 13:35	Driving License	 Load JPG	☒
12	13/08/19 13:35	Identification Card	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	13/08/19 13:35	Sketch Plan	 Load JPG	☒
2	13/08/19 13:36	Common Statement	 Load TIFF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CS/AIG19014849/KQD3E2

Date: 03/10/2019

REFERENCE

Insured/Claimant: DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.

Policy No: 0999994159

Date of Loss: 13/08/2019

Nature of Claim: OD Claim No: 9346289740SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLA8246H**
Make & Model: TOYOTA ESTIMA, 2.4 (A) Engine No: 2AZ4A19289
Reg. Date: 18/03/2016 (Man. Year: 2015) Chassis No: ACR500194737
Colour: Metallic Black Odometer: 50048 km
Engine Capacity: 2362 cc
Market Value/New Car Price: S\$104,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/50 R18 Rear Tyre Size: 225/50 R18
Front Left Side: Yokohama 8 mm Rear Left Side: Dunlop 7 mm
Front Right Side: Yokohama 8 mm Rear Right Side: Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,185.00	6,024.60	2,160.40	26.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,430.00	1,370.00	1,060.00	43.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,615.00	7,394.60	3,220.40	30.34
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	9,115.00	5,894.60	3,220.40	35.33
+ GST 7.00/7.00% (S\$)	638.05	412.62	225.43	35.33
Nett Amount (S\$)	9,753.05	6,307.22	3,445.83	35.33

INSPECTION

Date of Assignment: 23/08/2019

Date Inspected: 23/08/2019 Inspected At:

Tong Luck Auto Pte Ltd (HQ)
160 Sin Ming Drive, #07-01 Sin Ming
AutoCity
Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BONNET (WCP)	Bent	380.00 F	*380.00 F
2	1	*BONNET LOCK (WCP)	Serviceable	68.00 F	*- F
3	1	*BONNET INSULATOR CLIPS (10PCS)(WCP)	Necessary (6Pcs Only)	50.00 F	*30.00 F
4	1	*SUPPORT PANEL (WCP)	Repair	580.00 F	*- F
5	1	*SUPPORT PANEL TOP GARNISH (WCP)	Serviceable	160.00 F	*- F
6	1	*BRACE PANEL (WCP)	Bent	85.00 F	*85.00 F
7	1	*FRONT BUMPER (WCP)	Buckled	480.00 F	*480.00 F
8	1	*FRONT BUMPER REINFORCEMENT (WCP)	Bent	280.00 F	*280.00 F
9	1	*FRONT BUMPER SPONGE (WCP)	Cracked	68.00 F	*68.00 F
10	2	*FRONT BUMPER BRACKET - LH / RH (WCP)	Repair	116.00 F	*- F
11	1	*FRONT BUMPER SIDE RETAINER - LH / RH (WCP)	N/S Distorted	90.00 F	*45.00 F
12	1	*FRONT BUMPER TOWING COVER (WCP)	Dented	32.00 F	*32.00 F
13	1	*FRONT BUMPER LOWER GRILLE (WCP)	Distorted	295.00 F	*295.00 F
14	1	*FRONT BUMPER LOWER GRILLE CHROME (WCP)	Cracked	190.00 F	*190.00 F
15	1	*FRONT BUMPER CLIPS (15PCS)(WCP)	Necessary (10Pcs Only)	75.00 F	*50.00 F
16	1	*FRONT GRILLE ASSY (WCP)	Cracked	320.00 F	*320.00 F
17	1	*FRONT GRILLE EMBLEM (WCP)	Necessary	55.00 F	*55.00 F
18	1	*HEADLAMP ASSY - LH / RH (WCP)	N/S Mtg Cracked	1,900.00 F	*950.00 F
19	1	*RADIATOR ASSY (WCP)	Punctured	800.00 F	*800.00 F
20	1	*AIR-CON CONDENSER (WCP)	Bent / Punctured	580.00 F	*580.00 F
21	2	*RADIATOR COOLANT (TIN)	Necessary	60.00 FS	*60.00 FS
22	1	*FRONT NUMBER PLATE	Bent	40.00 FS	*40.00 FS
23	1	*FRONT BUMPER LOWER BAR (WCP)	Bent	520.00 F	*520.00 F
24	2	*HORN - RH / LH (WCP)	Cracked	170.00 F	*170.00 F
25	2	*RADIATOR GUIDE - RH / LH (WCP)	Cracked	56.00 F	*56.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	7,450.00	5,486.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	735.00	538.60
Total Parts (\$\$)	8,185.00	6,024.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT AIR-CON CONDENSER, PIPES, RADIATOR ASSY, INTER-COOLER ASSY AND REFILL AIR-CON GAS	New	150.00	100.00
2	TO CHECK AND RECTIFY WIRING SYSTEM	New	80.00	20.00
3	TO PANEL BEAT AND STRAIGHTEN FRONT CHASSIS FRAME INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY, TO REFIT AND ADJUST THE SAME	New	1,200.00	500.00
4	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS	New	1,000.00	750.00
Gross Labour Cost (\$\$)			2,430.00	1,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >