

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19014852/UDA3Q2

Date: 30/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700021576

Claimant
Vehicle No : FBG4998J **Insured Vehicle No :** SJX5767T

Date of Loss: 08/08/2019 Nature of Claim: TP Claim No: 3598871556SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBG4998J	Engine No:	B562537
Make & Model:	TRIUMPH TIGER 800, 800cc	Chassis No:	SMTTRE15B8D561335
Reg. Date:	11/08/2012 (Man. Year: 2012)	Odometer:	83331 km
Colour:	White		
Engine Capacity:	800 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/80 R19	Rear Tyre Size:	150/70 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,971.00	4,665.70	1,305.30	21.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	400.00	300.00	100.00	25.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,371.00	4,965.70	1,405.30	22.06
Approved Total (Overridden) (\$\$)		3,950.00		
(\$\$)	6,371.00	3,950.00	2,421.00	38.00
+ GST 7.00/7.00% (\$\$)	445.97	276.50	169.47	38.00
Nett Amount (\$\$)	6,816.97	4,226.50	2,590.47	38.00
+ Loss of Use (3.0 x S\$20.00/day) (\$\$)		60.00		
(\$\$)		4,286.50		
Liabile Amount (50.00%) (\$\$)		2,143.25		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		2,145.25		

INSPECTION

Date of Assignment: 23/08/2019

Date Inspected: 23/08/2019 Inspected At:

Ban Hock Hin Co. Pte Ltd (HQ)
No. 6 Defu Lane 4
Singapore 539410

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOX REAR (TRIUMPH) ASSY	Grazed	985.00 F	*985.00 FL
2	1		*BRACKET COWLING FRONT	Bent	408.00 F	*408.00 FL
3	1		*BRACKET WINSHIELD	Bent	79.00 F	*79.00 FL
4	1		*COVER COWLING FRONT LOWER LH	Cracked	158.00 F	*158.00 FL
5	1		*COVER FRONT BEAK CENTER	Cracked	192.00 F	*192.00 FL
6	1		*COVER SIDE UPPER LH	Cut	118.00 F	*118.00 FL
7	1		*COVER TANK CENTER	Cracked	313.00 F	*313.00 FL
8	1		*CRASH BAR (SWIMOTECH)	Bent	506.00 F	*506.00 FL
9	1		*FOOTREST REAR LH	Cut	118.00 F	*118.00 FL
10	1		*SET GUARD HANDLE (BARKBUSTER)	Cut	299.00 F	*299.00 FL
11	1		*HEADLIGHT ASSY	Cracked	810.00 F	*810.00 FL
12	1		*ION FOOTREST (SW MOTECH)	Cut	142.00 F	*142.00 FL
13	1		*MUDGUARD FRONT	Repair	408.00 F	*- FL
14	1		*PANEL COCKPIT LH	Cut	75.00 F	*75.00 FL
15	1		*PEDAL GEAR (TOURATECH) FOLDABLE	Bent	185.00 F	*185.00 FL
16	1		*PROTECTOR HEADLIGHT KIT	Cracked	153.00 F	*153.00 FL
17	1		*STAND MAIN	Cut	576.00 F	*576.00 FL
18	1		*STAND SIDE	Repair	378.00 F	*- FL
19	1		*STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT	Necessary	12.00 FS	*10.00 FS
20	1		*SUPPORT COVER FRONT BEAK	Cut	56.00 F	*56.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,971.00	5,183.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	517.30
Total Parts (\$\$)	5,971.00	4,665.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR-FOR DISMANTLE AND ASSEMBLING OF PARTS QUOTED	New	400.00	300.00
Gross Labour Cost (\$\$)			400.00	300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >