



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 34638

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
MOTOR CLAIMS DEPT

DATE : 23/08/2019
CLAIM NO. : 11409
POLICY NO. :

FROM : RAYMOND

VEHICLE NO. : FBG4998J
MAKE/MODEL : TRIUMPH / TIGER800 MANUAL

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BOX REAR (TRIUMPH) ASSY	REPLACE	1.00	\$985.00	985.00
2	BRACKET COWLING FRONT	REPLACE	1.00	\$408.00	408.00
3	BRACKET WINSHIELD	REPLACE	1.00	\$79.00	79.00
4	COVER COWLING FRONT LOWER LH	REPLACE	1.00	\$158.00	158.00
5	COVER FRONT BEAK CENTER	REPLACE	1.00	\$192.00	192.00
6	COVER SIDE UPPER LH	REPLACE	1.00	\$118.00	118.00
7	COVER TANK CENTER	REPLACE	1.00	\$313.00	313.00
8	CRASH BAR (SWMOTECH) P/N: 63781	REPLACE	1.00	\$506.00	506.00
9	FOOTREST REAR LH	REPLACE	1.00	\$118.00	118.00
10	GUARD HANDLE (BARKBUSTER) SET	REPLACE	1.00	\$299.00	299.00
11	HEADLIGHT ASSY	REPLACE	1.00	\$810.00	810.00
12	ION FOOTREST (SW MOTECH) P/N: 63793	REPLACE	1.00	\$142.00	142.00
13	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED	REPLACE	1.00	\$400.00	400.00



bizSAFE₃



Address: No. 6, DeFu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-1-0383
ISO 9001:2015

S/N	Description	Action	Qty	Unit Price	Amount
14	MUDGUARD FRONT	REPLACE	1.00	\$408.00	408.00
15	PANEL COCKPIT LH	REPLACE	1.00	\$75.00	75.00
16	PEDAL GEAR (TOURATECH) FOLDABLE	REPLACE	1.00	\$185.00	185.00
17	PROTECTOR HEADLIGHT KIT	REPLACE	1.00	\$153.00	153.00
18	STAND MAIN	REPLACE	1.00	\$576.00	576.00
19	STAND SIDE	REPLACE	1.00	\$378.00	378.00
20	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	REPLACE	1.00	\$12.00	12.00
21	SUPPORT COVER FRONT BEAK	REPLACE	1.00	\$56.00	56.00
SUB TOTAL					\$6,371.00
GST @ 7 %					\$445.97
GRAND TOTAL					\$6,816.97

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

Like Auto Consultants hence notify the following:

- Insurance company after spray painting
- Insurance company (part) during resurvey
- Repairs are subject to confirmation
- This survey is on a "Without Prejudice" basis
- No application is allowed
- Supplemental items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

bizSAFE₃

Address: No. 6, Delu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
 Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO. 2003-14083
 ISO 9001:2008



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

NO. : 34638

- Rev. 4

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
ATTN: MOTOR CLAIMS DEPT

DATE : 23/08/2019
CLAIM NO. : 11409
POLICY NO. :

FROM : RAYMOND

VEHICLE NO. : FBG4998J
MAKE/MODEL : TRIUMPH / TIGER800 MANUAL

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BOX REAR (TRIUMPH) ASSY	REPLACE	1.00	\$985.00	886.50
				Disc %: 10.00	
2	BRACKET COWLING FRONT	REPLACE	1.00	\$408.00	367.20
				Disc %: 10.00	
3	BRACKET WINSHIELD	REPLACE	1.00	\$79.00	71.10
				Disc %: 10.00	
4	COVER COWLING FRONT LOWER LH	REPLACE	1.00	\$158.00	142.20
				Disc %: 10.00	
5	COVER FRONT BEAK CENTER	REPLACE	1.00	\$192.00	172.80
				Disc %: 10.00	
6	COVER SIDE UPPER LH	REPLACE	1.00	\$118.00	106.20
				Disc %: 10.00	
7	COVER TANK CENTER	Replace	1.00	\$313.00	281.70
				Disc %: 10.00	
8	CRASH BAR (SWMOTECH)	REPLACE	1.00	\$506.00	455.40
	P/N: 63781			Disc %: 10.00	
9	FOOTREST REAR LH	REPLACE	1.00	\$118.00	106.20
				Disc %: 10.00	
10	GUARD HANDLE (BARKBUSTER) SET	REPLACE	1.00	\$299.00	269.10
				Disc %: 10.00	
11	HEADLIGHT ASSY	REPLACE	1.00	\$810.00	729.00
				Disc %: 10.00	
12	ION FOOTREST (SW MOTECH)	REPLACE	1.00	\$142.00	127.80
	P/N: 63793			Disc %: 10.00	
13	LABOUR		1.00	\$300.00	300.00
	P/N: 06766				
	- FOR DISMANTLING AND ASSEMBLING OF PARTS				
	QUOTED				

*34638 *

biSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO : 2002-140383
ISO 9001 2015

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
14	PANEL COCKPIT LH	REPLACE	1.00	\$75.00	67.50
				Disc %: 10.00	
15	PEDAL GEAR (TOURATECH) FOLDABLE	REPLACE	1.00	\$185.00	166.50
				Disc %: 10.00	
16	PROTECTOR HEADLIGHT KIT	REPLACE	1.00	\$153.00	137.70
				Disc %: 10.00	
17	STAND MAIN	Replace	1.00	\$576.00	518.40
				Disc %: 10.00	
18	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	REPLACE	1.00	\$10.00	10.00
19	SUPPORT COVER FRONT BEAK	REPLACE	1.00	\$56.00	50.40
				Disc %: 10.00	
SUB TOTAL					\$4,965.70
GST @ 7 %					\$347.60
GRAND TOTAL (SGD)					\$5,313.30

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*34638 *

bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
 Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO. 2002-1-0383
ISO 9001: 2015