Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19014858/EES3Q2

Date: 20/04/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd MCOM0015 Policy No: Claimant PC5603Y Insured Vehicle No: SHB4053R

Vehicle No:

Date of Loss: 12/08/2019 Nature of Claim: TP Claim No: MCT19080224

DESCRIPTION & IDENTIFICATION OF VEHICLE

PC5603Y Reg No:

Make & Model: YUTONG ZK6107HE, 6.7 D (A) Engine No: ISB67E525022189649 Reg. Date: 08/11/2016 (Man. Year: 2016) Chassis No: LZYTBTD63G1041951

Colour: Odometer: 113851 km Multi-colour

Engine Capacity: 6690 cc Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Yes Footbrake (Serviceable): Steering (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification:

CONDITION OF TYRES

Front Tyre Size: Rear Tyre Size: 11 R22.5 11 R22.5 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm Pirelli 6 mm Front Right Side: Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,407.00	621.00	6,786.00	91.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,400.00	2,800.00	1,600.00	36.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,807.00	3,421.00	8,386.00	71.03
Approved Total (Overridden) (S\$)		2,700.00		
(S\$)	11,807.00	2,700.00	9,107.00	77.13
+ GST 7.00/7.00% (S\$)	826.49	189.00	637.49	77.13
Nett Amount (S\$)	12,633.49	2,889.00	9,744.49	77.13
Global Sum S	Settlement (S\$)	0.00		_

INSPECTION

Date of Assignment: 21/08/2019

23/08/2019 Inspected At: Date Inspected: Feida Bus Consortium Pte Ltd (HQ)

6 SUNGEI KADUT WAY

Singapore 728786

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE Manager: Asher Sng Rong Yi Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference					
Part Source:		(Last Synchronised: 19 Apr 2021)			
Parts:	N/A	YUTONG ZK6107HE 6.7 D (A) (Model not available in database)			
Labour:	Repairer's	(Price-denominated Standard List)			
Print Code:	(Unsubmitted, no print-code for PC5603Y)				
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page				
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.					

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LEFT WHEEL ARCH PANEL	Dented	580.00 FL	*580.00 FL
2	1		*REAR LEFT ROCKER PANEL	Repair	620.00 FL	*- FL
3	1		*REAR LEFT LUGGAGE DOOR ASSY	Repair	3,500.00 FL	*- FL
4	1		*REAR LEFT LUGGAGE DOOR LOCK	Cut	110.00 FL	*110.00 FL
5	1		*REAR LEFT INSPECTION LID COVER ASSY	Repair	3,200.00 FL	*- FL
6	2		*REAR LEFT INSPECTION LID COVER LOCK	Not Necessary	220.00 FL	*- FL
F=Fra	ınchise	part. L=ListIt	temDisc List Item Discount on L Items *	Sub Total (S\$)	8,230.00 823.00	690.00 69.00
				Total Parts (S\$)	7,407.00	621.00
	Report was unsubmitted during this print-out.					

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO PUTTY AND SPRAY PAINTING ON REAR RIGHT WHEEL ARCH PANEL ,REAR RIGHT LUGGAGE REAR RIGHT INSPECTION LID COVER ,REAR BUMPER AND ALL AFFECTED ACCIDENT PART	New	2,900.00	1,800.00
2	TO KNOCK /STRAIGHTEN ALL NECESSARY PART INCLUDING REPAIRING AND CHANGING OF ALL DAMAGED PARTS AND ALIGN SAME	New	1,500.00	1,000.00
	Gross Labo	our Cost (S\$)	4,400.00	2,800.00
	Report was unsubmitted du	ring this print-out.		

< END OF ESTIMATES >