



# Feida Bus Consortium Pte Ltd

06 Sungei Kadut Way Singapore 728786

Tel: +656655 6665

Fax: +656655 665

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

BY HAND ONLY

23 August 2019

To: INDIA INTERNATIONAL INSURANCE PTE LTD

c/o : Attending Surveyor

(+65 6225 6371)

Dear Sirs

## THIRD PART CLAIM :- REPAIR ESTIMATE FOR PC 5603 Y

Traffic accident on 12/08/2019 at about 1735 hours along Sungei Kadut Way involving PC 5603 Y and SJW180Z

We append below the repair estimate for PC 5603 D, MODEL : YUTONG ZK6107HE AUTO

### Part required :-

1 pc	Rear right wheel arch panel	left	✓ MD	\$ 580.00
1 pc	Rear right rocker panel	left	✗ R	\$ 620.00
1 pc	Rear right luggage door assy.	left	✗ R	\$ 3500.00
1 pc	Rear right luggage door lock	left	✓ CW	\$ 110.00
1 pc	Rear right inspection lid cover assy.	left	✗ R	\$ 3200.00
2 pcs	Rear left inspection lid cover lock	left	✗	\$ 220.00
				\$ 8230.00
	Less 10% trade discount			\$ 823.00
	Total part cost			\$ 7407.00

### Labour charges:-

To putty and spray painting on rear right wheel arch panel, rear right luggage rear right inspection lid cover, rear bumper and all affected accident part

\$ 2900 1800

To knock/straighten all necessary part including repairing and changing of all damaged parts and align same 350

\$ 1500 1000

Total repair cost

\$ 11807.00

Note:- This estimate is based on visible damage only. Should any hidden parts and/or labour charges required during works in progress, insurer and/or their surveyor will be notified accordingly.

Price quoted is subjected to 7% GST

Encl.



Steve (LKK) NL 14/8/19, 11am  
 8372 8813  
 4 days  
 L/S - 20%  
 Rj Af Sky