



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise in Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading

Dealing In New/Used Cars, Hire Purchase & Insurance.



TP INSURER:
UNKNOWN

India International Insurance Pte Ltd (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	19/08/2019
Vehicle Reg. No.:	SKQ7085P	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PREVIA, 2.4 7-SEATER (A)	Vehicle Reg. Date:	22/12/2014
Vehicle Colour:	GREY	Chassis No:	JTEGD54M30A047042
Engine No:	2AZJ125361		
Odometer:	0 KM		
Paint Type:		Nett Item Discount:	10.00 %
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS	Amount
Parts	1,698.45
Miscellaneous Items	11.00
Labour	1,580.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	3,289.45
+ GST 7.00% (\$\$)	230.26
Nett Amount (\$\$)	3,519.71

This claim is handled by: WEI

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanpin 27495749
WP
4/9/19 @ 220pm
Resurvey after repair
3 days.
Sur C (Khatib) W m

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 22 Aug 2019)**Parts:** M1-MPV TOYOTA PREVIA 2.4 7-seater (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SKQ7085P)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BOOT - REPAIR	25.00	0.00	-
2	1		*REAR BOOT EMBELM	25.00	0.00	re ✓ *72.20 FL
3	1		*REAR BOOT LOGO (TOYOTA)	25.00	0.00	re ✓ *48.00 FL
4	1		*REAR BOOT LOGO (PREVIA)	25.00	0.00	re ✓ *65.95 FL
5	1		*REAR BUMPER	25.00	0.00	re ✓ *629.90 FL
6	2		*REAR TAILLAMP LOWER BRACKET L+R	25.00	0.00	X *118.80 FL
7	2		*REAR BUMPER RETAINER L+R	25.00	0.00	X *137.48 FL
8	1		*REAR PARKING SENSOR	0	0.00	200 ✓ *250.00 FS ?
9	10		*BUMPER CLIPS	25.00	0.00	re ✓ *48.00 FL
10	1		*REAR BUMPER TOW COVER	25.00	0.00	X *16.14 FL
11	2		*REAR REFLECTOR LIGHT L+R	25.00	0.00	X *129.20 FL
12	1		*REAR KEYLESS SENSOR	25.00	0.00	X *192.80 FL
13	1		*REAR END PANEL - REPAIR	25.00	0.00	-
14	1		*REAR END PANEL TOP GARNISH	25.00	0.00	X *292.80 FL
15	2		*SPONGE	25.00	0.00	7 *180.00 FL
Sub Total (S\$)						2,181.27
- List Item Discount on L Items (S\$)						482.82
Total Parts (S\$)						1,698.45

F=Franchise part, S=SpcNett, L=ListItemDisc.

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REPAIR REAR BOOT, REAR END PANEL. TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS & STRAIGHTEN ON ACCIDENT AFFECTED AREAS	New	300. 550.00
2	TO SPRAY PAINT ON ACCIDENT DAMAGED PARTS	New	450. 700.00
3	TO REMOVE & REFIX REAR PARKING SENSOR	New	30 X 80.00
4	TO RUST PROOF ON ACCIDENT DAMAGED PARTS	New	X 60.00
5	TO REMOVE & REFIX REAR SIDE TRIM BOARD, SPARE TYRE AND OTHER ATTACHMENT PARTS	New	40. 150.00
6	TO INSPECT REAR TAILLAMP WATER LEAKAGE	New	X 40.00
Gross Labour Cost (S\$)			1,580.00

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >