



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading
Dealing In New/Used Cars, Hire Purchase & Insurance.



TP INSURER: India International Insurance Pte Ltd (HQ)
UNKNOWN

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	19/08/2019
Vehicle Reg. No.:	SKQ7085P	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PREVIA, 2.4 7-SEATER (A)	Vehicle Reg. Date:	22/12/2014
Vehicle Colour:	GREY	Chassis No:	JTEGD54M30A047042
Engine No:	2AZJ125361		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	25.00 %	Nett Item Discount:	10.00 %
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS

	Amount
Parts	1,698.45
Miscellaneous Items	11.00
Labour	1,580.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	3,289.45
+ GST 7.00% (\$\$)	230.26
Nett Amount (\$\$)	3,519.71

This claim is handled by: WEI

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Aug 2019)
Parts:	M1-MPV	TOYOTA PREVIA 2.4 7-seater (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKQ7085P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BOOT - REPAIR	25.00	0.00	-
2	1		*REAR BOOT EMBELM	25.00	0.00	*72.20 FL
3	1		*REAR BOOT LOGO (TOYOTA)	25.00	0.00	*48.00 FL
4	1		*REAR BOOT LOGO (PREVIA)	25.00	0.00	*65.95 FL
5	1		*REAR BUMPER	25.00	0.00	*629.90 FL
6	2		*REAR TAILLAMP LOWER BRACKET L+R	25.00	0.00	*118.80 FL
7	2		*REAR BUMPER RETAINER L+R	25.00	0.00	*137.48 FL
8	1		*REAR PARKING SENSOR	0	0.00	*250.00 FS
9	10		*BUMPER CLIPS	25.00	0.00	*48.00 FL
10	1		*REAR BUMPER TOW COVER	25.00	0.00	*16.14 FL
11	2		*REAR REFLECTOR LIGHT L+R	25.00	0.00	*129.20 FL
12	1		*REAR KEYLESS SENSOR	25.00	0.00	*192.80 FL
13	1		*REAR END PANEL - REPAIR	25.00	0.00	-
14	1		*REAR END PANEL TOP GARNISH	25.00	0.00	*292.80 FL
15	2		*SPONGE	25.00	0.00	*180.00 FL
						Sub Total (\$\$)
						2,181.27
						- List Item Discount on L Items (\$\$)
						482.82
						Total Parts (\$\$)
						1,698.45

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (\$\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REPAIR REAR BOOT, REAR END PANEL. TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS & STRAIGHTEN ON ACCIDENT AFFECTED AREAS	New	550.00
2	TO SPRAY PAINT ON ACCIDENT DAMAGED PARTS	New	700.00
3	TO REMOVE & REFIX REAR PARKING SENSOR	New	80.00
4	TO RUST PROOF ON ACCIDENT DAMAGED PARTS	New	60.00
5	TO REMOVE & REFIX REAR SIDE TRIM BOARD,SPARE TYRE AND OTHER ATTACHMENT PARTS	New	150.00
6	TO INSPECT REAR TAILLAMP WATER LEAKAGE	New	40.00
Gross Labour Cost (\$\$)			1,580.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >