

SJE : LKK - Mr Lim
 Date of Survey :
 Date of ReSurvey: After-Paint:
 Contacts :
 Vehicle Nos : JLU 2415
 Model : Nissan Grand Livina
 Year : 2009
 Chassis No : PN888AL10TCA71933

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: Working Day:

Nos.	NETT ITEM	Qty	Unit S\$	TOTAL S\$	
1	Bonnet	1	\$ 991.90	\$ 991.90	DDV ✓
2	Bonnet hinges	2	\$ 61.80	\$ 123.60	SVC
3	Bonnet insulator	1	\$ 194.70	\$ 194.70	NA
4	Bonnet inner lock	1	\$ 113.20	\$ 113.20	DDV ✓
5	Bonnet safety lock lever	1	\$ 89.10	\$ 89.10	DDV ✓
6	Bonnet safety lock lever cable	1	\$ 50.90	\$ 50.90	DDV ✓
7	Bonnet safety lock lever bracket	1	\$ 113.70	\$ 113.70	DDV ✓
8	Front grille base	1	\$ 430.30	\$ 430.30	BRV ✓
10	Front grille logo	1	\$ 89.70	\$ 89.70	NECV
12	Headlamp	2	\$ 849.20 2,929.70	\$ 1698.40 5,859.40	BRV ✓
13	Headlamp lower bracket	2	\$ 57.50	\$ 115.00	SVC
14	Headlamp panel	2	\$ 105.20	\$ 210.40	RX
15	Front bumper	1	\$ 734.70	\$ 734.70	BRV ✓
16	Front bumper side retainer	2	\$ 50.90	\$ 101.80	NECV ✓
17	Front bumper centre grille	1	\$ 199.50	\$ 199.50	BRV ✓
19	Front bumper fog lamp	2	\$ 381.60	\$ 763.20	BRV ✓
20	Front bumper fog lamp garnish	2	\$ 102.90	\$ 205.80	X Reuse
23	Front bumper tow cover	1	\$ 40.30	\$ 40.30	DL ✓
25	Front bumper reinforcement	1	\$ 553.10	\$ 553.10	BT ✓
27	Front bumper emblem "impul"	1	\$ 60.00	\$ 60.00	NECV ✓
28	Front fender RH	1	\$ 683.40	\$ 683.40	X Reuse
29	Front fender arch garnish LH	1	\$ 102.90	\$ 102.90	BRV ✓
30	Front fender inner shield	2	\$ 141.60	\$ 283.20	X Reuse
31	Front fender inner panel	2	\$ 281.90	\$ 563.80	X Reuse
32	Radiator	1	\$ 1,200.00	\$ 1,200.00	SVC X
33	Condenser	1	\$ 1,350.20	\$ 1,350.20	BT ✓
Nett Item Total :				\$ 16,010.10	
30% Net Discount :				\$ 4,803.03	
PARTS TOTAL :				\$ 11,207.07	

7066.60
 @ 30% 2119.98
 4946.62

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
1	Sundries	1	\$ 60.00	\$ 60.00	X NA
2	Washer tank	1	\$ 251.90	\$ 251.90	DIS ✓
3	Washer tank filler hose	1	\$ 71.90	\$ 71.90	SVC

251.90

4	Washer tank motor	1	\$	116.20	\$	116.20	SVC
5	Front air guide	2	\$	60.50	\$	121.00	SVC
6	Coolant	1	\$	80.00	\$	50.00 80.00	NEL
7	Aircon gas	1	\$	120.00	\$	80.00 120.00	NEC
8	Car plate	2		\$80	\$	50.00 160.00	BR
9	Bonnet insulator clips	1	\$	60.00	\$	30 60.00	XReuse
10	Front grille clips	1	\$	40.00	\$		NEC
11	Front bumper clips	1	\$	60.00	\$	40.00 60.00	
12	Front bumper lower splash shield clips	1	\$	50.00	\$	50.00	Reuse
13	Front fender arch garnish clips	2	\$	35.00	\$	30.00 70.00	
14	Front fender inner shield clips	2	\$	40.00	\$	80.00	XReuse

SPECIAL NETT TOTAL : \$ 1,341.00

541.90

Nos.	LABOUR		\$
1	To Panel beating, Straighten & Realign Accident Damage Portion	\$	1,200.00
2	Check wiring	\$	50.00 100.00
3	To Spray Accident Damage Portion	\$	1,200.00
4	Mount Work Bench	\$	350.00
5	Chasis Alignment	\$	350.00
6	Rust proofing	\$	60.00 200.00
7	To R&R Condenser	\$	80.00 150.00
8	To R&R Radiator	\$	80.00 150.00
9	To R&R Aircon And Refill Air Con Gas	\$	40.00 150.00
10	Test Drive	\$	50.00
11	Grooming and car wash	\$	30.00
LABOUR TOTAL :		\$	3,930.00

PARTS TOTAL : \$ 4946.62 11,207.07
SPECIAL NETT TOTAL : \$ 541.90 1,341.00
LABOUR TOTAL : \$ 1910.00 3,930.00
GRAND TOTAL : \$ 7398.52 16,478.07

Survey on 23/8/19
TCU m

Lump sum repair
Repair days 6

7398.52
@ 20% 1479.70
5918.82

4/3 5900/2

TCU m
30/8/19

Resurvey on 26/8/19
TCU m

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: