

XINYA AUTO SERVICES PTE LTD

Add: BLK 1002 BUKIT MERAH LANE 3 #01-75 SINGAPORE 159719

E-mail : xinyaauto@singnet.com.sg

Tel: 6270 3481 Fax: 6278 7522

Date : 22/08/19

Address : MR TEO LUM SENG
BLK 151 PETIR ROAD
#05-180
SINGAPORE 670151

Reference : TP 1218/08/19
Vehicle No : SLF 4827G
Make/Model : SUB.FORESTOR
Insurance Co. : DIRECT ASIA

RE : QUOTATION REPAIRS TO SLF 4827G FOR THIRD PARTY CLAIMS.

PARTS REQUIRED

		QTY	AMT \$
1)	REAR BUMPER <i>TORW /</i>	1	\$ 600.30
2)	REAR BUMPER ENFORCEMENT <i>bt /</i>	1	\$ 320.30
3)	REAR BUMPER BRACKET <i>nee /</i>	2	\$ 40.60
4)	REAR BUMPER RETAINER <i>LH nee /</i>	<i>21pc</i>	\$ <i>614.30</i> 32.60
5)	REAR BUMPER REFLECTOR <i>cm /</i>	1	\$ 22.80
6)	REAR TAIL GATE <i>bt /</i>	1	\$ 1,072.30
7)	REAR TAIL GATE WEATHERSTRIPE <i>nee /</i>	1	\$ 120.30
8)	REAR TAIL GATE LOCK <i>X</i>	1	\$ <i>176.40</i>
9)	REAR WINDSCREEN SEALANT <i>nee /</i>	1	\$ 30.80
10)	REAR WINDSCREEN CLIPS <i>nee /</i>	4	\$ 42.80
11)	"SUBARU" LOGO <i>nee /</i>	1	\$ 72.30
12)	"4WD" EMBLEM <i>nee /</i>	1	\$ 68.05
13)	"SUBARU" EMBLEM <i>nee /</i>	1	\$ 72.30
14)	"XTI" EMBLEM <i>nee /</i>	1	\$ 72.30
15)	END PANEL <i>bt /</i>	1	\$ 320.00
16)	END PANEL GARNISH <i>X</i>	1	\$ <i>40.30</i>
17)	FRONT BUMPER <i>cm /</i>	1	\$ 594.55
18)	FRONT BUMPER ENFORCEMENT <i>bt /</i>	1	\$ 320.30
19)	FRONT BUMPER RETAINER <i>LH nee /</i>	<i>21pc</i>	\$ <i>620.30</i> 40.60
20)	FRONT BUMPER WATER NOZZLE <i>?</i>	1	\$ <i>79.20</i>
21)	FRONT BUMPER WATER NOZZLE COVER <i>ms /</i>	1	\$ 54.30
22)	FRONT GRILLE <i>sc /</i>	1	\$ 308.30
23)	FRT GRILLE BASE <i>?</i>	1	\$ <i>260.80</i>
24)	FRONT HEADLAMP LEFT <i>cm /</i>	1	\$ 2,400.30
25)	NOS PLATE HOLDER <i>X</i>	1	\$ <i>150.80</i>
26)	SPARE TYRE PANEL <i>repair</i>	1	\$ <i>432.50</i>
27)	FRONT LH FENDER <i>repair</i>	1	\$ <i>458.60</i>
28)	FENDER SPLASH GUARD <i>X</i>	1	\$ <i>102.00</i>
LIST PRICE TOTAL			\$ 8,306.70
LESS DISCOUNT 10%			\$ 830.67
LIST PRICE TOTAL AFTER LESS			\$ 7,476.03
26)	NOS PLATE WITH CASING <i>bt /</i>		\$ <i>38</i> 50.00
NETT PRICE TOTAL			\$50.00

TOTAL PARTS COST**\$7,526.03****LABOUR AND MISCELLANEOUS CHARGES**

- | | | | |
|----|--|----|-------------------------------------|
| 1) | TO REMOVE & REPLACE FRONT BUMPER & REAR BUMPER, FENDER, FRT & REAR ENFORCEMENT, TAIL GATE, HEADLAMP AND TO PANEL BEAT AND ALIGN. | \$ | 2,000.00 1400
10 DAYS |
| 2) | TO PUTTY & SPRAY PAINT FRONT & REAR BUMPER, FENDER, REAR TAIL GATE (INNER & OUTER), END PANEL, SPARE TYRE PANEL & OTHER AFFECTED AREA. | \$ | 1,800.00 1400
9 PANEL |
| 3) | TO REMOVE & REFIT REAR SIDE BOARD, GARNISH TO ENABLE HOT WORKS TO SPARE TYRE PANEL | \$ | 350.00 80 |
| 4) | TO REMOVE & FIT WINDSCREEN GLASS TO NEWS TAIL GATE AND CHECK FOR WATER TIGHT. | \$ | 150.00 120 |
| 5) | TO CHECK & RECTIFY WIRING AND FOCUS HEADLAMP | \$ | 60.00 30 |
| 6) | TUFF KOTE | \$ | 350.00 120 |

LABOUR TOTAL**\$ 4,710.00****TOTAL ESTIMATED REPAIR COST****\$ 12,186.03***Rasul**Hp 90010018**12 days**P/P**23/08/19 @ 1130**Resin before paint*