

Winto Tm

XINYA AUTO SERVICES PTE LTD

Add: BLK 1002 BUKIT MERAH LANE 3 #01-75 SINGAPORE 158719

E-mail: xinyaauto@singnet.com.sg

Tel: 6270 3481 Fax: 6278 7522

Date : 22/08/19

Address : MR TEO LUM SENG
BLK 151 PETIR ROAD
#05-180
SINGAPORE 670151

Reference : TP 1218/08/19
Vehicle No : SLF 4827G
Make/Model : SUB.FORESTOR
Insurance Co. : DIRECT ASIA

RE : QUOTATION REPAIRS TO SLF 4827G FOR THIRD PARTY CLAIMS.

PARTS REQUIRED		QTY	AMT \$
1)	REAR BUMPER <i>TDW /</i>	1	\$ 600.30
2)	REAR BUMPER ENFORCEMENT <i>bt /</i>	1	\$ 320.30
3)	REAR BUMPER BRACKET <i>re /</i>	2	\$ 40.60
4)	REAR BUMPER RETAINER <i>LH re /</i>	<i>21pc</i>	\$ <i>016.30</i> 32.60 16.30
5)	REAR BUMPER REFLECTOR <i>CM /</i>	1	\$ 22.80
6)	REAR TAIL GATE <i>bt /</i>	1	\$ 1,072.30
7)	REAR TAIL GATE WEATHERSTRIPE <i>re /</i>	1	\$ 120.30
8)	REAR TAIL GATE LOCK <i>X SUC</i>	1	\$ 176.40 X
9)	REAR WINDSCREEN SEALANT <i>re /</i>	1	\$ 30.80
10)	REAR WINDSCREEN CLIPS <i>re /</i>	4	\$ 42.80
11)	"SUBARU" LOGO <i>re /</i>	1	\$ 72.30
12)	"4WD" EMBLEM <i>re /</i>	1	\$ 68.05
13)	"SUBARU" EMBLEM <i>re /</i>	1	\$ 72.30
14)	"XTI" EMBLEM <i>re /</i>	1	\$ 72.30
15)	END PANEL <i>bt repair</i>	1	\$ 320.00 X
16)	END PANEL GARNISH <i>X SUC</i>	1	\$ 40.30 X
17)	FRONT BUMPER <i>CM /</i>	1	\$ 594.55
18)	FRONT BUMPER ENFORCEMENT <i>bt /</i>	1	\$ 320.30
19)	FRONT BUMPER RETAINER <i>LH re /</i>	<i>21pc</i>	\$ <i>620.30</i> 40.60 20.30
20)	FRONT BUMPER WATER NOZZLE <i>? X SUC</i>	1	\$ 79.20 X
21)	FRONT BUMPER WATER NOZZLE COVER <i>re /</i>	1	\$ 54.30
22)	FRONT GRILLE <i>SCA /</i>	1	\$ 308.30
23)	FRT GRILLE BASE <i>? X SUC</i>	1	\$ 260.80 X
24)	FRONT HEADLAMP LEFT <i>CM /</i>	1	\$ 2,400.30
25)	NOS PLATE HOLDER <i>X SUC</i>	1	\$ 150.80 X
26)	SPARE TYRE PANEL <i>repair</i>	1	\$ 432.50 X
27)	FRONT LH FENDER <i>repair</i>	1	\$ 458.60 X
28)	FENDER SPLASH GUARD <i>X SUC</i>	1	\$ 102.00 X
LIST PRICE TOTAL			\$ 8,306.70
LESS DISCOUNT <i>10% 20%</i>			\$ 830.67
LIST PRICE TOTAL AFTER LESS			\$ 7,476.03

26)	NOS PLATE WITH CASING <i>bt /</i>	\$ 38 50.00
NETT PRICE TOTAL		\$50.00

6249.50
20%
4999.60

35

TOTAL PARTS COST

\$7,528.03

LABOUR AND MISCELLANEOUS CHARGES

- | | | | |
|----|--|----|----------------------------|
| 1) | TO REMOVE & REPLACE FRONT BUMPER & REAR BUMPER, FENDER, FRT & REAR ENFORCEMENT, TAIL GATE, HEADLAMP AND TO PANEL BEAT AND ALIGN. | \$ | 2,080.00 / 1400
10 DAYS |
| 2) | TO PUTTY & SPRAY PAINT FRONT & REAR BUMPER, FENDER, REAR TAIL GATE (INNER & OUTER), END PANEL, SPARE TYRE PANEL & OTHER AFFECTED AREA. | \$ | 1,880.00 / 1400
9 PANEL |
| 3) | TO REMOVE & REFIT REAR SIDE BOARD, GARNISH TO ENABLE HOT WORKS TO SPARE TYRE PANEL | \$ | 350.00 / 80 |
| 4) | TO REMOVE & FIT WINDSCREEN GLASS TO NEWS TAIL GATE AND CHECK FOR WATER TIGHT. | \$ | 150.00 / 20 |
| 5) | TO CHECK & RECTIFY WIRING AND FOCUS HEADLAMP | \$ | 60.00 / 30 |
| 6) | TUFF KOTE | \$ | 350.00 / 20 |

3150

LABOUR TOTAL

\$ 4,710.00

TOTAL ESTIMATED REPAIR COST

\$ 12,188.03

4999.60

35.00

3150.00

8184.60

12 days

Rahul

Hp 900/100/18

12 days

P/P

23/08/19 @ 1130

Ready before paint