

ASS. REC. B.Y:

REF: CS/FCI19014870/ KSD3/12

Special Instruction:

Signature: Kenneth

ASSIGNMENT (Office)

From (Person): Sitharera of FCI Date/Time: 9:07am @ 23/8/19

Estimated Cost: Bill to:

OD TP WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLQ15B Insured: SHB357SH

at Workshop in/s: Optima Werkz Tel: 04811522

of: 6 Kung Chong Road

Policy No: Claim No: D1900543SMFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 21/08/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS ^{wp} H.O.D. Endorsement:

Date/Time: 12:13pm @ 23/8/19 Person Contacted: Lily Vehicle IN OUT

Date/Time	Action/Instruction	John? (✓)
	SLQ15B - NA / CI19014739/h+	DOA: 21/08/2019
	SHB 357SH - NA / CI19014739/h+	DOA: 21/8/2019
29/08/19	@ 15:23 pm	received PA to Sitharera via email.

REP: FCI

ASS. REC. BY:

ASSIGNMENT

From: _____ Date: 28/8/2019

Veh No: SLQ 15B Yr Regn: 11, 17

Estimated Cost: _____

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: SLQ 15B

Make: M 300 AMG-c.c 1991

at Workshop m/s Optima werkz

Colour: M-Black A/C: Insured / Std / NI / NA

of 9A Serangoon North Ave S

Sp. Reading: 41099 T/Radio: Insured / Std / NI / NA

Insured: _____

Eng/No: _____

Policy No. _____

C/No: WDD 2383482F 010707

Claims No. _____

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: _____

Excess: _____

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh: 10am (waiting)

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 245/40R19

R: 275/35R19

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value: 5190k

Front

Rear

IDAC Accident Rpt: _____ Consistent?: Yes or No

R/Bal. 8 mm

R/Bal. 8 mm

GIA / PR Seen: _____ Consistent?: Yes or No

L/Bal. 8 mm

L/Bal. 8 mm

Est. Repairs: 03 days Res.: Yes or No

D.O.A. 21/8/19

D.O.I. 28/8/19

Lum Sum: 1.3.1 % 3 Val.: Yes or No

Survey held at _____

CA / REV / REP. / 24 HRS ^{1up}

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
12/9	4316.50 email & confirm (5450/- Red - 9%)

RECEIVED 13 SEP 2019

Date/Time, File Pass to?

: Preli. Report

Days Of Repair: 3

1) 13/09/19 Typ: 54

: Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to?

Survey Fee:

2) _____

Add Fee: : Site Insp (\$)

Transportation:

Report Format:

: Interview (\$)

Photos:

Lump Sum (L.S.): 4,316.50 P/P

: Tech. Invs (\$)

Others:

: Weekend (\$)

TOTAL

303

135
50
50+50
18
TOTAL
303



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19005435MFSH

Date: 29 August 2019

Our Ref: CS/FCI19014870/Ksd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLQ 15B .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 28/08/2019 at the premises of M/s Optima Werkz Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ 4,766.50 .
Revised Estimate Amount	: S\$ 2,541.55 .
"Check" Items Amount	: S\$ 1,924.95 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the n/s rear portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 2 days

Yours faithfully

Kenneth Kong
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	22-08-2019	Our Ref No. D19005435MFSH
Accident Date	21-08-2019	Claim Type. Third Party
Insured Vehicle	SHB3575H	Third Party Vehicle. SLQ15B
Survey Location	6 KUNG CHONG ROAD	
Contact Person.	SHARON TEN (MS.)	
Contact No.	64811522/ 0	Fax No. 64811011
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	OPTIMA WERKZ PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Re: SURVEY ASSESSMENT - D19005435MFSH/1

Shirley Hiew (LKK Auto)

Thu 29/8/2019 3:23 PM

To: 'Sithara' <Sithara@msfirstcapital.com.sg>; 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>
Cc: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>

📎 1 attachments (80 KB)

PRELI ADVISE - SLQ 15B.pdf;

Dear Sithara,

Enclosed preliminary revised of vehicle SLQ 15B.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte LtdPhone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>**Sent:** Friday, 23 August 2019 12:17 PM**To:** 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>**Cc:** 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>**Subject:** RE: SURVEY ASSESSMENT - D19005435MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards

G.NIVITHA**LKK Auto Consultants Pte Ltd**Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Friday, 23 August 2019 9:07 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19005435MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	568M
Vehicle Details	
Vehicle No.:	SLQ15B
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Aug 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E300 AMG
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	27492031074005
Chassis No.:	WDD2383482F010707
Maximum Power Output:	180.0 kW (241 bhp)
Open Market Value:	\$70,328.00
Original Registration Date:	29 Nov 2017
First Registration Date:	29 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$98,591.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Nov 2027
PARF Rebate Amount:	\$73,943.00
Intended COE Rebate Details	
COE Expiry Date:	28 Nov 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,414.00
COE Rebate Amount:	\$47,462.00
Total Rebate Amount:	\$121,405.00

The information contained herein is correct as at 22 Aug 2019

OK

Date: 23.08.2019
Vehicle No: SLQ15B
Model: MERCEDES BENZ E300
Chassis: WDD2383482F010707 - 2017
Reg.Year: 2017

Third Party Insurer: FIRST CAPITAL
Third Party Veh No: SHB3575H
Date of Accident: 21.08.2019

*Not Auth with
2 days*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR ALLOY RIM LH		<i>net</i>	\$2,086.50
2	REAR WHEEL BEARING LH			\$207.00
3	REAR KNUCKLE ARM LH			\$1,598.50
4	REAR TYRE TUBE VALVE LH	1		<i>re</i> \$15.00
5	REAR BUMPER CLIPS	12	\$6.50	<i>re</i> \$78.00
6	REAR BUMPER			REPAIR
7	REAR QUARTER PANEL LH			REPAIR
SUB TOTAL				\$3,985.00
LESS 10%				-\$398.50
PARTS TOTAL				\$3,586.50

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR & READJUST REAR UNDERCARRIAGE REAR KNUCKLE ARM LH, REAR TRAILING ARM, REAR WHEEL BEARING & ETC. BACK TO ORIGINAL OPERATIONS

no \$300.00 *200?*

LABOUR CHARGES TO REPAIR, READJUST REAR BUMPER, REAR QUARTER PANEL LH & ETC BACK TO PROPER CONDITIONS

no \$200.00 *150*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER, REAR QUARTER PANEL & ETC

\$600.00 *400*

TO CHECK WHEEL ALIGNMENT & BALANCING

\$80.00 *300*

LABOUR TOTAL \$1,180.00

ONG

LKK Auto Consultants hence notify

the Repairer of the following: **TOTAL**

\$4,766.50

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No direct introduction is allowed
- Supplementary work must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer:

Signature:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 Fax: (+65) 6452 9223



Ks

Date: 23.08.2019
Vehicle No: SLQ15B
Model: MERCEDES BENZ E300
Chassis: WDD2383482F010707 - 2017
Reg. Year: 2017

Third Party Insurer: FIRST CAPITAL
Third Party Veh No: SHB3575H
Date of Accident: 21.08.2019
Not with work

ESTIMATE

2 days
4316.50

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR ALLOY RIM LH		<i>net</i>	\$2,086.50 ✓
2	REAR WHEEL BEARING LH		<i>net</i>	\$207.00 ✓
3	REAR KNUCKLE ARM LH		<i>net</i>	\$1,598.50 ✓
4	REAR TYRE TUBE VALVE LH	1		<i>net</i> \$15.00 ✓
5	REAR BUMPER CLIPS	12	\$6.50	<i>net</i> \$78.00 ✓
6	REAR BUMPER			REPAIR ✓
7	REAR QUARTER PANEL LH			REPAIR ✓
SUB TOTAL				\$3,985.00 ✓
LESS 10%				-\$398.50 ✓
PARTS TOTAL				\$3,586.50 ✓

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR & READJUST REAR UNDERCARRIAGE REAR KNUCKLE ARM LH, REAR TRAILING ARM, REAR WHEEL BEARING & ETC. BACK TO ORIGINAL OPERATIONS

200
150
300.00

LABOUR CHARGES TO REPAIR, READJUST REAR BUMPER, REAR QUARTER PANEL LH & ETC BACK TO PROPER CONDITIONS

200
150
200.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER, REAR QUARTER PANEL & ETC

600.00

TO CHECK WHEEL ALIGNMENT & BALANCING

80.00

LABOUR TOTAL \$1,180.00

ONG **TOTAL \$4,766.50**

part - 3586.50
labour - 1180.00
p/p 4766.50

ACCEPT
ONE HALF





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19014870/Ksd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 13-09-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 3575H	Veh. Inspected	SLQ 15B
Policy No.		Coverage (\$)	0.00
Claim No.	D19005435MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	23/08/2019
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES E300 AMG (A)	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WDD2383482F010707	Colour	METALLIC BLACK
Odometer	41099	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	245/40 ZR19	MICHELIN	8 mm
L/H Front Tyre	245/40 ZR19	MICHELIN	8 mm
R/H Rear Tyre	275/35 ZR19	MICHELIN	8 mm
L/H Rear Tyre	275/35 ZR19	MICHELIN	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	21/08/2019	Inspection Date	28/08/2019
Survey held at	OPTIMA WERKZ PTE LTD 6, KUNG CHONG ROAD SINGAPORE 159143		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 15B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR ALLOY RIM LH	DENTED	2,086.50	2,086.50
1	REAR WHEEL BEARING LH	NECESSARY	207.00	207.00
1	REAR KNUCKLE ARM LH	BENT	1,598.50	1,598.50
1	REAR TYRE TUBE VALVE LH	NECESSARY	15.00	15.00
12	REAR BUMPER CLIPS @\$6.50	NECESSARY	78.00	78.00
1	REAR BUMPER (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR QUARTER PANEL LH (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 10% DISCOUNT		-398.50	-398.50
			3,586.50	3,586.50
	<u>LABOUR</u>			
	LABOUR CHARGES TO REMOVE, REPLACE, REPAIR & READJUST REAR UNDERCARRIAGE, REAR KNUCKLE ARM LH, REAR TRAILING ARM, REAR WHEEL BEARING & ETC. BACK TO ORIGINAL OPERATIONS. INCLUSIVE OF THE REPAIR OF REAR BUMPER AND REAR QUARTER PANEL LH.		300.00	150.00
	LABOUR CHARGES TO REPAIR, READJUST REAR BUMPER, REAR QUARTER PANEL LH & ETC BACK TO PROPER CONDITIONS.		200.00	150.00
	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER, REAR QUARTER PANEL & ETC.		600.00	400.00
	TO CHECK WHEEL ALIGNMENT & BALANCING.		80.00	30.00
			1,180.00	730.00
	GRAND TOTAL		4,766.50	4,316.50
RECOMMENDED COST OF REPAIRS				4,316.50

Report Ref No. CS/FCI19014870/Ksd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.