



Case Details

Case Reference Number : TAX/08/19/2075
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB5717C

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-8168-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AXA Insurance Singapore Pte Ltd
 Accident Date and Time : 22/08/2019 04:40 AM
 Vehicle Age(In Months) : 22

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace ▾	ACC
One Time Key In	Main			PANEL SUB-ASSY, REAR DOOR , LH	1	1,243.90	1,243.90	25.00	932.93	Replace	1	0	Repair ▾	X R
One Time Key In	Main			MOULDING ASSY, BODY ROCKER PANEL , LH	1	576.00	576.00	25.00	432.00	Replace	1	0	Repair ▾	X R
One Time Key In	Main			PANEL SUB-ASSY, FENDER REAR LH	1	824.80	824.80	25.00	618.60	Replace	1	0	Repair ▾	X R
One Time Key In	Main			LINER, REAR FENDER , LH	1	135.80	135.80	25.00	101.85	Replace	0	0	Not Givr ▾	X N/A
One Time Key In	Main			WHEEL, DISC	1	1,555.10	1,555.10	25.00	1,166.32	Replace	1	0	Repair ▾	X R
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	0	Repair ▾	X R
One Time Key In	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	0	0	Not Givr ▾	X N/A
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	0	0	Not Givr ▾	X N/A

Total Spare Part Cost 4,675.35

Surveyor Total 214.88

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 4,675.35

Final Sur Total 214.88

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			RETAINER, RR BUMPER, LH	1	111.50	111.50	25.00	83.63	Replace	1	83.63	Replace ▾	✓ OR
One Time Key In	Main			SEAL, RR BUMPER, LH	1	85.20	85.20	25.00	63.90	Replace	0	0	Not Given ▾	✗ N/A
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace ▾	✓ APC
One Time Key In	Main			FILLER, RR BUMPER, LH	1	119.90	119.90	25.00	89.93	Replace	0	0	Not Given ▾	✗ N/A
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Given ▾	✗ N/A
Total Spare Part Cost									4,675.35	Surveyor Total		214.88		
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		0		
Final Spare Part Cost									4,675.35	Final Sur Total		214.88		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR LEFT REAR PORTION	507.00	300	
Total:			507.00	300.00	


Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY REAR DOOR LH	378.00	200	
2	Main	TO RESPRAY FRONT FENDER LH	378.00	200	Correct Rear LH Fender
3	Main	TO RESPRAY RIM	180.00	50	
4	Main	TO RESPRAY REAR BUMPER	378.00	200	
5	Main	TO RESPRAY ROCKER PANEL MOULDING	180.00	150	
Total:			1,494.00	800.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0	
2	Main	TO REPLACE SUNDRY PARTS	80.00	20	nlc
3	Main	TO CHECK WIRING AND SYSTEM FUNCTION	100.00	20	nlc
4	Main	TO TRANSFER DOOR MECHANISM	120.00	0	
5	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0	
Total:			480.00	40.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	4,675.35	214.88
Total Labour Cost	507.00	300.00
Total Spray Painting	1,494.00	800.00
Other	480.00	40.00
Overall Total	7,156.35	1,354.88
Lump Sum Repair Option		
Lump Sum Total	0.00	1,354.88
Surveyor Approved Amount		1,354.88
No of Repair Days*	5	3
Remarks	-	P/P repair, take before spray. Finalize sent to stevechen@lkkauto.com
Surveyor Name		STEVE CHEN
Signature		
Survey Date	23/08/2019	

Save

Clear

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: