

SHB 5717C

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1909-0412	Invoice Number	
Quotation Date	23.09.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LEFT REAR PORTION	\$507.00	\$300.00 ✓
Total Labour	\$507.00	\$300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR DOOR LH	\$378.00	\$200.00 ✓
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00 ✓
TO RESPRAY RIM	\$180.00	\$50.00 ✓
TO RESPRAY REAR BUMPER	\$378.00	\$200.00 ✓
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$150.00 ✓
Total Spray Painting & Panel Beating	\$1,494.00	\$800.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00 X
TO REPLACE SUNDRY PARTS	\$80.00	\$20.00 ✓
TO CHECK WIRING AND SYSTEM FUNCTION	\$100.00	\$20.00 ✓
TO TRANSFER DOOR MECHANISM	\$120.00	\$0.00 X
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00 X
Total Other Costs	\$480.00	\$40.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace ✓
		67004472 10	PANEL SUB-ASSY, REAR DOOR, LH	1.00	\$1,243.90	100.00	\$0.00	Replace	Repair R X
		75660479 00	MOULDING ASSY, BODY ROCKER PANEL, LH	1.00	\$576.00	100.00	\$0.00	Replace	Repair R X
		61602471 60	PANEL SUB ASSY, FENDER REAR LH	1.00	\$824.80	100.00	\$0.00	Replace	Repair R X
		65638470 60	LINER, REAR FENDER, LH	0.00	\$135.80	0.00	\$0.00	Replace	Not Given X
		42611474 50	WHEEL, DISC	1.00	\$1,555.10	100.00	\$0.00	Replace	Repair R X
		52159479 13	COVER, RR BUMPER ASSY	1.00	\$423.90	100.00	\$0.00	Replace	Repair R X
		52023470 30	REAR BUMPER REINFORCEMENT	0.00	\$318.80	0.00	\$0.00	Replace	Not Given X
		52159479 13	COVER, RR BUMPER ASSY	0.00	\$423.90	0.00	\$0.00	Replace	Not Given X
		52576470 40	RETAINER, RR BUMPER, LH	1.00	\$111.50	25.00	\$83.63	Replace	Replace ✓
		52592470 40	SEAL, RR BUMPER, LH	0.00	\$65.20	0.00	\$0.00	Replace	Not Given X
		52161160 10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace ✓



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park Ea, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68652623
Accident Reporting Number : 68662872

Date Generated : 23/09/2019

User ID : PohSuen

		52566479 00	FILLER, RR BUMPER, LH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given	X	mm
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	X	mm
Total					\$6,060.30		\$214.88				

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

8,614.80#

$$\begin{array}{r} 214.88 \\ + 300.00 \\ + 840.00 \\ \hline 1354.88 \end{array}$$