

Cecilia

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

23/08/2019 13:53

JOB-NO: 50111955

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE

64739522

SINGAPORE 575717 0

VEHICLE DETAILS

LICENSE NO: SHA9222S

TRANS: AUTO

CHASSIS: KMHLB41UMGU079761

MAKE / MODEL: HYUNDAI / i40

ENGINE: D4FDGU662621

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 CHECK WIRING SYS	1.00	120.00	0.00	120.00		Y	260
2 DIAGNOSTIC & REPROGRAMMED ELECTRICAL SYS	1.00	200.00	0.00	200.00		Y	260
3 STRAIGHTEN AND PANEL BEAT REAR PORTION & ACCIDENT AREAS	1.00	600.00	0.00	600.00		Y	250
4 SPRAY REAR BUMPER	1.00	250.00	0.00	250.00		Y	200
TOTAL:		1,170.00	0.00	1,170.00			
MATERIALS							
1 REAR BUMPER LOWER SPOILER repair	1.00	318.00	63.60	254.40	L	Y	
2 REAR BUMPER RETAINER RH X SUC	1.00	48.63	9.73	38.90	L	Y	
3 REAR BUMPER RETAINER LH X SUC	1.00	48.63	9.73	38.90	L	Y	
4 REAR BUMPER REINFORCEMENT X	1.00	488.40	97.68	390.72	L	Y	
5 REAR BUMPER red	1.00	669.50	133.90	535.60	L	Y	
6 REAR BUMPER CLIPS ne	1.00	100.00	0.00	100.00	S	Y	
7 RHR FENDER STICKER ne	1.00	180.00	0.00	180.00	S	Y	
8 LHR FENDER STICKER ne	1.00	180.00	0.00	180.00	S	Y	
9 REAR BUMPER STICKER ne	1.00	150.00	0.00	150.00	S	Y	
10 REVERSE SENSOR X SUC	1.00	200.00	0.00	200.00	S	Y	
11 REAR BUMPER TOP PADDING ne	1.00	150.00	0.00	150.00	S	Y	
TOTAL:		2,533.16	314.64	2,218.52			
TOTAL PARTS & LABOUR:		3,703.16	314.64	3,388.52			

EXCESS/LOADING: S\$ 0.00

No. Of Day: 3 days

RE-SURVEY: BEFORE/AFTER PAINTING

PART-BY-PART OR (LUMP SUM) S\$

DATE OF SURVEY: 27 / 08 / 19 @ 1100

SURVEYED BY: Rasul

CONTACT NO: 90010568 FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

Lump Sum

Labour = \$510

S/N = \$370

Parts = \$535.60

LTS = \$1415.60 - 20% LS
= \$1132.48

Final Amount = \$1132.48

1100 3 days