

Hsien Tng

O.S.K.Auto Spare Parts Trading (1994)

Blk 10 Ang Mo Kio Industrial Park 2A AMK Autopoint #04-09

Singapore 568047 HP 91004390/HP 91254449 Fax 64841482

Email: oskautomotiveamk@gmail.com

M/s FWD Singapore Pte Ltd	DATE	28.08.2019
6 Temasek Boulevard, #18-01	CAR NO	SMK 8976 U
Suntec Tower Four, Singapore 038986	MAKE	Volvo V60 T4

SUPPLEMENTARY CLAIMS FOR THE ABOVE MENTIONED VEHICLE.
YOUR INSURED : SGR 282 A

Pc	Pcs	YV1FW48HBD1104483	UNIT PRICE	AMOUNT
1	pc	Front bumper right side fog lamp garnish / CUT		\$182.00
		Labour for repair and modify front top panel. (LC) Local repair	200/	\$300.00
			Total	\$482.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

O.S.K.Auto Spare Parts Trading (1994)