

(Hsiao Tng)

# O.S.K. Auto Spare Parts Trading (1994)

Blk 10 Ang Mo Kio Industrial Park 2A AMK Autopoint #04-09

Singapore 568047 HP 91004390/HP 91254449 Fax 64841482

Email: [oskautomotiveamk@gmail.com](mailto:oskautomotiveamk@gmail.com)

02.10.2019

Our Ref : SMK 8976 U

Your Ref : SGR 282 A

Hafeez Bin Amran Bagarib

C/o O.S.K. Auto Spare Parts Trading (1994)

Attn: Motor Claims Department

FWD Singapore Pte Ltd

6 Temasek Boulevard, #18-01

Suntec Tower Four

Singapore 038986

Dear Sir/Mdm,

## **RE: ACCIDENT INVOLVING SMK 8976 U & SGR 282 A ON 18.08.2019.**

We refer to the above matter.

We are repairer of vehicle no. SMK 8976 U which was involved in an accident with vehicle no. SGR 282 A which is insured with you.

The accident was clearly caused by your insurer's negligence. We are therefore seeking compensation from you for the financial losses as itemized below:-

Cost of Repair				\$3,000.00
Loss of Use	4	Days	\$70.00	\$280.00
LTA Fee				\$7.45
Total				\$3,287.45

We enclose copies of the relevant documents to support our claim. Your prompt settlement of my claim would be much appreciated.

Please contact Susan(91004390) or Fion(91254449) from O.S.K. Auto Spare Parts Trading (1994) should you have any queries.

Yours faithfully,

  
O.S.K. Auto Spare Parts Trading (1994)

# O.S.K. Auto Spare Parts Trading (1994)

Blk 10 Ang Mo Kio Industrial Park 2A AMK Autopoint #04-09

Singapore 568047 HP 91004390/HP 91254449 Fax 64841482

Email: oskautomotiveamk@gmail.com

Invoice No : OSK 1112

M/s FWD Singapore Pte Ltd

DATE

02.10.2019

6 Temasek Boulevard, #18-01

CAR NO

SMK 8976 U

Suntec Tower Four S038986

MAKE

Volvo V60 T4

FINAL COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.  
YOUR INSURED : SGR 282 A

Qty	Pcs	YV1FW48HBD1104483	UNIT PRICE	AMOUNT
		<u>Recommended Parts</u>		
1	pcs	Front bumper		
10	pcs	Front bumper clips		
1	pcs	Front RH head lamp		
1	pcs	Front bumper RH fog lamp garnish		
		<u>Recommended Labour</u>		
		To dismantle & replace the above mentioned parts.		
		Labour for respray front bumper assy.		
		To check head lamp wiring.		
		Rust-proofing on the rear accident affected portions.		
		Labour for repair and modify front top panel.		
		Diamond coating.		
		Lump Sum Cost of Repair		\$3,000.00

> Back to OneMotoring



Land Transport Authority  
10 Sin Ming Drive  
Singapore 575701  
GST Registration No. : M4-0006529-2

Print Date/Time : 22 Aug 2019 / 09:27:23

Receipt Date/Time : 22 Aug 2019 / 09:27:23

### Tax Invoice/Receipt

Receipt No. : ITNET-00000-190822-000429

Previous Receipt No. :

**S/N Item Description/  
Business Transaction Reference  
No.**

Result of Insurance Enquiry - SGR282A  
As at 17 Aug 2019/13:15:00  
Insurance Co: FWD SINGAPORE PTE. LTD.

1 Insurance Enquiry - SGR282A  
Enquiry Fee  
20190822092537442300

Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
-------------------------------	------------------------	------------------------------

<b>Sub-Total</b>	7.00	0.49	7.49
<b>Total Before Rounding</b>	7.00	0.49	7.49
<b>Rounding Difference</b>			0.04
<b>Total Amount Payable</b>			7.45

Paid By

xxxxxxxxxxx9084

Credit Card:  
Visa/MasterCard

<b>Total</b>			7.45
<b>Cash Change</b>			0.00
<b>Tendered Amount</b>			7.45
<b>Excess Refundable Amount</b>			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Print Receipt

OK

Save as PDF

# O.S.K. Auto Spare Parts Trading (1994)

Blk 10 Ang Mo Kio Industrial Park 2A AMK Autopoint #04-09

Singapore 568047 HP 91004390/HP 91254449 Fax 64841482

Email: [oskautomotiveamk@gmail.com](mailto:oskautomotiveamk@gmail.com)

27.08.2019.

Our Ref : SMK 8976 U

Your Ref : SGR 282 A

Hafeez Bin Amran Bagarib  
C/o O.S.K. Auto Spare Parts Trading (1994)

Attn: Motor Claims Department  
FWD Singapore Pte Ltd  
6 Temasek Boulevard  
#18-01 Suntec Tower Four  
Singapore 038986

Dear Sir/Mdm,

## **LETTER OF AUTHORITY**

### **RE: ACCIDENT INVOLVING SMK 8976 U & SGR 282 A ON 18.08.2019.**

I, Hafeez Bin Amran Bagarib, owner of vehicle no. SMK 8976 U hereby authorize M/s O.S.K. Auto Spare Parts Trading (1994) as my authorized representative to write, negotiate and settle claim on my behalf in my claim against the owner and / or driver of vehicle no. SGR 282 A in respect of the above mentioned accident.

Kindly make payment directly to O.S.K. Auto Spare Parts Trading (1994).

Kindly contact Susan (HP:91004390) or Fion (HP:91254449) should you have any queries regarding the above.

Yours faithfully,

X 

Hafeez Bin Amran Bagarib.



# O.S.K. Auto Spare Parts Trading (1994)

Blk 10 Ang Mo Kio Industrial Park 2A AMK Autopoint #04-09

Singapore 568047 HP 91004390/HP 91254449 Fax 64841482

Email: oskautomotiveamk@gmail.com

## SATISFACTION & DISCHARGE VOUCHER

I, Hafeez Bin Amran Bagarib, owner of vehicle number SMK 8976 U declare that my vehicle have been completed to my satisfaction and was discharged from O.S.K. Auto Spare Parts Trading (1994) at Block 10 AMK Autopoint #04-09 Ang Mo Kio Industrial Park 2A Singapore 568047 on the 31 day of Aug 2019.

Signature of Assured,

X 

Hafeez Bin Amran Bagarib.

Accident Date : 17.08.2019

Name : Hafeez Bin Amran Bagarib

Address : 37 Punggol Field #01-35 Prive S828809