



樹發汽車修理廠 SHU FATT AUTO WORKS

0-79

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Our Ref: WSK/jw/SF-quo
23rd August 2019
TP35

SKV 5590 J HONDA ACCORD

Spare Parts		S\$
1	Rear boot. <i>bt</i>	952.20
1	Rear boot logo. <i>nee</i>	42.90
1	Rear boot 'Accord' emblem. <i>nee</i>	42.90
1	Rear boot 'i-VTEC' emblem. <i>nee</i>	46.20
1	Left rear boot reflector. <i>?</i>	352.20
2	Rear tail lights. @\$542.90 <i>X</i>	1085.80
2	Rear tail light holders. @\$147.20 <i>X</i>	354.40
1	Rear support panel. <i>repair</i>	393.20
1	Rear panel inner garnish. <i>?</i>	97.20
1	Rear bumper. <i>de</i>	630.50
1	Rear bumper reinforcement. <i>?</i>	354.20
2	Rear bumper brackets. @\$28.90 <i>nee</i>	57.80
1	Set rear bumper clips. <i>nee</i>	49.00
2	Rear bumper side retainers. @\$29.10 <i>X</i>	58.20
2	Rear bumper sensors. @\$159.40 <i>?</i>	318.80
1	Rear bumper lower garnish. <i>?</i>	215.90
1	Rear number plate. <i>sc</i>	35 55.00 Snet
		5106.40
	Less 20%	1010.28
		4096.12
Labour	To knock, straighten rear support panel, rear inner panel, rear lower panel, rear side panel, left rear fender, rt rear fender, renew rear boot, rear lights, rear support panel, rear bumper and assembly.	1200.00 500
	To respray damaged parts.	1200.00 600
	To remove rear garnishes, carpets, upholstery to facilitate repairs and assembly.	120.00 60
	To reseal joints, reinsulate, anti rust panels and assembly.	80.00 <i>X</i>
		6696.12

Dunlop 225/50R17
MRHCR1630EP000090
90558

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resue
4p 900 00068

5 days

4s

27/08/19 @ 1230

Resue after repair.

(19)