

Cocytia



樹發汽車修理廠 SHU FATT AUTO WORKS

8-19

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

On Road WSE, wse, etc
23rd August 2019
FIS: AYA

SKY 559 (J. BOND A. V. C. R. D.)

Parts: 1821.50
-20%: (364.30)
1457.20
Cott: 25.00
1482.20
Labour: 1160.00
2652.20
-20%: (530.44)
Labour: 2121.26
HS: 2100
5 days

1	Spare Parts	1	Rear boot	64	SS
1		1	Rear boot lugs	rec	95.20
1		1	Rear boot "Accord" emblem	rec	42.00
1		1	Rear boot "V-Tec" emblem	rec	42.00
1		1	Left rear boot reflector	? x su	46.20
2		2	Rear tail lights	as \$542.00 x su	1084.00
2		2	Rear tail light holders	as \$147.20 x su	354.40
1		1	Rear support panel	repair	393.20
1		1	Rear panel inner garnish	? x su	97.20
1		1	Rear bumper	de	330.50
1		1	Rear bumper reinforcement	? x su	330.50
2		2	Rear bumper brackets	as \$28.00 rec	57.80
1		1	Left rear bumper clips	rec	49.00
2		2	Rear bumper side retainers	as \$20.00 x su	50.20
2		2	Rear bumper sensors	as \$15.00 x su	48.80
1		1	Rear bumper lower garnish	? x su	15.00
1		1	Rear number plate	su	35
					55.00
					1010.28
					4096.12
					1200.00 500
					1200.00 600
					120.00 60
					80.00 x 29
					6096.12

To knock, straighten rear support panel, rear inner panel, rear lower panel, rear side panel, left rear fender, rt rear fender, renew rear boot, rear lights, rear support panel, rear bumper and assembly
To respray damaged parts
To remove rear garnishes, carpets, upholstery to facilitate repairs and assembly
To reseal joints, reinsulate, anti rust panels and assembly

Dunlop 225 Suk 17
MIRAC 1630 (P. 1000000)
20555
2018 (2018) 2018 (2018)
2018 (2018) 2018 (2018)
2018 (2018) 2018 (2018)
2018 (2018) 2018 (2018)
2018 (2018) 2018 (2018)
2018 (2018) 2018 (2018)
2018 (2018) 2018 (2018)
2018 (2018) 2018 (2018)
2018 (2018) 2018 (2018)

Passul
4p 900 10068
5 days
48
27/08/19 @ 1230
Rehury after repair.

(19)