

ASS. REC. BY:

REF: CS/CT19014892/UV f3N2

Special Instruction:

Surveyor MarcusASSIGNMENT (Office)From (Person): Irene Tay Hui Ping of CTI Date/Time: 23.8.19 15.32p.m

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SJP 43384 Insured: SJY 9891Kat Workshop m/s Automobile Hub Tel: 97864483of NO 16 Defu Lane 7Policy No: DMPC 3056871055 Claim No: SNM 19120392802

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 22.8.2019  
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 23.8.2019 4.01p.m Person Contacted: Mr Lim Vehicle IN OUT

Date/Time	Action/Instruction ( ✓ ) Estimate
	SJP 43384 - NA/ INC 19014731/h4 D.O.A - 22/08/2019
	SJY 9891K - NA/ INC 19014731/h4 D.O.A - 22/08/2019

marcus

REF: CT1

## ASSIGNMENT

From: Date: 26.8.2019

Estimated Cost

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJP 43384

at Workshop n/s: Automobile Hub

of No. 51 Defu Lane 9

Insured

Policy No.

Claims No.

Sum Insured

Excess:

(Client's Record)

Make of Veh:

Xiong 9786 4438

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

88/c

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.:

Yes or No

Lump Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

"up"

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SJP 43384

Yr Regn:

3 09

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Toyota wish

c.c.

1794

Colour:

white

A/C:

Insured / Std / NI / NA

Sp/Reading

184437

T/Radio:

Insured / Std / NI / NA

Eng/No:

G/No:

2NE 10 0 422527

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

20.5 / 5.5 R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

LEGO

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

22/8/19

D.O.I.

26/8/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

see 31-1-2029 LTA 29549

31/8/19

L/S 45-200 confirmed with AH Xiang. (Red 869.94, 679)

RECEIVED 02 SEP 2019

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 2A - typist

Days Of Repair:

6

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format:

merimen

Lump Sum / I.B.I. (\$

5200/c

Survey Fee:

Transportation

S + RS. St

Photos

Others

TOTAL

220

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Aug 2019		23 Aug 2019 15:32 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All																																													
<div style="text-align: right;">[Created by insurer]</div> <b>CLAIM SUBFOLDER DETAILS</b>																																																	
<table border="0"> <tr> <td>Insured:</td> <td colspan="4"><b>FULLTHROTTLE MOTORS PTE LTD</b></td> </tr> <tr> <td>Main Claimant:</td> <td><b>SJP4338Y</b></td> <td>Date of Loss:</td> <td colspan="2">22/08/2019 10:00 - :59</td> </tr> <tr> <td>Vehicle Reg. No.:</td> <td><b>TP / SNM19D203928C02</b></td> <td>Policy/Cover Note No.:</td> <td colspan="2">DMPCSN30568718055</td> </tr> <tr> <td>Claim Type:</td> <td><b>TP / SNM19D203928C02</b></td> <td>Policy No. (Claimant):</td> <td colspan="2"></td> </tr> <tr> <td>Vehicle Reg. No. (Insured):</td> <td><b>SJY9891K</b></td> <td>Excess:</td> <td colspan="2">\$0.00</td> </tr> <tr> <td>Repairer:</td> <td colspan="4"> <b>Automobile Hub Enterprise (HQ) NO. 16 DEFU LANE 7, 529339 Defu Lane - Tel:</b>  <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]</b> </td> </tr> <tr> <td>Handling Insurer:</td> <td colspan="4"> <b>LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/09/2019]</b> </td> </tr> <tr> <td>Adjuster:</td> <td colspan="4">PLEASE SURVEY AND REVERT</td> </tr> <tr> <td>Adj Asg. Remarks:</td> <td colspan="4"></td> </tr> </table>					Insured:	<b>FULLTHROTTLE MOTORS PTE LTD</b>				Main Claimant:	<b>SJP4338Y</b>	Date of Loss:	22/08/2019 10:00 - :59		Vehicle Reg. No.:	<b>TP / SNM19D203928C02</b>	Policy/Cover Note No.:	DMPCSN30568718055		Claim Type:	<b>TP / SNM19D203928C02</b>	Policy No. (Claimant):			Vehicle Reg. No. (Insured):	<b>SJY9891K</b>	Excess:	\$0.00		Repairer:	<b>Automobile Hub Enterprise (HQ) NO. 16 DEFU LANE 7, 529339 Defu Lane - Tel:</b> <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]</b>				Handling Insurer:	<b>LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/09/2019]</b>				Adjuster:	PLEASE SURVEY AND REVERT				Adj Asg. Remarks:				
Insured:	<b>FULLTHROTTLE MOTORS PTE LTD</b>																																																
Main Claimant:	<b>SJP4338Y</b>	Date of Loss:	22/08/2019 10:00 - :59																																														
Vehicle Reg. No.:	<b>TP / SNM19D203928C02</b>	Policy/Cover Note No.:	DMPCSN30568718055																																														
Claim Type:	<b>TP / SNM19D203928C02</b>	Policy No. (Claimant):																																															
Vehicle Reg. No. (Insured):	<b>SJY9891K</b>	Excess:	\$0.00																																														
Repairer:	<b>Automobile Hub Enterprise (HQ) NO. 16 DEFU LANE 7, 529339 Defu Lane - Tel:</b> <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]</b>																																																
Handling Insurer:	<b>LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/09/2019]</b>																																																
Adjuster:	PLEASE SURVEY AND REVERT																																																
Adj Asg. Remarks:																																																	
			View All	Compose Case Mail																																													
<b>ASSOCIATED MAIL RECEIVED</b> There are no mail for this case.																																																	
<b>ALL ASSOCIATED TASKS</b> <div style="text-align: right;"> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a> </div> <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.																																		
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?																																								
No results.																																																	

**DOWNTOWN EAST**  
31 AUG - 01 SEP 2019  
10AM TO 8PM

Sure-Win Lucky Dip!  
Free Ice Cream & Balloons!  
F1 Red Bull Simulator!

WIN a 2D1N stay at Amara Sanctuary Resort Sentosa!  
**AND**  
MOBIL 1 Engine Oil Giveaway!

Advanced Search

Home » Used Cars » Top Carz » Toyota Wish 1.8A X (COE till 04/2029)

Toyota Wish 1.8A X (COE till 04/2029)

- Overview
- Financial
- Insurance
- Accessories
- Similar
- Research
- Photos
- Map

Price	\$61,800		
Depreciation	\$6,380 /yr	Reg Date	26-Jun-2009 (9yrs 8mths 4days COE left)
Mileage	N.A.	Manufactured	2009
Road Tax	\$974 /yr	Transmission	Auto
Dereg Value	\$34,295 as of today (change)	OMV	\$21,562
COE	\$35,411	ARF	\$21,562
Engine Cap	1,797 cc	Power	106.0 kW (142 bhp)
Curb Weight	1,340 kg	No. of Owners	2
Type of Vehicle	MPV		

Features

1.8L DOHC 16V VVT-i Engine, Smooth 5 Speed Steptronic Gearbox. Digital Climatic Control Aircon, Dual Airbags. ABS. 7 Seater.

Description

No Gimmick On The Above Price And No Addition Deposit, Selling At Above Price, New Model Own By 1 Careful Lady Owner Only, Low Mileage And Accident Free, Regularly Serviced And Maintained, New Leather Seat, Beautiful Condition, Only \$6k Depreciation, No Repair Needed, Welcome Own Workshop Inspection, Loan And Trade In Available.

Category

COE Car

Status

Available

Resources



Car Valuation - Free  
Find out the market value of your existing car for free. Get started



Vehicle Evaluation  
Afraid of lemons? Request to have this car evaluated professionally. Find out more

Posted on: 25-Aug-2019 | Last Updated on: 25-Aug-2019


\* more Financial info

Upfront Payment

Transfer Fee	\$25	
Down Payment	\$18,540 (change)	Maximum 70% Loan



Price Chart



- Shortlist
- Compare
- Add note
- Report Error
- More Actions

Seller Information

Company	Top Carz » dealer's pricelist » 16 vehs sold   11 vehs available
Address	1 Bukit Batok Crescent #02-55 Search cars nearby this location

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	671R

### Vehicle Details

Vehicle No.:	SJP4338Y
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Aug 2019
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8X A
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	1ZZ3172673
Chassis No.:	ZNE100422527
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$22,218.00
Original Registration Date:	24 Mar 2009
First Registration Date:	24 Mar 2009
Transfer Count:	3
Actual ARF Paid:	\$22,218.00

### Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

### Intended COE Rebate Details

COE Expiry Date:	31 Jan 2029
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$31,335.00
COE Rebate Amount:	\$29,549.00
<b>Total Rebate Amount:</b>	<b>\$29,549.00</b>

The information contained herein is correct as at 26 Aug 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	22/08/2019 15:56
Date Of Accident	22/08/2019 10:30
Exact Location Of Accident	TELOK BLANGAH RD TWDS CITY LP/95
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJP4338Y
<b>Insured/Policyholder</b>	
Name Of Registered Owner	FULLTHROTTLE MOTORS PTE LTD
Co Reg No	201633671R
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-96843481

### Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5106595694
Cover Note Number	-

### Driver

Name of Driver	SIM IK PING
NRIC No	S1560895A
Date Of Birth	11/01/1962
Occupation	INDOOR
Date Of Driving Pass	11/06/1979
Driving Experience	40 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94563889
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 474 SEGAR RD #09-306  
 Postcode 670474  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OTHER - HIRER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 2  
 Was any body injured in the Accident? YES  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 2  
 Passenger 1 NAME: : LE KENG  
 GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

I WAS TRAVELLING ALONG TELOK BLANGAH RD TWDS CITY ON THE EXTREME RIGHT LANE, MY VEH WAS STATIONARY DUE TO TRAFFIC CONGESTED, ALL OF A SUDDEN, I FELT AN IMPACT FROM BEHIND. AFTER THE INCIDENT, I ALIGHTED FROM MY VEH AND REALIZED VEH B HIT ONTO MY VEH REAR PORTION.

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Remarks/ Reasons: HAVENT RETRIEVE  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJY9891K  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category PRIVATE CAR  
 Name of Driver SAW BOON BENG  
 NRIC/Passport Number S7964057C  
 Contact Number  
 Address  
 Postcode




Telok Blangah Rd towards City

SKETCH PLAN

A = SJP 4338 Y

B = SJY 9891 K



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please Refer to Statement

DECLARATION

We declare the foregoing particulars are true in every respect.

X

Policyholder's Signature

Date & Time:



Driver's Signature  
(if driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/PPN No.:



Repair Estimate

# Automobile Hub Enterprise

1 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit Singapore 417883  
Tel: (65) 9786 4483 Fax: (65) 6509 6584 Email: autohub325@gmail.com

Vehicle No: **SJP4338Y**

Model: Toyota Wish

Not Authorized  
26/8/19  
d/s \$5200  
Take the Average  
6 day

**QTY**

**List Price:**

**Prices \$**

1	Rear tailgate
2	Rear tailgate hinge- RH/LH @ 65.20
2	Rear tailgate damper- RH/LH @ 210.91
1	Rear tailgate stopper
1	Rear tailgate rubber
1	Rear tailgate lock
1	Rear tailgate lock catch
1	Rear tailgate inner pull handle
1	Rear tailgate inner trim
1	Rear tailgate wiper blade
1	Rear tailgate wiper arm
1	Rear tailgate wiper motor
1	Rear tailgate emblem LOGO
2	Rear number plate lamp @ 48.65
1	Rear tailgate opening control switch
1	Rear tailgate outer chrome moulding
2	Rear taillamp- RH/LH @ 484.65
4	Rear taillamp side holder clip @ 7.80
2	Rear taillamp panel housing- RH/LH @ 195.00
1	Rear bumper
4	Rear bumper clip @ 4.50
2	Rear bumper reflector- RH/LH @ 68.55
2	Rear bumper bracket- RH/LH @ 68.50
2	Rear bumper side retainer- RH/LH @ 64.43
1	Rear exhaust box
2	Rear exhaust moulding @ 42.60
1	Rear end panel
1	Rear end panel garnish
1	Rear spare wheel carrier
1	Rear floor panel
1	Rear floor cardboard holder garnish
1	Rear floor panel cardboard

Body	1248.95
17	130.40 X
17	421.82 X
17	12.90 X
Total	285.53
00/Jan	497.27
17	46.50 X
17	42.50 X
Defence	485.51
17	48.10 X
na	70.50 X
17	615.10 X
na	68.50
17	97.30 X
17	165.20 X
17	255.10 X
Misc	969.30 12C
17	31.20 X
2	390.00 X
Dis	635.10
na	18.00
Misc	137.10 12C
Misc	137.10 12C
Misc	128.86 12C
17	822.60 X
17	85.20 X
Body	475.10
na	218.97
17	335.10 X
2	618.70 X
17	216.50 X
waged	265.70

SJP4338Y

17	310.10	X
17	297.00	X
17	248.20	X
17	27.00	X
<i>Mike/Don</i>	1215.24	<i>120</i>
	<u>12073.25</u>	
	-3018.313	
Subtotal	9054.94	

1-5342-38  
25-2  
4006.78

**Special Nett Items:**

me	80.00	40
n1	400.00	X
n1	50.00	X
rec	65.00	50
shuld	280.00	220
<b>Subtotal</b>	<b>875.00</b>	

**Labour Charges:**

	1500.00	800
	1500.00	1100
	50.00	30
	200.00	120
	120.00	60
	180.00	80
	200.00	50
	150.00	X
Subtotal	3900.00	

**\$ 13829.94**

6536-78

[illegible]

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119014892/UVF3N2

Date: 06/09/2019

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30568718055
Claimant Vehicle No :	SJP4338Y	Insured Vehicle No :	SJY9891K
Date of Loss:	22/08/2019	Nature of Claim:	TP
		Claim No:	SNM19D203928C02/1 (THP)

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SJP4338Y	Engine No:	1ZZ3172673
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	ZNE100422527
Reg. Date:	24/03/2009 (Man. Year: 2008)	Odometer:	184437 km
Colour:	White		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	LEAO 6 mm	Rear Left Side:	LEAO 6 mm
Front Right Side:	LEAO 6 mm	Rear Right Side:	LEAO 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	9,929.94	4,296.78	5,633.16	56.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,900.00	2,240.00	1,660.00	42.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>13,829.94</b>	<b>6,536.78</b>	<b>7,293.16</b>	<b>52.73</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>5,200.00</b>		
<b>Nett Amount (\$\$)</b>	<b>13,829.94</b>	<b>5,200.00</b>	<b>8,629.94</b>	<b>62.40</b>

## INSPECTION

Date of Assignment:	23/08/2019		
Date Inspected:	26/08/2019	Inspected At:	Automobile Hub Enterprise (HQ) NO. 16 DEFU LANE 7 Singapore 529339

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 06 Sep 2019)
<b>Parts:</b>	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJP4338Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR TAILGATE	Badly Dented	1,248.95 FL	*1,248.95 FL
2	2	*REAR TAILGATE HINGE-RH/LH	Not Necessary	130.40 FL	*- FL
3	2	*REAR TAILGATE DAMPER-RH/LH	Not Necessary	421.82 FL	*- FL
4	1	*REAR TAILGATE STOPPER	Not Necessary	12.90 FL	*- FL
5	1	*REAR TAILGATE RUBBER	Torn/Twisted	285.53 FL	*285.53 FL
6	1	*REAR TAILGATE LOCK	Dented/Jammed	497.27 FL	*497.27 FL
7	1	*REAR TAILGATE LOCK CATCH	Not Necessary	46.50 FL	*- FL
8	1	*REAR TAILGATE INNER PULL HANDLE	Not Necessary	42.50 FL	*- FL
9	1	*REAR TAILGATE INNER TRIM	Deformed/Cracked	485.51 FL	*485.51 FL
10	1	*REAR TAILGATE WIPER BLADE	Not Necessary	48.10 FL	*- FL
11	1	*REAR TAILGATE WIPER ARM	Not Necessary	70.50 FL	*- FL
12	1	*REAR TAILGATE WIPER MOTOR	Not Necessary	615.10 FL	*- FL
13	1	*REAR TAILGATE EMBLEM LOGO	Necessary	68.50 FL	*68.50 FL
14	2	*REAR NUMBER PLATE LAMP	Not Necessary	97.30 FL	*- FL
15	1	*REAR TAILGATE OPENING CONTROL SWITCH	Not Necessary	165.20 FL	*- FL
16	1	*REAR TAILGATE OUTER CHROME MOULDING	Not Necessary	255.10 FL	*- FL
17	1	*REAR TAILLAMP-RH/LH	N/s Cracked	969.30 FL	*484.65 FL
18	4	*REAR TAILLAMP SIDE HOLDER CLIP	Not Necessary	31.20 FL	*- FL
19	2	*REAR TAILLAMP PANEL HOUSING-RH/LH	Repair	390.00 FL	*- FL
20	1	*REAR BUMPER	Distorted	635.10 FL	*485.10 FL
21	4	*REAR BUMPER CLIP	Necessary	18.00 FL	*18.00 FL
22	1	*REAR BUMPER REFLECTOR-RH/LH	N/s Cracked	137.10 FL	*68.55 FL
23	1	*REAR BUMPER BRACKET-RH/LH	N/s Bent	137.10 FL	*68.50 FL
24	1	*REAR BUMPER SIDE RETAINER-RH/LH	N/s Bent	128.86 FL	*64.43 FL
25	1	*REAR EXHAUST BOX	Not Necessary	822.60 FL	*- FL
26	2	*REAR EXHAUST MOULDING	Not Necessary	85.20 FL	*- FL
27	1	*REAR END PANEL	Badly Dented	475.10 FL	*475.10 FL
28	1	*REAR END PANEL GARNISH	Twisted	218.97 FL	*218.97 FL
29	1	*REAR SPARE WHEEL CARRIER	Not Necessary	335.10 FL	*- FL
30	1	*REAR FLOOR PANEL	Repair	618.70 FL	*- FL
31	1	*REAR FLOOR CARDBOARD HOLDER GARNISH	Not Necessary	216.50 FL	*- FL
32	1	*REAR FLOOR PANEL CARDBOARD	Warped	265.70 FL	*265.70 FL
33	2	*REAR FLOOR PANEL SIDE BOARD-RH/LH	Not Necessary	310.10 FL	*- FL
34	2	*REAR FENDER AIR VENT-RH/LH	Not Necessary	297.00 FL	*- FL
35	2	*REAR FENDER LOWER SHIELD-RH/LH	Not Necessary	248.20 FL	*- FL
36	6	*REAR FENDER LOWER SHIELD CLIP-RH/LH	Not Necessary	27.00 FL	*- FL
37	1	*REAR FENDER INNER TRIM-RH/LH	N/s Deformed/Torn	1,215.24 FL	*607.62 FL
38	1	*SET REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
39	1	*SET REAR REVERSE CAMERA	Not Necessary	400.00 FS	*- FS
40	1	*SET REAR NUMBER PLATE WITH CASING	Not Necessary	50.00 FS	*- FS
41	1	*SET REAR INNER TRIM CLIP	Necessary	65.00 FS	*50.00 FS
42	1	*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 12,948.25 5,632.38

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 25.00/25.00% (S\$)					3,018.31	1,335.60
Total Parts (S\$)					9,929.94	4,296.78

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING,CUT,WELD,REMOVE AND REPLACING ABOVE PARTS	New	1,500.00	800.00
2	TO RESPRAY PAINTING AND ETC	New	1,500.00	1,100.00
3	TO CHECKING REAR WIRING	New	50.00	30.00
4	TO REMOVE,REFIX REAR WINDSCREEN	New	200.00	120.00
5	TO TRANSFER REAR TAILGATE PARTS	New	120.00	60.00
6	TO REMOVE,REFIX CUSHION AND INNER TRIM	New	180.00	80.00
7	TO REFIX & REPLACE REVERSE SENSOR	New	200.00	50.00
8	TO REMOVE,REFIX REAR EXHAUST BOX	New	150.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,900.00</b>	<b>2,240.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >