

18/2018

INS. CASE OWNER:

CC 4/LPC1901

4893, K d639,

LKK:

IDAC:

Surveyor:

benneth

DOI:

ASSIGNMENT

22/8/19

Date / Time:

22/8/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJN 6076H

Name of Insured:

MOHAYATI BTE AHUHAN

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

20/8/19

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

15/11/19 (UP05/10/2019)

Policy No.:

718UP0501200

Make / Model:

FORO

Place of Accident:

DIE HEADING INTO EYE

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

SJL 71399

SJN 6076H

SJL 3647H



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

01



INSRS:
WSP:
Tel:
Liability:
RMKS:

KEHIN
TP



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time		STAGE	DATE / PIC
		Non-Reporting ltr (1st):	
		Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OI:	
		After call ltr to OI:	
		Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	☐
		After call ltr to OI:	☐
		Authorisation To Act	☒
		Release Voucher:	☒
		Final Repair Bill:	☒
		Car Rental Invoice:	☒
		Towing Invoice	☐
		LYA / GIA:	☐
		Medical Bill:	☐
		PIR:	☐
		Mandate/Reject Instruction:	☒
		LOD	☒
		Payment Breakdown Form:	☐
		Post-Repair Photos:	☐
		Others:	☐

PRELIMINARY ADVICE	Date/Time:	Sent By:	
FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	SS	(days) Reduction:	% Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time: 25/11/19	Confirm with: Margaret	Email ☒ Call ☐
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	28
Repair Cost: (w/lyst)	SS 4126.19		
Loss of Rental (LOR):	SS 700.00	(7 days) x \$100	
Loss of Use (LOU):	SS -	(5 x days)	
Loss of Income (LOI):	SS -	(5 x days)	
LOR only ☒ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐		(Tick only one)	
GIA/LTA Search	SS -		
Medical:	SS -		
Disbursement:	SS -	(e.g. Tow/ Independent)	
Legal Cost	SS -		
Total:	SS 4826.19	Global Sum SS:	
FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1:	SS 4826.19	Name 1:	K. Kim Hin Auto Pte Ltd
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	

ASS. REC. BY:

REF: LPC1

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No: _____

at Workshop m/s 1010111N

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 1.81 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLT 3847U Yr Regn: 12, 16Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda Tarz c.c. 1498Colour: M. Grey A/C: Insured / Std / NI / NASp. Reading: 4899p T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHM GK 585014X 200660Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front _____ Rear _____

R/Bal. 8 mm R/Bal. 6 mmL/Bal. 8 mm L/Bal. 6 mmD.O.A. 20/8/19 D.O.I. 22/8/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1/ File pass toPIP - \$3856.25 (Red \$576.50 | 137)

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S - RS \$

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE. L #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/LPC19014893/Kdb3

Date: 23.08.2019

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SLJ3647U

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 22.08.2019 at the premises of M/s K Kim Hin Auto Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	4,432.75
Revised Estimate Amount	: S\$	2,890.00
"Check" Items Amount	: S\$	323.00
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:
The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

(IN)
TP: LONPAC

Kd

W. Kim Hin

CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

No. : 30682

Vehicle Insured : SJU 6026 H
Accident Date : 20-Aug-2019

Date : 21-Aug-2019

Our Ref : 190475 (LONPAC) / LAVENDER

PAGE : 1

LI TAO (MR)
Singapore

5 days

*Not with paint
Respray B4 paint*

5 days

ESTIMATED COST OF REPAIR FOR HONDA JAZZ 1.5 (2016) SLJ3647U

- 1 pc reverse sensor
- 1 pc rear end panel
- 1 pc rear end panel top garnish
- 1 pc tailgate
- 1 pc tailgate lock
- 1 pc tailgate weatherstrip
- 1 pc tailgate windscreen glass moulding
- 1 pc tailgate outer garnish
- 1 pc smart key antenna
- 1 pc rear buzzer
- 1 pc rear bumper
- 2 pcs rear bumper side retainer (LH/RH)
- 10 pcs rear bumper clips
- 2 pcs rear bumper side garnish
- 1 pc tailgate logo
- 1 pc tailgate "JAZZ" emblem
- 1 pc tailgate inner trim board

@ S\$ 15.00

@ S\$ 1.00

@ S\$ 15.00

<i>Shw</i>	220.00	c	<i>200.00 ✓</i>
<i>Pr</i>	240.00	c	<i>✓</i>
<i>Pr</i>	45.00	c	<i>✓</i>
<i>Pr</i>	550.00	c	<i>✓</i>
<i>DM</i>	125.00	c	<i>✓</i>
<i>Gr</i>	55.00	c	<i>✓</i>
<i>Pr</i>	75.00	c	<i>✓</i>
<i>Sm</i>	160.00	c	<i>X</i>
<i>CM</i>	60.00	c	<i>✓</i>
<i>CM</i>	65.00	c	<i>✓</i>
<i>Bu</i>	190.00	c	<i>✓</i>
<i>Pr</i>	30.00	c	<i>✓</i>
<i>Pr</i>	10.00	c	<i>✓</i>
<i>Pr</i>	30.00	c	<i>X</i>
<i>Pr</i>	15.00	c	<i>X</i>
<i>Pr</i>	15.00	c	<i>✓</i>
<i>Sm</i>	100.00	c	<i>X</i>
	1,985.00		
Add 15% :	297.75		
	2,282.75		

- 1 pc tailgate windscreen glass sealant
- 1 pc tailgate windscreen glass damping seal
- 1 pc rear number plate

Pr 40.00 sn ✓
Pr 20.00 sn ✓
Sm 40.00 sn X

Supplementary item

1pc n/s Trilking

195.00

Con't Page 2 ...



CO. REG. NO: 199402370D

GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Vehicle Insured : SJU 6026 H
Our Ref : 190475

Page : 2
No. : 30682

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

601
750.00

To remove and refit rear windscreen
glass and conduct water leak test

120.00 ✓

To remove and refit rear upholstery
trimming, roof lining, seats,
speaker board in order to
facilitate repairing works

120.00 601

To transfer tailgate's fittings

80.00 601

To remove and refit reverse sensor
assy.

80.00 501

To putty and respray on affected
portions.

900.00 7501

Total : S\$ 4,432.75
=====

Singapore Dollars Four Thousand Four Hundred
and Thirty Two and Cents Seventy Five Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

1680.00 s/parts
+ 195.00 Supp

1875.00
15%

2156.25 s/parts
60.00 SN
+ 1640.00 Labour

\$ 3856.25 ✓ ok



CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhinh.com.sg

Vehicle Insured : SJU 6026 H
Accident Date : 20 -Aug- 2019

Date : 22-Aug-2019

Our Ref : 190475 (LONPAC) / Simon

LI TAO (MR)
Singapore

SUPPLEMENTARY ITEMS FOR HONDA JAZZ 1.5 SLJ 3647U

1 pc n/s Taillamp

	\$ 195.00 ✓

	\$ 195.00
Add 15%	\$ 19.50

	\$ 214.50

Note: Amount quoted above is subjected to prevailing GST at time of tax invoice.

(IN)
TP. Lompac

K. Kim Hin

CO. REG. NO: 199402370D

GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

No. : 30682

Vehicle Insured : SJU 6026 H
Accident Date : 20-Aug-2019

Date : 21-Aug-2019

Our Ref : 190475 (LONPAC) / LAVENDER

PAGE : 1

LI TAO (MR)
Singapore

*Not Notified
Pursuing B4 paint*

ESTIMATED COST OF REPAIR FOR HONDA JAZZ 1.5 (2016) SLJ3647U

5 days

- 1 pc reverse sensor
- 1 pc rear end panel
- 1 pc rear end panel top garnish
- 1 pc tailgate
- 1 pc tailgate lock
- 1 pc tailgate weatherstrip
- 1 pc tailgate windscreen glass moulding
- 1 pc tailgate outer garnish
- 1 pc smart key antenna
- 1 pc rear buzzer
- 1 pc rear bumper
- 2 pcs rear bumper side retainer (LH/RH)
- 10 pcs rear bumper clips
- 2 pcs rear bumper side garnish
- 1 pc tailgate logo
- 1 pc tailgate "JAZZ" emblem
- 1 pc tailgate inner trim board

@ S\$ 15.00

@ S\$ 1.00

@ S\$ 15.00

Short	220.00	c	<i>220.00 ✓</i>
B ₁	240.00	c	<i>✓</i>
Red	45.00	c	<i>✓</i>
B ₁	550.00	c	<i>✓</i>
	125.00	c	<i>?</i>
Gr	55.00	c	<i>✓</i>
Re	75.00	c	<i>✓</i>
Sn	160.00	c	<i>X</i>
	60.00	c	<i>?</i>
	65.00	c	<i>?</i>
Bu	190.00	c	<i>✓</i>
	30.00	c	<i>?</i>
Re	10.00	c	<i>✓</i>
Re	30.00	c	<i>X</i>
Re	15.00	c	<i>X</i>
Re	15.00	c	<i>✓</i>
	100.00	c	<i>?</i>

1,985.00

Add 15% : 297.75

2,282.75

- 1 pc tailgate windscreen glass sealant
- 1 pc tailgate windscreen glass damping seal
- 1 pc rear number plate

Re 40.00 sn ✓
Re 20.00 sn ✓
Sn 40.00 sn X

L&K Auto Consultants hereby notify the Repairer of the following:

- To ensure satisfactory repair
- To ensure damaged parts are replaced
- Parts placed on vehicle must be genuine
- First party insurance must be used for repair work
- No third party insurance claims
- Repairs must be carried out in accordance with the relevant standards
- Subject to the relevant insurance company's terms and conditions

Authorised Signature
Signature
Date

Con't Page 2 ...

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : SJU 6026 H
Our Ref : 190475

Page : 2
No. : 30682

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

750.00 *600*

To remove and refit rear windscreen
glass and conduct water leak test

120.00 ✓

To remove and refit rear upholstery
trimming, roof lining, seats,
speaker board in order to
facilitate repairing works

120.00 *600*

To transfer tailgate's fittings

80.00 *600*

To remove and refit reverse sensor
assy.

80.00 *500*

To putty and respray on affected
portions.

900.00 *7500*

Total : S\$ 4,432.75
=====

Singapore Dollars Four Thousand Four Hundred
and Thirty Two and Cents Seventy Five Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	408B
Vehicle Details	
Vehicle No.:	SLJ3647U
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Aug 2019
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.5 VTIR CVT ABS D/AIRBAG 2WD
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	L15B31190403
Chassis No.:	JHMGK5850HX200660
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$17,171.00
Original Registration Date:	07 Dec 2016
First Registration Date:	07 Dec 2016
Transfer Count:	0
Actual ARF Paid:	\$12,171.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Dec 2026
PARF Rebate Amount:	\$9,128.00
Intended COE Rebate Details	
COE Expiry Date:	06 Dec 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,668.00
COE Rebate Amount:	\$38,400.00
Total Rebate Amount:	\$47,528.00

The information contained herein is correct as at 21 Aug 2019

OK

Shu Pei (LKKAUTO)


From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Thursday, 29 August 2019 9:40 AM
To: Shu Pei (LKKAUTO)
Cc: MT_Claim_SG
Subject: RE: Accident Involving SLJ 3647 U and SJU 6026 H on 20 Aug 19 [External Confidential]
Attachments: 29082019093558.pdf

Lonpac External - Confidential
Our Ref : 18/19/19/VP05/022251

Dear Shu Pei,

Attached copy of insured's report for your attention.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Thursday, 29 August, 2019 9:19 AM
To: GERALD POH WEE BIN
Cc: MT_Claim_SG
Subject: RE: Accident Involving SLJ 3647 U and SJU 6026 H on 20 Aug 19 [External Confidential]

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

Kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>

Sent: Friday, 23 August 2019 4:53 PM

To: GERALD POH WEE BIN <geraldpoh@lonpac.com>; service@kkimhin.com.sg

Cc: MT_Claim_SG <mt_claim@lonpac.com>; Admin A <admin-a@lkkauto.com>; Jia Le (LKK Auto) <JiaLe@lkkauto.com>

Subject: RE: Accident Involving SLJ 3647 U and SJU 6026 H on 20 Aug 19 [External Confidential]

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SLJ 3647U at M/s K Kim Hin Auto Pte Ltd on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- TP's GIA report
- Estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Jia Le and she can be contacted at DID: 6749 5792.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>

Sent: Thursday, 22 August 2019 11:17 AM

To: service@kkimhin.com.sg

Cc: MT_Claim_SG <mt_claim@lonpac.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: Accident Involving SLJ 3647 U and SJU 6026 H on 20 Aug 19 [External Confidential]


Lonpac External - Confidential

Our Ref : 18/19/19/VP05/022251

Dear Nivitha,

For your necessary action.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: service [<mailto:service@kkimhin.com.sg>]
Sent: Wednesday, 21 August, 2019 9:37 PM
To: MT_Claim_SG
Cc: service@kkimhin.com.sg; Sandra (Gmail); simon@kkimhin.com.sg; survey@kkimhin.com.sg; survey2@kkimhin.com.sg
Subject: Accident Involving SLJ 3647 U and SJU 6026 H on 20 Aug 19

Your Ref: SJU 6026 H (Lonpac)
Our Ref: SLJ 3647 U

Dear Officer

Enclosed our client SLJ 3647 U GIA report who was hit by your insured SJU 6026 H on 20 Aug 2019.

Vehicle is in the workshop. Please kindly arrange for survey tomorrow (22 Aug Thu),

Many thanks
Sandra
64527018
96222116
K. Kim Hin Auto Pte Ltd

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC19014893/Kdb3q2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 16-12-2019	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJU 6026H	Veh. Inspected	SLJ 3647U	
Policy No.	Z18VP05021330	Coverage (\$)	0.00	
Claim No.	18/19/19/VP05/022251	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	22/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA JAZZ (A)	c.c	1498	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JHMGK5850HX200660	Colour	METALLIC GREY	
Odometer	48999	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/55 R16	YOKOHAMA	8 mm	
L/H Front Tyre	185/55 R16	YOKOHAMA	8 mm	
R/H Rear Tyre	185/55 R16	YOKOHAMA	6 mm	
L/H Rear Tyre	185/55 R16	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/08/2019	Inspection Date	22/08/2019	
Survey held at	K KIM HIN AUTOMOTIVE PTE LTD 160 SIN MING DRIVE #02-20 SIN MING AUTO CITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 3647U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REVERSE SENSOR (WCP)	SHORTED	220.00	220.00
1	REAR END PANEL (WCP)	BENT	240.00	240.00
1	REAR END PANEL TOP GARNISH (WCP)	DENTED	45.00	45.00
1	TAILGATE (WCP)	BENT	550.00	550.00
1	TAILGATE LOCK (WCP)	DAMAGED	125.00	125.00
1	TAILGATE WEATHERSTRIP (WCP)	CUT	55.00	55.00
1	TAILGATE WINDSCREEN GLASS MOULDING (WCP)	NECESSARY	75.00	75.00
1	TAILGATE OUTER GARNISH (WCP)	SERVICEABLE	160.00	-
1	SMART KEY ANTENNA (WCP)	CRACKED	60.00	60.00
1	REAR BUZZER (WCP)	CRACKED	65.00	65.00
1	REAR BUMPER (WCP)	BUCKLED	190.00	190.00
2	REAR BUMPER SIDE RETAINER (LH/RH)@\$15.00 (WCP)	DAMAGED	30.00	30.00
10	REAR BUMPER CLIPS @\$1.00 (WCP)	NECESSARY	10.00	10.00
2	REAR BUMPER SIDE GARNISH @\$15.00 (WCP)	SERVICEABLE	30.00	-
1	TAILGATE LOGO (WCP)	NOT NECESSARY	15.00	-
1	TAILGATE 'JAZZ' EMBLEM (WCP)	NECESSARY	15.00	15.00
1	TAILGATE INNER TRIM BOARD (WCP)	SERVICEABLE	100.00	-
1	N/S TAILLAMP (WCP) (ADDITIONAL)	CUT	195.00	195.00
	COST PLUS 15%		327.00	281.25
			2,507.00	2,156.25
SPECIAL NETT ITEMS				
1	TAILGATE WINDSCREEN GLASS SEALANT (SN)	NECESSARY	40.00	40.00
1	TAILGATE WINDSCREEN GLASS DAMPING SEAL (SN)	NECESSARY	20.00	20.00
1	REAR NUMBER PLATE (SN)	SERVICEABLE	40.00	-
			100.00	60.00
LABOUR				
	TO REMOVE ,CUT OUT DAMAGED PARTS,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW AFFECTED PARTS.		750.00	600.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.		120.00	120.00

Report Ref No. CC4/LPC19014893/Kdb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIT REAR UPHOLSTERY TRIMMING ,ROOF LINING ,SEATS ,SPEAKER BOARD IN ORDER TO FACILITATE REPAIRING WORKS.		120.00	60.00
	TO TRANSFER TAILGATE'S FITTINGS.		80.00	60.00
	TO REMOVE AND REFIT REVERSE SENSOR ASSY.		80.00	50.00
	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.		900.00	750.00
			2,050.00	1,640.00
GRAND TOTAL			4,657.00	3,856.25
RECOMMENDED COST OF REPAIRS				3,856.25

Report Ref No. CC4/LPC19014893/Kdb3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.