

(IN)
TP: Lompac

Kd



CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

No. : 30682

Vehicle Insured : SJU 6026 H
Accident Date : 20-Aug-2019

Date : 21-Aug-2019

Our Ref : 190475 (LONPAC) / LAVENDER

PAGE : 1

LI TAO (MR)
Singapore

5 days

Not Withhold
Reserve B4 paint

5 days

ESTIMATED COST OF REPAIR FOR HONDA JAZZ 1.5 (2016) SLJ3647U

1 pc	reverse sensor	
1 pc	rear end panel	
1 pc	rear end panel top garnish	
1 pc	tailgate	
1 pc	tailgate lock	
1 pc	tailgate weatherstrip	
1 pc	tailgate windscreen glass	
	moulding	
1 pc	tailgate outer garnish	
1 pc	smart key antenna	
1 pc	rear buzzer	
1 pc	rear bumper	
2 pcs	rear bumper side retainer	@ S\$ 15.00
	(LH/RH)	
10 pcs	rear bumper clips	@ S\$ 1.00
2 pcs	rear bumper side garnish	@ S\$ 15.00
1 pc	tailgate logo	
1 pc	tailgate "JAZZ" emblem	
1 pc	tailgate inner trim board	

Short	220.00	c	✓
B1	240.00	c	✓
Det	45.00	c	✓
B1	550.00	c	✓
	125.00	c	✓
CU	55.00	c	✓
Re	75.00	c	✓
Sn	160.00	c	X
CMA	60.00	c	✓
CU	65.00	c	✓
Bu	190.00	c	✓
	30.00	c	✓
Re	10.00	c	✓
Sn	30.00	c	X
Re	15.00	c	X
Re	15.00	c	✓
Sn	100.00	c	X
	1,985.00		
Add 15% :	297.75		

2,282.75

1 pc	tailgate windscreen glass	
	sealant	
1 pc	tailgate windscreen glass	
	damping seal	
1 pc	rear number plate	

Re 40.00 sn ✓
Re 20.00 sn ✓
Sn 40.00 sn X

Supplementary item

1pc n/s Tailamp

195.00

Con't Page 2 ...



CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : SJU 6026 H
Our Ref : 190475

Page : 2
No. : 30682

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

600
750.00

To remove and refit rear windscreen
glass and conduct water leak test

120.00 ✓

To remove and refit rear upholstery
trimming, roof lining, seats,
speaker board in order to
facilitate repairing works

120.00 600

To transfer tailgate's fittings

80.00 600

To remove and refit reverse sensor
assy,

80.00 500

To putty and respray on affected
portions.

900.00 7500

Total : S\$ 4,432.75
=====

Singapore Dollars Four Thousand Four Hundred
and Thirty Two and Cents Seventy Five Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

1680.00 s/parts
+ 195.00 Supp

1875.00
15%

2156.25 s/parts
60.00 SN

+ 1640.00 Labour

\$ 3856.25 ✓ ok



CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : SJU 6026 H
Accident Date : 20 -Aug- 2019

Date : 22-Aug-2019

Our Ref : 190475 (LONPAC) / Simon

LI TAO (MR)
Singapore

SUPPLEMENTARY ITEMS FOR HONDA JAZZ 1.5 SLJ 3647U

1 pc n/s Taillamp

✓ \$ 195.00 ✓

\$ 195.00

Add 15% \$ 19.50

\$ 214.50

Note: Amount quoted above is subjected to prevailing GST at time of tax invoice.