

(IN)  
TP: Lompac



CO. REG. NO: 199402370D  
GST NO: M2-0123250-3

AUTO PTE LTD

# 金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,  
Sin Ming AutoCity, Singapore 575722  
Tel: 6452 7018 Fax: 6458 3895  
Email: service@kkimhin.com.sg

No. : 30682

Vehicle Insured : SJU 6026 H  
Accident Date : 20-Aug-2019

Date : 21-Aug-2019

Our Ref : 190475 (LONPAC) / LAVENDER

PAGE : 1

LI TAO (MR)  
Singapore

Not Withdraw  
Resurvey B4 paint

5 days

## ESTIMATED COST OF REPAIR FOR HONDA JAZZ 1.5 (2016) SLJ3647U

- 1 pc reverse sensor
- 1 pc rear end panel
- 1 pc rear end panel top garnish
- 1 pc tailgate
- 1 pc tailgate lock
- 1 pc tailgate weatherstrip
- 1 pc tailgate windscreen glass moulding
- 1 pc tailgate outer garnish
- 1 pc smart key antenna
- 1 pc rear buzzer
- 1 pc rear bumper
- 2 pcs rear bumper side retainer (LH/RH)
- 10 pcs rear bumper clips
- 2 pcs rear bumper side garnish
- 1 pc tailgate logo
- 1 pc tailgate "JAZZ" emblem
- 1 pc tailgate inner trim board

@ S\$ 15.00

@ S\$ 1.00

@ S\$ 15.00

|       |        |   |          |
|-------|--------|---|----------|
| short | 220.00 | c | 220.00 ✓ |
| B1    | 240.00 | c | ✓        |
| Del   | 45.00  | c | ✓        |
| B1    | 550.00 | c | ✓        |
|       | 125.00 | c | ?        |
| GA    | 55.00  | c | ✓        |
| NA    | 75.00  | c | ✓        |
| Sn    | 160.00 | c | X        |
|       | 60.00  | c | ?        |
|       | 65.00  | c | ?        |
| Bu    | 190.00 | c | ✓        |
|       | 30.00  | c | ?        |
| NA    | 10.00  | c | ✓        |
| Sn    | 30.00  | c | X        |
| NA    | 15.00  | c | X        |
| NA    | 15.00  | c | ✓        |
|       | 100.00 | c | ?        |

1,985.00

Add 15% : 297.75

2,282.75

- 1 pc tailgate windscreen glass sealant
- 1 pc tailgate windscreen glass damping seal
- 1 pc rear number plate

NA 40.00 sn ✓  
NA 20.00 sn ✓  
Sn 40.00 sn X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...



CO. REG. NO: 199402370D  
GST NO: M2-0123250-3

AUTO PTE LTD

## 金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,  
Sin Ming AutoCity, Singapore 575722  
Tel: 6452 7018 Fax: 6458 3895  
Email: service@kkimhin.com.sg

Vehicle Insured : SJU 6026 H  
Our Ref : 190475

Page : 2  
No. : 30682

To remove, cut out damaged parts,  
panel beating, welding, align,  
refix and to renew affected parts.

600  
750.00

To remove and refit rear windscreen  
glass and conduct water leak test

120.00 ✓

To remove and refit rear upholstery  
trimming, roof lining, seats,  
speaker board in order to  
facilitate repairing works

120.00 600

To transfer tailgate's fittings

80.00 600

To remove and refit reverse sensor  
assy.

80.00 500

To putty and respray on affected  
portions.

900.00 7500

Total : S\$ 4,432.75  
=====

Singapore Dollars Four Thousand Four Hundred  
and Thirty Two and Cents Seventy Five Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.