

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 808X**

**AAD1908-160**

*Not Authorized  
Resurvey B4 paint  
@ 2374.57*

Vehicle No.:  
Chassis No.:  
Vehicle Make:  
Vehicle Model: 23 AUG 2019  
Date of Accident :  
Third Party Insurer :  
Date of Registration :

**SHD 808X**  
VF1ABL15AUC283345  
RENAULT  
LATITUDE  
22.8.19  
**TOKIO MARINE**  
29/12/2017

PART		LIST	
1	1 BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46
2	1 BUMPER LOWER REAR	\$	<i>part</i> 768.84
3	1 BUMPER BRACKET CTR REAR	\$	<i>SL</i> 113.47
4	1 BUMPER BRACKET SIDE RH REAR	\$	<i>SL</i> 135.97
5	1 BUMPER RETAINER RH REAR	\$	<i>SL</i> 44.99
6	1 BUMPER REFLECTOR RH	\$	<i>SL</i> 43.61
7	1 BUMPER BRACKET SIDE LH REAR	\$	<i>SL</i> 135.97
8	1 BUMPER RETAINER LH REAR	\$	<i>SL</i> 44.99
9	1 BUMPER REFLECTOR LH	\$	<i>SL</i> 43.61
10	1 BUMPER BEAM REAR	\$	<i>N</i> 777.52
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>N</i> 225.95
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>N</i> 225.95
13	1 OUTER PANEL REAR (End Panel)	\$	<i>N</i> 1,471.77
14	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>SL</i> 404.56
15	1 TAILLAMP RH	\$	<i>SL</i> 552.55
16	1 TAILLAMP PANEL RH	\$	<i>N</i> 986.70
17	1 TAILLAMP LH	\$	<i>SL</i> 552.55
18	1 TAILLAMP PANEL LH	\$	<i>N</i> 986.70
19	1 BOOT REAR	\$	<i>N</i> 2,872.68
20	1 BOOT FINISHER	\$	<i>SL</i> 470.06
21	1 BOOT WHEATERSTRIP	\$	<i>SL</i> 323.05
22	1 BOOT REFLECTOR LAMP LH	\$	<i>SL</i> 493.35
23	1 BOOT REFLECTOR LAMP RH	\$	<i>SL</i> 493.35
24	1 BOOT BADGE 'RENAULT'	\$	<i>un</i> 225.36
25	1 BOOT BADGE	\$	<i>un</i> 225.36
26	1 BOOT STRUT LH	\$	<i>SL</i> 276.08
27	1 BOOT STRUT RH	\$	<i>SL</i> 276.08

**Trans-cab Auto Services Pte Ltd**

**AAD1908-160**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 808X**

28	1	BOOT HINGE LH	\$	<i>n</i>	367.84	}
29	1	BOOT HINGE RH	\$	<i>n</i>	367.84	
30	1	BOOT INNER TRIM	\$	<i>sh</i>	586.45	
31	1	BOOT SWITCH	\$	<i>sh</i>	168.13	
32	1	BOOT LOCK	\$	<i>n</i>	202.67	
33	1	BOOT LOCK CATCH	\$	<i>n</i>	74.40	
34	1	EXHAUST REAR	\$	<i>n</i>	7,489.05	
35	1	EXHAUST CAP REAR	\$	<i>n</i>	230.49	
<b>TOTAL</b>			<b>\$</b>		<b>23,766.42</b>	
<b>10%</b>			<b>\$</b>		<b>2,376.64</b>	
			<b>\$</b>		<b>21,389.78</b>	

**Special Nett**

1	1SET	PARKING AID	\$	<i>sh</i>	700.00	X
2	1SET	REAR BUMPER CLIP	\$	<i>na</i>	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	<i>na</i>	33.00	—
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i>	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	<i>na</i>	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	<i>na</i>	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	<i>na</i>	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	<i>na</i>	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	<i>na</i>	66.00	—
10	1	BOOT STICKER "Trans-cab"	\$	<i>na</i>	30.00	}
11	1	BOOT STICKER "6555-3333"	\$	<i>na</i>	30.00	
12	1	EXHAUST MOUNTING REAR	\$	<i>sh</i>	17.82	
13	2	REAR WINDSCREEN SEALANT	\$	<i>na</i>	80.00	
14	1	WINDSCREEN MOULDING	\$	<i>na</i>	100.00	
15	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i>	100.00	
16	1	BOOT INNER TRIM CLIP	\$	<i>na</i>	45.00	
17	1SET	BOOT FINISHER CLIP	\$	<i>na</i>	24.20	
18	1	TAILLAMP CLIP LH	\$	<i>na</i>	5.00	}
19	1	TAILLAMP CLIP RH	\$	<i>na</i>	5.00	
20	1	REAR BUMPER PROTECTOR	\$	<i>na</i>	100.00	<i>405n</i>
<b>TOTAL</b>			<b>\$</b>		<b>1,484.02</b>	

**TOTAL PARTS \$ 22,873.80**

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 808X****AAD1908-160****LABOUR**

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>un</i> 380.00	<i>X</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>un</i> 170.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	<i>un</i> 170.00	<i>X</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>un</i> 170.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>un</i> 170.00	<i>X</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>601</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,500.00	<i>2001</i>
Putty And Spray Painting Of The Affected Portion.	\$	4,500.00	<i>2201</i>
To repair and realign rear exhaust pipe.	\$	<i>un</i> 170.00	<i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>un</i> 170.00	<i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>un</i> 170.00	<i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>un</i> 170.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>un</i> 220.00	<i>X</i>

**Trans-cab Auto Services Pte Ltd**

**AAD1908-160**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 808X**

To transfer of rear bumper fittings, attachment and perform water seepage test. \$ *va* 380.00 X

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair. \$ *an* 380.00 X

**TOTAL \$ 11,890.00**

**Over All Total \$ 34,763.80**

**PART BY PART ( REPAIR DAY)**

~~15 DAYS~~  
*2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: