

ASS. REC. BY:

REF:

TM1/CC3/TM19614934/KVf3n2

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

1.3.1%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHD 808X

Yr Regn:

12.17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Logan c.c. 1895

Colour:

M. White/Red

A/C: Insured / Std / NI / NA

Sp. Reading

271 995

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VF/ABL 15AUC. 283345

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: M / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Sailun

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

22/8/19

D.O.I.

23/8/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

26/8/19

File pass to

26/8/19

Email GIA to TMS

26/8/19

2374.57 (Red 32,389.23, 93%)

SHD 808X - CC4/AXA 19614934/KVf3n2

GZ 6283R - X

D.O.A - 04/05/2018

RECEIVED 28 AUG 2019

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 26/8 - typist

Days Of Repair:

2

Resurvey No. of Trlp:

-

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S - RS. SI

Fixtures

Others

TOTAL

Report Format:

merimen

Lump Sum / I.B.I. (\$

2374.57

250

11

261

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Aug 2019		26 Aug 2019 11:47 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

**CLAIM SUBFOLDER DETAILS** [Created by insurer]

Insured:	FAVELLE FAVCO CRANES PTE LTD, Co. Reg. No.: 199503800G		
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Vehicle Reg. No.:	SHD808X	Date of Loss:	22/08/2019 09:00 - :59
Claim Type:	TP / M1906495	Policy/Cover Note No.:	MC011095 (Third Party Only) Coverage: 14/07/2019 - 13/07/2020
Vehicle Reg. No. (Insured):	GZ6283R	Policy No. (Claimant):	VFX/P1680520
		Excess:	S\$0.00
Repairer:	Trans Cab Auto Services Pte Ltd - Amk (HQ) No 2 Ang Mo Kio St 63, 569111 Ang Mo Kio - Tel:		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Dillen Senthilan so Selvarajoo]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 04/09/2019]		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

There are no mail for this case.

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Monday, 26 August 2019 11:23 AM  
**To:** SUR; 'motorclaims'  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP -TRANS-CAB AUTO SERVICES PTE LTD, DOA:22/8/2019, SHD 808X (TP VEHICLE), GZ 6283R (OI VEHICLE)  
**Attachments:** GIA.pdf; MARKING.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHD 808X at M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 23/8/2019

Enclosed herewith a copy of TP's GIA report and estimated cost of repair.

Kindly create claim in merimen for our necessary action.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**Veron Chen (LKKAUTO)**

---

**From:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Sent:** Monday, 26 August 2019 1:10 PM  
**To:** Veron Chen (LKKAUTO)  
**Subject:** FW: SHD 808X-DOA:22/8/2019 -- AAD1908-160  
**Attachments:** MARKING.pdf

Hi Veron

Amount confirmed \$ 2,374.57 (before GST).

Thank You  
Best Regards,  
**Ng Wai Yin**  
Finance Department  
TEL: 6603 1265 Ext.308

**\*\*\* Please be reminded that all claims correspondence to be send to [claims@transcab.com.sg](mailto:claims@transcab.com.sg)**



**TRANS-CAB SERVICES PTE LTD**  
No. 2 Ang Mo Kio Street 63, Singapore 569111  
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764  
Website: [www.transcab.com.sg](http://www.transcab.com.sg)

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

---

**From:** Veron Chen (LKKAUTO) [<mailto:veronchen@lkkauto.com>]  
**Sent:** Monday, 26 August, 2019 11:27 AM  
**To:** Ng Wai Yin <waiyin.ng@transcab.com.sg>; calvin.er@transcab.com.sg  
**Cc:** jasminetan@transcab.com.sg; SUR <sur@lkkauto.com>  
**Subject:** SHD 808X-DOA:22/8/2019

Dear Wai Yin/Calvin,

WITHOUT PREJUDICE

Finalize amount \$2374.57 @ 2 working days.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Monday, 26 August 2019 11:27 AM  
**To:** Ng Wai Yin; 'calvin.er@transcab.com.sg'  
**Cc:** jasminetan@transcab.com.sg; SUR  
**Subject:** SHD 808X-DOA:22/8/2019  
**Attachments:** MARKING.pdf

Dear Wai Yin/Calvin,

WITHOUT PREJUDICE

Finalize amount \$2374.57 @ 2 working days.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

8/22/2019

PARF/COE Rebate Enquiry

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	878K

**Vehicle Details**

Vehicle No.:	SHD808X
Vehicle to be Exported:	Yes
Intended Deregistration Date:	22 Aug 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C003357
Chassis No.:	VF1ABL15AUC283345
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	29 Dec 2017
First Registration Date:	29 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$19,998.00

**Intended PARF Rebate Details**

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Dec 2025
PARF Rebate Amount:	\$14,998.00

**Intended COE Rebate Details**

COE Expiry Date:	28 Dec 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$34,159.00
COE Rebate Amount:	\$27,111.00
<b>Total Rebate Amount:</b>	<b>\$42,109.00</b>

**Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 22 Aug 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	22/08/2019 11:15
Date Of Accident	22/08/2019 09:50
Exact Location Of Accident	UPPER BUKIT TIMAH ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD808X
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

### Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 D DCI (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VFX/P1680520
Cover Note Number	

### Driver

Name of Driver	A JO LEW YI PING
NRIC No	S7617159I
Date Of Birth	08/06/1976
Occupation	OUTDOOR
Date Of Driving Pass	25/03/2002
Driving Experience	17 YEARS AND 4 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91076988
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 660 YISHUN AVENUE 4 #04-307
Postcode	760660
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : JONATHAN GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

ON 22/08/2019 AT ABOUT 0950HRS, I WAS TRAVELLING STRAIGHT ALONG THE SECOND LANE OF UPPER BUKIT TIMAH ROAD. THE VEHICLES IN FRONT OF ME BRAKED AND I FOLLOW SUIT. SUDDENLY I HEARD A SCREECHING SOUND FOLLOWED BY AN IMPACT FROM THE REAR OF MY TAXI. VEHICLE B(GZ6283R) HAS FAILED TO STOP IN TIME AND COLLIDED ONTO THE REAR PORTION OF MY TAXI.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE SIZE TOO LARGE
Was there any audio recorded?	NO

#### Details of Witness 1

Name	JONATHAN
Phone Number	91175777
Email Address	

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GZ6283R
Vehicle Make/Model/Colour	LORRY
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE



Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name	A JO LEW YI PING
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SHD808X
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

## Sketch Plan Pg. 1

### SKETCH PLAN


#### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Sketch Plan #2 Pg. 1

### SKETCH PLAN

**SKETCH PLAN**

xxxx  
Read  
Write  
xxxx

Upper Bus & Timal Read.

A: SHD80BX  
B: G26283R

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to CIA Report.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Zhenxi

---

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 808X**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

23 AUG 2019

**AAD1908-160***Not Notified**Resurvey B4 paint**8 2374.57***SHD 808X**

VF1ABL15AUC283345

RENAULT

LATITUDE

22.8.19

**TOKIO MARINE**

29/12/2017

**PART**

1	1	BUMPER COVER REAR
2	1	BUMPER LOWER REAR
3	1	BUMPER BRACKET CTR REAR
4	1	BUMPER BRACKET SIDE RH REAR
5	1	BUMPER RETAINER RH REAR
6	1	BUMPER REFLECTOR RH
7	1	BUMPER BRACKET SIDE LH REAR
8	1	BUMPER RETAINER LH REAR
9	1	BUMPER REFLECTOR LH
10	1	BUMPER BEAM REAR
11	1	BUMPER BEAM BRACKET LH REAR
12	1	BUMPER BEAM BRACKET RH REAR
13	1	OUTER PANEL REAR (End Panel)
14	1	OUTER PANEL REAR (End Panel)TRIM
15	1	TAILLAMP RH
16	1	TAILLAMP PANEL RH
17	1	TAILLAMP LH
18	1	TAILLAMP PANEL LH
19	1	BOOT REAR
20	1	BOOT FINISHER
21	1	BOOT WHEATERSTRIP
22	1	BOOT REFLECTOR LAMP LH
23	1	BOOT REFLECTOR LAMP RH
24	1	BOOT BADGE 'RENAULT'
25	1	BOOT BADGE
26	1	BOOT STRUT LH
27	1	BOOT STRUT RH

**LIST**

\$	<i>Bur</i>	1,108.46	✓
\$	<i>notion</i>	768.84	✓
\$	<i>SL</i>	113.47	}
\$	<i>SL</i>	135.97	
\$	<i>SL</i>	44.99	
\$	<i>SL</i>	43.61	
\$	<i>SL</i>	135.97	
\$	<i>SL</i>	44.99	
\$	<i>SL</i>	43.61	
\$	<i>N</i>	777.52	
\$	<i>N</i>	225.95	
\$	<i>N</i>	225.95	
\$	<i>N</i>	1,471.77	} X
\$	<i>SL</i>	404.56	
\$	<i>SL</i>	552.55	
\$	<i>N</i>	986.70	
\$	<i>SL</i>	552.55	
\$	<i>N</i>	986.70	
\$	<i>N</i>	2,872.68	
\$	<i>SL</i>	470.06	
\$	<i>SL</i>	323.05	}
\$	<i>SL</i>	493.35	
\$	<i>SL</i>	493.35	
\$	<i>N</i>	225.36	
\$	<i>N</i>	225.36	
\$	<i>SL</i>	276.08	}
\$	<i>SL</i>	276.08	

**Trans-cab Auto Services Pte Ltd**

AAD1908-160

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 808X**

28	1	BOOT HINGE LH	\$	N	367.84	}	X
29	1	BOOT HINGE RH	\$	N	367.84		
30	1	BOOT INNER TRIM	\$	SL	586.45		
31	1	BOOT SWITCH	\$	SL	168.13		
32	1	BOOT LOCK	\$	N	202.67		
33	1	BOOT LOCK CATCH	\$	N	74.40		
34	1	EXHAUST REAR	\$	N	7,489.05		
35	1	EXHAUST CAP REAR	\$	N	230.49		
TOTAL			\$		23,766.42	0	
10%			\$		2,376.64		
			\$		21,389.78		

**Special Nett**

Special Nett					
1	1SET	PARKING AID	\$	700.00	X
2	1SET	REAR BUMPER CLIP	\$	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	33.00	—
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	66.00	} X
10	1	BOOT STICKER "Trans-cab"	\$	30.00	
11	1	BOOT STICKER "6555-3333"	\$	30.00	
12	1	EXHAUST MOUNTING REAR	\$	17.82	
13	2	REAR WINDSCREEN SEALANT	\$	80.00	
14	1	WINDSCREEN MOULDING	\$	100.00	
15	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00	
16	1	BOOT INNER TRIM CLIP	\$	45.00	
17	1SET	BOOT FINISHER CLIP	\$	24.20	
18	1	TAILLAMP CLIP LH	\$	5.00	
19	1	TAILLAMP CLIP RH	\$	5.00	
20	1	REAR BUMPER PROTECTOR	\$	100.00	405n
TOTAL			\$	1,484.02	

**TOTAL PARTS \$ 22,873.80**

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 808X****AAD1908-160****LABOUR**

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00	<i>X</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	<i>nn</i> 170.00	<i>X</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i> 170.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	<i>X</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>sol</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,500.00	<i>2001</i>
Putty And Spray Painting Of The Affected Portion.	\$	4,500.00	<i>2201</i>
To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00	<i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i> 170.00	<i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	<i>X</i>

**Trans-cab Auto Services Pte Ltd****AAD1908-160**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 808X**

To transfer of rear bumper fittings, attachment and  
perform water seepage test.

\$ *nn* 380.00 X

Labour charge to mount and dismount vehicle on jig  
bench, to facilitate repair.

\$ *nn* 380.00 X**TOTAL \$ 11,890.00****Over All Total \$ 34,763.80****PART BY PART ( REPAIR DAY)***15 DAYS**2 days**78*

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19014934/KVF3N2

Date: 28/08/2019

## REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MC011095
Claimant Vehicle No :	SHD808X	Insured Vehicle No :	GZ6283R
Date of Loss:	22/08/2019	Nature of Claim:	TP
		Claim No:	M1906495

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SHD808X	Engine No:	M9R8839C003357
Make & Model:	RENAULT LATITUDE, 2.0 D dCi (A)	Chassis No:	VF1ABL15AUC283345
Reg. Date:	29/12/2017 (Man. Year: 2015)	Odometer:	271995 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Sailun 9 mm	Rear Left Side:	Sailun 9 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Sailun 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,873.78	1,894.57	20,979.21	91.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,890.00	480.00	11,410.00	95.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>34,763.78</b>	<b>2,374.57</b>	<b>32,389.21</b>	<b>93.17</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>2,433.46</b>	<b>166.22</b>	<b>2,267.24</b>	<b>93.17</b>
<b>Nett Amount (S\$)</b>	<b>37,197.24</b>	<b>2,540.79</b>	<b>34,656.45</b>	<b>93.17</b>

## INSPECTION

Date of Assignment:	26/08/2019	
Date Inspected:	23/08/2019 Inspected At:	Trans Cab Auto Services Pte Ltd - Amk (HQ) No 2 Ang Mo Kio St 63 Singapore 569111
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 28 Aug 2019)
<b>Parts:</b> 143	RENAULT LATITUDE 2.0 D dCi (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SHD808X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled	1,108.46 FL	*1,108.46 FL
2	1		*BUMPER LOWER REAR	Dented/Cut	768.84 FL	*768.84 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	113.47 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
9	1		*BUMPER REFLECTOR LH	Serviceable	43.61 FL	*- FL
10	1		*BUMPER BEAM REAR	Repair	777.52 FL	*- FL
11	1		*BUMPER BEAM BRACKET LH REAR	Repair	225.95 FL	*- FL
12	1		*BUMPER BEAM BRACKET RH REAR	Repair	225.95 FL	*- FL
13	1		*OUTER PANEL REAR (END PANEL)	Repair	1,471.77 FL	*- FL
14	1		*OUTER PANEL REAR (END PANEL) TRIM	Serviceable	404.56 FL	*- FL
15	1		*TAILLAMP RH	Serviceable	552.55 FL	*- FL
16	1		*TAILLAMP PANEL RH	Repair	986.70 FL	*- FL
17	1		*TAILLAMP LH	Serviceable	552.55 FL	*- FL
18	1		*TAILLAMP PANEL LH	Repair	986.70 FL	*- FL
19	1		*BOOT REAR	Repair	2,872.68 FL	*- FL
20	1		*BOOT FINISHER	Serviceable	470.06 FL	*- FL
21	1		*BOOT WEATHERSTRIP	Serviceable	323.05 FL	*- FL
22	1		*BOOT REFLECTOR LAMP LH	Serviceable	493.35 FL	*- FL
23	1		*BOOT REFLECTOR LAMP RH	Serviceable	493.35 FL	*- FL
24	1		*BOOT BADGE RENAULT	Not Necessary	225.36 FL	*- FL
25	1		*BOOT BADGE	Not Necessary	225.36 FL	*- FL
26	1		*BOOT STRUT LH	Serviceable	276.08 FL	*- FL
27	1		*BOOT STRUT RH	Serviceable	276.08 FL	*- FL
28	1		*BOOT HINGE LH	Repair	367.84 FL	*- FL
29	1		*BOOT HINGE RH	Repair	367.84 FL	*- FL
30	1		*BOOT INNER TRIM	Serviceable	586.45 FL	*- FL
31	1		*BOOT SWITCH	Serviceable	168.13 FL	*- FL
32	1		*BOOT LOCK	Repair	202.67 FL	*- FL
33	1		*BOOT LOCK CATCH	Repair	74.40 FL	*- FL
34	1		*EXHAUST REAR	Repair	7,489.05 FL	*- FL
35	1		*EXHAUST CAP REAR	Repair	230.49 FL	*- FL
36	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
37	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
38	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
39	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
40	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
41	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
42	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
43	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
44	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*BOOT STICKER TRANS-CAB	Not Necessary	30.00 FS	*-FS
46	1		*BOOT STICKER 6555-3333	Not Necessary	30.00 FS	*-FS
47	1		*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*-FS
48	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*-FS
49	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*-FS
50	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*-FS
51	1		*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*-FS
52	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*-FS
53	1		*TAILLAMP CLIP LH	Not Necessary	5.00 FS	*-FS
54	1		*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*-FS
55	1		*REAR BUMPER PROTECTOR	Necessary	100.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>25,250.42</b>	<b>2,082.30</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>2,376.64</b>	<b>187.73</b>
<b>Total Parts (\$\$)</b>	<b>22,873.78</b>	<b>1,894.57</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
2	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
3	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
4	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
5	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	0.00
6	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
7	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	4,500.00	200.00
8	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,500.00	220.00
9	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
10	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
11	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
12	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
13	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
14	TO TRANSFER OF REAR BUMPER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
15	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR	New	380.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>11,890.00</b>	<b>480.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >