

ASS. REC. BY: _____ REF: CS/MSG19014938 / Uqf3n2 Special Instruction: _____

Waiman
Surveyor: Marcus ASSIGNMENT (Office)

From (Person): Monica Chung Pizher of MS19 Date/Time: 26.8.19 9.25.4.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: PA 7876Z Insured: SLV 8698G

at Workshop m/s: Focus Auto Tel: 68869097

of 1 Kati Bukit Ave 6 #02-48

Policy No: A29062933AVW Claim No: 603606

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 21.8.19
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 26.8.19 9.32.4.m Person Contacted: Lau H.O.D. Endorsement: _____

Vehicle: (IN) OUT

Date/Time	Action/Instruction (✓) Estimate
	SLV 8698G - X
	PA 7876Z - X
02/9/19 @ 3.12pm revised to Monica Chung via Messenger.	

08/11/2017 wef
ASS. REC. BY: *Marius*

REF:

MS161

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: *PA 78762*
at Workshop n/s *focus*
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: *PA 78762* Yr Regn: *9 08*
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or *CA*
Make: *Toyota hiace* *commuter 6-L* *2982*
Colour: *Silver* A/C: Insured / Std / NI / NA
Sp. Reading: *425670* T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: *KDH 2230004399*
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *195-215*
R: _____
6 SS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front 6 mm Rear 6 mm
R/Bal. 6 mm L/Bal. 6 mm
D.O.A. *21/8/19* D.O.I. *26/8/19*
Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rear
The U/C / Chassis frame / Body Structure affected due to collision.

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: *5* days Res.: Yes or No

Lum Sum: *20* % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

HIA 12 472 coe 14-9-2023

29/8/19 d/s 64650 confirmed with MR Wong (led to 4150.53, 47%)

RECEIVED 03 SEP 2019

2/9/2019

Date/Time, File Pass to?

1) *02/5/2019*

Date/Time, File Return to?

2) _____

☐ : Preli. Report

☐ : Final Report

Days Of Repair: *5*

Resurvey No. of Trip: *1*

Survey Fee:

Transportation:

Add Fee:

☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

____ S + RS ____ S

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.A. (\$ _____)

MER-TP

4650

150
11

161

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 27 Aug 2019

Preliminary Advice

Insured Vehicle No	: SLU8698G	Accident Date	: 21/08/2019
TP Vehicle No	: PA7876Z	Assignment Date	: 26/08/2019
Make	: TOYOTA HIACE	Est. Duration of Repair	: 5.00
Date of Inspection	: 26/08/2019		
Inspection At	: FOCUS AUTO PTE LTD (HQ) 1 KAKI BUKIT AVE 6, #02-48/50 AUTOBAY SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,800.53
Revised Amount	:S\$	5,839.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,839.50
Lump Sum Repair	:S\$	4,650.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Aug 2019		26 Aug 2019 09:25 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TARAK ASHOK PUJARA, ID: S7489394E, Tel: +6598359917								
Main Claimant:	TEO TRANSPORT TRADING, Co. Reg. No.: 53178343W								
Vehicle Reg. No.:	PA7876Z	Date of Loss:	21/08/2019 12:00 - :59 [131 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 603606	Policy/Cover Note No.:	A29062933AVW (Comprehensive) Coverage: 15/12/2018 - 14/12/2019						
Vehicle Reg. No. (Insured):	SLU8698G	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	Focus Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #02-48/50 Autobay, 417883 Kaki Bukit - Tel: 68869097								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 27/08/2019]								
Driver/Custodian (Insured):	PUJARA TRUPTI TARAK (43 / Female), NRIC: S7655897C, Tel: +6591680457 Email:								
Adj Asg. Remarks:	on WP. Liab: NA. Agree on SJE. Assign: Marcus Chua from LKK Auto Consultants Pte Ltd. Contact: Lau @ 6886 9097.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Das WeltAuto.
Used cars you can trust. Guaranteed.

Click this banner to view available models.



toyota hiace commuterPrice RangeDepreciation> 10 yearVehicle TypeSubmitAdvanced Search

Home > Used Cars > Valley Trading > Toyota Hiace Commuter 3.0A (COE till 08/2023)

Toyota Hiace Commuter 3.0A (COE till 08/2023)

OverviewFinancialAccessoriesSimilarResearchPhotosMap

Price	\$28,800	Lifespan	06-Aug-2028
Depreciation	\$7,290 /yr	Reg Date	07-Aug-2008 (3yrs 11mths 11days COE left)
Mileage	N.A.	Manufactured	2008
Road Tax	N.A.	Transmission	Auto
Dereg Value	\$12,303 as of today (change)	OMV	\$36,177
COE	\$15,582	ARF	\$1,809
Engine Cap	2,982 cc	No. of Owners	2
Curb Weight	2,180 kg		
Type of Vehicle	Bus/Mini Bus		

Features

14 Seater PA Bus. Automatic Transmission. View specs of the Toyota Hiace

Description

2 Owners. Durable Toyota Hiace 14 Seater PA Bus. Very Well Maintained And Powerful Euro 4 1KD Turbo Engine. Able To Renew 5 Or 10 Years COE.

Category

COE Car, Premium Ad Car

Status

Available

Resources



Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free
Find out the market value of your existing car for free. Get started



ShortlistCompareAdd note
Report ErrorMore Actions

Seller Information

Company	Valley Trading
	• dealer's pricelist
	• 26 vehs sold 48 vehs available
Address	210 Turf Club Road Lot C6 Search cars nearby this location
Location	Car Mall @ The Grandstand
Office No	63445088
Contact Person(s)	Thomas 96302490 Patrick Teo 96681822 Richard Teo 90251988

Posted on: 26-Aug-2019 | Last Updated on: 26-Aug-2019

Upfront Payment	+ more Financial info	
Transfer Fee	\$25	
Down Payment	\$2,880 (change)	Maximum 90% Loan
1st Instalment	\$649	Based on 4.5% interest rate
Compare		

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Business
Owner ID: 343W

Vehicle Details

Vehicle No.: PA7876Z
Vehicle to be Exported: No
Intended Deregistration Date: 22 Aug 2019
Vehicle Make: TOYOTA
Vehicle Model: HIACE COMMUTER 3.0GL A
Primary Colour: Silver
Manufacturing Year: 2008
Engine No.: 1KD1841372
Chassis No.: KDH2230004399
Maximum Power Output: -
Open Market Value: \$38,550.00
Original Registration Date: 15 Sep 2008
First Registration Date: 15 Sep 2008
Transfer Count: 2
Actual ARF Paid: \$1,928.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 14 Sep 2023
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 5
PQP Paid: \$15,348.00
COE Rebate Amount: \$12,472.00
Total Rebate Amount: \$12,472.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 22 Aug 2019.

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/08/2019 18:25
Date Of Accident	21/08/2019 12:05
Exact Location Of Accident	SLIP ROAD OF NEW CHANGI ROAD TO SIGLAP ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	PA7876Z
Insured/Policyholder	
Name Of Registered Owner	TEO TRANSPORT TRADING
Co Reg No	53178343W
Email Address	TEO.TRANSPORTSERVICES@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-97714360

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE COMMUTER
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VBX/P2174629
Cover Note Number	CN013206

Driver

Name of Driver	GIAM THIAM POH
NRIC No	S1267999H
Date Of Birth	06/09/1957
Occupation	OUTDOOR
Date Of Driving Pass	29/12/1978
Driving Experience	40 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96356880
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 24 HOUGANG AVE 3 #07-414 SG
Postcode	520024
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : CYNTHIA GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

(1) I, GIAM THIAM POH work for TEO TRANSPORT TRADING and using the vehicle for work at the time of accident. (2) Refer to SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLU8698G
Vehicle Make/Model/Colour	RED
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	PIYARA TRUPTI TARAK
NRIC/Passport Number	S7655897C
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

IMPORTANT NOTICE

1. Please report correctly the details of the accident to avoid up the Claims process
2. This form must be completed by the Policyholder and/or the Authorized Driver
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The need and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies
5. Any false reporting may be referred to the Police for investigation
6. The report will be forwarded by the insurers to the GDA (General Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.

7. By the signing of this report to the insurers, who hereby consent to the archiving of this report at the time and to consent of the report being made available thereafter.

6. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurers, my workshop and the General Insurance Association of Singapore ("GIA") may have permission to collect, use, disclose and/or process my personal data (personal information) set out in this report and any other personal information provided by me or furnished by my insurer to which I am the "Personal Information" and (b) I consent and authorize such personal information to all insurers who have provided services to me in this accident (all insurers) who have insured my vehicle's insurance in this accident shall be collectively referred to as the "Insurers"; the Insurers' respective forms, the Insurers' Authority of Singapore and any relevant government agency/authority (such as the police, for the Insurers) or

- (b) processing, handling, without sharing with the claimants including the settlement of the claims and any Insurers' investigations relating to the claims.

- (c) investigating the accident and/or the claims;

- (d) carrying out and/or dealing with my concerns or requesting to any Insurers by me;

- (e) administering my claims (including the making of arrangements, statements, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the claim as well as the external issue of investigation/claim handling, and/or

- (f) complying with applicable law in administering, processing, handling and/or dealing with my claims, including the "Purposes".

- (g) all Insurers (who have insured my vehicle) involved in this accident and the Insurers' respective forms, any/any specified Insurers, use, disclose and/or process my personal information for any or some of the above purposes, and

- (h) any personal information may be disclosed by any of the Insurers and/or can be, then third party service providers, representing these Insurers (Third Parties), which may be, with details of Insurers, for power of attorney of the above Insurers.

- (i) my personal information will also be collected and used to manage claims through for the purposes of third government investigations and management or payment of all future claims.

- (j) my personal information will also be used for the purpose of insurance.

- (k) as an insurer, while my other third parties, that exist in handling, investigating, claiming or managing these regulations, we will collect and process personal information or personally required for the purposes stated, or

- (l) for complying with other regulatory requirements and/or government, laws or regulations.



Policyholder's Signature
Date & Time

Insurer's Signature
(Signature and full name)
Date & Time


Signatures of Insurers
Agency
Date & Time

SKETCH PLAN

Sketch Plan #2 Pg. 1

SKETCH PLAN

Sigbee Road



Vehicle A: PATTERNS
Vehicle B: MACHINERY

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the above said time, I was ~~was~~ driving my vehicle
upwards
(1A78765) traveling along New Orleans Road turning left to
Sigbee Road. I was stationary at the stop line of the junction
and waiting the traffic close suddenly vehicle bearing number
plate (SAU 8674) collected into my vehicle rear portion

DECLARATION

(I/We hereby declare the foregoing particulars are true to best of my/our knowledge)



Police Officer's Signature

Name & Title

Driver's Signature

(If driver is not the person/ persons)

Date & Time

Accident Investigator's Signature

Name

Date & Time

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883
 TEL: 6886 9097 FAX: 6841 9095 Email: focusautoptehd@yahoo.com.sg
 GST:201004495R RCB NO:201004495R

*not Antboard
 26/8/19
 2/5 = 4650/
 to be paid to After repair
 567.*

M/S: MSIG Insurance (Singapore) Pte Ltd
 16 Raffles Quay,
 #24-01 Hong Leong Building,
 Singapore 048581

TEL: 6220 9644 FAX: 6225 6371
 ATTN: Motor Claim Department

Estimate No: EST0000981
 Date: 19 Aug 2019
 Policy No: VBX/P2174629
 Veh Reg No: PA7876Z
 Make/Model: TOYOTA HIACE
 COMMUTER 3.0GL A
 Chassis No: KDH2230004399
 Engine No: 1KD1841372
 Reg. Date:

Your Ref No: PA7876Z
 Claim Type: Third Party
 Accident Date: 21/08/2019
 TP Veh Reg No: sln8698G

Estimate Repair Cost for Vehicle No :PA7876Z

PAGE:1/2

Description	U/Price	Quantity	List Price SS	Amount SS
List Price				
1 Rear Boot <i>Taifete</i> <i>1955-10</i> <i>Body 20</i>	2,065.00	1 PC	2,065.00	
2 Rear Boot Lock	275.00	1 PC	275.00	
3 Rear Boot Lock Catch	45.00	1 PC	45.00	X
4 Rear Boot Rubber	395.00	1 PC	395.00	
5 Rear Boot Emblem (GL)	45.00	1 PC	45.00	
6 Rear Boot Centre Logo	65.00	1 PC	65.00	
7 Rear Boot Inner Cover Board <i>425-10</i> <i>del/cn</i>	450.00	1 PC	450.00	
8 Rear Boot Shock Absorber	195.00	1 PC	195.00	X
9 Rear Tail Lamp <i>303-10</i> <i>o/s rne</i>	398.00	2 PCS	796.00	<i>1 PC</i>
10 Rear Tail Lamp Lower Garnish	145.00	2 PCS	290.00	X
11 Rear Tail Lamp Lower Garnish Side Bracket	56.00	2 PCS	112.00	X
12 Rear End Panel Inner	890.00	1 PC	890.00	
13 Rear End Panel Outer	544.50	1 PC	544.50	
14 Rear Bumper Side Retainer	55.00	2 PCS	110.00	
15 Rear Bumper Lower Bracket <i>25x4=100</i> <i>Best</i>	45.00	4 PCS	180.00	
16 Rear Bumper Clip	5.50	6 PCS	33.00	
17 Rear Floor Panel Top Garnish	165.20	1 PC	165.20	
18 Rear Boot Centre Garnish	165.00	1 PC	165.00	X
			6,820.70	
	Less 25%		1,705.18	5,115.53
Special Net				
19 Rear Boot Sticker 70km/h	20.00	1 PC	20.00	<i>10</i>
20 Rear Boot Sticker (Emergency Door)	15.00	1 PC	15.00	<i>10</i>
21 Rear Boot Sticker (Pull to Open)	10.00	1 PC	10.00	<i>✓</i>
22 Rear Bumper Sensor	480.00	<i>1 set</i> 2 SET	960.00	<i>200</i>
23 Rear Number Plate	50.00	1 PC	50.00	X
24 Rear Windscreen <i>Gum sealant</i>	80.00	1 PC	80.00	<i>40</i>
			1,135.00	1,135.00

Labour

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883
 TEL: 6886 9097 FAX: 6841 9095 Email: focus.autopetltd@yahoo.com.sg
 GST:201004495R RCB NO:201004495R

M/S : MSIG Insurance (Singapore) Pte Ltd
 16 Raffles Quay,
 #24-01 Hong Leong Building,
 Singapore 048581

TEL: 6220 9644 FAX: 6225 6371

ATTN: Motor Claim Department

Your Ref No: PA7876Z
 Claim Type: Third Party
 Accident Date: 21/08/2019
 TP Veh Reg No: sln8698G


Estimate No: EST0000981
 Date: 19 Aug 2019
 Policy No: VBX/P2174629
 Veh Reg No: PA7876Z
 Make/Model: TOYOTA HIACE
 COMMUTER 3.0GL A
 Chassis No: KDH2230004399
 Engine No: 1KD1841372
 Reg. Date:

Estimate Repair Cost for Vehicle No :PA7876Z

PAGE:2/2

Description	U/Price	Quantity	List Price SS	Amount SS
25 Panel Beating	1,400.00	1	1,400.00	800
26 Check Wiring	60.00	1	60.00	30
27 Rust Proofing	80.00	1	80.00	60
28 To Remove & Replace Bumper Sensor	160.00	1	160.00	50
29 Spray Painting	850.00	1	850.00	650
			2,550.00	2,550.00
			Total	SS 8,800.53

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND EIGHT HUNDRED AND CENTS FIFTY THREE ONLY



For FOCUS AUTO PTE LTD

Focus Auto Pte Ltd
 No 1 Kaki Bukit Ave 6 Auto Bay
 #02-50 Singapore 417883
 Tel: 68349695

AUTHORISED SIGNATURE

P- 5306.00
 25%
 P- 3979.50
 S.N 270.00
 L-- 1590.00
 5839.50
 4671.60

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19014938/UQF3N2

Date: 06/09/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A29062933AVW
Claimant Vehicle No :	PA7876Z	Insured Vehicle No :	SLU8698G
Date of Loss:	21/08/2019	Nature of Claim:	TP
		Claim No:	603606

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PA7876Z		
Make & Model:	TOYOTA HIACE, 3.0 D COMMUTER GL AT 2WD 4DR LWB (M)	Engine No:	1KD1841372
Reg. Date:	15/09/2008 (Man. Year: 2008)	Chassis No:	KDH2230004399
Colour:	Silver	Odometer:	425670 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,250.52	4,249.50	2,001.02	32.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,550.00	1,590.00	960.00	37.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,800.52	5,839.50	2,961.02	33.65
Approved Total (Overridden) (\$\$)		4,650.00		
(\$\$)	8,800.52	4,650.00	4,150.52	47.16
+ GST 7.00/7.00% (\$\$)	616.04	325.50	290.54	47.16
Nett Amount (\$\$)	9,416.56	4,975.50	4,441.06	47.16

INSPECTION

Date of Assignment:	26/08/2019	
Date Inspected:	26/08/2019	Inspected At: Focus Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #02-48/50 Autobay Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 06 Sep 2019)	
Parts:	N/A	TOYOTA HIACE 3.0 D COMMUTER GL AT 2WD 4DR LWB (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PA7876Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Badly Dented	2,065.00 FL	*1,955.10 FL
2	1		*REAR BOOT LOCK	Dented/Jammed	275.00 FL	*275.00 FL
3	1		*REAR BOOT LOCK CATCH	Not Necessary	45.00 FL	*- FL
4	1		*REAR BOOT RUBBER	Twisted	395.00 FL	*395.00 FL
5	1		*REAR BOOT EMBLEM (GL)	Necessary	45.00 FL	*45.00 FL
6	1		*REAR BOOT CENTRE LOGO	Necessary	65.00 FL	*65.00 FL
7	1		*REAR BOOT INNER COVER BOARD	Deformed/Cracked	450.00 FL	*425.10 FL
8	1		*REAR BOOT SHOCK ABSORBER	Not Necessary	195.00 FL	*- FL
9	1		*REAR TAIL LAMP	O/s Cracked	796.00 FL	*303.10 FL
10	2		*REAR TAIL LAMP LOWER GARNISH	Repair	290.00 FL	*- FL
11	2		*REAR TAIL LAMP LOWER GARNISH SIDE BRACKET	Not Necessary	112.00 FL	*- FL
12	1		*REAR END PANEL INNER	Badly Dented	890.00 FL	*890.00 FL
13	1		*REAR END PANEL OUTER	Badly Dented	544.50 FL	*544.50 FL
14	2		*REAR BUMPER SIDE RETAINER	Bent/Cracked	110.00 FL	*110.00 FL
15	4		*REAR BUMPER LOWER BRACKET	Bent	180.00 FL	*100.00 FL
16	6		*REAR BUMPER CLIP	Necessary	33.00 FL	*33.00 FL
17	1		*REAR FLOOR PANEL TOP GARNISH	Twisted	165.20 FL	*165.20 FL
18	1		*REAR BOOT CENTRE GARNISH	Not Necessary	165.00 FL	*- FL
19	1		*REAR BOOT STICKER 70KM/H	Necessary	20.00 FS	*10.00 FS
20	1		*REAR BOOT STICKER (EMERGENCY DOOR)	Necessary	15.00 FS	*10.00 FS
21	1		*REAR BOOT STICKER (PULL TO OPEN)	Necessary	10.00 FS	*10.00 FS
22	1		*SET REAR BUMPER SENSOR	Shorted	960.00 FS	*200.00 FS
23	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
24	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	7,955.70	5,576.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,705.18	1,326.50
Total Parts (\$\$)	6,250.52	4,249.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,400.00	800.00
2	CHECK WIRING	New	60.00	30.00
3	RUST PROOFING	New	80.00	60.00
4	TO REMOVE & REPLACE BUMPER SENSOR	New	160.00	50.00
5	SPRAY PAINTING	New	850.00	650.00
Gross Labour Cost (S\$)			2,550.00	1,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >