

ASS. REC. BY:

REF:

CS/CT219014943/DSF302

Special Instruction:

Signature

Daman

ASSIGNMENT (Office)

From (Person): Tan Kah Leong

of

CT2

Date/Time: 23.8.19

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SH 7153D

Insured:

YN 7088G

at Workshop m/s Channi Motor

Tel:

6542 5119

of 10 Ame Industrial park 2A #03-19

Policy No: DMCVSR17 39921902

Claim No:

SNM190703936102

Sum Insured:

Excess:

Make of Veh:

D.O.A.

23.8.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 26.8.19 12.03 p.m

Person Contacted:

Lynn

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	YN 7088G - X
	SH 7153D: CS/III 18013780/Gtd 302 D.O.A: 20/07/2018

Surveyor

ASSIGNMENT

COE Sept 2024

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop n/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 86 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SH 7153 D Yr Regn: 2016 / Sept
 Type: M.Car / M.Cycle / Bus / Van / Lorry (Taxi) / Prime Mover /
 Truck / Trailer or
 Make: Hyundai I40 c.c. 1685
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 469988 T/Radio: Insured / Std / NI / NA
 Eng/No: D4FDGU670248
 C/No: KMHLB41UMGU093515
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: NA / S/Rim / STD A/Rim or
 Tyre Size: F: 205 / 60 R16
 R: —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Campeon

Front Rear
 R/Bal. S mm R/Bal. S mm
 L/Bal. S mm L/Bal. S mm
 D.O.A. 23/08/2019 D.O.I. 27/08/2019
 Survey held at Chunni AMK

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

0/8 Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Chun Teiping YH 7088G

24/09/19 pinay 2/5 83001 - with 8 days of rev
(C\$ 5,902.84 Red - 42%)

RECEIVED 25 SEP 2019

Date/Time, File Pass to?

25/09/19
Type

Date/Time, File Return to?

2)

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 8

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ + RS, SI

Photos

Others

TOTAL

220

Report Format :

Lump Sum / I.B.I: (\$ 8,300 / 45)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Aug 2019		23 Aug 2019 17:30 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SH7153D	Date of Loss:	23/08/2019 08:00 - :59
Claim Type:	TP / SNM19D203936C02	Policy/Cover Note No.:	DMCVSN17389219022
Vehicle Reg. No. (Insured):	YN7088G	Policy No. (Claimant):	MCOM0015
		Excess:	S\$800.00
Repairer:	Chunni Motor Pte Ltd (HQ) 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint, 568047 Ang Mo Kio - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]		
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/09/2019]		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

MC0819111094 / ComfortDelGro Engineering Pte Ltd - Loyal
 ENTRY DATE & TIME: 23/08/2019 14:01
 SUBMITTED BY: Huang XiaoYen

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 23/08/2019 14:01
 Date Of Accident 23/08/2019 08:00
 Exact Location Of Accident UPPER THOMSON TOWARDS YISHUN
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SH7153D
 Insured/Policyholder
 Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD
 Co Reg No 199303821R
 Email Address FLEETSAFETY@CDGTAXI.COM.SG
 Mobile Phone No
 Alternative Phone No OFFICE-65508768
 Vehicle Particulars
 Manufacturer HYUNDAI
 Model I40
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category TAXI
 Insurance Company
 Name of Insurance Company INDIA INTERNATIONAL INSURANCE PTE LTD
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
 Fleet Policy YES
 Policy Number MCOM0015
 Cover Note Number
 Driver
 Name of Driver PUAH SIEW KHOON
 NRIC No S0172224G
 Date Of Birth 31/05/1952
 Occupation OUTDOOR
 Date Of Driving Pass 06/11/1975
 Driving Experience 43 YEARS AND 9 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-96718290
 Fax Number
 Contact Number
 Email Address NOEMAIL

Address BLK 750 YISHUN STREET 72 #06-140
 Postcode 760750
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) Involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1

NAME: -
 GENDER: FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of Intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLS REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: -
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YN7088G
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver
 NRIC/Passport Number
 Contact Number 86890252
 Address
 Postcode
 Insurance Company Name CHINA TAIPING INSURANCE (SINGAPORE) PTE, LTD.
 Nature Of Damage FRT LEFT

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)

Date & Time: 23.08.2019@1000HRS

Reporting Centre Personnel's Signature
Name:

NRIC/FIN No.: June

SKETCH PLAN

A- SH 7153D
B- YN 7088G

Along Upper Thomson twds Yishun

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 23.08.2019 @ 0800hrs I was travelling along Upper Thomson twds Yishun with one female passenger onboard.

As I was travelling straight suddenly veh(B) YN 7088G cut into my lane and hit onto my vehicle rear right portion.

I have company video and photos at scene to support my claims.

No injury in this accident .

Veh(B) YN 7088G Male Driver HP: 8689 0252

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time: 23.08.2019@1030HRS

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.: June

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SH 7153D

DATE : 23.08.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Chunni Quiping

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper LT			\$ 553.00
	Rear Bumper Clip 10 pcs H/c			\$ 22.00
	Rear Bumper Bracket H/H		\$ 35.60	\$ 71.20
	Rear Fender With Housing (RH) Dented with housing		2020.00	\$ 4,736.80 4736.80
	Rear Fender Inner Lining (RH) H/H			\$ 169.30
	Rear Windscreen Moulding H/c			\$ 28.30
	Rear Door (RH) LT			\$ 2,201.10
	Rear Tyre Rim (RH) LT			\$ 325.30
	Rear Wheel Hub-Cap (RH) H/F			\$ 107.10
	Rear Wheelbearing ING & Hub Distorted			\$ 362.00
	Rear Trailing Arm (RH) Distorted			\$ 192.00
	Rear Assist (RH) Distorted			\$ 145.70
	Rear Shock Absorber (RH) Distorted			\$ 276.30
	Rear Shock Absorber Mounting (RH) H/H			\$ 81.30
	Rear Crossmember H/H			\$ 1,021.50
	Stabilizer Bar H/H			\$ 199.60
	Stabilizer Link H/H			\$ 85.90
	Rear Upper Arm (RH) Distorted			\$ 335.75
	Rear Lower Arm (RH) Distorted			\$ 353.80
	Rear Knuckle Arm (RH) Distorted			\$ 545.60
			10077.65	
			8062.12	
	SUB TOTAL			\$ 11,813.55
	LESS 20%			\$ 2,362.71
	DISCOUNTED TOTAL			\$ 9,450.84
	Rear Bumper Advertisement Logo H/c			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH) H/c		\$ 100.00	\$ 200.00
	Rear Windscreen Sealant H/c			\$ 46.00
	Rear Door Advertisement Logo (RH) H/c			\$ 100.00
	Rear Door Comfortdelgro & Apps Sticker (RH) H/c			\$ 80.00
	Rear Tyre (RH) H/H			\$ 216.00
			476.00	
				\$ 692.00

✓

✓

X

✓ 4736.80

X

✓

✓

✓

X

Z ✓

Z ✓

Z ✓

Z ✓

X

X

X

Z ✓

Z ✓

Z ✓

Z ✓

Z ✓

Z ✓

Z ✓

Z ✓

Z ✓

Z ✓

Z ✓

Z ✓

Z ✓

Z ✓

Z ✓

Z ✓

Z ✓

Z ✓

Z ✓

Z ✓

Z ✓



Z ✓

Z ✓

Z ✓

Z ✓

SH 7153D

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,200.00
	Spray Painting Charge			\$ 1,000.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 100.00
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00
	Remove/Refix Rear Windscreen Glass			\$ 120.00
	Remove/Refix Reverse Sensor			\$ 120.00
	Transfer of Door			\$ 120.00
	Remove/Refix Undercarriage (RR)		1860.00	\$ 200.00
	Rear Wheel Alignment			\$ 120.00
	Re-set Rear ABS System			\$ 200.00
	Re-set Rear Power Window System			\$ 200.00
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00
	TOTAL LABOUR			\$ 4,060.00
	ESTIMATE TOTAL			\$ 14,202.84
	27/08/2019 @ 1000m		10398.12	
	HA Arthur	L/S	8300/-	
	2/Sept 18 days.			
				
	LKK Auto			
				
	<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p>			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SH 7153 D

Technician:

Mileage: 469988

Time Printed 27.8.19 10:41 AM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
-0°50'		-3°00' 3°00'
3°52'		-0°19' 5°41'
-0°01'		-1°30' 1°30'
20°05'		
19°15'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-0°11'		-3°00' 3°00'
3°30'		-0°19' 5°41'
-0°01'		-1°30' 1°30'
12°53'		
12°42'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
-0°39'		-3°00' 3°00'
0°21'		-3°00' 3°00'
7°12'		-3°00' 3°00'
-0°02'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
-1°10'		-3°30' 2°30'
-0°03'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-0°43'		-3°30' 2°30'
2°12'		-1°30' 1°30'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
-0°27'		-3°00' 3°00'
2°09'		-3°00' 3°00'
-1°08'		-3°00' 3°00'

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19014943/DSF3N2

Date: 27/09/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN17389219022	
Claimant Vehicle No :	SH7153D	Insured Vehicle No :	YN7088G	
Date of Loss:	23/08/2019	Nature of Claim:	TP	Claim No: SNM19D203936C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH7153D		
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Engine No:	D4FDGU670248
Reg. Date:	15/09/2016 (Man. Year: 2016)	Chassis No:	KMHLB41UMGU093515
Colour:	Blue	Odometer:	469988 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Campeon 5 mm	Rear Left Side:	Campeon 5 mm
Front Right Side:	Campeon 5 mm	Rear Right Side:	Campeon 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,142.84	8,538.12	1,604.72	15.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,060.00	1,860.00	2,200.00	54.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,202.84	10,398.12	3,804.72	26.79
Approved Total (Overridden) (S\$)		8,300.00		
(S\$)	14,202.84	8,300.00	5,902.84	41.56
+ GST 7.00/7.00% (S\$)	994.20	581.00	413.20	41.56
Nett Amount (S\$)	15,197.04	8,881.00	6,316.04	41.56

INSPECTION

Date of Assignment: 23/08/2019

Date Inspected: 27/08/2019 Inspected At:

Chunni Motor Pte Ltd (HQ)
10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint
Singapore 568047

Estimated Period of Repair: 8.0 days

Adjuster: BRYAN TANI

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Sep 2019)
Parts:	143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SH7153D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	553.00 FL	*553.00 FL
2	10		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
3	2		*REAR BUMPER BRACKET	Not Necessary	71.20 FL	*- FL
4	1		*REAR FENDER INNER LINING (RH)	Not Necessary	169.30 FL	*- FL
5	1		*REAR WINDSCREEN MOULDING	Necessary	28.30 FL	*28.30 FL
6	1		*REAR DOOR (RH)	Bent	2,201.10 FL	*2,201.10 FL
7	1		*REAR TYRE RIM (RH)	Bent	325.30 FL	*325.30 FL
8	1		*REAR WHEEL HUP-CAP (RH)	Not fitted	107.10 FL	*- FL
9	1		*REAR WHEELBEARING ING & HUB	Damaged	362.00 FL	*362.00 FL
10	1		*REAR TRAILING ARM (RH)	Distorted	192.00 FL	*192.00 FL
11	1		*REAR ASSIST (RH)	Distorted	145.70 FL	*145.70 FL
12	1		*REAR SHOCK ABSORBER (RH)	Distorted	276.30 FL	*276.30 FL
13	1		*REAR SHOCK ABSORBER MOUNTING (RH)	Not Necessary	81.30 FL	*- FL
14	1		*REAR CROSSMEMBER	Not Necessary	1,021.50 FL	*- FL
15	1		*STABILIZER BAR	Not Necessary	199.60 FL	*- FL
16	1		*STABILIZER LINK	Not Necessary	85.90 FL	*- FL
17	1		*REAR UPPER ARM (RH)	Distorted	335.75 FL	*335.75 FL
18	1		*REAR LOWER ARM (RH)	Distorted	353.80 FL	*353.80 FL
19	1		*REAR KNUCKLE ARM (RH)	Distorted	545.60 FL	*545.60 FL
20	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 FS	*50.00 FS
21	2		*REAR FENDER ADVERTISEMENT LOGO (LH/RH)	Necessary	200.00 FS	*200.00 FS
22	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
23	1		*REAR DOOR ADVERTISEMENT LOGO (RH)	Necessary	100.00 FS	*100.00 FS
24	1		*REAR DOOR COMFORTDELGRO & APPS STICKER (RH)	Necessary	80.00 FS	*80.00 FS
25	1		*REAR TYRE (RH)	Not Necessary	216.00 FS	*- FS
26	1		*REAR FENDER WITH HOUSING (RH)	Dented	4,736.80 FL	*4,736.80 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,505.55	10,553.65
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,362.71	2,015.53
Total Parts (\$\$)	10,142.84	8,538.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	600.00
2	SPRAY PAINTING CHARGE	New	1,000.00	600.00
3	WIRING CHARGE	New	50.00	0.00
4	TUFF KOTE	New	100.00	40.00
5	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
6	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	80.00
7	REMOVE/REFIX REVERSE SENSOR	New	120.00	40.00
8	TRANSFER OF DOOR	New	120.00	60.00
9	REMOVE/REFIX UNDERCARRIAGE (RR)	New	200.00	150.00
10	REAR WHEEL ALIGNMENT	New	120.00	60.00
11	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE }	New	480.00	150.00
12	RE-SET REAR ABS SYSTEM }	New	200.00	0.00
13	RE-SET REAR POWER WINDOW SYSTEM }	New	200.00	0.00
Gross Labour Cost (\$\$)			4,060.00	1,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >