

2/03/2002

ASS. REC. BY:

REF:

CS/MSG/19014944/K15f302

Special Instruction:

Surveyor: Kalin

ASSIGNMENT (Office)

From (Person): Mhd Ashik B madi

of MS19

Date/Time: 23.8.19 17.40p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHB 8985A

Insured: SLM 9740C

at Workshop m/s Premier

Tel: 65 446689

23 Changi South Ave 2 #01-02

Policy No: 29795704mcx

Claim No: 603647

Sum Insured:

Excess:

Make of Veh:

D.O.A. 21.8.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 21.8.19 12.10p.m

Person Contacted: Liew

Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLM 9740C - X
	SHB 8985A - CC3 / CII1701916/H2ha302 D.O.A. 26/01/2017
27/08/19	@ 13:14 pm received RA to Mhd Ashik via minim

(08/11/13)

Surveyor: Kalvin

REF: _____

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHB 8985A Yr Regn: 28 May 2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA Optima c.c. 1685Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 642627 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNAH M414 ME 5463100

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/65R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hakk

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 20/8/19 D.O.I. 26/8/19Survey held at Premise

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

1/s Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
25/9/19	Chd 45 \$1550 / 3 Bp.
	C\$ 1,396.65 Red - 47%)

RECEIVED 28 SEP 2019

Date/Time, File Pass to?

26/09/19

1) Typist

Date/Time, File Return to?

2) _____

☐ : Prel. Report☒ : Final ReportDays Of Repair: 3Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)Survey Fee: 190

Transportation: _____

S + RS, SI

Photos

Others 11

TOTAL

161

Report Format:

Lump Sum / I.B.I. (\$) 1,550/- 4/5

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Aug 2019		23 Aug 2019 17:40 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	SKYWAY MOTOR PTE LTD, Co. Reg. No.: 199904194N								
Main Claimant:	PREMIER TAXIS PTE LTD, Co. Reg. No.: 200304975H								
Vehicle Reg. No.:	SHB8985A	Date of Loss:	21/08/2019 00:00 - :59 [62 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 603647	Policy/Cover Note No.:	28795104MCX Coverage: 08/08/2019 - 07/08/2020						
Vehicle Reg. No. (Insured):	SLM9740C	Policy No. (Claimant):							
		Excess:							
Repairer:	Premier Automotive Services Pte Ltd (HQ) 23 Changi South Ave 2, #01-02, 486443 Changi - Tel: 62148880								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 24/08/2019]								
Adj Asg. Remarks:	on WP. CAR IN. Liab: NA. Contact: Liew @ 6544 6689.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 27 Aug 2019

Preliminary Advice

Insured Vehicle No	: SLM9740C	Accident Date	: 21/08/2019
TP Vehicle No	: SHB8985A	Assignment Date	: 23/08/2019
Make	: KIA OPTIMA	Est. Duration of Repair	: 3 days
Date of Inspection	: 26/08/2019		
Inspection At	: Premier Automotive Services Pte Ltd (HQ) 23 Changi South Ave 2, #01-02 Singapore 486443		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,806.15
Revised Amount	:S\$	1,837.45
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,837.45

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/08/2019 10:30
Date Of Accident	21/08/2019 18:35
Exact Location Of Accident	GARDENS BY THE BAY - DRIVEWAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB8985A
Insured/Policyholder	
Name Of Registered Owner	PREMIER TAXIS PTE LTD
Co Reg No	200304975H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62148880

Vehicle Particulars

Manufacturer	KIA
Model	OPTIMA-1.7 D (A)
Exact Purpose for which vehicle was being used at time of accident	HIRED & REWARDS
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	5107202885
Cover Note Number	

Driver

Name of Driver	ONG HUA LIAN
NRIC No	S1668764B
Date Of Birth	14/06/1964
Occupation	OUTDOOR
Date Of Driving Pass	01/12/1982
Driving Experience	36 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96353547
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 349 #04-428 TAMPINES ST 33
Postcode	520349
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : PAX IN THE REAR SEAT - FOREIGNER GENDER: : MALE
Passenger 2	NAME: : PAX IN THE REAR SEAT - FOREIGNER GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

VEH A - 2 PAX VEH. B - NO PAX

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLM9740C
Vehicle Make/Model/Colour	HONDA VEZEL
Details Of Properties	VEH. B
Vehicle Category	PRIVATE HIRE
Name of Driver	MS ALICE NG
NRIC/Passport Number	S9120820B
Contact Number	93879241
Address	
Postcode	

Insurance Company Name	
Nature Of Damage	DAMAGED ON THE FRONT RIGHT PORTION
No. Of Passenger (Including Driver)	1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

816687648
8HB 8985A

22 AUG 2019

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

A: JHB 8985A
 B: SLM 9740C.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:



Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

22 AUG 2019

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Describe Circumstance of the Accident.

ON 21/08/2019 @ 1835HRS, I WAS DRIVING MY TAXI (SHB 8985 A) TRAVELLING ALONG THE DRIVEWAY @ GARDENS BY THE BAY, WITH 2 PASSENGERS ONBOARD, IN THE RIGHT LANE.

WHILE I WAS MOVING STRAIGHT AHEAD – WITHIN MY LANE & ACCORDING TO THE FLOW OF TRAFFIC, SUDDENLY I FELT AN IMPACT FROM MY LEFT.

WHEN INSPECTED, I DISCOVERED THAT VEHICLE B (SLM 9740 C – HONDA VEZEL) WHICH WAS IN THE MIDDLE LANE, FAILED TO KEEP FOR PROPER LOOK OUT & FAILED TO OBSERVE FOR CLEARANCE FROM MY ROUTE, HAD ENCROACHED ONTO MY PATH MY LEFT ABRUPTLY.

AS SUCH, THE FRONT RIGHT OF VEHICLE B COLLIDED ONTO THE LEFT PORTION OF MY TAXI – WHILE SHE WAS FILTERING INTO THE RIGHT LANE.


DUE TO THE IMPACT, MY TAXI HAD DAMAGES ON THE LEFT PORTION AND VEHICLE B HAD DAMAGES ON THE FRONT RIGHT PORTION.

NO INJURY INVOLVED.

NO PASSENGERS ONBOARD VEHICLE B.

*SCENE PHOTOS & VIDEO FOOTAGE CAPTURED.

DAMAGES FOUND ON VEHICLE A & VEHICLE B



[Handwritten signature]

81668764B

Driver's Signature & NRIC Number

@ 10:39:17 AM

(attended by

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	28 May 2014 / 09:24:44	Receipt No.:	AACCK001-AX239-140528-000006
Asset Type:	Vehicle	Transaction Amount:	\$73,050.00
Asset ID:	SHB8985A	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20140528092444984930		

Vehicle No.:	SHB8985A
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	28 May 2014
Original Registration Date:	28 May 2014
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414ME5463100
Engine No.:	D4FDDH309720
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2013
Open Market Value:	\$19,996.00
Minimum PARF Benefit:	\$7,497.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	28 May 2014 09:24:44
COE No.:	2014052801000877G
COE Expiry Date:	27 May 2022
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$60,414.00
Lifespan Expiry Date:	27 May 2022
Owner ID Type:	Company

Premier Automotive Services Pte Ltd

#01-02, 23 Changi Sth Ave 2

486443

Insurer Reference:

Repairer Reference: SHB8985A

Date calculated: 26/08/2019 1:10 PM

Full Report

Registration: SHB8985A

Printed: 26/08/2019 1:10 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	WEEDEK GOH	Currency:	SGD
Claim Reference:		Date of Incident:	21/08/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	KIA
Model:	OPTIMA (TF)
Sub Model:	2 LUXE
Model Sheet Number:	28 36 38
Registration:	SHB8985A
VIN number:	
Odometer:	

Vehicle Condition

Vehicle Status


Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐

Underbody ☐



Labour

Time Base 10 WU/h

Price = 50.00 SGD/h

Premier Automotive Services Pte Ltd

#01-02, 23 Changi Sth Ave 2

486443

Insurer Reference:

Repairer Reference: SHB8985A

Date calculated: 26/08/2019 1:10 PM

Full Report

Registration: SHB8985A

Printed: 26/08/2019 1:10 PM

Code	Description	WU	Price SGD
66300R00)	RENEW L/FRT WING (BUMPER REMOVED) INCLUDE: WHEELHOUSE LINER AND REQUIRED ATTACHED PARTS IN REPAIR AREA R + R	6.0	30.00
86512R00)	RENEW FRONT BUMPER (BUMPER REMOVED) INCLUDES: R + R NECESSARY ATTACHED PARTS	3 7.0	15 35.00
76000R00	RENEW L/F DOOR INCLUDES: R + R DOOR AND ALL NECESSARY ATTACHED PARTS, RENEW IF NECESSARY	16.0	80.00
87755R00	R + R L/SILL TRIM	3.0	15.00
1781	L/R DOOR REPAIR	20.0*	100.00
0283	FRT Bumper Repair	20	100
	Labour Cost	Hrs	WU
	Panel / Mechanical Labour	5.20	52.0
	Total of Labour	68	340

Paint

Paint Work

SYSTEM AZT

Time Basis 10 WU/h

Code	Description	WU	Price SGD
	L/F WING NEW PART PAINTING	9.0	
	LEFT FRONT DOOR NEW PART PAINTING	15.0	
	FRONT BUMPER NEW PART PAINT K1R	11.0	15
	L/SILL PANELLING NEW PART PAINT K1R	6.0	
	L/R OUTER SIDE PANEL REPAIR PAINTING <50%	15.0	
	L/R DOOR REPAIR PAINTING >50%	22.0	
	L/DOOR MIRROR SURFACE PAINT PLAST.	3.0	

Paint Material Per Part

Code	Description	Price SGD
0741	L/F WING NEW PART PAINTING	12.90
1481	LEFT FRONT DOOR NEW PART PAINTING	35.06
0283	FRONT BUMPER NEW PART PAINT K1R	40.50 47.12
2207	L/SILL PANELLING NEW PART PAINT K1R	20.24
3485	L/R OUTER SIDE PANEL REPAIR PAINTING <50%	20.25
1781	L/R DOOR REPAIR PAINTING >50%	24.72
1737	L/DOOR MIRROR SURFACE PAINT PLAST.	1.31

Premier Automotive Services Pte Ltd

#01-02, 23 Changi Sth Ave 2

486443

Insurer Reference:

Repairer Reference: SHB8985A

Date calculated: 26/08/2019 1:10 PM

Full Report

Registration: SHB8985A

Printed: 26/08/2019 1:10 PM

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor	50.00 SGD/h	85	
Time Paint		81.0	
Preparation Main Work Metal	1.70	17.0	85.00
Preparation Comp. Work Plastic	0.30	3.0	15.00
Total	10 WU/h	101.0	505.00

Material Cost - Paint

	Price SGD
New Part Painting	47.96
New Part Painting - Plastic K1R	67.36
Repair Painting	44.97
Surface Painting Plastic	1.31
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	188.70

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01	Price SGD
0283	FRONT BUMPER	865112T500	X repair		696.00
0319	L/F CTR BUMPER BRKT	865132T500	X su		16.00
0431	GRILLE BADGE	863183R500	X su		44.00
0741	L/F WING	663112T000	X RML		384.00
1481	LEFT FRONT DOOR	760032T000	X RML		791.00
1687	L/F DOOR RR MOULDING	863632T010	X su		0.00
1691	L/F UPP DOOR MLDG	828502T000	X su		0.00
2207	L/SILL PANELLING	877512T000	X su		286.00
7211	L/F WHEEL COVER	529602T100	X RML		116.00
f: OEM Parts	Savings				0.00
n: Non-OEM Parts	Subtotal				2,333.00
u: Used parts	Subtotal Discount(+35.00%)				-816.55
	Total				1,516.45

Extras

Code	Description	Price SGD
1000	Front bumper clips X	48.00*
1001	Fr Fender Sticker X	30.00*
1002	Fender Shield Clips X	28.00*
1003	Sundry	50.00*
1004	Check Alignment	80.00*
1005	Door Sticker	100.00*
	Total Extras	336.00

Premier Automotive Services Pte Ltd

#01-02, 23 Changi Sth Ave 2

486443

Insurer Reference:

Repairer Reference: SHB8985A

Date calculated: 26/08/2019 1:10 PM

Full Report

Registration: SHB8985A

Printed: 26/08/2019 1:10 PM

Code	Description	Price SGD
------	-------------	-----------

Final Calculation

	SGD	SGD
Parts	2,333.00	
Total Discount(+35.00%)	-816.55	
Total Parts		1,516.45
Labour Time Base 10 WU/h		
Total 52.0 WU X 50.00 SGD/h	260.00 ⁵⁴⁰	
Total of Labour		260.00
Total Of Extras		336.00
Paint Work Time Base 10 WU/h		
Labour Cost 101.0 WU X 50.00 SGD/h	505.00 ⁵⁴⁰	
Material Cost 10%	188.70 ^{185.78}	
Total Paint Including Material		693.70
Repair Cost Excludes GST	2946.65	2,806.15
GST (+7.0%)		196.43
Repair Cost Included GST		3,002.58

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

2921.15

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Kalvin (LKK)

26/8/19 17:05

3 Days

L/s

After Repair photo

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Insurer Reference:
Repairer Reference: SHB8985A
Date calculated: 25/09/2019 2:14 PM
Summary Information

Full Report
Registration: SHB8985A
Printed: 25/09/2019 2:14 PM

Claim			
Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:		Date of Incident:	21/08/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details


Vehicle
Manufacturer: KIA
Model: OPTIMA (TF)
Sub Model: 2 LUXE
Model Sheet Number: 28 36 38
Registration: SHB8985A
VIN number:
Odometer:

Vehicle Condition

Vehicle Status
Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Time Base 10 WU/h

Price = 50.00 SGD/h

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Insurer Reference:

Repairer Reference: SHB8985A

Date calculated: 25/09/2019 2:14 PM

Full Report

Registration: SHB8985A

Printed: 25/09/2019 2:14 PM

Code	Description	WU	Price SGD
66300R00)	RENEW L/FRT WING (BUMPER REMOVED) INCLUDE: WHEELHOUSE LINER AND REQUIRED ATTACHED PARTS IN REPAIR AREA R + R	6.0	30.00
86512R00 ZAX	R + R FRONT BUMPER	3.0	15.00
76000R00	RENEW L/F DOOR INCLUDES: R + R DOOR AND ALL NECESSARY ATTACHED PARTS, RENEW IF NECESSARY	16.0	80.00
87755R00	R + R L/SILL TRIM	3.0	15.00
0283	FRONT BUMPER REPAIR	20.0*	100.00
1781	L/R DOOR REPAIR	20.0*	100.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		6.80	68.0
Total of Labour			340.00

Paint

Code	Description	WU	Price SGD
Paint Work		SYSTEM AZT	
		Time Basis 10 WU/h	
	L/F WING NEW PART PAINTING	9.0	
	LEFT FRONT DOOR NEW PART PAINTING	15.0	
	L/SILL PANELLING NEW PART PAINT K1R	6.0	
	FRONT BUMPER REPAIR PAINT PLASTIC	15.0	
	L/R OUTER SIDE PANEL REPAIR PAINTING <50%	15.0	
	L/R DOOR REPAIR PAINTING >50%	22.0	
	L/DOOR MIRROR SURFACE PAINT PLAST.	3.0	

Paint Material Per Part

Code	Description	Price SGD
0741	L/F WING NEW PART PAINTING	12.90
1481	LEFT FRONT DOOR NEW PART PAINTING	35.06
2207	L/SILL PANELLING NEW PART PAINT K1R	20.24
0283	FRONT BUMPER REPAIR PAINT PLASTIC	40.50
3485	L/R OUTER SIDE PANEL REPAIR PAINTING <50%	20.25
1781	L/R DOOR REPAIR PAINTING >50%	24.72
1737	L/DOOR MIRROR SURFACE PAINT PLAST.	1.31

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Insurer Reference:

Repairer Reference: SHB8985A

Date calculated: 25/09/2019 2:14 PM

Full Report

Registration: SHB8985A

Printed: 25/09/2019 2:14 PM

Labour Cost - Paint

Factor

50.00 SGD/h

Time Paint

85.0

Preparation Main Work Metal

1.70

17.0

85.00

Preparation Comp. Work Plastic

0.60

6.0

30.00

Total

10 WU/h

10.80

108.0

540.00

Material Cost - Paint

Price SGD

New Part Painting

47.96

New Part Painting - Plastic K1R

20.24

Repair Painting

44.97

Repair Painting Plastic

40.50

Surface Painting Plastic

1.31

Material-constant Metal

18.10

Material-constant Plastic

12.70

Total

185.78

Spare Parts

				prices as at 2015-06-01
Code	Description	Part Number	Supplier	Price SGD
0741	L/F WING	663112T000		384.00
1481	LEFT FRONT DOOR	760032T000		791.00
1687	L/F DOOR RR MOULDING	863632T010		0.00
1691	L/F UPP DOOR MLDG	828502T000		0.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			1,175.00
u: Used parts	Subtotal Discount(+35.00%)			-411.25
	Total			763.75

Extras

Code	Description	Price SGD
1000	SUNDRY	20.00*
1001	DOOR STICKER	100.00*
	Total Extras	120.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Insurer Reference:
Repairer Reference: SHB8985A
Date calculated: 25/09/2019 2:14 PM

Full Report
Registration: SHB8985A
Printed: 25/09/2019 2:14 PM

Final Calculation

	SGD	SGD
Parts	1,175.00	
Total Discount(+35.00%)	-411.25	
Total Parts		763.75
Labour Time Base 10 WU/h		
Total 68.0 WU X 50.00 SGD/h	340.00	
Total of Labour		340.00
Total Of Extras		120.00
Paint Work Time Base 10 WU/h		
Labour Cost 108.0 WU X 50.00 SGD/h	540.00	
Material Cost	185.78	
Total Paint Including Material		725.78
Repair Cost Excludes GST		1,949.53
GST (+7.0%)		136.47
Repair Cost Included GST		2,086.00

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

Author	Date	Text
premier	25/09/2019 9:17 AM	finalize confirmed 25/9/2019

Premier Automotive Services Pte Ltd
#01-02, 23 Changi Sth Ave 2
486443

Insurer Reference:

Repairer Reference: SHB8985A

Date calculated: 24/09/2019 12:31 PM

Full Report

Registration: SHB8985A

Printed: 24/09/2019 12:32 PM

Summary Information

Claim

Location: Singapore (SG)

Work Provider:

MSIG Insurance
(Singapore) Pte Ltd

Printed by: WEEDEK GOH

Currency:

SGD

Claim Reference:

Date of Incident:

21/08/19

Estimated Repair Time:

Hire Car Start:

Hire Car End:

Actual Repair Days:

Vehicle Details

Vehicle

Manufacturer:

KIA

Model:

OPTIMA (TF)

Sub Model:

2 LUXE

Model Sheet Number:

28 36 38

Registration:

SHB8985A

VIN number:

Odometer:

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Time Base 10 WU/h

Price = 50.00 SGD/h

Premier Automotive Services Pte Ltd
#01-02, 23 Changi Sth Ave 2
486443

Insurer Reference:

Repairer Reference: SHB8985A

Date calculated: 24/09/2019 12:31 PM

Full Report

Registration: SHB8985A

Printed: 24/09/2019 12:32 PM

Code	Description	WU	Price SGD
66300R00)	RENEW L/FRT WING (BUMPER REMOVED) INCLUDE: WHEELHOUSE LINER AND REQUIRED ATTACHED PARTS IN REPAIR AREA R + R	6.0	30.00
86512R00 ZAX	R + R FRONT BUMPER	3.0	15.00
76000R00	RENEW L/F DOOR INCLUDES: R + R DOOR AND ALL NECESSARY ATTACHED PARTS, RENEW IF NECESSARY	16.0	80.00
87755R00	R + R L/SILL TRIM	3.0	15.00
0283	FRONT BUMPER REPAIR	20.0*	100.00
1781	L/R DOOR REPAIR	20.0*	100.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		6.80	68.0
Total of Labour			340.00

Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h
Code	Description	WU	Price SGD
	L/F WING NEW PART PAINTING	9.0	
	LEFT FRONT DOOR NEW PART PAINTING	15.0	
	L/SILL PANELLING NEW PART PAINT K1R	6.0	
	FRONT BUMPER REPAIR PAINT PLASTIC	15.0	
	L/R OUTER SIDE PANEL REPAIR PAINTING <50%	15.0	
	L/R DOOR REPAIR PAINTING >50%	22.0	
	L/DOOR MIRROR SURFACE PAINT PLAST.	3.0	

Paint Material Per Part

Code	Description	Price SGD
0741	L/F WING NEW PART PAINTING	12.90
1481	LEFT FRONT DOOR NEW PART PAINTING	35.06
2207	L/SILL PANELLING NEW PART PAINT K1R	20.24
0283	FRONT BUMPER REPAIR PAINT PLASTIC	40.50
3485	L/R OUTER SIDE PANEL REPAIR PAINTING <50%	20.25
1781	L/R DOOR REPAIR PAINTING >50%	24.72
1737	L/DOOR MIRROR SURFACE PAINT PLAST.	1.31

Premier Automotive Services Pte Ltd
#01-02, 23 Changi Sth Ave 2
486443

Insurer Reference:

Repairer Reference: SHB8985A

Date calculated: 24/09/2019 12:31 PM

Full Report

Registration: SHB8985A

Printed: 24/09/2019 12:32 PM

Labour Cost - Paint		Hrs	WU	Price SGD
Factor	50.00 SGD/h			
Time Paint			85.0	
Preparation Main Work Metal		1.70	17.0	85.00
Preparation Comp. Work Plastic		0.60	6.0	30.00
Total	10 WU/h	10.80	108.0	540.00

Material Cost - Paint	Price SGD
New Part Painting	47.96
New Part Painting - Plastic K1R	20.24
Repair Painting	44.97
Repair Painting Plastic	40.50
Surface Painting Plastic	1.31
Material-constant Metal	18.10
Material-constant Plastic	12.70
Total	185.78

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01	Price SGD
0741	L/F WING	663112T000			384.00
1481	LEFT FRONT DOOR	760032T000			791.00
1687	L/F DOOR RR MOULDING	863632T010			0.00
1691	L/F UPP DOOR MLDG	828502T000			0.00
f: OEM Parts	Savings				0.00
n: Non-OEM Parts	Subtotal				1,175.00
u: Used parts	Subtotal Discount(+35.00%)				-411.25
	Total				763.75

Extras

Code	Description	Price SGD
1003	Sundry	20.00*
1005	Door Sticker	100.00*
	Total Extras	120.00

Premier Automotive Services Pte Ltd
#01-02, 23 Changi Sth Ave 2
486443

Insurer Reference:

Repairer Reference: SHB8985A

Date calculated: 24/09/2019 12:31 PM

Full Report

Registration: SHB8985A

Printed: 24/09/2019 12:32 PM

Final Calculation

	SGD	SGD
Parts	1,175.00	
Total Discount(+35.00%)	-411.25	
Total Parts		763.75
Labour Time Base 10 WU/h		
Total 68.0 WU X 50.00 SGD/h	340.00	
Total of Labour		340.00
Total Of Extras		120.00
Paint Work Time Base 10 WU/h		
Labour Cost 108.0 WU X 50.00 SGD/h	540.00	
Material Cost	185.78	
Total Paint Including Material		725.78
Repair Cost Excludes GST		1,949.53
GST (+7.0%)		136.47
Repair Cost Included GST		2,086.00

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Aug 2019		23 Aug 2019 17:40 Edit Adj Rpt	S\$1,550.00 Edit Estimates	S\$1,550.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by Insurer]

Insured:	SKYWAY MOTOR PTE LTD, Co. Reg. No.: 199904194N		
Main Claimant:	PREMIER TAXIS PTE LTD, Co. Reg. No.: 200304975H		
Vehicle Reg. No.:	SHB8985A	Date of Loss:	21/08/2019 00:00 - :59 [62 Months and 24 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 603647	Policy/Cover Note No.:	28795104MCX Coverage: 08/08/2019 - 07/08/2020
Vehicle Reg. No. (Insured):	SLM9740C	Policy No. (Claimant):	
		Excess:	
Repairer:	Premier Automotive Services Pte Ltd (HQ) 23 Changi South Ave 2, #01-02, 486443 Changi - Tel: 62148880		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 22/09/2019]		
Adj Asg. Remarks:	on WP. CAR IN. Liab: NA. Contact: Liew @ 6544 6689.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHB8985A (603647)
[SLM9740C]
TP
PREMIER TAXIS PTE LTD
Aug 21 2019 12:00AM
[SKYWAY MOTOR PTE LTD]
Premier Automotive Services Pte Ltd

Upload Documents

Upload Photos


Compose New Letter

View

View in Browser


































Assessment Reports

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/08/19 13:14	Adjuster Immediate Advice	 Load HTM	


Photos/Images


3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/08/19 08:51	General View	 Load JPG	
2	27/08/19 08:51	General View	 Load JPG	
3	27/08/19 08:51	General View	 Load JPG	
4	27/08/19 08:51	General View	 Load JPG	
5	27/08/19 08:51	General View	 Load JPG	
6	27/08/19 08:51	General View	 Load JPG	
7	27/08/19 08:51	General View	 Load JPG	
8	27/08/19 08:51	General View	 Load JPG	
9	27/08/19 08:51	General View	 Load JPG	
10	27/08/19 08:51	General View	 Load JPG	
11	27/08/19 08:51	General View	 Load JPG	
12	27/08/19 08:51	General View	 Load JPG	
13	27/08/19 08:51	General View	 Load JPG	
14	27/08/19 08:51	General View	 Load JPG	
15	27/08/19 08:51	General View	 Load JPG	
16	27/08/19 08:51	General View	 Load JPG	
17	27/08/19 08:51	General View	 Load JPG	
18	27/08/19 08:51	General View	 Load JPG	
19	27/08/19 08:51	General View	 Load JPG	
20	27/08/19 08:51	General View	 Load JPG	
21	27/08/19 08:51	General View	 Load JPG	
22	27/08/19 08:51	General View	 Load JPG	
23	27/08/19 08:51	General View	 Load JPG	
24	27/08/19 08:51	General View	 Load JPG	
25	27/08/19 08:51	General View	 Load JPG	
26	27/08/19 08:51	General View	 Load JPG	
27	27/08/19 08:51	General View	 Load JPG	
28	27/08/19 08:51	General View	 Load JPG	
29	27/08/19 08:51	General View	 Load JPG	
30	27/08/19 08:51	General View	 Load JPG	
31	25/09/19 08:08	Reinspection Photo	 Load JPG	
32	25/09/19 08:08	Reinspection Photo	 Load JPG	
33	25/09/19 08:08	Reinspection Photo	 Load JPG	

Documentation

1 per page

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/08/19 15:54	PRI	 Load PDF	

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/09/19 14:24	SHB 8985A - AUDATEX.pdf	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19014944/K1SF3E2

Date: 07/10/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28795104MCX

Claimant SHB8985A

Insured Vehicle No : SLM9740C

Vehicle No : SHB8985A

Nature of Claim: TP

Claim No: 603647

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHB8985A

Make & Model: KIA OPTIMA, 1.7 D (A)

Engine No: D4FDDH309720

Reg. Date: 28/05/2014 (Man. Year: 2013)

Chassis No: KNAGM414ME5463100

Colour: Silver

Odometer: 642627 km

Engine Capacity: 1685 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65R16

Rear Tyre Size: 205/65R16

Front Left Side: Hankook 7 mm

Rear Left Side: Hankook 7 mm

Front Right Side: Hankook 7 mm

Rear Right Side: Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,772.45	883.75	888.70	50.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,148.70	1,065.78	82.92	7.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,921.15	1,949.53	971.62	33.26
Approved Total (Overridden) (S\$)		1,550.00		
(S\$)	2,921.15	1,550.00	1,371.15	46.94
+ GST 7.00/7.00% (S\$)	204.48	108.50	95.98	46.94
Nett Amount (S\$)	3,125.63	1,658.50	1,467.13	46.94

INSPECTION

Date of Assignment: 23/08/2019

Date Inspected: 26/08/2019 Inspected At:

Premier Automotive Services Pte Ltd (HQ)

23 Changi South Ave 2, #01-02
Singapore 486443

Estimated Period of Repair: 3.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Oct 2019)
Parts:	143	KIA OPTIMA 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB8985A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	696.00 FL	*- FL
2	1		*L/F CTR BUMPER BRKT	Serviceable	16.00 FL	*- FL
3	1		*GRILLE BADGE	Not Necessary	44.00 FL	*- FL
4	1		*L/F WING	Buckled	384.00 FL	*384.00 FL
5	1		*LEFT FRONT DOOR	Buckled	791.00 FL	*791.00 FL
6	1		*L/F DOOR RR MOULDING (NPA)	Serviceable	0.00 FL	*- FL
7	1		*L/F UPP DOOR MLDG (NPA)	Serviceable	0.00 FL	*- FL
8	1		*L/SILL PANELLING	Serviceable	286.00 FL	*- FL
9	1		*L/F WHEEL COVER	Repair	116.00 FL	*- FL
10	1		*FRONT BUMPER CLIPS	Not Necessary	48.00 FS	*- FS
11	1		*FR FENDER STICKER	Not Necessary	30.00 FS	*- FS
12	1		*FENDER SHIELD CLIPS	Not Necessary	28.00 FS	*- FS
13	1		*SUNDRY	Necessary	50.00 FS	*20.00 FS
14	1		*DOOR STICKER	Necessary	100.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,589.00	1,295.00
- List Item Discount on L Items 35.00/35.00% (\$\$)	816.55	411.25
Total Parts (\$\$)	1,772.45	883.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK ALIGNMENT	New	80.00	0.00
2	68.0 WU X 50.00 SGD/H	New	340.00	340.00
3	LABOUR COST 108.0 WU X 50.00 SGD/H	New	540.00	540.00
4	MATERIAL COST	New	188.70	185.78
Gross Labour Cost (S\$)			1,148.70	1,065.78

Report was unsubmitted during this print-out.

< END OF ESTIMATES >