

2012001

ASS. REC. BY:

REF: CS/ALG/19014950/Kqf302

Special Instruction:

Written

SURVAYOR: Kenneth

ASSIGNMENT (Office)

From (Person): Hor Yiarul

of ALG

Date/Time: 2.8.19 11.20am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMJ 2612P

Insured: SLF 1927X

at Workshop m/z Massive Trading & Auto

Tel: 91082728

of BIK 5038 AMK Industrial Park 2 #01-405

Policy No: 0999994251

Claim No: 049732208956

Sum Insured:

Excess:

Make of Veh:

D.O.A. 24.8.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Enforcement:

Date/Time: 2.8.19 1.39pm

Person Contacted: Anthony

Vehicle: IN/OUT

Date/Time	Action/Instruction ( ✓ ) Estimate
	SLF 1927X / CC4 / ASM / 3021391 / WPA 302 P.O. 029/10/2018
	SMJ 2612P X
	Kenneth confirmed LS @ 5700, 8 days (Red @ 2706.07, 32%)

ASS. REC. BY:

REF: 196/

Kenneth

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop n/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SMJ2612P Yr Regn: 0219

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Vio 5 c.c 1296

Colour: M. Grey AC: Insured / Std / NI / NA

Sp. Reading: 36734 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MR2B23F320116578

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD/Rim or

Tyre Size: F: 185/60R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 24/8/19

Rear

R/Bal. 7 mm

L/Bal. 7 mm

D.O.I. 28/8/19

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
1	File pass to SH NOT READY

RECEIVED 03 SEP 2019

Date/Time, File Pass to?

11/03/19

Date/Time, File Return to?

: Prell. Report

: Final Report

Days Of Repair: 8

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S - RS. St

Furnish

Others

TOTAL

Add Fee:  : Site Insp (\$

: Interview (\$

: Tech Invs (\$

: Weekend (\$

250

11

261

Report Format:

NER-7P

Lump Sum / I.B.X (\$

5700

**PRE-REPAIR INSPECTION REQUEST – SMJ2612P vs SLF1927X (OJ) on D.O.A.: 24/08/2019**

From: Hor, Yinnul  
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)  
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divy  
Sent: 8/26/2019 11:26:46 AM  
Attachments: 20190826103111078.pdf; 20190826103111078.pdf

Hi,

Please refer to the enclosed request from **Teo Keng Siang LLC**.  
Kindly carry out Policy coverage verification **first** before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.  
Kindly assist to assign **Kenneth Kong** as Single Joint Expert as requested.

Thanks & Regards,

Hor Yin Rul (Yvriane)  
AIG  
FNOL Adjunct  
Singapore FNOL | Claims Operations – Auto

[Yinnul.Hor@aig.com](mailto:Yinnul.Hor@aig.com) | [www.aig.sg](http://www.aig.sg)

**From:** Janice Kee [mailto:janice.kee@ksteoptr.com]

**Sent:** Monday, August 26, 2019 11:20 AM

**To:** Hor, Yinnul

**Cc:** Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashni; Tong, Wahkin; Anthony Cheong

**Subject:** [EXTERNAL] Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLF1927X AND SMJ2612P ON 24/08/2019

This message is from an external sender; be cautious with links and attachments.

Dear Sir

Our client has agree to the usage of Mr Kenneth Kong from LKK Auto Consultants Pte Ltd as the Single Joint Expert to conduct the Pre-Repair Survey.

Kindly proceed to engage Mr Kenneth Kong from LKK Auto Consultants Pte Ltd to perform the said Pre-Repair Survey in accordance to the NIMA Protocol.

Thank you.

Regards,  
Janice Kee  
c/o Teo Keng Siang LLC  
111 North Bridge Road,  
#29-07/08 Peninsula Plaza,  
Singapore 179098  
Tel: 6333 4222 Fax: 6333 5676

On Mon, Aug 26, 2019 at 10:58 AM Hor, Yinnul <Yinnul.Hor@aig.com> wrote:

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ เพื่ออ่านมัน  
โปรดเปิดไฟล์แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려  
면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya,  
membuka attachment.

[Click here](#) by 2019-09-02 10:58 +08 to read your message.  
After that, open the attachment.

[More info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the individual named. If you have received this email in error or simply do not know the individual named, please do not disseminate the information. Please notify the sender if you have received this email in error or simply delete it.

Secured by Postquant Encryption, Copyright © 2008-2017 Postquant, Inc. All rights reserved.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Yinnul.Hor@aig.com  
To: janice.kee@ksteoptr.com  
Cc: Andy-SY.Fong@aig.com, Lee-Ying.Chin@aig.com, NoorMariesa.AbuKasim@aig.com, Syazairina.Azlan@aig.com, yokeshi.chan@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com, Theerthan.Parthiban@aig.com, Divyashni.Subramaniam@aig.com, Wahxin.Tong@aig.com  
Subject: aigenrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLF1927X AND SMJ2612P ON 24/08/2019  
Date: Mon, 26 Aug 2019 02:57:43 +0000

Without Prejudice

Your Reference : TKSF/M492-ACC-42392.19/sf  
Our Reference : SLF1927X

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Ping Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yinn Ru (Viviane)  
AIG  
FNOL Adjuster |  
Singapore FNOL | Claims Operations – Auto

[Yinnul.Hor@aig.com](mailto:Yinnul.Hor@aig.com) | [www.aig.ae](http://www.aig.ae)

**From:** Janice Kee [mailto:janice.kee@ksteoptr.com]  
**Sent:** Monday, August 26, 2019 10:33 AM  
**To:** Hor, Yinnul; Parthiban, Theerthan; Fong, Andy-SY; Abu Kassim, Noor Mariesa; Azlan, Syazairina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni; Tong, Wahxin  
**Cc:** Anthony Cheong  
**Subject:** [EXTERNAL] Pre Repair Survey for SMJ 2612 P (Your Ref: SLF 1927 X Our Ref: TKSF/M492-ACC-42392.19/sf)

This message is from an external sender; be cautious with links and attachments.

Dear Sir,

We attach herewith our Pre-repair survey letter for your attention.

Kindly let us have the surveyor list for our attention.

Thank you

Regards,  
Janice Kee  
c/o Teo Keng Siang LLC  
111 North Bridge Road,  
#29-07/08 Peninsula Plaza,  
Singapore 179098



张景祥大律師樓  
(律師兼公証及宣誓官)

# Teo Keng Siang LLC

Advocates & Solicitors • Notary Public • Commissioner For Oaths

111 North Bridge Road #29-07/08 Peninsula Plaza Singapore 179098  
ROC: 201510228C GST Reg No.: 201510228C

Tel: 6333 4222 Fax: 6333 5676 / 5688  
Email: KSTEOCO@singnet.com.sg

(FAX - NOT FOR SERVICE OF COURT DOCUMENTS)

Our Ref : TKSF/M492-ACC-42392.19/sf (mc)  
Your Ref : SLF 1927 X  
Date : 26 August 2019

Secretary in charge: Janice  
Tel : 6333 4222 (ext 60)  
Fax : 6333 5676 / 6333 5688  
Email : janice.kee@ksteoptr.com

To: AIG Asia Pacific Insurance Pte. Ltd  
AIG Building  
78 Shenton Way  
#07-16 Singapore 079120  
Attn: Motor Claims Dept

**WITHOUT PREJUDICE**  
**BY PDX# 8181 & FAX 6835 7416 ONLY**

Cc: Jin & Wei Enterprises (Owner)  
Adi Akbar Bin Arifin (Driver)  
C/o 210 Turf Club Road  
C03 The Grandstand  
Singapore 287995

BY POST ONLY

PDX Intercompany Exchange Pte Ltd



010808762352

FROM TEO KENG SIANG LLC  
PDX Box No. 8902

Dear Sirs

**RE: ACCIDENT INVOLVING SMJ 2612 P / SLF 1927 X ON 24/8/19 ALONG NEWTON ROAD TOWARDS NEWTON CIRCLE**

We are instructed by **Lim Lye Hoek** to notify you of a road traffic accident on 24/8/19 at about 18:30 hours at **ALONG NEWTON ROAD TOWARDS NEWTON CIRCLE** involving our client's vehicle registration number **SMJ 2612 P** and vehicle registration number **SLF 1927 X** driven by you at the material time. A copy of our client's Singapore accident statement is enclosed. Kindly let us have a copy your Singapore accident statement report on an urgent basis.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please note that our client's motor vehicle **SMJ 2612 P** is now at the following workshop:-

**Massive Trading & Auto**  
Blk 5038 Ang Mo Kio Industrial Park 2  
#01-405  
Singapore 569541  
Contact: 9108 2728 Anthony

Yours faithfully,

  
M/s Teo Keng Siang LLC  
encs

Teo Keng Siang  
LL.M(Singapore),  
LL.B (Hons) (Singapore)

\*\*Survey was conducted by:-

Name of Surveyor:

Date of Survey:

Time of Survey:

\_\_\_\_\_  
Signature

Wong Yong Sheng, Kenneth  
LL.B (Hons) University of Bristol

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	26/08/2019 09:32
Date Of Accident	24/08/2019 18:30
Exact Location Of Accident	NEWTON RD TWDS NEWTON CIRCLE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMJ2612P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LIM LYE HOCK
NRIC No	S0189994E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90480327
Alternative Phone No	OTHERS-90480327
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	VIOS
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5107604549
Cover Note Number	
<b>Driver</b>	
Name of Driver	LIM LYE HOCK
NRIC No	S0189994E
Date Of Birth	22/02/1950
Occupation	OUTDOOR
Date Of Driving Pass	16/06/1978
Driving Experience	41 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90480327
Fax Number	
Contact Number	OTHERS-90480327
Email Address	NOEMAIL

Address	BLK 837 HOUGANG CTRL #12-529
Postcode	530837
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	HOGANG N.P.C
Police Station Address	ROAD: 60 HOUGANG AVE 9 SINGAPORE 538775 , POSTCODE: 538775 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

ON 24/8/2019 ARD 1830HRS, I WAS TRAVELLING ALONG NEWTON RD TOWARDS NEWTON CIRCLE, JUST INFRONT HOTEL ROYAL. I SLOWED DOWN MY VEHICLE IN ORDER TO TURN INTO SURREY RD. SUDDENLY I FELT AN STRONG IMPACT FROM THE REAR OF MY VEHICLE. I GOT OUT OF MY VEHICLE AND REALISED THAT VEH B (SLF 1927 X) HAD COLLIDED INTO MY VEHICLE REAR PORTION.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	KIV, SUBMIT BY CLAIMANT W/S
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLF1927X
Vehicle Make/Model/Colour	HONDA VEZEL
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ADI AKBAR BIN ARIFIN
NRIC/Passport Number	S1744467J
Contact Number	

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Sketch Plan #2 Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 24/8/2019 @ arnd 1830hrs, I was travelling along Newton Rd towards Newton Circle. Just in front Hotel Royal, I slowed down my vehicle in order to turn into Surrey Rd. Suddenly, I felt an strong impact from the rear of my vehicle. I got out of my vehicle and realised that veh B (SKF1927X) had collided into my vehicle rear portion

DECLARATION

(We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

1kg

# Massive Trading & Auto

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541  
H/p 91082728

Fax : 64816131

Lim Lye Hock  
Blk 837 Hougang Central  
#12-529 Singapore 530837

*Not with care*  
*L1 Pong @ 5700h*  
*Resurvey After Paint*  
*8 days*

Vehicle No : SMJ 2612 P  
Make : Toyota Vios  
Year : 2019

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

### Estimate Cost Of Repair

1 pc	Rear o/s fender	Buc/1kg \$965.70	✓
1 pc	Rear o/s fender inner trim	CM \$387.60	✓
1 pc	Rear windscreen moulding	M \$95.10	✓
1 pc	Rear boot lid	R \$772.20	✓
1 pc	Rear o/s boot lid reflector	CM \$370.20	✓
1 pc	Rear boot lid inner lock	R \$205.70	X
1 pc	Rear boot lid inner lock sensor	M \$185.70	✓
1 pc	Rear boot lid emblem " Logo "	M \$55.10	✓
1 pc	Rear boot lid emblem " Vios "	M \$53.20	✓
1 pc	Rear boot lid emblem " E "	M \$35.10	✓
1 pc	Rear boot rubber	M/1kg \$175.10	✓
1 pc	Rear o/s tail-lamp assy	CM \$455.10	✓
1 pc	Rear o/s tail-lamp lower bracket	CM \$38.10	✓
1 pc	Rear o/s tail-lamp panel	R \$187.20	✓
1 pc	Rear end panel	R \$550.20	✓
1 pc	Rear end panel inner garnish	CM \$237.40	✓
1 pc	Rear bumper	R/CM \$559.70	✓
1 pc	Rear bumper reinforcement	R \$397.20	✓
1 pc	Rear o/s bumper side retainer	M \$75.20	✓
1 pc	Rear o/s bumper bracket	R \$95.20	✓
1 pc	Rear o/s bumper reflector	CM \$155.80	✓
1 pc	Rear o/s reverse sensor	CM \$385.70	✓
1 pc	Rear exhaust silencer	R \$550.80	X
		\$6,988.10	
		Less 25 %	\$1,747.03
			\$5,241.07

### S Nett

1 pc Rear windscreen sealant  
20 pcs Clip

M \$45.00  
\$2.00 M \$40.00  
balance c/f \$5,326.07

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

SMJ 2612 P

balance b/f \$5,326.07

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.	\$1,200.00	110d
To putty & spray paint on rear accident affected portion.	\$1,200.00	100d
Check/reconnect wiring.	\$40.00	20d
To spray anti rust on accident affected portion.	\$120.00	9d
Remove/refit rear boot upholstery to facilitate repair	\$150.00	100d
Remove/refit rear windscreen to facilitate repair	\$100.00	✓
Remove/refit roof lining to facilitate replacement of rear o/s fender	\$150.00	X
Remove/renew rear exhaust silencer	\$120.00	X
Total	<u>\$8,406.07</u>	

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19014950/KQF3

Date: 09/09/2019

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994251
Claimant Vehicle No :	SMJ2612P	Insured Vehicle No :	SLF1927X
Date of Loss:	24/08/2019	Nature of Claim:	TP
		Claim No:	0497322089SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ2612P	Engine No:	2NR5323794
Make & Model:	TOYOTA VIOS, 1.5 (A)	Chassis No:	MR2B23F3201165783
Reg. Date:	27/02/2019 (Man. Year: 2019)	Odometer:	36734 km
Colour:	Metallic Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Dunlop 7 mm
Front Right Side:	Dunlop 7 mm	Rear Right Side:	Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,326.07	4,753.70	572.37	10.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,080.00	2,410.00	670.00	21.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,406.07</b>	<b>7,163.70</b>	<b>1,242.37</b>	<b>14.78</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,700.00</b>		
<b>Nett Amount (S\$)</b>	<b>8,406.07</b>	<b>5,700.00</b>	<b>2,706.07</b>	<b>32.19</b>

INSPECTION

Date of Assignment:	26/08/2019	
Date Inspected:	26/08/2019	Inspected At:
		Massive Trading & Auto
		Blk 5038 #01-405, Ang Mo Kio Industrial
		Pk 2
		Singapore 569541
Estimated Period of Repair:	8.0 days	

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR O/S FENDER	Buckled/Bent	965.70 FL	*965.70 FL
2	1		*REAR O/S FENDER INNER TRIM	Cracked	387.60 FL	*387.60 FL
3	1		*REAR WINDSCREEN MOULDING	Necessary	95.10 FL	*95.10 FL
4	1		*REAR BOOT LID	Bent	772.20 FL	*772.20 FL
5	1		*REAR O/S BOOT LID REFLECTOR	Cracked	370.20 FL	*370.20 FL
6	1		*REAR BOOT LID INNER LOCK	Repair	205.70 FL	*- FL
7	1		*REAR BOOT LID INNER LOCK SENSOR	Dented	185.70 FL	*185.70 FL
8	1		*REAR BOOT LID EMBLEM LOGO	Necessary	55.10 FL	*55.10 FL
9	1		*REAR BOOT LID EMBLEM VIOS	Necessary	53.20 FL	*53.20 FL
10	1		*REAR BOOT LID EMBLEM E	Necessary	35.10 FL	*35.10 FL
11	1		*REAR BOOT RUBBER	Distorted/Dented	175.10 FL	*175.10 FL
12	1		*REAR O/S TAIL LAMP ASSY	Cracked	455.10 FL	*455.10 FL
13	1		*REAR O/S TAIL LAMP LOWER BRACKET	Cracked	38.10 FL	*38.10 FL
14	1		*REAR O/S TAIL LAMP PANEL	Bent	187.20 FL	*187.20 FL
15	1		*REAR END PANEL	Bent	550.20 FL	*550.20 FL
16	1		*REAR END PANEL INNER GARNISH	Cracked	237.40 FL	*237.40 FL
17	1		*REAR BUMPER	Bent/Cracked	559.70 FL	*559.70 FL
18	1		*REAR BUMPER REINFORCEMENT	Bent	397.20 FL	*397.20 FL
19	1		*REAR O/S BUMPER SIDE RETAINER	Distorted	75.20 FL	*75.20 FL
20	1		*REAR O/S BUMPER BRACKET	Bent	95.20 FL	*95.20 FL
21	1		*REAR O/S BUMPER REFLECTOR	Cracked	155.60 FL	*155.60 FL
22	1		*REAR O/S REVERSE SENSOR	Cracked	385.70 FL	*385.70 FL
23	1		*REAR EXHAUST SILENCER	Repair	550.80 FL	*- FL
24	1		*REAR WINDSCREEN SEALANT	Necessary	45.00 FS	*40.00 FS
25	20		*CLIP	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,073.10</b>	<b>6,311.60</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>1,747.03</b>	<b>1,557.90</b>
<b>Total Parts (\$\$)</b>	<b>5,326.07</b>	<b>4,753.70</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING,WELDING & CUTTING	New	1,200.00	1,100.00
2	TO PUTTY & SPRAY PAINT ON REAR ACCIDENT AFFECTED PORTION	New	1,200.00	1,000.00
3	CHECK/RECONNECT WIRING	New	40.00	20.00
4	TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PORTION	New	120.00	90.00
5	REMOVE/REFIT REAR WINDSCREEN TO FACILITATE REPAIR	New	100.00	100.00
6	REMOVE/REFIT REAR BOOT UPHOLSTERY TO FACILITATE REPAIR }	New	150.00	100.00
7	REMOVE/REFIT ROOF LINING TO FACILITATE REPLACEMENT OF REAR O/S FENDER }	New	150.00	0.00
8	REMOVE/RENEW REAR EXHAUST SILENCER	New	120.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>3,080.00</b>	<b>2,410.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >