

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5263J

AAD1908-159

Not Authorized

Accruing B4 paint

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration:

23 AUG 2019

SHD 5263J

JTDKB3FU403079007

TOYOTA

PRIUS

21.8.19

AIG

11/1/2019

PART		LIST	
1	1 REAR BUMPER	\$	<i>R</i> 458.60 ✓
2	1 REAR BUMPER RE-INFORCEMENT	\$	318.80 ?
3	1 REAR BUMPER TOWING COVER	\$	<i>Sm</i> 14.70 X
4	1 REAR BUMPER UNDER COVER (BLACK)	\$	<i>CM</i> 552.60 ✓
5	1 ANTENNA, ELECTRICAL KEY	\$	<i>Sm</i> 61.40
6	1 REAR BUMPER SIDE RETAINER LH	\$	<i>Sm</i> 112.70
7	1 REAR BUMPER SIDE RETAINER RH	\$	<i>Sm</i> 112.70
8	1 REAR TAILGATE	\$	<i>R</i> 1,547.27
9	1 REAR TAILGATE OUTER GARNISH	\$	<i>Sm</i> 910.40
10	1 COVER, REAR COMBINATION LAMP, RH	\$	<i>Sm</i> 54.70
11	1 COVER, REAR COMBINATION LAMP, LH	\$	<i>Sm</i> 54.70
12	1 GARNISH, BACK DOOR SIDE, LH	\$	<i>Sm</i> 93.60
13	1 GARNISH, BACK DOOR SIDE, RH	\$	<i>Sm</i> 93.60
14	1 MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER RH	\$	<i>Sm</i> 55.40
15	1 MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER LH	\$	<i>Sm</i> 55.40
16	1 BOARD ASSY, BACK DOOR TRIM	\$	<i>Sm</i> 254.40
17	1 PANEL ASSY, BACK DOOR TRIM, UPPER	\$	<i>Sm</i> 51.20
18	1 REAR TAILGATE WEATHERSTRIP	\$	<i>Sm</i> 365.20
19	1 PANEL SUB-ASSY, BODY LOWER BACK (REAR END PANEL)	\$	<i>R</i> 641.50
20	1 TAILLAMP LOWER RH	\$	<i>Sm</i> 548.40
21	1 TAILLAMP UPPER RH	\$	<i>Sm</i> 557.90
22	1 REAR BUMPER SIDE RH	\$	<i>Sm</i> 232.00
23	1 REAR BUMPER SIDE LH	\$	<i>Sm</i> 232.00
24	1 TAILLAMP LOWER LH	\$	<i>Sm</i> 548.40
25	1 TAILLAMP UPPER LH	\$	<i>Sm</i> 557.90
26	1 REAR RH FENDER PANEL	\$	<i>R</i> 836.70

X

Trans-cab Auto Services Pte Ltd

AAD1908-159

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5263J

27	1	REAR LH FENDER PANEL	\$	<i>11</i>	836.70	}
28	1	LINER, REAR WHEEL HOUSE, LH	\$	<i>Sn</i>	138.10	
29	1	LINER, REAR WHEEL HOUSE, RH	\$	<i>Sn</i>	138.10	
30	1	BOARD, BACK DOOR TRIM	\$	<i>Sn</i>	222.00	
31	1	PANEL ASSY, DECK TRIM SIDE, RH	\$	<i>Sn</i>	351.10	
32	1	PANEL ASSY, DECK TRIM SIDE, LH	\$	<i>Sn</i>	351.10	
33	1	COVER, FLOOR UNDER, NO.1	\$	<i>Sn</i>	172.60	
34	1	COVER, FLOOR UNDER, NO.2	\$	<i>Sn</i>	238.70	
35	1	COVER, REAR FLOOR	\$	<i>Sn</i>	226.80	
36	1	COVER, DECK TRIM, REAR	\$	<i>Sn</i>	125.00	
TOTAL			\$		12,122.37	
25%			\$		3,030.59	
			\$		9,091.78	

Special Nett

1	1SET	PARKING AID	\$	<i>Shan</i>	700.00	}
2	1SET	REAR BUMPER CLIP	\$	<i>na</i>	55.00	
3	2	REAR WINDSCREEN SEALANT	\$	<i>na</i>	80.00	
4	1	WINDSCREEN MOULDING	\$	<i>na</i>	100.00	
5	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i>	100.00	
6	1	REAR TAILGATE TOYOTA LOGO	\$	<i>na</i>	47.00	
7	1	REAR TAILGATE WORDING 'PRIUS'	\$	<i>na</i>	52.90	
8	1	REAR TAILGATE WORDING 'HYBRID'	\$	<i>na</i>	53.50	
9	1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	<i>na</i>	80.00	
10	1	REAR TAILGATE STICKER '6555-3333'	\$	<i>na</i>	80.00	
11	1	REAR BUMPER PROTECTOR	\$	<i>na</i>	100.00	}
12	1	REAR WHEEL RIM	\$	<i>Sn</i>	1,570.55	
13	1	REAR TYRE 195/65/15	\$	<i>Sn</i>	350.00	
14	1	REAR WHEEL RIM COVER	\$	<i>Sn</i>	175.80	
15	1	SPARE WHEEL RIM	\$	<i>Sn</i>	1,570.55	
16	1	SPARE WHEEL RIM COVER	\$	<i>Sn</i>	175.80	
17	1SET	FENDER WHEELARCH REAR LH CLIP	\$	<i>na</i>	35.00	
18	1SET	FENDER WHEELARCH REAR RH CLIP	\$	<i>na</i>	35.00	
TOTAL			\$		5,361.10	

TOTAL PARTS \$ 14,452.88

Trans-cab Auto Services Pte Ltd

AAD1908-159

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5263J**LABOUR**

To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	<i>na</i>	170.00	X
Putty And Spray Painting Of The Affected Portion.	\$		4,500.00	<i>2201</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		4,500.00	<i>2001</i>
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	<i>na</i>	170.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	<i>↪</i>	170.00	X
To Rust-Proofing Of The Affected Areas.	\$	<i>↪</i>	170.00	X
To reinstall rear bumper parking sensor.	\$		170.00	<i>501</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>na</i>	170.00	X
To check steering geometry and computer wheel alignment	\$	<i>na</i>	220.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>na</i>	170.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>na</i>	380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i>	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>na</i>	380.00	X

Trans-cab Auto Services Pte Ltd

AAD1908-159

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5263J

To Check Electrical Lighting Concerned.

	\$	170.00	<i>rol</i>
TOTAL	\$	11,720.00	

Over All Total	\$	26,172.88
-----------------------	-----------	------------------

(PART-BY-PART) Repair Days

~~15 Days~~

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: