

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5459S

AAD1908-134

*Not Authored**1/Sup & Prod*

Vehicle No.:
Chassis No.:
Vehicle Make: 23 AUG 2019
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration :

SHC 5459S

VF1ABL15AUC280944

RENAULT

LATITUDE

18.8.19

AIG

18/12/2014

		PART		LIST	
1	1	BUMPER COVER REAR	\$	<i>N</i> 1,108.46 ✓	
2	1	BUMPER LOWER REAR	\$	<i>Red/wh</i> 768.84	
3	1	BUMPER BRACKET CTR REAR	\$	<i>SL</i> 113.47	
4	1	BUMPER BRACKET SIDE RH REAR	\$	<i>SL</i> 135.97	
5	1	BUMPER RETAINER RH REAR	\$	<i>SL</i> 44.99	
6	1	BUMPER REFLECTOR RH	\$	<i>SL</i> 43.61	
7	1	BUMPER BRACKET SIDE LH REAR	\$	<i>SL</i> 135.97	
8	1	BUMPER RETAINER LH REAR	\$	<i>SL</i> 44.99	
9	1	BUMPER REFLECTOR LH	\$	<i>SL</i> 43.61	
10	1	BUMPER BEAM REAR	\$	<i>N</i> 777.52	
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>N</i> 225.95	
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>N</i> 225.95	
13	1	OUTER PANEL REAR (End Panel)	\$	<i>N</i> 1,471.77	
14	1	OUTER PANEL REAR (End Panel)TRIM	\$	<i>SL</i> 404.56	
15	1	TAILLAMP RH	\$	<i>SL</i> 552.55	
16	1	TAILLAMP PANEL RH	\$	<i>N</i> 986.70	
17	1	TAILLAMP LH	\$	<i>SL</i> 552.55	
18	1	TAILLAMP PANEL LH	\$	<i>N</i> 986.70	
19	1	BOOT REAR	\$	<i>N</i> 2,872.68	
20	1	BOOT FINISHER	\$	<i>SL</i> 470.06	
21	1	BOOT WHEATERSTRIP	\$	<i>SL</i> 323.05	
22	1	BOOT REFLECTOR LAMP LH	\$	<i>SL</i> 493.35	
23	1	BOOT REFLECTOR LAMP RH	\$	<i>SL</i> 493.35	
24	1	BOOT BADGE 'RENAULT'	\$	<i>N</i> 225.36	
25	1	BOOT BADGE	\$	<i>N</i> 225.36	
26	1	BOOT STRUT LH	\$	<i>SL</i> 276.08	
27	1	BOOT STRUT RH	\$	<i>SL</i> 276.08	
28	1	BOOT HINGE LH	\$	<i>N</i> 367.84	
29	1	BOOT HINGE RH	\$	<i>N</i> 367.84	

Trans-cab Auto Services Pte Ltd**AAD1908-134**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5459S

30	1	BOOT INNER TRIM	\$	Sh	586.45	}	X
31	1	BOOT SWITCH	\$	Sh	168.13		
32	1	BOOT LOCK	\$	A	202.67		
33	1	BOOT LOCK CATCH	\$	n	74.40		
34	1	EXHAUST REAR	\$	n	7,489.05		
35	1	EXHAUST CAP REAR	\$	n	230.49		
TOTAL			\$		23,766.42		
10%			\$		2,376.64		
			\$		21,389.78		

Special Nett

1	1SET	PARKING AID	\$	Sh	700.00	}	X
2	1SET	REAR BUMPER CLIP	\$	nn	66.00		
3	1SET	BUMPER BRACKET CTR CLIP	\$	nn	33.00		
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	nn	10.00		
5	1SET	BUMPER RETAINER RH CLIP RR	\$	nn	20.00		
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	nn	10.00		
7	1SET	BUMPER RETAINER CLIP LH RR	\$	nn	20.00		
8	1SET	BUMPER LOWER REAR RIVET	\$	nn	22.00		
9	1SET	BUMPER LOWER REAR CLIP	\$	nn	66.00	}	X
10	1	BOOT STICKER "Trans-cab"	\$	nn	30.00		
11	1	BOOT STICKER "6555-3333"	\$	nn	30.00		
12	1	EXHAUST MOUNTING REAR	\$	Sh	17.82		
13	2	REAR WINDSCREEN SEALANT	\$	nn	80.00		
14	1	WINDSCREEN MOULDING	\$	nn	100.00		
15	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00		
16	1	BOOT INNER TRIM CLIP	\$	nn	45.00		
17	1SET	BOOT FINISHER CLIP	\$	nn	24.20		
18	1	TAILLAMP CLIP LH	\$	nn	5.00		
19	1	TAILLAMP CLIP RH	\$	nn	5.00		
20	1	REAR BUMPER PROTECTOR	\$	nn	100.00	40.00	
TOTAL			\$		1,484.02		

TOTAL PARTS \$ 22,873.80**LABOUR**

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ nn 380.00 X

Trans-cab Auto Services Pte Ltd**AAD1908-134**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5459S

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn	170.00	X
To Check Electrical Lighting Concerned.	\$	nn	170.00	X
To Rust-Proofing Of The Affected Areas.	\$	nn	170.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn	170.00	X
To reinstall rear bumper parking sensor.	\$	nn	170.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		4,500.00	100%
Putty And Spray Painting Of The Affected Portion.	\$		4,500.00	220%
To repair and realign rear exhaust pipe.	\$	nn	170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	7	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	4	170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	4	170.00	X
To check steering geometry and computer wheel alignment	\$	4	220.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	4	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair	\$	4	380.00	X

TOTAL \$ 11,890.00**Over All Total \$ 34,763.80****LUMP SUM (REPAIR DAY)****15 DAYS***1 1/2 days*

Acknowledged by Repairer

Signature:

Date: