

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

**GST REG. NO : M2 - 0020081 - X****E S T I M A T E**

Estimate No.	: b1 52463	Page No. : 1 of 5
Date Estimated	: 24/08/2019	
Prepared By	: Gary Poh Chai Hoon	

- ESTIMATE REPAIR FOR - Rakesh Das 11 Nathan Road #21-04 Regency Park Singapore 248732	- ACCOUNT - 40000 Cash Sales - Service Singapore
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLS5181K	BH11119	27/09/2017	420iA GC	0

DESCRIPTION	VALUE
To replace left front fender, left front door . left rear door and r/i left side skirt ,left rear fender,rear bumper & attachment include knocking	5100 5,950.00
Painting left front fender, left front door,left rear door ,left side skirt ,left rear fender and rear bumper .	4863 5,404.00
To carry out body cavity preservation. (Per panel).	300 354.00
To conduct checks on all doors and bootlid central locking system for proper function.	150 171.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 171.00
To replace left rear rim including balancing. (1x).	80 94.00
To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1x)	451 531.00
Sundries.	? 150.00
Total Labour 1:	12,837.00

DESCRIPTION	QTY	PRIC	VALUE
ALLOY RIM 8JX18 STAR SPK 707 <i>see</i>	1	966.50	966.50
HUB CAP WITH CHROME EDGE (BMW) <i>see</i>	1	28.35	28.35
RR LH DOOR <i>bt</i>	1	1,267.50	1,267.50
FRT LH DOOR <i>bt</i>	1	1,267.50	1,267.50
FRT LH SIDE PANEL <i>bt</i>	1	702.65	702.65
FRT LH 3 SIDE PANEL BRACKET <i>see</i>	1	34.25	34.25
LH UPPER FRT DOOR HINGE ?	1	56.00	56.00
LH LOWER FRT DOOR HINGE ?	1	56.00	56.00
LH LOWER REAR DOOR HINGE ?	1	58.60	58.60

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 52463**
Date Estimated : **24/08/2019**
Prepared By : **Gary Poh Chai Hoon**

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLS5181K	BH11119	27/09/2017	420ia GC	0

DESCRIPTION	QTY	PRIC	VALUE
LH UPPER REAR DOOR HINGE ?	1	58.60	58.60
MODEL LETTERING SIDE (SPORT LINE) <i>neu</i>	1	46.30	46.30
FRONT DOOR BRAKE ?	1	77.20	77.20
RR LH DOOR BRAKE ?	1	77.20	77.20
FRT LH DOOR CHANNEL COVER EXTERIOR ?	1	126.50	126.50
REAR LH DOOR OUTER WEATHERSTRIP (SC) <i>neu</i>	1	126.50	126.50
FRT LH COVER WHEEL ARCH ?	1	116.55	116.55
LH COVER BOTTOM ?	1	116.55	116.55
RR LH DOOR WEATHERSTRIP <i>neu</i>	1	140.70	140.70
FRT LH DOOR SEALING <i>neu</i>	1	140.70	140.70
FRT LH AIR DUCT SIDE PANEL PRIMED ?	1	55.95	55.95
REAR DOOR JOINT SEAL <i>neu</i>	1	84.45	84.45
FRT DOOR JOINT SEAL <i>neu</i>	1	58.60	58.60
LH B PILLAR JOINT SEAL ?	1	58.60	58.60
Total Parts :			5,721.75

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time _____ Excess S\$ _____

Surveyor's Name _____ Sign _____

Surveyor's Tel _____ Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail _____

No. of Working Days Recommend _____

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 09/09/19 @ 1410 Excess S\$ _____

Surveyor's Name RSL Sign _____

Surveyor's Tel 92010068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail _____

No. of Working Days Recommend 11 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Labour 1	:	12,837.00
Parts	:	5,721.75
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,299.11
Grand Total	:	19,857.86

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **