



南方摩哆 SOUTHERN MOTOR

Business Reg. No: 234147/00L
Block 1006, Bukit Merah Lane 2. #01-10, Singapore 159762
Tel: 6273-0369 (3 Lines) Fax: 6274-6614

23rd August 2019

India International Insurance Pte Ltd
64 Cecil Street #05-00
IOB Building
SINGAPORE (049711)

Dear Sirs,

RE: Cost of repair to Yamaha Jupiter 135 – FBK789B

1pc of Cover Set <i>crn</i> ✓	S\$ 580.00
1pc of Handle Bar <i>?</i>	68.00
1pc of Front Fork Complete <i>repair</i>	380.00
1pc of Mirror <i>mis</i> ✓	45.00
1pc of Handle Grip <i>cut</i> ✓	35.00
1pc of Front Footrest <i>bt</i> ✓	68.00
1pc of Footrest Rubber <i>cut</i> ✓	20.00
1pc of Spoke Rim <i>repair</i>	480.00
1pc of Exhaust Pipe <i>scr</i> ✓	580.00
1pc of Rear Mudguard <i>crn</i> ✓	65.00
1pc of Brake Lever <i>* (pedal) bt</i> ✓	68.00
2pc of Rear Footrest <i>cm</i> ✓	40.00
1pc of Rear Headlight <i>?</i>	110.00
2pc of Rear Footrest Stand <i>* (crn) (bracket)</i> ✓	110.00
1pc of Steering Corn <i>na</i> ✓	85.00
1pc of Repair Brake Body	180.00 <i>120</i>
1pc of Seat Bar <i>scr</i> ✓	55.00
1pc of Gear Lever <i>bt</i> ✓	68.00
	3,037.00
	Less 10%
	303.70
	Nett 2,733.30
Transport	40.00
Labour	350.00
	S\$ 3,123.30

Yours Faithfully,
Southern Motor

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature

Repair

Hp 96012068

4 days

26/08/19 @ 15W

Repair after repair