

ASS. REC. BY:

REF: CS/MS419014966/Dgd3

Special Instructions:

Survey: Bryen

ASSIGNMENT (Office)

From (Person): Crystal Lee

of

MS/4Date/Time: 26/8/19 @ 1.59pm

Estimated Cost:

Bill to:

OD TP WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHA 3412A

Insured:

SLQ 99324

at Workshop m/s

Chunni Motor

Tel:

65425119

of

AMR Autopoint #01-05/06

Policy No:

79114756

Claim No:

603859

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/8/2014

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 2:13pm @ 26/8/14

Person Contacted:

LynnVehicle IN/OUT

Date/Time

Action/Instruction

JohnnieSHA 3412A - CS/III 6003806SLQ 99324 - X02/9/14 @ 1.36pm revised to Crystal Lee via Meimien.

REF:

ASSIGNMENT

COE May 2024

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No.:

at Workshop n/s:

of

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 86 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No. SHH 3412 A Yr Regn. 2016 May
 Type: M. Car / M. Cycle / Bus / Van / Lorry / ☒ Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai I40 C.C. 1685

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 553362 T/Radio: Insured / Std / NI / NA

Eng/No: D4FDGU626554

C/No: KMHLB41UMGU090155

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orMod: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60 R16

R: ———

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 23/08/2019 D.O.I. 27/08/2019

Survey held at Chunni AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Brnt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MSG SLC 9932U

RECEIVED 26 SEP 2019

24/09/19 Jmann 4/5 8700/- with 8 days of van
 (Red 8885.08, 51%)

20/9/2019

Date/Time, File Pass to?

☐

: Preli. Report

1) 26/9/2019

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 8

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS: 21

Photos

Others

TOTAL

200
11

211

Report Format:

MER-P

Lump Sum / L.B.A. (\$) 8700

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 02 Sep 2019

Preliminary Advice

Insured Vehicle No	: SLQ9932U	Accident Date	: 23/08/2019
TP Vehicle No	: SHA3412A	Assignment Date	: 26/08/2019
Make	: HYUNDAI I40	Est. Duration of Repair	: 6.00
Date of Inspection	: 27/08/2019		
Inspection At	: SOON HOCK MOTOR PTE LTD (HQ) BLK 10 ANG MO KIO INDUSTRIAL PARK 2A, #01-05/06 AMK AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,585.08
Revised Amount	:S\$	10,955.88
Check Items (Estimated)	:S\$	0.00
Total	:S\$	10,955.88

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Nivitha (LKK Auto)

From: Crystal Lee <crystal_lee@sg.msig-asia.com>
Sent: Monday, 26 August 2019 1:59 PM
To: Admin-D (LKKAuto); assignments
Cc: Ong Zi Hui
Subject: Survey Request - Manual Assigned

Accident involving veh no:SHA3412A/SLQ9932U (GRAB) On 23/8/2019

Manual Assigned

Dear LKK,

Refer to the email and attachment, please survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment

Thank you & Best regards,

Crystal Lee

Admin Officer, Claims Services (In-House Survey)

D: +65 6594 2535 | F: +65 6643 1349 | crystal_lee@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Winnie Chua

Sent: Monday, 26 August, 2019 11:58 AM

To: assignments <assignments@lkkauto.com>

Cc: Helene Phua <helene_phua@sg.msig-asia.com>; Crystal Lee <crystal_lee@sg.msig-asia.com>; Ong Zi Hui <zihui_ong@sg.msig-asia.com>

Subject: FW: FW: Accident involving veh no:SHA3412A/SLQ9932U (GRAB) On 23/8/2019 (Manual assigned)

Hi,

Thank you for your selection.

We will proceed to appoint/assign LKK Auto Consultants Pte Ltd via Merimen at our end and update you upon confirmation.

Please do not contact them directly to prevent confusion.

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol.

Best Regards

Winnie Chua

Senior Admin Officer, Claims Services (In-House Survey)

Direct line +65 6594 2556 | Direct fax +65 6225 7402 | pingping_chua@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Chunni Motor [<mailto:chunnimotor@gmail.com>]

Sent: Monday, 26 August 2019 11:48 AM

To: Winnie Chua <pingping_chua@sg.msig-asia.com>

Subject: Re: FW: Accident involving veh no:SHA3412A/SLQ9932U (GRAB) On 23/8/2019

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Sir,

We appoint LKK Auto Consultants .

Thank you

Regards,
Chunni Motor Work P/L

On Mon, Aug 26, 2019 at 11:33 AM Winnie Chua <pingping_chua@sg.msig-asia.com> wrote:

Hi,

We refer to your email/faxed dated 24/08/19.

Please choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection:

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) Automobile Inspection Services Pte Ltd
- 4) STA Inspection Pte Ltd
- 5) Appraisal VP Pte Ltd
- 6) AutoProbe Consultants
- 7) **MSIG In-House Surveyors (Appointment is full on 26/08/19)**

This Fast-Lane settlement option is for clear-cut liability which MSIG will expedite offer @ 100% with express payment. Priority will be given to those opted for our in-house surveyor

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert).

If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability:

1) Calvin Ang	6) Chow Bo Xiong
2) Kenneth Kong	7) E C Looi
3) Marcus Chua	8) Daniel Chan
4) Ng You Han	9) Victor Png
5) Gary Soon	10) Samuel Phun

In your response, please also provide us a list of 10 surveyors as your nominated SJE, regardless of whether you agree or disagree to our above nominated SJE. We may consider appointing one of your nominated SJE in case of any of our nominated SJE is not available.

NB:

(a) ***Fast lane settlement is not applicable for cases that liability is in dispute***

(b) If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We have created a dedicated motor survey mailbox for your motor survey request and pre-repair inspection. Please contact us (MSIG) by clicking this link: motorsurvey@sg.msig-asia.com

Best Regards

Winnie Chua

Senior Admin Officer, Claims Services (In-House Survey)

Direct line +65 6594 2556 | Direct fax +65 6225 7402 | pingping_chua@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



From: Chunni Motor [<mailto:chunnimotor@gmail.com>]
Sent: Saturday, 24 August 2019 8:39 AM
To: Motor Survey <motorsurvey@sg.msig-asia.com>; Nabilah Rasol <nabilah_rasol@sg.msig-asia.com>
Subject: Accident involving veh no:SHA 3412A/SLQ 9932U On 23/8/2019

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Sir/ Mdm,

We refer the above mentioned matter.

We enclosed herewith the relevant documents for your necessary action.

In line with the new protocol, kindly provide us with the list of surveyors on your panel for assessment of the damaged accident taxi involved.

Kindly survey at AMK Autopoint, Soon Hock Motor,#01-05/06.

Should you have any queries, please do not hesitate to contact Ms Lynn or Ms Irene at 65425119 or 6542 7162

Thank you for your kind assistance.

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

MCD619111409 / ComfortDelGro Engineering Pte Ltd - Layan
 ENTRY DATE & TIME: 24/08/2019 07:40
 SUBMITTED BY: Catherine Por May Juan

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 24/08/2019 07:40
 Date Of Accident 23/08/2019 03:40
 Exact Location Of Accident OPHIR ROAD TWDS ECP
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHA3412A
Insured/Policyholder
 Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD
 Co Reg No 199303821R
 Email Address FLEETSATY@CDGTAXI.COM.SG
 Mobile Phone No
 Alternative Phone No OFFICE-65508768

Vehicle Particulars

Manufacturer HYUNDAI
 Model I40
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category TAXI
Insurance Company
 Name of Insurance Company INDIA INTERNATIONAL INSURANCE PTE LTD
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
 Fleet Policy YES
 Policy Number MCOM0015
 Cover Note Number

Driver

Name of Driver RAJASEGARAN S/O MANIKAM
 NRIC No S1196167C
 Date Of Birth 13/03/1956
 Occupation OUTDOOR
 Date Of Driving Pass 05/09/1980
 Driving Experience 38 YEARS AND 11 MONTHS
 Gender FEMALE
 Mobile Number (LOCAL) +65-94526616
 Fax Number
 Contact Number
 Email Address RAJASEGARANMANIKAM@GMAIL.COM

Address 336 #04-829 UBI AVENUE 1
Postcode 400336
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident SIDE SWIPE
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? YES
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2
Passenger 1 NAME: : -
GENDER: : MALE

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
POLICE STATION NAME [OTHER] KG UBI NPP
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

SEE POLICE REPORT.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Remarks/ Reasons: -
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLQ9932U
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver JEFFREY TAN JUN TONG
NRIC/Passport Number S8102086H
Contact Number
Address
Postcode
Insurance Company Name

Nature Of Damage

FRT LEFT

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	RAJASEGARAN S/O MANIKAM
Approximate Age	63
Injuries Sustain	NECK,BACK,SHOULDER
Injured person in which vehicle?	SHA3412A
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

DETAILS OF INJURED PERSON 2

Name	CHYE KEE NAM
Approximate Age	
Injuries Sustain	CHEST,LEG
Injured person in which vehicle?	SHA3412A
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)

Date & Time: 23.08.2019 @ 1645HRS

Reporting Centre Personnel's Signature
Name:

NRIC/FIN No.: June

SKETCH PLAN

A- SHA 3412A
B- SLQ 9932U

Along Ophir Rd twds ECP

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to attachment: T/20190823/2117

DECLARATION

I/We declare the foregoing particulars are true in every respect.
CO. REG. NO. 199303821RPolicyholder's Signature
Date & Time:Driver's Signature
(If driver is not the policyholder)
Date & Time: 23.08.2019@1645HRSReporting Centre Personnel's Signature
Name:
SC/FIN No.: June



**SINGAPORE
POLICE FORCE**



T/20190823/2117

Police Station Of Origin:
Kampong Ubi NPP
9 Eunos Crescent #01-2687 SINGAPORE
400009
Tel No: 1800-7479999

1 of 4

Report No. T/20190823/2117

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 23/08/2019 15:12		Vide Report No.: A/20190823/0028		Station Diary No.: 9	
Informant's Particulars					
Name of Informant: RAJASEGARAN S/O MANIKAM			Address: APT BLK 336 UBI AVENUE 1 #04-829 SINGAPORE 400336		
ID Type / ID No.: NRIC NO / S1196167C			Contact No.: Home/Office: Mobile: 94526616		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 63	Date of Birth: 13/03/1956	Type of Informant: Driver		
Race: Indian			Language:		Institution / School Name:
Occupation: Taxi Driver			Driving Licence Information: Class: 2B,2A,2,3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 23/08/2019 03:40	Type of Location: Straight Road
Location: Along Road 1 OPHIR ROAD				
Junction East Coast Park Expressway Before Rochor Canal				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: No Traffic
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHA3412A	Car	HYUNDAI	I40 1.7 CRDI F/L AT ABS AIRBAG 4DR	Blue	Slightly Damaged	1
SLQ9932U	Car	TOYOTA	I40 1.7 CRDI F/L AT ABS AIRBAG 4DR	White	Slightly Damaged	1



**SINGAPORE
POLICE FORCE**



T/20190823/2117

2 of 4

Police Station Of Origin:
Kampong Ubi NPP
9 Eunos Crescent #01-2687 SINGAPORE
400009
Tel No: 1800-7479999

Report No. T/20190823/2117

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Passenger			
Name	Chye Kee Nam	ID No.	NIL
Related Vehicle	SHA3412A (Car)	Contact No.	88099059
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight
Driver			
Name	RAJASEGARAN S/O MANIKAM	ID No.	S1196167C
Related Vehicle	SHA3412A (Car)	Contact No.	94526616
Hospital/Clinic	ACCORD MEDICAL CLINIC	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	23/08/2019	Date Discharge	23/08/2019
No. of Days granted Medical Leave	04	Degree of Injury	Slight
Driver			
Name	Jeffrey Tan Jun Tong	ID No.	S8102086H
Related Vehicle	SLQ9932U (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 23/08/2019 at about 0323hrs I picked up my passenger from Toa payoh Lorong 1 to go to Beach Road. On the same day at about 0337hrs I was driving on the left most lane at along Ophir Road out of the sudden a vehicle (SLU9932U) side swiped into me.

After the incident, we stopped at the location near to the bus stop and exchanged our particulars. I would like to state that there were no visible injuries on the driver and our passengers. But however, my passenger complained pain on his body as such I called for ambulance for him as well as the traffic police and shortly afterwards I was attended by the police and my passenger was conveyed to Tan Tock Seng



**SINGAPORE
POLICE FORCE**



T/20190823/2117

3 of 4 .

Report No. T/20190823/2117

Police Station Of Origin:

Kampong Ubi NPP

9 Eunos Crescent #01-2687 SINGAPORE

400009

Tel No: 1800-7479999

CONTINUATION OF REPORT

Hospital.

I would like to state that due to the incident the front right side of my taxi was damaged and had to be towed during the incident and after the incident I felt pain on my shoulder, neck and lower back as such I went to seek medical attention and was given 4 days of MC.

**SINGAPORE
POLICE FORCE**

T/20190823/2117

4 of 4

Report No. T/20190823/2117

Police Station Of Origin:
Kampong Ubi NPP
9 Eunos Crescent #01-2687 SINGAPORE
400009
Tel No: 1800-7479999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sgt 2 ANG YI FENG, ELSON

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

23/08/2019 15:12

Officer In Charge Of Case:

TP / GIT /


SI THABAGESH JEYATHESH

Contact No.: 65476232

Classification Of Case:

Authentication Stamp

NP168



SIGNATURE

REPAIR ESTIMATE*

DATE : 23.08.2019



TEL : 6542 5119

FAX : 6542 6039

11566

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover Dented			\$ 1,052.20 ✓
	Front Bumper Sponge NM			\$ 99.20 X
	Front Bumper Bracket Top (RH) NM			\$ 22.40 X
	Front Bumper Bracket (RH) broken			\$ 24.60 ✓
	Headlamp Support Top Cover NM			\$ 222.60 X
	Headlamp Support Panel Assy broken 1st			\$ 907.40 ✓
	Headlamp (RH) broken			\$ 1,388.00 ✓
	Radiator Expansion Tank NM			\$ 28.30 X
	Front Fender (RH) Dented			\$ 566.30 ✓
	Front Fender Apron Panel (RH) Dented			\$ 637.00 ✓
	Front Fender Shield (RH) damaged			\$ 174.90 ✓
	Rocker Panel Outer Garnish NM			\$ 341.40 X
	Wiper Container broken			\$ 61.90 ✓
	Wiper Container Motor Dam			\$ 75.00 ✓
	Front Wheel Rim (RH) Bt			\$ 325.30 ✓
	Front Wheel Hub Cap (RH) It			\$ 107.10 ✓
	Front Wheel Bearing 2 Dam			\$ 540.50 Z ✓
	Front Shock Absorber (Assy) (RH) 2 disturbed			\$ 342.20 Z ✓
	Front Shock Absorber Mounting (RH) NM			\$ 108.80 X
	Front Drive Shaft (RH) 2 disturbed			\$ 1,030.80 Z ✓ X
	Rack & Pinion Assy 2 Dam			\$ 969.60 X ✓
	STG Tie End 2 disturbed			\$ 62.60 Z ✓
	Stabilizer Bar NM			\$ 252.30 X
	Stabilizer Bar Bush (RH) NM			\$ 16.40 X
	Stabilizer Bar Link NM			\$ 61.10 X
	Stabilizer Bracket NM			\$ 24.00 X
	Front Suspension Lower Arm (RH) 2 Bt			\$ 529.30 Z ✓
	Knuckle Arm (RH) 2 disturbed			\$ 552.00 Z ✓
	Engine Crossmember 2 disturbed			\$ 2,094.40 Z ✓ X
	ABS Sensor NM			\$ 234.00 X
	Electric Power Steering NM			\$ 3,641.00 X
	SUB TOTAL			\$ 16,492.60
	LESS 20%			\$ 3,298.52
	DISCOUNTED TOTAL			\$ 13,194.08
	Front Door Comfort Logo (RH) NM			\$ 75.00 Nett ✓
Fender	Front Door Advertisement Logo (RH) NM			\$ 100.00 ✓ Nett ✓
	Front Tyre (RH) Punctured 50% depreciation			\$ 216.00 ✓ 108.00
				\$ 391.00

SHA 3412A

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,500.00 600/-
	Spray Painting Charge			\$ 1,200.00 500/-
	Wiring Charge			\$ 50.00 30/-
	Tuff Kote			\$ 50.00 30/-
	Towing Charge			\$ 50.00 22
	Remove/Refix Undercarriage (FRT)			\$ 200.00 150/-
	FRT Wheel Alignment		1520.00	\$ 120.00 60/-
	Remove/Refix Aircon & Refill Gas			\$ 150.00 22
	Re-set Frt ABS System			\$ 200.00 } 150/-
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00
	TOTAL LABOUR			\$ 4,000.00
	ESTIMATE TOTAL			\$ 17,585.08
	27/08/2019 @ 0930hrs		10880.88	
	Not Antimal		2/3 8700/-	
	2/3 Sun 8 days.			
				
	LKK Auto			
				
	<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p>			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHA 3412 A

Technician:

Mileage: 553362

Time Printed 27.8.19 10:50 AM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
-0°42'		-3°00' 3°00'
3°56'		-0°19' 5°41'
-0°01'		-1°30' 1°30'
19°07'		
18°25'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-0°27'		-3°00' 3°00'
3°33'		-0°19' 5°41'
1°51'		-1°30' 1°30'
16°04'		
15°37'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
-0°14'		-3°00' 3°00'
0°23'		-3°00' 3°00'
3°03'		-3°00' 3°00'
1°50'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
-1°16'		-3°30' 2°30'
-0°07'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-0°57'		-3°30' 2°30'
0°08'		-1°30' 1°30'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
-0°19'		-3°00' 3°00'
0°01'		-3°00' 3°00'
-0°08'		-3°00' 3°00'

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19014966/DQD3N2

Date: 02/10/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29114756
Claimant Vehicle No :	SHA3412A	Insured Vehicle No :	SLQ9932U
Date of Loss:	23/08/2019	Nature of Claim:	TP
		Claim No:	603859

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA3412A		
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Engine No:	D4FDGU626554
Reg. Date:	12/05/2016 (Man. Year: 2016)	Chassis No:	KMHLB41UMGU090155
Colour:	Blue	Odometer:	553362 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Hankook 5 mm	Rear Left Side:	Hankook 5 mm
Front Right Side:	Hankook 5 mm	Rear Right Side:	Hankook 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,585.08	9,360.88	4,224.20	31.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,000.00	1,520.00	2,480.00	62.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,585.08	10,880.88	6,704.20	38.12
Approved Total (Overridden) (S\$)		8,700.00		
(S\$)	17,585.08	8,700.00	8,885.08	50.53
+ GST 7.00/7.00% (S\$)	1,230.96	609.00	621.96	50.53
Nett Amount (S\$)	18,816.04	9,309.00	9,507.04	50.53

INSPECTION

Date of Assignment:	26/08/2019	
Date Inspected:	27/08/2019	Inspected At:
		Chunni Motor Work Pte Ltd - Amk (HQ)
		Blk 10 #01-05/06, AMK Autopoint
		Singapore 568047
Estimated Period of Repair:	8.0 days	

Adjuster: BRYAN TANI

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Oct 2019)
Parts:	143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA3412A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER COVER	Dented	1,052.20 FL	*1,052.20 FL
2	1	*FRONT BUMPER SPONGE	Not Necessary	99.20 FL	*- FL
3	1	*FRONT BUMPER BRACKET TOP (RH)	Not Necessary	22.40 FL	*- FL
4	1	*FRONT BUMPER BRACKET (RH)	Broken	24.60 FL	*24.60 FL
5	1	*HEADLAMP SUPPORT TOP COVER	Not Necessary	222.60 FL	*- FL
6	1	*HEADLAMP SUPPORT PANEL ASSY	Broken/Bent	907.40 FL	*907.40 FL
7	1	*HEADLAMP (RH)	Broken	1,388.00 FL	*1,388.00 FL
8	1	*RADIATOR EXPANSION TANK	Not Necessary	28.30 FL	*- FL
9	1	*FRONT FENDER (RH)	Dented	566.30 FL	*566.30 FL
10	1	*FRONT FENDER APRON PANEL (RH)	Dented	637.00 FL	*637.00 FL
11	1	*FRONT FENDER SHIELD (RH)	Deformed	174.90 FL	*174.90 FL
12	1	*ROCKER PANEL OUTER GARNISH	Not Necessary	341.40 FL	*- FL
13	1	*WIPER CONTAINER	Broken	61.90 FL	*61.90 FL
14	1	*WIPER CONTAINER MOTOR	Damaged	75.00 FL	*75.00 FL
15	1	*FRONT WHEEL RIM (RH)	Bent	325.30 FL	*325.30 FL
16	1	*FRONT WHEEL HUB CAP (RH)	Bent	107.10 FL	*107.10 FL
17	1	*FRONT WHEEL BEARING	Damaged	540.50 FL	*540.50 FL
18	1	*FRONT SHOCK ABSORBER (ASSY)(RH)	Distorted	342.20 FL	*342.20 FL
19	1	*FRONT SHOCK ABSORBER MOUNTING (RH)	Not Necessary	108.80 FL	*- FL
20	1	*FRONT DRIVE SHAFT (RH)	Distorted	1,030.80 FL	*1,030.80 FL
21	1	*RACK & PINION ASSY	Damaged	969.60 FL	*969.60 FL
22	1	*STG TIE END	Distorted	62.60 FL	*62.60 FL
23	1	*STABILIZER BAR	Not Necessary	252.30 FL	*- FL
24	1	*STABILIZER BAR BUSH (RH)	Not Necessary	16.40 FL	*- FL
25	1	*STABILIZER BAR LINK	Not Necessary	61.10 FL	*- FL
26	1	*STABILIZER BRACKET	Not Necessary	24.00 FL	*- FL
27	1	*FRONT SUSPENSION LOWER ARM (RH)	Bent	529.30 FL	*529.30 FL
28	1	*KNUCKLE ARM (RH)	Distorted	552.00 FL	*552.00 FL
29	1	*ENGINE CROSSMEMBER	Distorted	2,094.40 FL	*2,094.40 FL
30	1	*ABS SENSOR	Not Necessary	234.00 FL	*- FL
31	1	*ELECTRIC POWER STEERING	Not Necessary	3,641.00 FL	*- FL
32	1	*FRONT DOOR COMFORT LOGO (RH)	Not Necessary	75.00 FS	*- FS
33	1	*FRONT FENDER ADVERTISEMENT LOGO (RH)	Necessary	100.00 FS	*100.00 FS
34	1	*FRONT TYRE (RH)(50%)(DEPRECIATION)	Punctured	216.00 FS	*108.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	16,883.60	11,649.10
- List Item Discount on L Items 20.00/20.00% (S\$)	3,298.52	2,288.22
Total Parts (S\$)	13,585.08	9,360.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,500.00	600.00
2	SPRAY PAINTING CHARGE	New	1,200.00	500.00
3	WIRING CHARGE	New	50.00	30.00
4	TUFF KOTE	New	50.00	30.00
5	TOWING CHARGE	New	50.00	0.00
6	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	200.00	150.00
7	FRT WHEEL ALIGNMENT	New	120.00	60.00
8	REMOVE/REFIX AIRCON & REFILL GAS	New	150.00	0.00
9	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE }	New	480.00	150.00
10	RE-SET FRT ABS SYSTEM }	New	200.00	0.00
Gross Labour Cost (\$\$)			4,000.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >