

ASS. REC. BY:

REP

02/FCI19014969/GSD3/12

Special Instruction:

Survey: GA

ASSIGNMENT (Office)

W/S

From (Person): Jason Teo

of

FCI

Date/Time: 23/8/19 @ 9:58am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKQ 86531

Insured:

SHA17784

at Workshop n/s

Borneo Motor

Tel:

9221 3150

of

2 Pinden Crescent

Policy No:

Claim No:

D19005433 MPFH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 20/08/2019

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time: 11:18am 26/8/19

Person Contacted:

Raymond

Vehicle IN / OUT

Date/Time

Action/Instruction

10/09/19 ✓

SKQ 86531-X

SHA17784-003/ANG/8003101/KLWB342

D.O.A. 12/12/2018

13/09/19 @ 16:27 pm revised RA to Jason V.a email.

INS. REC. BY

GR

REF FCI

ASSIGNMENT

From:

Date:

17/9/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKQ 8653T

at Workshop m/s

Borneo Motor

of

17 ubi Road 4

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

10:30am (meeting)

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKQ 8653T

Vr Regn:

02 Jan 2015

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota wish

c.c

1798

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

12731

T/Radio:

Insured / Std / NI / NA

Eng/No:

JTDGG 20W 50J 001956

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65 R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A.

D.O.I.

17-09-19

Survey held at

w/s

10:30

Des. of Damages: Fry / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

23/9/19

Confirmed P/P \$ 4,332.00 @ 4 days with X6Q.
(\$ 9,495.70 Red - 69%)

RECEIVED 23 SEP 2019

[Signature]
23/9/2019

Date/Time, File Pass to:

23/9/19

1) Typist

Date/Time, File Return to:

2)

Eq. & Form

Equip. Cost

4,332.00 P/P

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp

(\$

☐

Interview

(#

☐

Tech. Insp

(#

☐

Witness

(#

Survey Fee:

Transportation:

S = P.S. 3A

1. Dinner

2. Cab Fare

1. P.M.S.

3x15=45

170+45

50

50

25

340



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19005433MFSH

Date: 18 September 2019

Our Ref: CS/FCI19014969/Gsd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SKQ 8653T

Please be informed that we had conducted the inspection of the abovementioned vehicle on 17/09/2019 at the premises of M/s Borneo Motors (Singapore) Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ 13,827.70
Revised Estimate Amount	: S\$ 4,332.00
"Check" Items Amount	: S\$ 1,027.80
Market Value	: S\$ -
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -


Description of Damage:

The vehicle sustained damages at the front portion.

Comments/ Present Status:

Damages Consistent.

Repair days: 4 days



Yours faithfully

Xing Guo Qiang
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	22-08-2019	Our Ref No. D19005433MFSH
Accident Date	20-08-2019	Claim Type. Third Party
Insured Vehicle	SHA1778H	Third Party Vehicle. SKQ8653T
Survey Location	INCHCAPE BODYCARE CENTRE LEVEL 4 INCHCAPE CENTRE2 PANDAN CRESCENT	
Contact Person.	ASHLYN CHNG	
Contact No.	66311874/ 0	Fax No. 68727260
Survey Type	WITHOUT PREJUDICE: LIABILITY UNCLEAR: ACCIDENT OCCURS AT THE YELLOW BOX, INSURED TURNING RIGHT, TP S	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	BORNEO MOTORS (SINGAPORE) PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JASON TEA CHEE KIAT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Re: FINALIZE FOR SKQ8653T

Shirley Hiew (LKK Auto)

Mon 23/9/2019 3:23 PM

To: Raymond Seah PTCBC <Raymond.Seah@borneomotors.com.sg>

Cc: SUR <sur@lkkauto.com>

Dear Raymond,

Confirmed final fig \$ 4,332.00 @ 4 day of repairs before GST.

Final invoice and all supporting documents sent over to First Capital Ins Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte LtdPhone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Raymond Seah PTCBC <Raymond.Seah@borneomotors.com.sg>**Sent:** Friday, 20 September 2019 2:52 PM**To:** Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>**Subject:** FINALIZE FOR SKQ8653T

Dear Guo Qiang,

Attach are photos and estimate of SKQ8653T to finalize.

Thanks

Raymond Seah

9776 2689

From: Ubi_ToyotaBP@inchcape.com.sg <Ubi_ToyotaBP@inchcape.com.sg>**Sent:** Friday, September 20, 2019 2:50 PM**To:** Raymond Seah PTCBC**Subject:** Scan Data from [FX20FF88]

Re: SURVEY ASSESSMENT - D19005433MFSH/1

Shirley Hiew (LKK Auto)

Wed 18/9/2019 4:26 PM

To: 'Jason Tea' <JasonTea@msfirstcapital.com.sg>; 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>
Cc: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>

 1 attachments (81 KB)

PRELI ADVISE - SKQ 8653T.pdf;

Dear Jason,

Enclosed preliminary revised of vehicle SKQ 8653T.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte LtdPhone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>**Sent:** Monday, 26 August 2019 11:20 AM**To:** 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>**Cc:** 'Jason Tea' <JasonTea@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>**Subject:** RE: SURVEY ASSESSMENT - D19005433MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards

G.NIVITHA**LKK Auto Consultants Pte Ltd**Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	564F

Vehicle Details

Vehicle No.:	SKQ8653T
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Sep 2019
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 CVT
Primary Colour:	Silver
Manufacturing Year:	2014
Engine No.:	2ZRB485812
Chassis No.:	JTDGG20W50J001956
Maximum Power Output:	105.0 kW (140 bhp)
Open Market Value:	\$23,454.00
Original Registration Date:	02 Jan 2015
First Registration Date:	02 Jan 2015
Transfer Count:	0
Actual ARF Paid:	\$19,836.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Jan 2025
PARF Rebate Amount:	\$14,877.00

Intended COE Rebate Details

COE Expiry Date:	01 Jan 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$74,000.00
COE Rebate Amount:	\$39,148.00
Total Rebate Amount:	\$54,025.00

The information contained herein is correct as at 17 Sep 2019

OK

TYPE OF CLAIM: ☐ OD ☐ OD/UL ☒ DS

MCA: Roy

MOTOR ACCIDENT REPORT

Date Of Report : 21 AUG 2019	Time: 9:44	Date Of Accident : 20 AUG 2019	Time: 6:20 PM
Exact Location Of Accident : T Junction, A1K AVE 6 and A1K Street 31			
Country/State of Loss: Singapore ☐ / Wilayah Persekutuan ☐ / Selangor Darul Ehsan ☐ / Negeri Sembilan ☐ / Melaka ☐ / Pahang ☐ /			
OWN VEHICLE DETAILS (INSURED/POLICY HOLDER)			
Vehicle Registration Number : SKO 2653 T		Co. Reg. No(for Co. Vehicle)/NRIC/PP/FIN No : 58028564 F	
Name Of Registered Owner : TAN GEE LOCK			
Mobile Number: 9129 0980		Alternative No: Email Address: rule_44@hotmail.com	
Vehicle Particulars			
Manufacturer : Toyota ☒ Lexus ☐ Suzuki ☐ Hino ☐		Model : W154	
Exact Purpose for which vehicle was being used at time of accident: Normal Usage ☒ Other ☐ (please specify) :			
Are you claiming under your own insurance policy for repair to your vehicle? Yes ☐ Reporting Only ☐ Third Party ☒ D)			
Vehicle Category : Private Car ☒ Commercial Vehicle ☐ Others ☐			
Insurance Company			
Name of Insurance Company: AIG			
Type Of Coverage: Comprehensive ☒		Third Party ☒ Third Party Fire and/or Theft ☐	
Fleet Policy: Yes ☐ No ☒		Policy / Cover Note No: 21003 97570 -04	
DRIVER DETAILS AT POINT OF ACCIDENT			
Name of Driver: TAN GEE LOCK		NRIC/ Passport / FIN No : 58028564 F	
Date Of Birth: 05 Sept 1980		Occupation: Indoor ☒ Outdoor ☐	
Date Of Driving Pass: 26 Jul 1999		Gender: Male ☒ Female ☐	
Mobile Number: 9129 0980		Fax No: Alternative No:	
Address: 310A ANG MO KIO AVE 1 #05-329		Postal Code: 561310	
Email Address: rule-44@hotmail.com			
Was driver an employee of the Insured's Company? Yes ☐ No ☐ State relationship of the driver with the insured:			
Vehicle Registration Number of Driver's Own Vehicle (if applicable):			
Insurance Company of Driver's Own Vehicle (if applicable):			
GENERAL INFORMATION OF THE ACCIDENT			
Type Of Accident: TP HIT INJURED WHILE TURNING			
Number of Passengers in the above vehicle (Including Driver): 3 / If more than 2 Pax Please fill ANNEX B			
PASSENGER 1:			
Name: CHAN KAE LING		Gender: Male ☐ Female ☒	
Weather Conditions: Clear ☒ Raining ☐ Others ☐ (If others, please state condition):			
Road Surface: Wet ☐ Dry ☒ Others ☐ (If others, please state condition):			
Was any body injured in the Accident? No ☒ Yes ☐			
Was any injured conveyed to hospital by ambulance? No ☒ Yes ☐			
Was any foreign vehicle involved in this accident? No ☒ Yes ☐ Vehicle No: Vehicle type:			
Number of vehicles involved in the accident: 2			
Was there any witness? No ☒ Yes ☐ If yes, please furnish witness details column below			
Witness Name:		Contact No.: Email:	
Was there any other vehicle or property damaged? No ☐ Yes ☒			
Was there any video captured by Car Camera? No ☐ Yes ☒		Are accident scene photos available for attachment? No ☐ Yes ☒	
Was the accident reported to the police? No ☒ Yes ☐ (If yes, please state which Police Station):			
Was notice of intended Prosecution given? No ☒ Yes ☐ (If yes, please state against whom):			
I have been approached by unknown person(s) soliciting/offering accident claims assistance. No ☒ Yes ☐			
DETAILS OF OTHER VEHICLE PROPERTY 1 (Please fill Annex A if more vehicles involved)			
Vehicle Registration Number: SHA 1778 H		Vehicle Make/Model/Colour: HYUNDAI i40 / Blue	
Details Of Properties Damage In Accident: left side bottom left hand side of the car only.			
Vehicle Category: Sedan			
Name of Driver: HO WENG KEONG			
NRIC/Passport/FIN Number: S0904927 D		Contact Number: 98533780	
Address: BK 215 ANG MO KIO AVENUE 1, #08-883		Postal Code: 560215	
Insurance Company Name:			
Nature Of Damage:		No. Of Passenger (Including Driver):	

PASSENGER 1	
Name: TAN ZI HAN	Gender: Male ☐ Female ☒
PASSENGER 2	
Name:	Gender: Male ☐ Female ☐
PASSENGER 3	
Name:	Gender: Male ☐ Female ☐
PASSENGER 4	
Name:	Gender: Male ☐ Female ☐
PASSENGER 5	
Name:	Gender: Male ☐ Female ☐
PASSENGER 6	
Name:	Gender: Male ☐ Female ☐
PASSENGER 7	
Name:	Gender: Male ☐ Female ☐
PASSENGER 8	
Name:	Gender: Male ☐ Female ☐
PASSENGER 9	
Name:	Gender: Male ☐ Female ☐
PASSENGER 10	
Name:	Gender: Male ☐ Female ☐



MOTOR ACCIDENT INTERVIEW FORM

NAME (DRIVER) : TAN GEE LOCK
VEHICLE NUMBER : SKQ 8653 T
DATE/TIME OF ACCIDENT : 20 AUG , 6:20 (about)
PLACE OF ACCIDENT : T junction, AMK AVE 6 and AMK Street 31
THIRD PARTY VEHICLE (IF ANY) : SHA 1778 H

WHERE DID YOU START YOUR JOURNEY AND WHERE WAS THE INTENDED DESTINATION BEFORE THE ACCIDENT?

I started from 700B AMK AVE 6, #01-320, 5562700, to pick up my daughter from school and go back home, 310A AMK AVE 1, #05-329, 5561310.

DID YOU DRINK ANY ALCOHOLIC DRINKS BEFORE YOU DRIVE ON THE DAY OF THE ACCIDENT? IF YES, DID THE TRAFFIC POLICE CONDUCT ANY BREATHE-ANALYSER TEST ON YOU? IF YES, WHAT IS THE RESULT?

NO.

WHAT IS THE TYPE OF COLLISION AND THE EXTENSIVENESS OF THE DAMAGES TO ALL VEHICLES INVOLVED?

Scratch collision. (TP HIT indicated) vehicle taking

WERE YOU OR YOUR PASSENGER/S INJURED? IF INJURED, WHICH HOSPITAL? WERE YOU TAKEN TO THE TRAFFIC POLICE FOR INVESTIGATION?

NO injury.

GLW
TAN GEE LOCK

.....
Name:

I Affirmed The Above Information Is Given To My Best Knowledge.

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8026564F



Name

TAN GEE LOCK
(CHEN RULE)

陈如乐

Race

CHINESE

Date of birth

05-09-1980

Sex

M

Country of birth

SINGAPORE

S8026564F

REPUBLIC OF SINGAPORE DRIVING LICENCE



License Number: S8026564F

Name:

TAN GEE LOCK
(CHEN RULE)

Birth Date: 05 Sep 1980

Issue Date: 10 Jul 2003



NRIC No: S8026564F

Date of issue

13-09-2010

ART DES 310A AND MO KIO AVENUE 1 #05-389
SINGAPORE 581310

NRIC No: S8026564F

Date: 17/05/2012

No: 7099030

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3

Motor Cars and Motor Tractors the weight of
which (including does not exceed 2500 kilograms

PASS DATE

25 Jul 1999



NP 438A

AUTOPLUS PRIVATE VEHICLE

Name of Policyholder : Tan Gee Lock (Chen Rule)
Period of Insurance : 02 Jan 2019 To 01 Jan 2020
Engine No. : 2ZRB485812
Chassis No. : JTDGG20W50J001956

Vehicle No. : SKQ8653T
Policy No. : 2100397570-04
Endorsement No. :
Issued Date : 04 Dec 2018

ABOUT THE COVER

Make/Model : TOYOTA NEW WISH
Engine Capacity/Tonnage : 1,798.00 CC
Driver Restriction : NA
Person or Classes of Persons Entitled to Drive* :

Sum Insured : Market Value
Off Peak Car : No

First Year of Registration : 2015
Insuring with COE/PARF : Yes

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less years' driving experience.

Age Condition : All Age Condition
Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trials, speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Tan Gee Lock (Chen Rule) - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Approved Reporting Centres/ AIG Authorised Repairers (For claims related repairs)

Any accident repairs to the Vehicle must be carried out by one of our Authorised Repairers. Within the first 3 years of the first registration of the Vehicle in Singapore, You have the option of having the accident repairs carried out at the Sole Agent's workshop.

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, You may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: TOKYO CENTURY LEASING (SINGAPORE) PTE LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0030210000

AIG ASIA PACIFIC INSURANCE PL
 78 SHENTON WAY #07-16 AIG BUILDING
 SINGAPORE 079120

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Manile

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE
 AIGSGM



Co Reg No. : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyota.com.sg

Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept	S1000005 / ICFIC1	Mr Tan Gee Lock 310A Ang Mo Kio Avenue 1 #05-389 Singapore 561310 Mobile: 91290980
	Document No 0	
	Document Date 17/09/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
14	HPXNP	S4	2GE20R	02/01/2015	SKQ8653T	0	18856 :9DS/SKQ8653T-20081:

Chassis No	Engine No	Terms	Service Engineer	Vehicle in	Collected On
JTDGG20W50J001956	2ZRB485812	60	Raymond Seah L M	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP VEH:SHA1778H ACC DATE:20/08/2019 TP INS:1ST CAP NO OF REPAIR DAYS: DATE-IN:17/09/2019 DATE SURVEY:17/09/2019 BY:LKK- AUTHORIZED ON:12/09/2019 -TP/DS CLAIM				30.00
2	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				180.00
3	S	BP-SUBLET TO SUPPLY AND INSTALL FRONT NO. PLATE WITH CASING. / Sca	E33			68.00
4	B	BP-LAB2 TO CHECK WIRING AND LIGHTING. TO FOCUS HEADLAMP.				122.40
5	B	BP-LAB2 TO REPLACE FRONT ACCIDENT DAMAGE PARTS. STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS.				3600.00
6	B	BP-RES2 TO SPRAY PAINT ON FRONT ACCIDENT AFFECTED AREAS.				2950.00
7	1	T81145-68100 UNIT, HEADLAMP RH X NN	1.00	1265.70		1265.70
8	2	T81185-68100 UNIT, HEADLAMP LH / Sca CAA	1.00	1265.70		1265.70
9	3	T81220-47010 LAMP ASSY, FOG, LH X	1.00	295.20		295.20
10	4	T52040-68010 L/F BUMPER HOLE COVER X	1.00	85.50		85.50
11	5	T52618-68010 F/LOWER BPR ABSORBER, X NN	1.00	142.60		142.60

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Material Lubricants Others	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 17/09/2019
TIME 09:12

Acknowledged by Repairer
Signature:
Date:

4036627

4036627

VEHICLE NO SKQ8653T

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape



Borneo Motors (Singapore) Pte Ltd

Online Service Booking

www.toyota.com.sg

Toyota Bodycare Centre

17 Ubi Road 4

Singapore 409611

Tel no.: 6631 1188

Co Reg No. : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE**

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No	Customer Detail
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept	S1000005 / ICFIC1	Mr Tan Gee Lock 310A Ang Mo Kio Avenue 1 #05-389 Singapore 561310 Mobile: 91290980
	Document No 0	
	Document Date 17/09/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
14	HPXNP	S4	2GE20R	02/01/2015	SKQ8653T	0	18856 :9DS/SKQ8653T-20081:
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTDGG20W50J001956	2ZRB485812	60	Raymond Seah L M	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
12	6	T53149-68010 PROTECTOR RADIATOR	1.00	32.40		32.40
13	7	T53113-68010 L/F LWR RADIATOR GRILLE	1.00	57.00		57.00
14	8	T52119-68909 FRONT BUMPER COVER	1.00	591.80		591.80
15	9	T53879-28010 RETAINER, FR FENDER	2.00	10.50		21.00
16	0	T52115-68031 R/FRT BUMPER SUPPORT	1.00	62.80		62.80
17	1	T52116-68031 L/FRT BUMPER SUPPORT	1.00	62.80		62.80
18	2	T52611-68030 FRT BUMPER ABSORBER	1.00	101.90		101.90
19	3	T52021-68020 FRT BPR REINFORCEMENT	1.00	305.20		305.20
20	4	T53101-68010 GRILLE, RADIATOR	1.00	415.10		415.10
21	5	S52161-OK040 CLIPS	4.00	4.10		16.40
22	6	T90975-02086 FRONT BONNET EMBLEM	1.00	72.20		72.20
23	7	T53301-68020 FRONT BONNET ASSY	1.00	977.80		977.80
24	8	T53410-68030 R/FRT BONNET HINGE	1.00	58.90		58.90
25	9	T53420-68030 L/FRT BONNET HINGE	1.00	58.90		58.90
26	0	T53812-68060 FENDER SUB-ASSY, LH	1.00	988.40		988.40

Handwritten notes:
 19/9/19
 before paint photos.
 17/9/19

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	13,827.70
	Please acknowledge receipt of vehicle	Parts	6,877.30	GST 7.00%
		Labour	6,882.40	
		Materials	68.00	
		Lubrication/Fluid	0.00	
		Others	0.00	
			Less	0.00
			Amount Due	14,795.64

PLEASE TEAR ALONG PERFORATED LINE

4036628

TO SECURITY GUARD

4036628

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 17/09/2019
TIME 09:12

VEHICLE NO SKQ8653T

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**

Inchcape



o Reg No : 196700086Z
ST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd
Online Service Booking :
www.toyota.com.sg
Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188

Account Detail		Account No	Customer Detail	
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept		S1000005 / ICFIC1	Mr Tan Gee Lock 310A Ang Mo Kio Avenue 1 #05-389 Singapore 561310 Mobile: 91290980	
		Document No		
		Document Date		
		0		
		19/09/2019		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
4	HPXNP	S4	ZGE20R	02/01/2015	SKQ8653T	0	18856 :9DS/SKQ8653T-20081:

Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On
TDGG20W50J001956	22RB485812	60	Raymond Seah L M	17/09/2019 10.57	19/09/2019 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP VEH:SHA1778H ACC DATE:20/08/2019 TP INS:1ST CAP NO OF REPAIR DAYS:04 DATE-IN:17/09/2019 DATE SURVEY:17/09/2019 BY:LKK-GUO QIANG AUTHORIZED ON:12/09/2019 -TP/DS CLAIM				30.00
2	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				180.00
3	S	BP-SUBLET TO SUPPLY AND INSTALL FRONT NO. E33 PLATE WITH CASING.				68.00
4	S	BP-SUBLET TO CHECK WIRING AND LIGHTING. A45 TO FOCUS HEADLAMP.				122.40
5	S	BP-SUBLET TO REPLACE FRONT ACCIDENT DAMAGE PARTS. A45 STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS.				720.00
6	S	BP-SUBLET TO SPRAY PAINT ON FRONT ACCIDENT A45 AFFECTED AREAS.				1180.00
7	1	T81185-68100 UNIT, HEADLAMP LH	1.00	1265.70		1265.70
8	2	T52119-68909 COVER, FR BUMPER	1.00	591.80		591.80
9	3	T52611-68030 ABSORBER FR BUMPER	1.00	101.90		101.90
10	4	T90975-02086 EMBLEM, SYMBOL	1.00	72.20		72.20

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	4,332.00
		Labour	
		Materials	2,031.60
		Lubrication/Fluid	210.00
		Others	2,090.40
			0.00
			0.00
			Amount Due
			4,635.24

PLEASE TEAR ALONG PERFORATED LINE

SECURITY GUARD
LEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 19/09/2019
TIME 08:32

VEHICLE NO SKQ8653T

CUSTOMER SIGNATURE FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motor

Vehicle Diagnostic Report

2ZRFAE

SKQ8653T

Borneo Motors

Printed By: Default User(1)

20/09/2019 11:29:28 AM

Health Check Results All Systems(1 of 1)

Enhanced	System	DTC Related Information					RoB	Calibration
		FFD	DTC	Curr Conf	Pend	Hist		
	Engine and ECT	Yes	P1604	X		X	-	36824200
							-	A0C01000
	ABS/VSC/TRC						-	F152668071
	EMPS						-	JCF305F0
	Air Conditioner						-	838006827102
	Combination Meter						-	660C1SCV**02
	Main Body						-	-
	D-Door Motor						-	-
	Entry&Start						-	-
	P-Door Motor						-	-
	RR-Door Motor						-	-
	RL-Door Motor						-	-
	Master Switch						-	-
	HL AutoLeveling						-	8917F68010
	SRS Airbag						-	-
	PM2 Gateway						-	-
	Starting Control						-	-
	Power Source Control						-	-

Vehicle Diagnostic Report

2ZRFAE

SKQ8653T

Borneo Motors

Printed By: Default User(1)

20/09/2019 11:30:35 AM

Health Check Results All Systems(1 of 1)

Enhanced

System	DTC Related Information						RoB	Calibration
	FFD	DTC	Curr Conf	Pend	Hist	Test Failed		
Engine and ECT								36824200
								A0C01000
ABS/VSC/TRC								F152668070
EMPS								JCF305F0
Air Conditioner								-
Combination Meter								838006825001
Main Body								660C1SCV**02
D-Door Motor								-
Entry&Start								-
R-Door Motor								-
RR-Door Motor								-
RL-Door Motor								-
Master Switch								-
HL AutoLeveling								-
IRS Airbag								8917F68010
M2 Gateway								-
Starting Control								-
Power Source Control								-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19014969/Gsd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 24-09-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 1778H	Veh. Inspected	SKQ 8653T
Policy No.		Coverage (\$)	0.00
Claim No.	D19005433MFSH	Excess (\$)	0.00
Assign From	JASON TEA	Assign Date	23/08/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA WISH	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JTDGG20W50J001956	Colour	SILVER
Odometer	72731	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	20/08/2019	Inspection Date	17/09/2019
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKQ 8653T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	UNIT,HEADLAMP RH (SN)	NOT NECESSARY	1,265.70	-
1	UNIT,HEADLAMP LH (SN)	CRACKED	1,265.70	1,265.70
1	LAMP ASSY,FOG,LH (SN)	NOT NECESSARY	295.20	-
1	L/F BUMPER HOLE COVER (SN)	NOT NECESSARY	85.50	-
1	F/LOWER BPR ABSORBER (SN)	NOT NECESSARY	142.60	-
1	PROTECTOR RADIATOR (SN)	NOT NECESSARY	32.40	-
1	L/F LWR RADIATOR GRILLE (SN)	NOT NECESSARY	57.00	-
1	FRONT BUMPER COVER (SN)	CUT	591.80	591.80
2	RETAINER,FR FENDER (SN)	NOT NECESSARY	21.00	-
1	R/FRT BUMPER SUPPORT (SN)	NOT NECESSARY	62.80	-
1	L/FRT BUMPER SUPPORT (SN)	NOT NECESSARY	62.80	-
1	FRT BUMPER ABSORBER (SN)	CRACKED	101.90	101.90
1	FRT BPR REINFORCEMENT (SN)	NOT NECESSARY	305.20	-
1	GRILLE RADIATOR (SN)	NOT NECESSARY	415.10	-
4	CLIPS (SN)	NOT NECESSARY	16.40	-
1	FRONT BONNET EMBLEM (SN)	NECESSARY	72.20	72.20
1	FRONT BONNET ASSY (SN)	TO REPAIR SEE LABOUR	977.80	-
1	R/FRT BONNET HINGE (SN)	NOT NECESSARY	58.90	-
1	L/FRT BONNET HINGE (SN)	NOT NECESSARY	58.90	-
1	FENDER SUB-ASSY,LH (SN)	NOT NECESSARY	988.40	-
1	SUNDRIES (SN)	NECESSARY	30.00	30.00
1	FRONT NO PLATE WITH CASING (SN)	SCRATCHED	68.00	68.00
			6,975.30	2,129.60
LABOUR				
TO RESET ECU AND REPROGRAMME.			180.00	180.00
TO CHECK WIRING AND LIGHTING,TO FOCUS HEADLAMP.			122.40	122.40
TO REPLACE FRONT ACCIDENT DAMAGE PARTS,STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF FRONT BONNET ASSY.			3,600.00	720.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY PAINT ON FRONT ACCIDENT AFFECTED AREAS.		2,950.00	1,180.00
			6,852.40	2,202.40
GRAND TOTAL			13,827.70	4,332.00
RECOMMENDED COST OF REPAIRS				4,332.00

Report Ref No. CS/FCI19014969/Gsd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.