



Owner: CFI TRANSPORT PTE LTD
 Vehicle Reg No: GBF 5349A
 Make / Model: NISSAN NV350

Date: 20 AUGUST 2019

Dear Sirs,

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

Cost Price

QTY	LIST ITEMS	AMOUNT(US)
1	Front panels / <i>Buc</i>	\$ 858.60
1	Front corner panels LH / <i>Buc</i>	\$ 477.60
1	Front door LH / <i>Buc</i>	\$1015.60
1	Front door inner board ?	\$481.70
2	Front door hinges X <i>NN</i>	\$58.10
1	Door Pillar X <i>Repairs</i>	\$152.80
1	Front door regulator motor X <i>NN</i>	\$147.90
1	Door Check link X <i>NN</i>	\$66.00
1	Front bumper / <i>CRA</i>	\$ 514.70
1	Front bumper fog lamps L/H ?	\$ 311.80
1	Front bumper fog lamp covers L/H / <i>CRA</i>	\$ 91.60
1	Front bumper reinforcement L/H ?	\$ 591.90
1	Front bumper reinforcement stays L/R ?	\$ 91.70
1	Front bumper bracket L/H ?	\$ 110.00
1	Front bumper tow hook cover X	\$ 19.40
1	Air con blower unit X	\$ 851.10
1	Air intake duct X	\$ 179.00
1	Front wiper motor X	\$ 242.40
1	Front wiper garnish (1 set) X	\$ 432.00
1	Front wiper link (1 set) X	\$ 210.00
1	Intercooler X	\$ 2121.60
1	Intercooler hose X	\$ 189.00
1	Front step panel L/H / <i>Cut</i>	\$ 65.00
1	Front headlamp L/H / <i>Cut</i>	\$ 380.00
1	Front grille / <i>M.S</i>	\$ 480.00
1	Front grille logo / <i>M.C.</i>	\$ 65.00
1	Air con cooling coil (aircon housing) -Full set X <i>NN</i>	\$ 2,100.00

Total	\$ 12294.50
Additional 10%	\$ 1229.45
Total of List Items	\$ 13523.95

QTY	SPECIAL NETT ITEMS	AMOUNT (SGD)
1	Front grille clip (1 set) <i>MSC.</i>	\$ 45.00
1	Front bumper clip (1 set)	\$ 25.00
1	Front car plate <i>BT</i>	\$ 30.00
Total		\$ 100.00
Additional 10%		\$ 10.00 X
Total List Items		\$ 110.00

S/N	LABOUR CHARGES	AMOUNT
1	To remove, replaced damaged lamps & checkup rear wiring	\$ 80.00 <i>30</i>
2	To remove & refit inner garnishes	\$ 150.00 <i>60</i>
3	To remove, replace air-con and conduct leakage test	\$ 200.00 <i>?</i>
4	To remove & refit dashboard to assist repair	\$ 250.00 <i>?</i>
5	To remove and refit front windscreen glass	\$ 180.00 <i>x</i>
6	To apply undercoating on repaired and repaired panel	\$ 350.00 <i>60</i>
7	Panel beating	\$ 2,000.00 <i>500</i>
8	To re-spray on the affected areas & polishing back	\$ 1,600.00 <i>800.</i>
Total		\$ 4,810.00

GRAND TOTAL (Total Parts + Total Labour) \$ 18443.95

(S) 075

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Not Authorised. *28/8/19*

Excess: TBA
part by part.
~~Insurance report.~~ 5 Days.

before/After repair photos.

Lim Qiang - 82880282
26/8/19.

Veron Chen (LKKAUTO)

From: Gforce auto <gforce.workforce@gmail.com>
Sent: Friday, 30 August 2019 4:07 PM
To: Veron Chen (LKKAUTO)
Subject: Re: GBH 5339A-DOA: 5/7/2019 (MSIG OD)

Dear Veron

after dismantle need to add supplementary item

- ~~Car center door~~ \$250

Front LH ~~door~~ Door lock \$250 / BT

Please revert.

Best Regards,

Derek

Gforce Autotech Pte Ltd
10 Kaki Bukit Rd 2
First East Centre
#01-34 S417868
Tel no: +65-6205 8108

On Wed, Aug 28, 2019 at 3:05 PM Veron Chen (LKKAUTO) <veronchen@lkkauto.com> wrote:

Dear Adrian,

As instructed by our client , please proceed to repair the **insured vehicle GBH 5339A (Excess \$600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Owner: CH TRANSPORT PTE LTD
Vehicle Reg No.: GBF 5339A
Make / Model: NISSAN NV350

Date: 20 AUGUST 2019

Dear Sirs,

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

<u>QTY</u>	<u>LIST ITEMS</u>	<u>AMOUNT(S\$)</u>
1 /	Front panels / <i>Buc</i>	\$ 858.60
1 /	Front corner panels LH / <i>Buc</i>	\$ 477.60
1 /	Front door L/H / <i>Buc</i>	\$1015.60
1	Front door inner board <i>X suc</i>	\$481.70
2	Front door hinges <i>X un</i>	\$58.10
1	Door Pillar <i>X depends</i>	\$152.80
1	Front door regulator motor <i>X un</i>	\$147.90
1	Door Check link <i>X un</i>	\$65.00
1 /	Front bumper / <i>CRA</i>	\$ 514.70
1 /	Front bumper fog lamps L/H <i>CRA</i>	\$ 311.80
1 /	Front bumper fog lamp covers L/H <i>CRA</i>	\$ 91.60
1 /	Front bumper reinforcement L/H <i>BT</i>	\$ 591.90
1	Front bumper reinforcement stays L/H <i>X suc</i>	\$ 91.70
1 /	Front bumper bracket L/H <i>CRA</i>	\$ 110.00
1	Front bumper tow hook cover <i>X suc</i>	\$ 19.40
1 /	Air con blower unit <i>CRA</i>	\$ 851.10
1	Air intake duct <i>X un</i>	\$ 179.00
1	Front wiper motor <i>X suc</i>	\$ 242.40
1	Front wiper garnish (1 set) <i>X un</i>	\$ 432.00
1 /	Front wiper link (1 set) <i>BT</i>	\$ 210.00
1	Intercooler <i>X un</i>	\$ 2121.60
1	Intercooler hose <i>X un</i>	\$ 180.00
1 /	Front step panel L/H <i>CRA</i>	\$ 65.00
1 /	Front headlamp L/H <i>CRA</i>	\$ 380.00
1 /	Front grille / <i>Mis</i>	\$ 480.00
1 /	Front grille logo / <i>Mis</i>	\$ 65.00
1	Air con cooling coil (aircon housing) -Full set <i>X un</i>	\$ 2,100.00

Total	\$ 12294.50
Additional 10%	\$ 1229.45
Total of List Items	\$ 13523.95

<u>QTY</u>	<u>SPECIAL NETT ITEMS</u>	<u>AMOUNT (SGD)</u>
✓ 1	Front grille clip (1 set) <i>1 set</i>	\$ 45.00
✓ 1	Front bumper clip (1 set) <i>1 set</i>	\$ 25.00
✓ 1	Front car plate <i>BM</i>	\$ 30.00
	Total	\$ 100.00
	Additional 10%	\$ 10.00
	Total List Items	\$ 110.00

<u>S/N</u>	<u>LABOUR CHARGES</u>	<u>AMOUNT</u>
1	To remove, replaced damaged lamps & checkup rear wiring	\$ 80.00 <i>30</i>
2	To remove & refit inner garnishes	\$ 150.00 <i>60</i>
3	To remove, replace air-con and conduct leakage test	\$ 200.00 <i>2</i>
4	To remove & refit dashboard to assist repair	\$ 250.00 <i>2200</i>
5	To remove and refit front windscreen glass	\$ 180.00 <i>X</i>
6	To apply undercoating on repaired and repaired panel	\$ 350.00 <i>60</i>
7	Panel beating	\$ 2,000.00 <i>500 700</i>
8	To re-spray on the affected areas & polishing back	\$ 1,600.00 <i>800</i>
	Total	\$ 4,810.00
	GRAND TOTAL (Total Parts + Total Labour)	\$ 18443.95

13708.95

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

Not Authorised.
Excess: TBA
Lump sum repair. 5 Days.
After repair photos.
Geo Q:amp - 82880282

Geo Q:amp. 26/8/19.
LKK 30/8/19.

GFORCE AUTOTECH PRIVATE LIMITED

10 KAKI BUKIT ROAD 2 #01-34
SINGAPORE 417868
MOBILE: +65-9139 1448
CO REGISTRATION NO: 201631929K



GFORCE
AUTOTECHNIK

Date: 2nd September 2019

To: LKK Auto Consultants Pte Ltd

For the vehicle GBH 5339

after dismantled, we found out that need to add in 1 supplementary item

- Car center door \$250 **BT**



Best Regards,

Derek

Gforce Autotech Pte Ltd

10 Kaki Bukit Rd 2

First East Centre

#01-34 5417868

Tel no: +65-6205 8108

GFORCE AUTOTECH PRIVATE LIMITED

10 KAKI BUKIT ROAD 2 #01-34

FIRST EAST CENTER

SINGAPORE 417868

MOBILE: +65 91391448

CO.REGISTRATION NO: 201631929K



Owner: CFI TRANSPORT PTE LTD
Vehicle Reg No: GBF 5399A
Make/Model: NISSAN NV350

Date: 20th August 2019

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

<u>S/N</u>	<u>LIST ITEMS</u>	<u>QTY</u>	<u>AMOUNT \$</u>
	Front panels	1	\$ 858.60
	Front corner panels LH	1	\$ 477.60
	Front door L/H	1	\$ 1,015.60
	Front bumper	1	\$ 514.70
	Front bumper fog lamps L/H	1	\$ 311.80
	Front bumper fog lamp covers L/H	1	\$ 91.60
	Front bumper reinforcement L/H	1	\$ 591.90
	Front bumper bracket L/H	1	\$ 110.00
	Air con blower unit	1	\$ 851.10
	Front wiper link (1 set)	1	\$ 210.00
	Front step panel L/H	1	\$ 65.00
	Front headlamp L/H	1	\$ 380.00
	Front grille	1	\$ 480.00
	Front grille logo	1	\$ 65.00
	Car centre door	1	\$ 250.00
	Sub-Total		\$ 6,272.90
	Additional 10%		\$ 627.29
	Total Amount		\$ 6,900.19

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 4 September 2019 11:30 AM
To: Gforce auto; SUR
Subject: RE: FW: GBH 5339A-DOA: 5/7/2019 (MSIG OD)

Dear Derek,

Confirmed mount \$8850.19 before excess \$600 @ 5 working days.

For parts GST please submit in separate bill.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Gforce auto <gforce.workforce@gmail.com>
Sent: Wednesday, 4 September 2019 10:41 AM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: Re: FW: GBH 5339A-DOA: 5/7/2019 (MSIG OD)

Dear Veron

the parts invoice

Best Regards,

Derek

Gforce Autotech Pte Ltd

10 Kaki Bukit Rd 2

First East Centre

#01-34 S417868

Tel no: +65-97706106

On Tue, Sep 3, 2019 at 10:47 AM Gforce auto <gforce.workforce@gmail.com> wrote:

Dear Veron

the additional 10% for Special Nett Items.

-deleted

So i proceed?

Best Regards,

Derek

Gforce Autotech Pte Ltd
10 Kaki Bukit Rd 2
First East Centre
#01-34 S417868
Tel no: +65-97706106

On Tue, Sep 3, 2019 at 10:41 AM Veron Chen (LKKAuto) <veronchen@lkkauto.com> wrote:

Dear Derek,

No additional 10% for Special Nett Items.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Gforce auto <gforce.workforce@gmail.com>
Sent: Tuesday, 3 September 2019 10:23 AM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: Re: GBH 5339A-DOA: 5/7/2019 (MSIG OD)

Dear Veron

Please double confirm whether is all correct first before i pass you the invoice

Best Regards,

Derek

Gforce Autotech Pte Ltd

10 Kaki Bukit Rd 2

First East Centre

#01-34 S417868

Tel no: +65-97706106

On Tue, Sep 3, 2019 at 10:01 AM Veron Chen (LKKAuto) <veronchen@lkkauto.com> wrote:

Dear Derek,

Please provide parts invoice for finalise.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Gforce auto <gforce.workforce@gmail.com>

Sent: Tuesday, 3 September 2019 9:58 AM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Subject: Re: GBH 5339A-DOA: 5/7/2019 (MSIG OD)

Dear Veron

yesterday i was very busy when you called. And i forget what you asked me to do. Can you repeat again?

So sorry for any inconvenience caused.

Best Regards,

Derek

Gforce Autotech Pte Ltd

10 Kaki Bukit Rd 2

First East Centre

#01-34 S417868

Tel no: +65-97706106

On Mon, Sep 2, 2019 at 11:08 AM Gforce auto <gforce.workforce@gmail.com> wrote:

Best Regards,

Derek

Gforce Autotech Pte Ltd

10 Kaki Bukit Rd 2

First East Centre

#01-34 S417868

Tel no: +65-6205 8108

On Mon, Sep 2, 2019 at 10:55 AM Gforce auto <gforce.workforce@gmail.com> wrote:

Dear Veron

this is the letter with company letter head you requested

Best Regards,

Derek

Gforce Autotech Pte Ltd

10 Kaki Bukit Rd 2

First East Centre

#01-34 S417868

Tel no: +65-6205 8108

On Fri, Aug 30, 2019 at 4:07 PM Gforce auto <gforce.workforce@gmail.com> wrote:

Dear Veron

after dismantle need to add supplementary item

- Car center door \$250

Please revert.

Best Regards,

Derek

Gforce Autotech Pte Ltd

10 Kaki Bukit Rd 2

First East Centre

#01-34 S417868

Tel no: +65-6205 8108